

MOTORIMAGE ENTERPRISES PTE. LTD.

19 LORONG 8, TOA PAYOH

SINGAPORE 319255

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : TOA PAYOH
CONTACT NO : 64730333
REFERENCE : INS/IC/CHI/1033/2018
DATE : 15-NOV-2018

AXA INSURANCE PTE LTD

8 SHENTON WAY

#27-01 AXA TOWER

S(068811)

TEL : 63387288

FAX : 68804838/ 3382522

MS LINA EXT: 824

OWNER'S NAME : ENG KEE WEE (HUANG JIWEI)

ADDRESS : BLK 156 RIVERVALE CRESCENT #01-164

S(540156)

TELEPHONE NO : 91894462

TYPE OF CLAIM : THIRD PARTY CLAIM

POLICY NO : 1700083520

VEHICLE NO : SLU4317H

MODEL CODE : SJ5EK7C

MODEL/YEAR : FORESTER 2.0I-L AWD CVT

ENGINE NO : FB20YB44407

CHASSIS NO : JF1SJ5KC5JG100386

MILEAGE : 1 KM

DATE IN : 15/11/2018

LIABILITY : 0.00

EXCESS CLAUSE : 0.00

ESTIMATE BY : DANIEL A JUDE**

ACCIDENT DATE : 04/11/2018

Print Date : 15/11/2018

Print Time : 11:50:01

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLU4317H

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	TPCLAIM	CONDUCT BODYWORK REPAIR (THIRD PARTY CLAIM) AGAINST SMD8311A - AXA INSURED		
2	ZZ/001	CONDUCT TP CLAIM AXA LOCATION:SHEARES AVE 1 MARINA BLVD DATE:04/11/2018 TIME:1103HRS		
3	ZZ/002	REPAIR/REPLACE RR BUMPER AND PANEL	1680.00	
4	ZZ/003	RESPRAY RR BUMPER,RR LEFT FENDER AND PANEL	1680.00	
5	ZZ/004	TRANSFER / BALANCE TYRE / RIM	50.00	
6	ZZ/005	4 WHEEL ALIGNMENT	200.00	
7	ZZ/006	FAULT DIAGNOSTIC AND RESET SYSTEM	280.00	
8	ZZ/007	TO CONDUCT PROTECTANT COATING	500.00	
9	ZZ/008	TO CONDUCT ANTI-RUST COATING	580.00	
10	ZZ/009	TO SUPPLY AND INSTALL REVERSE SENSOR-2EYES	300.00	
11	ZZ/011	TO CONDUCT REAR LIGHTING TEST	50.00	
12	ZZ/10	SUNDRIES	100.00	
TOTAL LABOUR CHARGES			5420.00	

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLU4317H

		DAMAGED PARTS & PRICES				
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT	S/LIST REMARKS
1	DISC WHEEL AL 17	28111SG130	1500.00			
2	SKIRT COMPL R	52401SG0109P	288.00			
3	BUMPER FACE REAR FORESTER IL	57704SG012	540.00			
4	BRKT SD R RH	(1) 57707SG080	14.40			
5	BRKT SD R LH	57707SG090	14.40			
6	BEAM COMPL R EU	57711SG0219P	288.00			
7	COVER HOOK R	57731SG010NN	12.60			
8	COVER BMFR R (EXHAUST)	57731SG060	14.40			
9	MUD GUARD R LH	59122SG070	57.60			
10	LENS & BODY COMPLJPL	84912SG111	432.00			
11	CARGO STEP PANEL SILVER	E7710SG000	460.00			
12	FORESTER 2.0I-S KIT REAR UNDER SPOILER (TCS)	TCS-FJ8-RL-002	1656.00			
SUB TOTAL			5277.40	0.00	0.00	0.00
LESS DISCOUNT (NETT-20 %)			1055.48	0.00	0.00	0.00
GRAND TOTAL			4221.92	0.00	0.00	0.00
OVERALL TOTAL			4221.92			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SLU4317H

TOTAL LABOUR CHARGES	5420.00
TOTAL SPARE PARTS CHARGES	4221.92

GRAND TOTAL	9641.92 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.