

15/2/18

INS. CASE OWNER:

CC 3 /AIG1802

LKK:

IDAC:

Surveyor:

DOI:

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

Excess Sec II :SS

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call Of:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Repair Cost:

PIP

SS8,719.30

(4 days) Reduction:

19 %

Confirm by: YTH

Email ☒ Call ☐

FINAL SETTLEMENT

Date/Time: 27-3-19

Confirm with CAROLINE

Email ☒ Call ☐

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No.:

24

If NO or B 28, Ass. Lia:

Repair Cost:

W/L

SS9,339.65

OLD REVERSED INTO PARKING LOT 400 TP.

Loss of Rental (LOR):

SS -

(days)

Loss of Use (LOU):

SS 600.00

(S 120 x 5 days)

Loss of Income (LOI):

SS -

(S x days)

LOR only ☐ LOU only ☒LOR + LOU ☐LOR + LO ☐

[Tick only one]

GIA/LTA Search

SS 2.00

Medical:

SS -

Disbursement:

SS -

(e.g. Tow/ Independent)

Legal Cost

SS -

1) Claim status: Normal/Reject/Private Settle

2) Report Format: TP

3) Survey fee: 9320

Total:

SS9,931.65

Global Sum SS:

FINAL PAYMENT

Date/Time: 27-3-19

Confirm with: CAROLINE

Email ☒ Call ☐

Payee 1:

SS9,931.65

Name 1: PERFORMANCE MOTORS LIMITED

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

Tampkin

1A 1G7

2

ASSIGNMENT

PIP: +8,719.30 (RED: +2,012.45 19%)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CC3/AIG18020795/eb3

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 16-11-2018



Code : AIG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKV 2086T	Veh. Inspected	SKF 1665M
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	16/11/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	09/11/2018	Inspection Date	
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

Mon 26/11 @ 9am
S&R

SKF1665M

BMW Dealer

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To resurvey damaged part(s) during resurvey
- To resurvey after confirmation
- To resurvey without "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and confirmed from Insurance Company

16 NOV 2018

Signature: _____
Date: _____



GST REG. NO : M2 - 0020081-X

ESTIMATE

Estimate No. : b1 49096
Date Estimated : 13/11/2018
Prepared By : Han Kwan Yong

Page No. : 1 of 4

- ESTIMATE REPAIR FOR -

Chin Yun Fang
31 Tai Keng Gardens

Singapore 535312

- ACCOUNT - 40000

Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKF1665M	C951344	30/12/2011	730LiA	0

DESCRIPTION

To replace front bumper & attachments including to knock out front right fender and dented area caused by the accident

To respray front bumper and front right fender

To check electrical wiring systems at the front section for proper function including adjustments of headlights.

Sundries.

VALUE

1700, 2,550.00

1730, 1,923.00

150, 177.00

rec 80.00

Total Labour 1: 4,730.00

DESCRIPTION

PLASTIC NUT
FRT BUMPER TOP CARRIER
FRT BUMPER RH MOULDING (CHROME)
FRT BUMPER FLAP COVER SPRING
FRT BUMPER RH FLAP COVER (PRIMED)
FRT BUMPER (PDC)

C-CLIP NUT

FRT BUMPER TOP IMPACT ABSORBER

RH HIGH PRESSURE NOZZLE

QTY PRIC VALUE

4 0.90 3.60

1 814.70 814.70

1 36.80 36.80

1 5.25 5.25

1 51.95 51.95

1 1,510.95 1,510.95

10 1.30 13.00

1 69.10 69.10

1 183.80 183.80

Total Parts : 2,689.15

Claims On / For Part / Under Insurance / Out Settlement

Regn No. _____

Date & Time _____ Excess \$ _____

Surveyor's Name _____ Sign _____

Surveyor's Tel _____ Authorised Yes / No _____

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No

Surveyor's E-mail _____

No. of Working Days Recommend _____

Labour 1 : 4,730.00

Parts : 2,689.15

Labour 2 : 0.00

Excess : 0.00

Total GST @ 7% : 519.34

Grand Total : 7,938.49

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

10731.75

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



SUPPLEMENTARY

Estimate No. : b1 49096
Date Estimated : 13/11/2018
Prepared By : Han Kwan Yong

Page No. :

REPAIR FOR -
Chin Yun Fang
31 Tai Keng Gardens

- ACCOUNT - 121
AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

Singapore 535312

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE
SKF1665M	C951344	30/12/2011	730LiA	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
# To replace RH bi xenon headlight include programming and conducting tests for proper function	451.00		451.00 <i>net</i>

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# RH BI-XENON HEADLIGHT *	2,861.60	1.00		2,861.60 <i>net</i>

Total Labour :	451.00
Total Parts :	2,861.60
Total Labour & Parts :	3,312.60

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



FINAL REPORT

Estimate No. : b1 49096
Date Estimated : 13/11/2018
Prepared By : Han Kwan Yong

Page No. :

REPAIR FOR -
Chin Yun Fang
31 Tai Keng Gardens

- ACCOUNT - 121
AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

Singapore 535312

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE
SKF1665M	C951344	30/12/2011	730LiA	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	
To replace front bumper and attachments, RH high pressure nozzle include making good the front RH fender and knocking out dents caused by the accident	1700.00		1,700.00	
To respray front bumper and front RH fender	1730.00		1,730.00	
To check electrical wiring systems at the front section for proper function	150.00		150.00	
# To replace RH bi xenon headlight include programming and conducting tests for proper function	451.00		451.00	
Sundries	80.00		80.00	

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
FRT BUMPER RH FLAP COVER (PRIMED)	51.95	1.00		51.95
FRT BUMPER (PDC)	1,510.95	1.00		1,510.95
RH HIGH PRESSURE NOZZLE	183.80	1.00		183.80
# RH BI-XENON HEADLIGHT *	2,861.60	1.00		2,861.60

SUPPLEMENTARY ITEMS

Total Labour :	4,111.00
Total Parts :	4,608.30
Total Labour & Parts :	8,719.30
Deduction for Excess :	0.00
Total Repair Costs less Excess:	8,719.30
GST @7%:	610.35
Grand Total :	9,329.65

Asher Sng (LKKAUTO)

From: Asher Sng (LKKAUTO)
Sent: Tuesday, 20 November 2018 1:52 PM
To: PBSP; Shu Pei (LKKAUTO)
Cc: CS A Team; Admin A
Subject: RE: REQUEST FOR DIRECT SETTLEMENT - SKF1665M & SKV2086T ON 09/11/2018
***LKK REF:CC3/AIG18020795/EB3

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Hi Sir/Mdm,

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear / under BOLA (subject to BOLA guideline settlement) and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident. And the days of LOU/ LOR will base on the number of days of repair as recommended by our surveyor.

Kindly take note that the case handler in-charge is Asher and she can be contacted at her DID 6841 6051

In order to expedite the claim process, please forward all relevant documents to us (LKK) to proceed on negotiate settlement.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: ashersng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: PBSP <pml-pbsp@simedarby.com.sg>
Sent: Tuesday, 20 November 2018 11:47 AM
To: Shu Pei (LKKAUTO) <shupe@lkkauto.com>
Cc: CS A Team <cs-a@lkkauto.com>; Admin A <admin-a@lkkauto.com>
Subject: Re: REQUEST FOR DIRECT SETTLEMENT - SKF1665M & SKV2086T ON 09/11/2018 ***LKK
REF:CC3/AIG18020795/EB3

Dear Sirs,

Kindly reply on liability.

Thank you.

Regards,
Caroline
C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

From: Shu Pei (LKKAuto) <shupeil@lkkauto.com>

Sent: Friday, 16 November 2018 4:02:26 PM

To: PBSP

Cc: CS A Team; 甯珺 ©

Subject: FW: REQUEST FOR DIRECT SETTLEMENT - SKF1665M & SKV2086T ON 09/11/2018 ***LKK
REF:CC3/AIG18020795/EB3

Dear Caroline,

We refer to the below email.

Please be informed that we are currently pending for our insured's report.

Kindly note that for liability, claim negotiation and settlement, please contact Asher at 6841 6051.

Our respective case handler will look into the matter and revert to you in due course.

Thank you

To check availability of the case handler , you may contact the undersigned.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: PBSP <pml-pbsp@simedarby.com.sg>

Sent: Friday, 16 November 2018 10:52 AM

To: CS A Team <cs-a@lkkauto.com>; Admin A <admin-a@lkkauto.com>

Subject: REQUEST FOR DIRECT SETTLEMENT - SKF1665M & SKV2086T ON 09/11/2018

Dear Sirs,

We refer to the above matter.

We have instructions from our client to seek repair cost and loss of use/car rental from you through Direct Settlement.

Attached is the estimates and supporting documents for your consideration.

Please let us have your confirmation that you agree that liability is clear and we may proceed with Direct Settlement.

If Direct Settlement is approved, kindly let us have your offer for LOU / rental.

Thank you.

Regards,
Caroline
C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."

Asher Sng (LKKAuto)

From: Asher Sng (LKKAuto)
Sent: Monday, 25 February 2019 11:24 AM
To: 'Lee, Ming-Yao'
Subject: [MANDATE REQUEST] Your ref : 2715796484SG, ACCIDENT ON 09/11/2018 INVOLVING SKV 2086T (OI) & SKF 1665M (TP)

Your ref : **2715796484SG**
Our ref : CC3/AIG18020795/T1eb3

Dear Sirs,

ACCIDENT ON 09/11/2018 INVOLVING SKV 2086T (OI) & SKF 1665M (TP)

We refer to the above matter.

The accident occurred when our insured reversed into the parking lot hit third party parked vehicle.

Basing on the reports of the circumstance of the accident, we propose to settle third-party claim at 100% liability.

We did clarify with insured the nature of the accident and he's aware that NCD (if any) would be affected.

We seek your approval to offer repairer "**PERFORMANCE MOTORS LTD**" at **\$ 9,931.65 (all-in).**

The summary is as follows: -

	Amount Claimed	Amount Revised
1. Cost of Repairs (with GST)	\$ 11,482.97	\$ 9,329.65
2. Loss of Use (6days x \$120)	\$ 500.00	\$ 600.00 (5days x \$120)
3. LTA Search Fee	\$ 2.00	\$ 2.00
Total	\$ 12,084.97	<u>\$ 9,931.65</u>

For your approval in merimen please.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: ashersng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Print Received Message

This mail is associated with :

***SKF1665M (2715796484SG)**

[SKV2086T]

TP

CHIN YUN FANG

Nov 9 2018 7:00AM

[TRI ENERGY GLOBAL PTE LTD]

Performance Motors Limited

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 11/03/2019 19:03 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$9931.65) - SKF1665M - Claim Handler: Lee, Ming-Yao

Approved:9931.65:hi, May proceed to settle claim at best terms.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**AIG THIRD PARTY EXPRESS SETTLEMENT
FOR ACCIDENTS ON OR AFTER 1ST JUNE 2008
(PAYMENT BREAKDOWN)**

Vehicle No:	SKF 1665M	Model:	
Date of Accident:	9.11.2018		

Global Sum Settlement	: [] Yes [] No	
Repair Estimate	: \$	7938.49
Final Repair Cost	: \$	9329.65
Loss of Use	: \$	600.00
Rental (if any)	: \$	5 days at \$120 per day
LTA / GIA Search Fee	: \$	2.00
Others:	: \$	
	: \$	
Final Settlement Sum	: \$	9931.65

Is Third Party Workshop GIA Registered? [] YES [] NO (Kindly indicate below)	
A) For Non GIA Registered Workshop:	Agreed Liability _____ (%)
B) For GIA Registered Workshop:	BOLA Applicable: Yes/ No
	BOLA Scenario No: _____
BOLA Liability: _____ (%)	Assessed Liability (*): _____ (%)
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.	
Remarks	

Payment Instruction: Payee's Breakdown		
1)	Performance Motors Ltd	: \$ 9329.65
2)	Performance Motors Ltd	: \$ 2.00
3)	Chin Yun Fang	: \$ 600.00

Signed by appointed surveyor _____

Date _____

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act;
Survey Report; Medical Report/ Bill (if any))

SKF1665M -

Spoken with owner (Ms Chin) dated 29/11.

We will move up ~~to~~ the initial LOU ~~pro~~ (\$80)

Propose to her to between (\$100 - 120)

owner does not agreed with the initial proposed of \$80 by CSA Plan.

please also based on owner car high mileages usage for proposal to insurance for higher LOU.

Teng 30/11

SKF1665M -

Spoken with owner (Ms Chin) dated 29/11.

We will move up ~~to~~ the initial LOU ~~pro~~ (\$80)

Propose to her to between (\$100 - 120)

owner does not agreed with the initial proposed of \$80 by CSA Plan.

please also based on owner car high mileages usage for proposal to insurance for higher LOU.

Teng 30/11

...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	09 Nov 2018 Edit Reg		26 Nov 2018 00:00 Edit Adj Rpt	S\$8,719.30 Edit Estimates	S\$8,719.30 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	TRI ENERGY GLOBAL PTE LTD, Co. Reg. No.: 201523268Z		
Main Claimant:	CHIN YUN FANG, ID: S6837691B		
Vehicle Reg. No.:	SKF1665M	Date of Loss:	09/11/2018 07:00 - :59 [82 Months and 10 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 2715796484SG	Policy/Cover Note No.:	2100427651 (Comprehensive)
Vehicle Reg. No. (Insured):	SKV2086T	Policy No. (Claimant):	PNPV2018-00008570
		Excess:	
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Lee, Ming-Yao] MingYao.Lee@aig.com		
Claimant's Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 27/11/2018]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AIG_SG_EXPRESS (11/03/2019): Alert - Adj Mandate Approved (S\$9931.65) - SKF1665M - Claim Handler: Lee, Ming-Y...

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date Priority Type Task Group Subject Handler Assigned By Completed On Created On Done?

No results.

Claim Documents

*SKF1665M (2715796484SG)
[SKV2086T]
TP
CHIN YUN FANG
Nov 9 2018 7:00AM
[TRI ENERGY GLOBAL PTE LTD]
Performance Motors Limited

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View		View in Browser ▼	
Letters/Correspondences															1 per page ▼		<input checked="" type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail	Print		
1	(Draft)	Third Party Express Settlement – Payment Breakdown													Edit			
Photos/Images															3 per page ▼		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail	Print		
1	26/12/18 10:31	Odometer Reading													Load JPG	<input checked="" type="checkbox"/>		
2	26/12/18 10:31	Chassis Number													Load JPG	<input checked="" type="checkbox"/>		
3	26/12/18 10:31	General View													Load JPG	<input checked="" type="checkbox"/>		
4	26/12/18 10:31	General View													Load JPG	<input checked="" type="checkbox"/>		
5	26/12/18 10:31	General View													Load JPG	<input checked="" type="checkbox"/>		
6	26/12/18 10:31	General View													Load JPG	<input checked="" type="checkbox"/>		
7	26/12/18 10:31	General View													Load JPG	<input checked="" type="checkbox"/>		
8	26/12/18 10:31	General View													Load JPG	<input checked="" type="checkbox"/>		
9	26/12/18 10:31	General View													Load JPG	<input checked="" type="checkbox"/>		
10	26/12/18 10:31	General View													Load JPG	<input checked="" type="checkbox"/>		
11	26/12/18 10:31	General View													Load JPG	<input checked="" type="checkbox"/>		
12	26/12/18 10:31	General View													Load JPG	<input checked="" type="checkbox"/>		
13	26/12/18 10:31	General View													Load JPG	<input checked="" type="checkbox"/>		
14	26/12/18 10:31	General View													Load JPG	<input checked="" type="checkbox"/>		
15	26/12/18 10:31	General View													Load JPG	<input checked="" type="checkbox"/>		
16	26/12/18 10:31	General View													Load JPG	<input checked="" type="checkbox"/>		
17	26/12/18 10:31	General View													Load JPG	<input checked="" type="checkbox"/>		
18	26/12/18 10:31	General View													Load JPG	<input checked="" type="checkbox"/>		
19	26/12/18 10:31	General View													Load JPG	<input checked="" type="checkbox"/>		
20	26/12/18 10:31	General View													Load JPG	<input checked="" type="checkbox"/>		
21	26/12/18 10:31	General View													Load JPG	<input checked="" type="checkbox"/>		
22	26/12/18 10:31	General View													Load JPG	<input checked="" type="checkbox"/>		
23	26/12/18 10:31	General View													Load JPG	<input checked="" type="checkbox"/>		
24	26/12/18 10:31	General View													Load JPG	<input checked="" type="checkbox"/>		
25	26/12/18 10:31	General View													Load JPG	<input checked="" type="checkbox"/>		
26	26/12/18 10:31	General View													Load JPG	<input checked="" type="checkbox"/>		
27	26/12/18 10:31	General View													Load JPG	<input checked="" type="checkbox"/>		
28	26/12/18 10:31	Reinspection Photo													Load JPG	<input checked="" type="checkbox"/>		
29	26/12/18 10:31	Reinspection Photo													Load JPG	<input checked="" type="checkbox"/>		
30	26/12/18 10:31	Reinspection Photo													Load JPG	<input checked="" type="checkbox"/>		
31	26/12/18 10:31	Reinspection Photo													Load JPG	<input checked="" type="checkbox"/>		
32	26/12/18 10:31	Reinspection Photo													Load JPG	<input checked="" type="checkbox"/>		

Letters/Correspondences			1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
33	26/12/18 10:31	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page ▼	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	16/11/18 15:50	TP EST & GIA REPORT	Load PDF	
2	27/11/18 19:21	TP ESTIMATE- MARKED	Load PDF	
3	28/12/18 09:34	LETTER TO OI	Load PDF	
4	22/01/19 14:40	GIA SEARCH	Load PDF	
5	01/04/19 13:42	AUTHORISATION TO ACT	Load PDF	
6	01/04/19 13:42	RELEASE VOUCHER	Load PDF	
7	01/04/19 13:42	WORKSHOP INVOICE	Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	19/11/18 09:46	OI GIA REPORT	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SKV2086T (Insd veh)	Model:	BMW 730LI 3.0 AT ABS D/AB
	SKF1665M (TP veh)		2WD 4DR NAV HID SR (A)
Date of Accident:	09/11/2018		

Global Sum Settlement	:	[] Yes	[X] No	
Repair Estimate	:	\$		11,482.97
Final Repair Cost	:	\$		9,329.65
Loss of Use	:	\$		600.00
Rental (if any)	:	\$		5.00 days at \$120.00 per day
LTA / GIA Search Fee	:	\$		2.00
Others:	:	\$		days
	:	\$		
Final Settlement Sum	:	\$		9,931.65

Is Third Party Workshop GIA Registered?	[X] YES	[] NO	(Kindly indicate below)
A) For <u>Non GIA Registered Workshop</u> :	Agreed Liability _____ (%)		
B) For <u>GIA Registered Workshop</u> :	BOLA Applicable: Yes/ No BOLA Scenario No: _____		
BOLA Liability: _____ (%)	Assessed Liability (*): _____ (%)		
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	Performance Motors Limited	:	\$ 9,931.65
2)		:	\$
3)		:	\$

NUR SHAQILAH BTE ABDOL WAHAB

LKK Auto Consultants Pte Ltd

01 Apr
2019

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG18020795/T1EB3S2

Date: 01/04/2019

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100427651
Claimant Vehicle No :	SKF1665M	Insured Vehicle No :	SKV2086T
Date of Loss:	09/11/2018	Nature of Claim:	TP
		Claim No:	2715796484SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKF1665M		
Make & Model:	BMW 730LI, 3.0 AT ABS D/AB 2WD 4DR NAV HID SR (A)	Engine No:	09247941N52B30AF
Reg. Date:	30/12/2011 (Man. Year: 2011)	Chassis No:	WBAKB22080C951344
Colour:	Silver	Odometer:	140211 km
Engine Capacity:	2996 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	245/50R18	Rear Tyre Size:	245/50R18
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,630.75	4,688.30	942.45	16.74
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,101.00	4,031.00	1,070.00	20.98
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	10,731.75	8,719.30	2,012.45	18.75
+ GST 7.00/7.00% (S\$)	751.22	610.35	140.87	18.75
Nett Amount (S\$)	11,482.97	9,329.65	2,153.32	18.75
+ Loss of Use (5.0 x S\$120.00/day) (S\$)		600.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		9,931.65		

INSPECTION

Date of Assignment:	26/11/2018	
Date Inspected:	26/11/2018 Inspected At:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre Singapore 159941
Estimated Period of Repair:	4.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	4		*PLASTIC NUT	Not Necessary	3.60 FS	*-FS
2	1		*FRT BUMPER TOP CARRIER	Not Necessary	814.70 FS	*-FS
3	1		*FRT BUMPER RH MOULDING (CHROME)	Not Necessary	36.80 FS	*-FS
4	1		*FRT BUMPER FLAP COVER SPRING	Not Necessary	5.25 FS	*-FS
5	1		*FRT BUMPER RH FLAP COVER (PRIMED)	Missing	51.95 FS	*51.95 FS
6	1		*FRT BUMPER (PDC)	Deformed	1,510.95 FS	*1,510.95 FS
7	10		*C CLIP NUT	Not Necessary	13.00 FS	*-FS
8	1		*FRT BUMPER TOP IMPACT ABSORBER	Not Necessary	69.10 FS	*-FS
9	1		*RH HIGH PRESSURE NOZZLE	Distorted	183.80 FS	*183.80 FS
10	1		*SUNDRIES	Necessary	80.00 FS	*80.00 FS
11	1		*RH BI-XENON HEADLIGHT	Cracked	2,861.60 FS	*2,861.60 FS
					Total Parts (S\$)	5,630.75
						4,688.30

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE FRONT BUMPER & ATTACHMENTS INCLUDING TO KNOCK OUT FRONT RIGHT FENDER AND DENTED AREA CAUSED BY THE ACCIDENT.	New	2,550.00	1,700.00
2	TO RESPRAY FRONT BUMPER AND FRONT RIGHT FENDER.	New	1,923.00	1,730.00
3	TO CHECK ELECTRICAL WIRING SYSTEM AT THE FRONT SECTION FOR PROPER FUNCTION INCLUDING ADJUSTMENTS OF HEADLIGHTS.	New	177.00	150.00
4	TO REPLACE RH BI XENON HEADLIGHT INCLUDE PROGRAMMING AND CONDUCTING TESTS FOR PROPER FUNCTION.	New	451.00	451.00
Gross Labour Cost (\$\$)			5,101.00	4,031.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >