

15/5/2010

INS. CASE OWNER:

Peter
CC / AXA1802

LKK:

IDAC:

Surveyor:

Fennell

DOI:

ASSIGNMENT

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

Excess Sec II :SS

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO. Driver Name / Age: GUNDARAWATNY INTERVIEW

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No

INSRS:
WSP:
Tel:
Liability:
RMKS:Falcon
AtrINSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time

SUP 61373 - X

SUP 70344 - X

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI: - 30/4/19 - khanduc

After call ltr to OI: C-1001/01/19

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

days Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with: Florence

Email

Call

Final Liability:

%

(Agreed / Assessed) BOLA S/N No.:

28

Repair Cost:

SS

23540.00 (at per Alex)

Loss of Rental (LOR):

SS

2568.00 (29 days) x 2100

Loss of Use (LOU):

SS

(S x days)

Loss of Income (LOI):

SS

(S x days)

LOR only ☐ LOU only ☐

SS

LOR + LOU ☐ LOR + LO ☐

[Tick only one]

GIA/LTA Search

SS

2.00

Medical:

SS

121.00

Disbursement:

SS

(e.g. Tow/ Independent)

Legal Cost

SS

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

Total:

SS

26231.00

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

26231.00

Name 1:

Falcon - Atr Auto Services Pte Ltd

GIA

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

REF: ASM(Ax1)

ASSIGNMENT

From: Date: 16/11/2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SLP 6137Z

at Workshop m/s

Falcon-Air

of

176 Sin Ming Dr #01-06

Insured

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

\$72k

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

23 days

Res.: Yes or No

Lum Sum:

1.21 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No: SLP 6137Z Yr Regn: 06 17

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda

C.C.

1998

Colour:

Yellow

A/C:

Insured / Std / NI / NA

Sp. Reading

039914

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

THMGK 58504X201110

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

Dun

185/55R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

7

mm

R/Bal.

6

mm

L/Bal.

7

mm

L/Bal.

6

mm

D.O.A.

13/11/18

D.O.I.

16/11/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

19/11 File pass to Customer

#5 \$23200 (Reel of 10214.40 / 31%).
Repair sum.NW \$: 72K
LA: \$48224.00
NW = \$23226.00

Date/Time. File Pass to?

☐ : Prel. Report
☐ : Final Report

1)

Date/Time. File Return to?

2)

Report Format :

Lump Sum / I.B.I. (\$)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐ Site Insp (\$)
☐ Interview (\$)
☐ Tech Invs (\$)
☐ Weekend (\$

Survey Fee:

Transportation

) \$ + RS \$

) Photos

) Others

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD		Ref : CC4/ASM18020796/Khb3		
8 SHENTON WAY #24-01 AXA TOWERS SINGAPORE 068811		Date : 16-11-2018		
		Code : ASM		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLF 7034H	Veh. Inspected	SLP 6137Z	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	16/11/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	13/11/2018	Inspection Date	16/11/2018	
Survey held at	FALCON-AIR AUTO SERVICES PTE LTD BLK 8 PANDAN LOOP SINGAPORE 128226			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



FALCON - AIR

TAN CHIN HAN AMAS
C/O 176 SIN MING DRIVE #01-06/07
SIN MING AUTOCARE 575721

Attention : Motor Claim Department

Contact : 92774008

Not Noted
Resurvey B4 ppm

23 days

Estimate : ES011723

Date : 15/11/2018

Vehicle Num. : SLP 6137Z

Make/Model : HONDA JAZZ-2016/2017

Chassis/Eng# : JHMGK5850HX201110

Accident Date : 13/11/2018

Claim No. :

Reference : TP - AVIVA AGT AXA (SM)

Policy No. : 10835015

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

- | | | | | |
|-----|--------|---------------------------------|--|--|
| 1. | 1 PC | LIST ITEMS : | | |
| 2. | 2 PCS | BONNET | | |
| 3. | 2 PCS | BONNET RUBBER (FRONT) | | |
| 4. | 1 PC | BONNET RUBBER (SIDE) | | |
| 5. | 10 PCS | BONNET INSULATOR | | |
| 6. | 1 PC | BONNET INSULATOR CLIPS | | |
| 7. | 1 PC | BONNET LOCK | | |
| 8. | 2 PCS | BONNET HINGE | | |
| 9. | 2 PCS | HEADLAMP | | |
| 10. | 2 PCS | HEADLAMP RETAINER | | |
| 11. | 2 PCS | HEADLAMP PANEL | | |
| 12. | 1 PC | RADIATOR GRILLE | | |
| 13. | 1 PC | RADIATOR GRILLE CHROME MOULDING | | |
| 14. | 1 PC | RADIATOR GRILLE LOGO | | |
| 15. | 1 PC | RADIATOR GRILLE EMBLEM (RS) | | |
| 16. | 1 PC | FRONT BUMPER | | |
| 17. | 10 PCS | FRONT BUMPER CLIPS | | |
| 18. | 2 PCS | FRONT BUMPER SIDE RETAINER | | |
| 19. | 1 PC | FRONT BUMPER REINFORCEMENT | | |
| 20. | 1 PC | LH FOG LAMP | | |
| 21. | 1 PC | LH FOG LAMP GRILLE | | |
| 22. | 1 PC | LH FRONT DAY LIGHT | | |
| 23. | 1 PC | FRONT SUPPORT PANEL | | |

25.10	25.10	1,011.70	
24.30	24.30	50.20	
186.70	186.70	48.60	
5.00	5.00	186.70	
137.00	137.00	50.00	
150.00	150.00	137.00	
1,336.50	1,336.50	150.00	
45.90	45.90	2,673.00	
180.00	180.00	91.80	
508.50	508.50	360.00	
118.00	118.00	508.50	
65.00	65.00	118.00	
95.00	95.00	65.00	
695.60	695.60	95.00	
50.00	50.00	695.60	
70.80	70.80	50.00	
353.20	353.20	70.80	
340.00	340.00	353.20	
90.30	90.30	340.00	
288.20	288.20	90.30	
655.90	655.90	288.20	

CONTINUE / ...

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

FALCON - AIR AUTO SERVICES PTE LTD
(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office : Blk 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare S(575721) Tel: 6452-0880 / 6458-0880 Fax: 6454-7862

Branches : Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No 8 Pandan Loop (Blk 1/Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110

Website: www.falconair.com.sg Email: email@falconair.com.sg



FALCON-AIR

TAN CHIN HAN AMAS
C/O 176 SIN MING DRIVE #01-06/07
SIN MING AUTOCARE 575721

Attention : Motor Claim Department

Contact : 92774008

Estimate : ES011723

Date : 15/11/2018
Vehicle Num. : SLP 6137Z
Make/Model : HONDA JAZZ-2016/2017
Chassis/Eng# : JHMGK5850HX201110
Accident Date : 13/11/2018
Claim No. :
Reference : TP - AVIVA AGT AXA (SM)
Policy No. : 10835015

S/N	Quantity	Particular	Unit Price	Amount S\$
23.	1 PC	FRONT SUPPORT PANEL GARNISH		
24.	2 PCS	FRONT FENDER		
25.	2 PCS	FRONT FENDER SHIELD		
26.	16 PCS	FRONT FENDER SHIELD CLIP		
27.	1 PC	AIR DUCT		
28.	1 PC	AIR DUCT HOSE		
29.	2 PCS	AIR GUIDE		
30.	1 PC	AIR CON CONDENSER		
31.	1 PC	AIR CON FAN COWLING		
32.	1 PC	AIR CON FAN BLADE		
33.	1 PC	AIR CON FAN MOTOR		
34.	1 PC	AIR CON LIQUID PIPE		
35.	1 PC	AIR CON SUCTION HOSE		
36.	1 PC	AIR CON DISCHARGE HOSE		
37.	1 PC	RADIATOR		
38.	1 PC	RADIATOR FAN COWLING		
39.	1 PC	RADIATOR FAN BLADE		
40.	1 PC	RADIATOR FAN MOTOR		
41.	2 PCS	RADIATOR TOP MOUNTING		
42.	1 PC	RADIATOR TOP HOSE		
43.	1 PC	INTAKE MANIFOLD		
44.	1 PC	INTAKE MANIFOLD GASKET		
45.	1 PC	WIPER WASHER TANK		
46.	1 PC	WIPER WASHER TANK NECK		

CONTINUE / ...

FALCON-AIR AUTO SERVICES PTE LTD
(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13 #05-12/17 Sin Ming AutoCare Singapore 575721 Tel: 452-0880/458-0880 Fax: 454-7862/458-7997
Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 789-7997 Fax: 788-7997 • Pandan Loop Blk 1 #01-20 S(128219) Tel: 779-5665 Fax: 779-1110
Websites: www.falconair.com.sg & www.carlovers.com.sg E-mail: email@falconair.com.sg



FALCON-AIR

FALCON-AIR AUTO SERVICES PTE LTD

Co. Reg. No.: 199501140D
GST Reg. No.: 199501140DTAN CHIN HAN AMAS
C/O 176 SIN MING DRIVE #01-06/07
SIN MING AUTOCARE 575721Attention : Motor Claim Department
Contact : 92774008

Estimate : ES011723

Date : 15/11/2018
Vehicle Num. : SLP 6137Z
Make/Model : HONDA JAZZ-2016/2017
Chassis/Eng# : JHMGK5850HX201110
Accident Date : 13/11/2018
Claim No. :
Reference : TP - AVIVA AGT AXA (SM)
Policy No. : 10835015

S/N	Quantity	Particular	Unit Price	Amount S\$
47.	2 PCS	HORN	65.10	130.20
48.	1 PC	TAILGATE GLASS	925.60	
49.	1 PC	TAILGATE GLASS MOULDING	181.80	
50.	1 PC	TAILGATE	1,114.00	
51.	1 PC	TAILGATE GARNISH W/LOGO	353.70	
52.	1 PC	TAILGATE EMBLEM (JAZZ)	55.10	
53.	1 PC	TAILGATE EMBLEM (RS)	55.10	
54.	1 PC	TAILGATE WEATHERSTRIP	142.30	
55.	1 PC	TAILGATE INNER TRIM	298.00	
56.	10 PCS	TAILGATE INNER TRIM CLIP	5.00	50.00
57.	2 PCS	TAILGATE REFLECTOR	189.30	378.60
58.	1 PC	TAILGATE LOCK	227.50	
59.	1 PC	TAILGATE INNER HANDLE	40.70	
60.	1 PC	REAR WIPER ARM	71.20	X
61.	1 PC	REAR WIPER BLADE	59.50	X
62.	2 PCS	TAILLAMP	417.30	834.60
63.	4 PCS	TAILLAMP CLIPS	5.00	20.00
64.	2 PCS	TAILLAMP PANEL	175.60	351.20
65.	1 PC	REAR BUMPER	692.60	
66.	10 PCS	REAR BUMPER CLIPS	5.00	50.00
67.	2 PCS	REAR BUMPER SIDE RETAINER	33.80	67.60
68.	1 PC	RH REAR BUMPER GRILLE	49.00	
69.	1 PC	REAR END PANEL	514.00	
70.	1 PC	REAR END PANEL GARNISH	120.50	

CONTINUE / ...

FALCON-AIR AUTO SERVICES PTE LTD
(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office : Blk 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare S(575721) Tel: 6452-0880 / 6458-0880 Fax: 6454-7862
 Branches : Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No 8 Pandan Loop (Blk 1/Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110
 Website: www.falconair.com.sg Email: email@falconair.com.sg



FALCON - AIR AUTO SERVICES PTE LTD

Co. Reg. No.: 199501140D
GST Reg. No.: 199501140D

FALCON - AIR

TAN CHIN HAN AMAS
C/O 176 SIN MING DRIVE #01-06/07
SIN MING AUTOCARE 575721

Estimate : ES011723

Attention : Motor Claim Department

Contact : 92774008

Date : 15/11/2018
Vehicle Num.: SLP 6137Z
Make/Model : HONDA JAZZ-2016/2017
Chassis/Eng#: JHMGK5850HX201110
Accident Date : 13/11/2018
Claim No.:
Reference : TP - AVIVA AGT AXA (SM)
Policy No.: 10835015

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

71.	1 PC	REAR COMPARTMENT BOARD	<i>CRP</i> 298.20	<i>✓</i>
72.	1 PC	REAR COMPARTMENT SPONGE	<i>cm</i> 188.60	<i>✓</i>
73.	1 PC	REAR COMPARTMENT PANEL	<i>R</i> 997.00	<i>✓</i>
74.	1 PC	RH REAR CHASSIS	<i>R. R</i> 710.30	<i>x</i>
75.	1 PC	RH REAR FENDER	<i>R. R</i> 838.50	<i>x</i>
76.	1 PC	RH REAR FENDER QUARTER GLASS MOULDING	<i>m</i> 60.10	<i>✓</i>
77.	2 PCS	RH REAR FENDER INNER TRIM	<i>Net form/cm</i> 285.60	<i>✓</i>
78.	20 PCS	RH REAR FENDER INNER TRIM CLIP	<i>m</i> 5.00	<i>✓</i>
79.	1 PC	REAR EXHAUST SILENCER	<i>R</i> 604.40	<i>✓</i>
80.	2 PCS	REAR EXHAUST SILENCER MOUNTING	<i>35.60 m</i> 71.20	<i>✓</i>
81.	1 PC	REAR EXHAUST SILENCER HEAT SHIELD	<i>nl</i> 65.90	<i>✓</i>
82.	1 PC	ANTENNA SENSOR	<i>nl</i> 158.10	<i>✓</i>
List Total S\$:			26,403.50	
20.00% Discount S\$:			5,280.70	
			21,122.80	

1.	1 PC	SPECIAL NETT ITEMS : FRONT NUMBER PLATE	<i>nd</i> 45.00	<i>✓</i>
2.	1 PC	TAILGATE SEALANT	<i>m</i> 40.00	<i>✓</i>
3.	1 PC	REAR NUMBER PLATE	<i>n</i> 45.00	<i>✓</i>
4.	2 PCS	REAR BUMPER STICKER	<i>60.00</i> 120.00	<i>for m</i>
5.	1 SET	REVERSE SENSOR	<i>nd</i> 250.00	<i>200sm</i>

CONTINUE / ...

FALCON - AIR AUTO SERVICES PTE LTD
(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office : Blk 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare S(575721) Tel: 6452-0880 / 6458-0880 Fax: 6454-7862

Branches : Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No 8 Pandan Loop (Blk 1/Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110
Website: www.falconair.com.sg Email: email@falconair.com.sg



FALCON-AIR

FALCON-AIR AUTO SERVICES PTE LTD

Co. Reg. No.: 199501140D
GST Reg. No.: 199501140DTAN CHIN HAN AMAS
C/O 176 SIN MING DRIVE #01-06/07
SIN MING AUTOCARE 575721

Attention : Motor Claim Department

Contact : 92774008

Estimate : ES011723

Date : 15/11/2018
Vehicle Num. : SLP 6137Z
Make/Model : HONDA JAZZ-2016/2017
Chassis/Eng# : JHMGK5850HX201110
Accident Date : 13/11/2018
Claim No. :
Reference : TP - AVIVA AGT AXA (SM)
Policy No. : 10835015

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

6.	1 PC	REAR COMPARTMENT PANEL INSULATOR		
7.	1 PC	RH REAR FENDER QUARTER GLASS SEALANT		

Net 280.00 X
m 40.00 30.00

Special Nett Total S\$:

820.00

LABOUR :

TO FOCUS HEADLAMP
TO REMOVE/REFIX AIR CON CONDENSER, PIPE
VACUUM AND TOP UP AIR CON GAS
TO REMOVE/REFIX TRIMS, ETC TO FACILITATE REPAIRS
TO CHECK REAR WIRING
TO REMOVE/REFIX REAR WINDSCREEN GLASS
TO CONDUCT WATER TEST TO CHECK FOR LEAKAGE
TO TRANSFER TAILGATE MECHANISM
TO REMOVE/REFIX RH REAR QUARTER GLASS
TO CONDUCT CHASSIS ALIGNMENT
TO REFIX REVERSE SENSOR
TO REMOVE/REPLACE/RE-ALIGN REAR EXHAUST SYSTEM
TO REMOVE/REFIX REAR AXLE TO FACILITATE REPAIRS
TO APPLY BODY SEALANT TO CAR JOINTS
TO RUSTPROOF ACCIDENT DAMAGE AREA
TO STRAIGHTEN LH/RH FRONT CHASSIS, LH/RH FRONT WHEEL
HOUSE, LH/RH FRONT DOOR, LH REAR FENDER, LH REAR
CHASSIS, LH/RH REAR DOOR, RH ROOF PANEL CUT-OUT/RE-WELD

50.00 201

120.00 1001

280.00 1201

50.00 201

120.00 1201

50.00 301

100.00 601

100.00 501

480.00 2501

50.00 501

280.00 801

400.00 201

260.00 901

260.00 1801

CONTINUE / ...

FALCON-AIR AUTO SERVICES PTE LTD
(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office : Blk 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare S(575721) Tel: 6452-0880 / 6458-0880 Fax: 6454-7862

Branches : Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No 8 Pandan Loop (Blk 1/Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110
Website: www.falconair.com.sg Email: email@falconair.com.sg



FALCON-AIR

FALCON - AIR AUTO SERVICES PTE LTD

Co. Reg. No.: 199501140D
GST Reg. No.: 199501140D Page 6 / 6

TAN CHIN HAN AMAS
C/O 176 SIN MING DRIVE #01-06/07
SIN MING AUTOCARE 575721

Attention : Motor Claim Department
Contact : 92774008

Estimate : ES011723

Date : 15/11/2018
Vehicle Num. : SLP 6137Z
Make/Model : HONDA JAZZ-2016/2017
Chassis/Eng# : JHMGK5850HX201110
Accident Date : 13/11/2018
Claim No. :
Reference : TP - AVIVA AGT AXA (SM)
Policy No. : 10835015

S/N	Quantity	Particular	Unit Price	Amount S\$
		FRONT SUPPORT PANEL, RH REAR CHASSIS, RH REAR FENDER, REAR END PANEL, REAR COMPARTMENT PANEL INCLUDING REPLACEMENT OF PARTS TO SPRAY PAINT ON BONNET, FRONT BUMPER, FRONT BUMPER REINFORCEMENT, LH/RH FRONT FENDER, FRONT SUPPORT PANEL, LH/RH FRONT DOOR, LH/RH REAR DOOR, LH/RH ROOF PANEL, ROOF PANEL, TAILGATE, REAR BUMPER, REAR END PANEL, REAR COMPARTMENT PANEL, LH/RH REAR FENDER		2600 3,600.00 2600 3,600.00 9,800.00
		Labour Total S\$:		9,800.00

E. & O.E.

Total S\$: 31,742.80

=====

33614.40

for FALCON AIR AUTO SERVICES PTE LTD

The quotation was prepared from visual inspection. Further materials and labour charges may be required when repair commences. We will advise you accordingly.

FALCON - AIR AUTO SERVICES PTE LTD
(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office : Blk 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare S(575721) Tel: 6452-0880 / 6458-0880 Fax: 6454-7862
Branches : Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No 8 Pandan Loop (Blk 1/Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110
Website: www.falconair.com.sg Email: email@falconair.com.sg



FALCON-AIR

FALCON-AIR AUTO SERVICES PTE LTD

Co. Reg. No.: 199501140D

GST Reg. No.: 199501140D

TAN CHIN HAN AMAS
C/O 176 SIN MING DRIVE #01-06/07
SIN MING AUTOCARE 575721

Attention : Motor Claim Department
Contact : 92774008

Supplementary Estimate : ES011757

Date : 18/01/2019
Vehicle Num. : SLP 6137Z
Make/Model : HONDA JAZZ-2016/2017
Chassis/Eng#: JHMGK5850HX201110
Accident Date : 13/11/2018
Claim No. :
Reference : TP - AVIVA AGT AXA (SM)
Policy No. : 10835015

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

- | | | | | |
|----|------|------------------------------|--|--|
| | | LIST ITEMS : | | |
| 1. | 1 PC | WIPER GARNISH | | |
| 2. | 1 PC | LH FRONT WINDSCREEN MOULDING | | |
| 3. | 1 PC | FRONT NUMBER PLATE GARNISH | | |
| 4. | 1 PC | BATTERY TRAY | | |
| 5. | 1 PC | BATTERY COVER | | |
| 6. | 1 PC | AIR FILTER HOUSING (BOTTOM) | | |

cm	296.70	✓
m	90.40	✓
cm	90.90	✓
cm	88.90	✓
ra	70.70	✓
cm	226.90	✓

List Total S\$:
20.00% Discount S\$:

864.50
172.90
691.60

- | | | | | |
|----|-------|----------------------------|--|--|
| | | SPECIAL NETT ITEMS : | | |
| 1. | 1 PC | TAILGATE TOP STICKER | | |
| 2. | 2 PCS | TAILGATE REFLECTOR TINTING | | |
| 3. | 2 PCS | TAILLAMP TINTING | | |
| 4. | 2 PCS | HEADLAMP TINTING | | |

150.00	nee	280.00	180.00
150.00	nee	300.00	160.00
150.00	nee	300.00	160.00
150.00	nee	300.00	160.00

Special Nett Total S\$:

1,180.00

E. & O.E.

Total S\$: 1,871.60

for FALCON AIR AUTO SERVICES PTE LTD

The quotation was prepared from visual inspection. Further materials and labour charges may be required when repair commences. We will advise you accordingly.

33614.40

FALCON-AIR AUTO SERVICES PTE LTD
(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office : Blk 176 Sin Ming Drive #01-06/07/13, #05 17 Sin Ming Autocare S(575721) Tel: 6452-0880 / 6458-0880 Fax: 6454-7862
Branches : Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6789-7997 • No 8 Pandan Loop (Blk 1/Blk K) S(178226) Tel: 6779-5665 Fax: 6779-1110
Website: www.falconair.com.sg Email: email@falconair.com.sg

Kh

FALCON - AIR AUTO SERVICES PTE LTD

Co. Reg. No.: 199501140D
GST Reg. No.: 199501140D Page 1/6

FALCON - AIR

TAN CHIN HAN AMAS
C/O 176 SIN MING DRIVE #01-06/07
SIN MING AUTOCARE 575721

Attention: Motor Claim Department
Contact: 92774008

Not with work
Resurvey by paint
23 days
822,800

Estimate: ES011723

Date: 15/11/2018
Vehicle Num.: SLP 6137Z
Make/Model: HONDA JAZZ-2016/2017
Chassis/Eng#: JHMGK5850HX201110
Accident Date: 13/11/2018
Claim No.:
Reference: TP - AVIVA AGT AXA (SM)
Policy No.: 10835015

S/N Quantity Particular Unit Price Amount S\$

1.	1 PC	BONNET		1,011.70	✓
2.	2 PCS	BONNET RUBBER (FRONT)	25.10	50.20	✓
3.	2 PCS	BONNET RUBBER (SIDE)	24.30	48.60	✓
4.	1 PC	BONNET INSULATOR		186.70	✓
5.	10 PCS	BONNET INSULATOR CLIPS	5.00	50.00	✓
6.	1 PC	BONNET LOCK		137.00	✓
7.	2 PCS	BONNET HINGE	75.00	150.00	✓
8.	2 PCS	HEADLAMP	1,336.50	2,673.00	✓
9.	2 PCS	HEADLAMP RETAINER	45.90	91.80	✓
10.	2 PCS	HEADLAMP PANEL	100.00	200.00	✓
11.	1 PC	RADIATOR GRILLE		508.50	✓
12.	1 PC	RADIATOR GRILLE CHROME MOULDING		118.00	✓
13.	1 PC	RADIATOR GRILLE LOGO		65.00	✓
14.	1 PC	RADIATOR GRILLE EMBLEM (RS)		95.00	✓
15.	1 PC	FRONT BUMPER		695.60	✓
16.	10 PCS	FRONT BUMPER CLIPS	5.00	50.00	✓
17.	2 PCS	FRONT BUMPER SIDE RETAINER	35.40	70.80	✓
18.	1 PC	FRONT BUMPER REINFORCEMENT		353.20	✓
19.	1 PC	LH FOG LAMP		340.00	✓
20.	1 PC	LH FOG LAMP GRILLE		90.30	✓
21.	1 PC	LH FRONT DAY LIGHT		288.20	✓
22.	1 PC	FRONT SUPPORT PANEL		655.90	✓

Wiper garnish - 296.70
LH front window moulding - 90.40
air filter housing (bottom) - 220.90
Battery tray - 88.90
Battery cover - 70.70

CONTINUE / ...

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

front number plate garnish - 90.90
1PC tailgate top strike - 280.22/2

FALCON - AIR AUTO SERVICES PTE LTD
(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: Blk 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare S(575721) Tel: 6452-0880 / 6458-0880 Fax: 6454-7862
Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 No 8 Pandan Loop (Blk 1/Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110
Website: www.falconair.com.sg Email: email@falconair.com.sg



FALCON-AIR AUTO SERVICES PTE LTD

FALCON-AIR

TAN CHIN HAN AMAS
C/O 176 SIN MING DRIVE #01-06/07
SIN MING AUTOCARE 575721

Attention : Motor Claim Department
Contact : 92774008

Estimate : ES011723

Date : 15/11/2018
Vehicle Num. : SLP 6137Z
Make/Model : HONDA JAZZ-2016/2017
Chassis/Eng# : JHMGK5850HX201110
Accident Date : 13/11/2018
Claim No. :
Reference : TP - AVIVA AGT AXA (SM)
Policy No. : 10835015

S/N	Quantity	Particular	Unit Price	Amount S\$
23.	1 PC	FRONT SUPPORT PANEL GARNISH		60.00 ✓
24.	2 PCS	FRONT FENDER	468.50	937.00 ✓
25.	2 PCS	FRONT FENDER SHIELD	121.50	243.00 X
26.	16 PCS	FRONT FENDER SHIELD CLIP	5.00	80.00 X
27.	1 PC	AIR DUCT		49.40 ✓
28.	1 PC	AIR DUCT HOSE		55.40 ✓
29.	2 PCS	AIR GUIDE	36.00	72.00 ✓
30.	1 PC	AIR CON CONDENSER		804.90 ✓
31.	1 PC	AIR CON FAN COWLING		193.90 ✓
32.	1 PC	AIR CON FAN BLADE		88.90 ?
33.	1 PC	AIR CON FAN MOTOR		368.10 ?
34.	1 PC	AIR CON LIQUID PIPE		235.00 ?
35.	1 PC	AIR CON SUCTION HOSE		238.40 ?
36.	1 PC	AIR CON DISCHARGE HOSE		275.00 ?
37.	1 PC	RADIATOR		1,450.60 ✓
38.	1 PC	RADIATOR FAN COWLING		189.30 ✓
39.	1 PC	RADIATOR FAN BLADE		138.00 ✓
40.	1 PC	RADIATOR FAN MOTOR		389.00 ✓
41.	2 PCS	RADIATOR TOP MOUNTING	22.60	45.20 ?
42.	1 PC	RADIATOR TOP HOSE		58.80 ?
43.	1 PC	INTAKE MANIFOLD		672.10 ✓
44.	1 PC	INTAKE MANIFOLD GASKET		65.00 ✓
45.	1 PC	WIPER WASHER TANK		124.00 ?
46.	1 PC	WIPER WASHER TANK NECK		38.70 X

2PLS Headlamp tinting 2x 150 S/N
2PLS tailgate Retainer tinting 2x 150 S/N
2PLS tail lamp tinting 2x 150 S/N

CONTINUE / ...

FALCON-AIR AUTO SERVICES PTE LTD
(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13 #05-12/17 Sin Ming AutoCare Singapore 575721 Tel: 452-0880/458-0880 Fax: 454-7862/458-7997
Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 789-7997 Fax: 788-7997 • Pandan Loop Blk 1 #01-20 S(128219) Tel: 779-5685 Fax: 779-1110
Websites: www.falconair.com.sg & www.carlovers.com.sg E-mail: email@falconair.com.sg



FALCON - AIR

FALCON - AIR AUTO SERVICES PTE LTD

Co. Reg. No.: 199501140D
GST Reg. No.: 199501140DTAN CHIN HAN AMAS
C/O 176 SIN MING DRIVE #01-06/07
SIN MING AUTOCARE 575721Attention: Motor Claim Department
Contact: 92774008

Estimate: ES011723

Date: 15/11/2018
Vehicle Num: SLP 6137Z
Make/Model: HONDA JAZZ-2016/2017
Chassis/Eng#: JHMGK5850HX201110
Accident Date: 13/11/2018
Claim No.:
Reference: TP - AVIVA AGT AXA (SM)
Policy No.: 10835015

S/N	Quantity	Particular	Unit Price	Amount S\$	
47.	2 PCS	HORN	65.10	130.20	X
48.	1 PC	TAILGATE GLASS	925.60		✓
49.	1 PC	TAILGATE GLASS MOULDING	181.80		✓
50.	1 PC	TAILGATE	1,114.00		✓
51.	1 PC	TAILGATE GARNISH W/LOGO	353.70		✓
52.	1 PC	TAILGATE EMBLEM (JAZZ)	55.10		✓
53.	1 PC	TAILGATE EMBLEM (RS)	55.10		✓
54.	1 PC	TAILGATE WEATHERSTRIP	142.30		✓
55.	1 PC	TAILGATE INNER TRIM	298.00		✓
56.	10 PCS	TAILGATE INNER TRIM CLIP	5.00	50.00	✓
57.	2 PCS	TAILGATE REFLECTOR	189.30	378.60	✓
58.	1 PC	TAILGATE LOCK		227.50	✓
59.	1 PC	TAILGATE INNER HANDLE		40.70	✓
60.	4 PG	REAR WIPER ARM		71.20	X
61.	4 PG	REAR WIPER BLADE		59.50	X
62.	2 PCS	TAILLAMP	417.30	834.60	✓
63.	4 PCS	TAILLAMP CLIPS	5.00	20.00	✓
64.	2 PCS	TAILLAMP PANEL	175.60	351.20	✓
65.	1 PC	REAR BUMPER		692.60	✓
66.	10 PCS	REAR BUMPER CLIPS	5.00	50.00	✓
67.	2 PCS	REAR BUMPER SIDE RETAINER	33.80	67.60	✓
68.	1 PC	RH REAR BUMPER GRILLE		49.00	✓
69.	1 PC	REAR END PANEL		514.00	✓
70.	1 PC	REAR END PANEL GARNISH		120.50	✓

CONTINUE / ...

FALCON - AIR AUTO SERVICES PTE LTD
(a subsidiary of Falcon-Air Holdings Pte Ltd)Head Office: Blk 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare S[575721] Tel: 6452-0880 / 6458-0880 Fax: 6454-7862
Branches: Tampines St 93 Blk 9006 #01-200 S[528840] Tel: 6789-7997 Fax: 6788-7997 • No 8 Pandan Loop (Blk 1/Blk K) S[128226] Tel: 6779-5665 Fax: 6779-1110
Website: www.falconair.com.sg Email: email@falconair.com.sg



FALCON - AIR AUTO SERVICES PTE LTD

Co. Reg. No: 199501140D
GST Reg. No: 199501140D

FALCON - AIR

TAN CHIN HAN AMAS

C/O 176 SIN MING DRIVE #01-06/07

SIN MING AUTOCARE 575721

Attention: Motor Claim Department

Contact: 92774008

Estimate: ES011723

Date: 15/11/2018

Vehicle Num: SLP 6137Z

Make/Model: HONDA JAZZ-2016/2017

Chassis/Eng#: JHMGK5850HX201110

Accident Date: 13/11/2018

Claim No.:

Reference: TP - AVIVA AGT AXA (SM)

Policy No.: 10835015

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

71.	1 PC	REAR COMPARTMENT BOARD	CM	298.20	✓
72.	1 PC	REAR COMPARTMENT SPONGE	CM	188.80	✓
73.	1 PC	REAR COMPARTMENT PANEL	R	997.00	✓
74.	1 PC	RH REAR CHASSIS	R	710.30	✓
75.	1 PC	RH REAR FENDER	R	838.50	✓
76.	1 PC	RH REAR FENDER QUARTER GLASS MOULDING	R	60.10	✓
77.	2 PCS	RH REAR FENDER INNER TRIM	Net form / CM	285.60	✓
78.	20 PCS	RH REAR FENDER INNER TRIM CLIP	5.00	100.00	✓
79.	1 PC	REAR EXHAUST SILENCER	R	604.40	✓
80.	2 PCS	REAR EXHAUST SILENCER MOUNTING	35.60	71.20	✓
81.	1 PC	REAR EXHAUST SILENCER HEAT SHIELD		65.90	✓
82.	1 PC	ANTENNA SENSOR	R	158.10	✓
List Total S\$:				26,403.50	
20.00% Discount S\$:				5,280.70	
				21,122.80	

SPECIAL NETT ITEMS :				
1.	1 PC	FRONT NUMBER PLATE	ND	45.00 ✓
2.	1 PC	TAILGATE SEALANT	M	40.00 ✓
3.	1 PC	REAR NUMBER PLATE	ND	45.00 ✓
4.	2 PCS	REAR BUMPER STICKER	60.00	120.00 ✗
5.	1 SET	REVERSE SENSOR	R	250.00
				200.00

CONTINUE / ...

FALCON - AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: Blk 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare S(575721) Tel: 6452-0880 / 6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No 8 Pandan Loop (Blk 1/Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110
Website: www.falconair.com.sg Email: email@falconair.com.sg



FALCON-AIR

FALCON - AIR AUTO SERVICES PTE LTD

Co. Reg. No.: 199501140D
GST Reg. No.: 199501140DTAN CHIN HAN AMAS
C/O 176 SIN MING DRIVE #01-06/07
SIN MING AUTOCARE 575721Attention: Motor Claim Department
Contact: 92774008

Estimate: ES011723

Date: 15/11/2018
Vehicle Num.: SLP 6137Z
Make/Model: HONDA JAZZ-2016/2017
Chassis/Eng#: JHMGK5850HX201110
Accident Date: 13/11/2018
Claim No.:
Reference: TP - AVIVA AGT AXA (SM)
Policy No.: 10835015

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

6.	1 PC	REAR COMPARTMENT PANEL INSULATOR		
7.	1 PC	RH REAR FENDER QUARTER GLASS SEALANT		

280.00 X
40.00 30.00

Special Nett Total S\$:

820.00

LABOUR:

TO FOCUS HEADLAMP
TO REMOVE/REFIX AIR CON CONDENSER, PIPE
VACUUM AND TOP UP AIR CON GAS
TO REMOVE/REFIX TRIMS, ETC TO FACILITATE REPAIRS
TO CHECK REAR WIRING
TO REMOVE/REFIX REAR WINDSCREEN GLASS
TO CONDUCT WATER TEST TO CHECK FOR LEAKAGE
TO TRANSFER TAILGATE MECHANISM
TO REMOVE/REFIX RH REAR QUARTER GLASS
TO CONDUCT CHASSIS ALIGNMENT
TO REFIX REVERSE SENSOR
TO REMOVE/REPLACE/RE-ALIGN REAR EXHAUST SYSTEM
TO REMOVE/REFIX REAR AXLE TO FACILITATE REPAIRS
TO APPLY BODY SEALANT TO CAR JOINTS
TO RUSTPROOF ACCIDENT DAMAGE AREA
TO STRAIGHTEN LH/RH FRONT CHASSIS, LH/RH FRONT WHEEL
HOUSE, LH/RH FRONT DOOR, LH REAR FENDER, LH REAR
CHASSIS, LH/RH REAR DOOR, RH ROOF PANEL, CUT-OUT/RE-WELD

50.00 20.00
120.00 100.00
280.00 120.00
50.00 20.00
120.00 50.00
50.00 30.00
100.00 60.00
100.00 50.00
480.00 250.00
50.00 50.00
280.00 80.00
400.00 80.00
260.00 90.00
260.00 180.00

CONTINUE / ...

FALCON - AIR AUTO SERVICES PTE LTD
[a subsidiary of Falcon-Air Holdings Pte Ltd]

Head Office: Blk 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare S(575721) Tel: 6452-0880 / 6458-0880 Fax: 6454-7862
Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 No 8 Pandan Loop (Blk 1/Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110
Website: www.falconair.com.sg Email: email@falconair.com.sg



FALCON-AIR

FALCON-AIR AUTO SERVICES PTE LTD

Co. Reg. No.: 199501140Q
GST Reg. No.: 199501140Q Page 6/6

TAN CHIN HAN AMAS
C/O 176 SIN MING DRIVE #01-06/07
SIN MING AUTOCARE 575721

Attention: Motor Claim Department
Contact: 92774008

Estimate: ES011723

Date: 15/11/2018
Vehicle Num.: SLP 6137Z
Make/Model: HONDA JAZZ-2016/2017
Chassis/Eng#: JHMGK5850HX201110
Accident Date: 13/11/2018
Claim No.:
Reference: TP - AVIVA AGT AXA (SM)
Policy No.: 10835015

S/N	Quantity	Particular	Unit Price	Amount S\$
		FRONT SUPPORT PANEL, RH REAR CHASSIS, RH REAR FENDER, REAR END PANEL, REAR COMPARTMENT PANEL INCLUDING REPLACEMENT OF PARTS TO SPRAY PAINT ON BONNET, FRONT BUMPER, FRONT BUMPER REINFORCEMENT, LH/RH FRONT FENDER, FRONT SUPPORT PANEL, LH/RH FRONT DOOR, LH/RH REAR DOOR, LH/RH ROOF PANEL, ROOF PANEL, TAILGATE, REAR BUMPER, REAR END PANEL, REAR COMPARTMENT PANEL, LH/RH REAR FENDER		2600 3,600.00
		Labour Total S\$:		2600 3,600.00 9,800.00

E. & O.E.

Total S\$: 31,742.80

for FALCON AIR AUTO SERVICES PTE LTD

The quotation was prepared from visual inspection. Further materials and labour charges may be required when repair commences. We will advise you accordingly.

Parts - 16171.28
Supply - 691.60
Supply S/N - 1180.00
S/N - 680.00
Labour - 6370.00
Total - \$22092.88
P/P

FALCON-AIR AUTO SERVICES PTE LTD
(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: Blk 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare S(575721) Tel: 6452-0880 / 6458-0880 Fax: 6454-7862
Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No 8 Pandan Loop (Blk 1/Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110
Website: www.falconair.com.sg Email: email@falconair.com.sg

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 4008A

Vehicle Details

Vehicle No.: SLP6137Z

Vehicle to be Exported: No

Intended Deregistration Date: 16 Nov 2018

Vehicle Make: HONDA

Vehicle Model: JAZZ 1.5 VTIR CVT ABS D/AIRBAG 2WD

Primary Colour: Yellow

Manufacturing Year: 2016

Engine No.: L15B31190782

Chassis No.: JHMGK5850HX201110

Maximum Power Output: 96.0 kW (128 bhp)

Open Market Value: \$16,839.00

Original Registration Date: 12 Jun 2017

First Registration Date: 12 Jun 2017

Transfer Count: 0

Actual ARF Paid: \$11,839.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 11 Jun 2027

PARF Rebate Amount: \$8,879.00

Intended COE Rebate Details

COE Expiry Date: 11 Jun 2027

COE Category: A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years): 10

QP Paid: \$46,489.00

COE Rebate Amount: \$39,845.00

Total Rebate Amount: \$48,724.00

The information contained herein is correct as at 16 Nov 2018

OK

Inchcape
Pre-Owned
6303 6303

FREE SERVICE & TYRE CREDITS
WHEN YOU PURCHASE A CAR FROM INCHCAPE-PREOWNED

PIT & GO
FREE SERVICE & TYRE CREDITS
WALK IN \$1,500
FOR PURCHASES BELOW \$10K

PIT & GO
FREE SERVICE & TYRE CREDITS
WALK IN \$3,000
FOR PURCHASES ABOVE \$10K



LEARN MORE
»

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

New Battery.



Best Buy, All Wear And Tear
Done. View To Believe.
Direct Owner Stand

Lake View
Credit Pte Ltd

view our cars

> Low prices guaranteed
> Specialist in Japanese cars
> Easy loan approval
> All terms are negotiable

Browse by Category

Sort by Date Posted

20 results/page

7 vehicles

Honda Jazz

Advanced Search

Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status	
Search Selection Honda Jazz	Any	Any	2017	Any	Any	Any	Available	
	Honda Jazz 1.5A RS	\$69,800	\$7,760 /yr	25-Jan-2017	1,498 cc	30,000 km	Hatchback	Available
Lowest Interest Rate Starting From 2.28%! Wide Range Of Loan Packages With Low Down Payment! Kah Motor Warranty Till Jan 2022 With 2 Free Engine Oil Servicing And 1 Free Gear Oil Servicing! Great Savl...								
Posted: 17-Nov-2018 Tags: 2017 Honda Jazz, 2017 honda jazz, Honda Jazz, honda jazz, Honda, Jazz, jazz, Used Honda								
	Honda Jazz 1.5A RS	\$69,800	\$7,820 /yr	23-Jan-2017	1,498 cc	32,956 km	Hatchback	Available
Price Slashed To Clear! Guaranteed Cheapest In The Whole Market! 5 Years Unlimited Mileage Warranty By Agent! Owner Upgrading To New 7-Seater SUV Due To Family Expansion, Built In Japan Model! High Lo...								
Posted: 17-Nov-2018 Tags: 2017 Honda Jazz, 2017 honda jazz, Honda Jazz, honda jazz, Honda, Jazz, jazz, Used Honda								
	Honda Jazz 1.5A RS	\$69,000	\$7,630 /yr	06-Feb-2017	1,498 cc	37,000 km	Hatchback	Available
10% Down Payment With Low Interest Rate At 2.78%! Very Well Maintained And Low Mileage, 2 Years Warranty/Servicing By Platinum Motoring In House Workshop. New \$2k Metallic Paint Color Of Your Choice A...								
Posted: 16-Nov-2018 Tags: 2017 Honda Jazz, 2017 honda jazz, Honda Jazz, honda jazz, Honda, Jazz, jazz, Used Honda								
	Honda Jazz 1.5A RS	\$70,800	\$7,700 /yr	30-Mar-2017	1,498 cc	18,000 km	Hatchback	Available
1 Owner, Low Down Payment Available. Comes With 5 Years Warranty. Fully Agent Service And Maintain. Kah Motor Unit. As Good As New, Popular Hatch In Sporty Blue, New Earth Dream Transmission Which Giv...								
Posted: 14-Nov-2018 Tags: 2017 Honda Jazz, 2017 honda jazz, Honda Jazz, honda jazz, Honda, Jazz, jazz, Used Honda								
	Force BBK Big 4 Pot Brake Kit FORCE Big 4 Pot Big Brake Kit (BBK) for Honda Integra DC5 More info about this product							
	Honda Jazz 1.5A RS	\$69,800	\$7,810 /yr	03-Jan-2017	1,498 cc	30,000 km	Hatchback	Available
Accredited Company! 1 Owner, Enjoy Exclusive 1.98% Interest Rate! Accident Free, Low Mileage Done, Low Down Payment. Low Interest Rate. Maintained And Warranty By Kah Motors, In-house Financing Option...								
Fu Yiap Motor Trading Posted: 07-Nov-2018 Tags: 2017 Honda Jazz, 2017 honda jazz, Honda Jazz, honda jazz, Honda, Jazz, jazz, Used Honda								
	Honda Jazz 1.5A RS	\$69,500	\$7,700 /yr	02-Feb-2017	1,498 cc	23,000 km	Hatchback	Available
Only 10% Down Payment! Safe Purchase! Agent Warranty! Fuel Saver! Trouble Free! Good Handling And Performance, 90% Loan Can Be Arranged! High Trade In For Your Car! Buying A Beauty Pre-Owned Car With ...								
GD Motoring Posted: 03-Nov-2018 Tags: 2017 Honda Jazz, 2017 honda jazz, Honda Jazz, honda jazz, Honda, Jazz, jazz, Used Honda								
	Honda Jazz 1.5A (OPC)	\$67,500	\$7,160 /yr	31-May-2017	1,498 cc	19,000 km	Hatchback	Available
Funky Orange With Black Interior, New Facelifted Model, One Extremely Careful Owner, Super Low Mileage Done, Excellent Condition, As Similar As Brand New, Low Fuel Consumption, Don't Miss This Rare Op...								
Posted: 03-Oct-2018 Tags: 2017 Honda Jazz, 2017 honda jazz, Honda Jazz, honda jazz, Honda, Jazz, jazz, Used Honda								

Compare



Service Request Details

Claim

S8M012ZF

Reference

None 

Loss Date

November 13, 2018

Request Date

November 15, 2018

Due Date

November 22, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Direct settlement

16.11.2018 @ 9.11am
Florence veh in
Kenneth.

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SLP6137Z

Make

TPVD HONDA

Model

JAZZ 1.5 VTIR CVT ABS D/AIRBAG 2WD

Service Address

51 Ubi Avenue 1, #01-25, . . 408933

Primary Contact/Insured

AMV PTE LTD

231 MOUNTBATTEN ROAD, #02-01 BLOCK B, 397999, Singapore

66944456

michael@amv-singapore.com

Claim Handler

WANG Peter

peter.wang@axa.com.sg

Additional Instructions

Wkshop: Falcon Air

Messages

Invoices

History

Documents

Assessment

Metrics

Notes

[New Message](#)

TYPE



SENT

11/15/18 5:53 PM

FROM

WANG Peter

SUBJECT

TP Excess: \$1500

BODY



TYPE



SENT

11/15/18 5:14 PM

FROM

WANG Peter

SUBJECT

Liability Clear - Pending Company Authorization Letter

BODY



TYPE



SENT

11/15/18 5:06 PM

FROM

WANG Peter

SUBJECT

Pls notify me if TP objects to this appointment

BODY



DHAKAL Raghav

From: Florence Loh <fa_autoservices@falconair.com.sg>
Sent: Wednesday, November 14, 2018 2:45 PM
To: SG AXA Insurance SM AXA SGP - Motor Survey; SG AXA Insurance SM Claims Service Team
Cc: Joshua
Subject: Accident Involving SLP6137Z and SLF7034H on 13/11/2018
Attachments: tp search_001.pdf; gia.pdf
Categories: Raghav

Dear Sir/Madam,

We are assisting vehicle owner SLP 6137Z with third party claim against your insured SLF 7034H .

Attach GIA report and LTA search fee for your perusal.

Please provide a list of the 10 motor surveyor list to us to arrange for survey.

Thank you.

Falcon-Air Auto Services Pte Ltd
176 Sin Ming Drive
#01-06/07 Sin Ming AutoCare
Singapore 575721

Tel: 6452 0880 Fax: 6454 7862

IMPORTANT NOTE: Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No : _____ Vehicle Registration No: SLF7034H

Name(as shown in NRIC) : _____ NRIC/FIN/Passport No : _____

(*Vehicle Driver / Vehicle Owner) (*) Please delete as appropriate

Address : _____ Singapore()

Contact (Tel) : _____ Mobile No. : _____

Email Address : _____

Date of Accident : 13/11/2018 Time of Accident : _____

Place of Accident : _____

Insurance Company : _____

(B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

" THE NAME OF THE DRIVER SHOULD BE SUNDARAMURTHY THANIKAIVELAN. THAT'S ALL!"



Policyholder / Driver's Signature
Date:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:
Date:

Hsiao Tong (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Thursday, 6 June 2019 8:56 AM
To: Vic (LKKAUTO)
Subject: FW: Acknowledgement Your Ref:SLP6137Z Our Ref: S8M012ZF MC/PWS

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Joshua Ng <joshua@falconair.com.sg>
Sent: Thursday, 6 June 2019 8:55 AM
To: Kenneth Kong (LKKAUTO) <KennethKong@lkkauto.com>
Cc: florence <fa_autoservices@falconair.com.sg>
Subject: Re: Acknowledgement Your Ref:SLP6137Z Our Ref: S8M012ZF MC/PWS

Dear Kenneth,

Yes \$23,800.00 is the lowest we can accept.

Thanks
Joshua Ng
Falcon-Air Auto Services Pte Ltd
Tel : 6452 0880

From: Kenneth Kong (LKKAUTO)
Sent: Thursday, June 06, 2019 8:29 AM
To: Joshua Ng
Subject: RE: Acknowledgement Your Ref:SLP6137Z Our Ref: S8M012ZF MC/PWS

Hi Joshua, is this the lowest amount you can accept? If yes, I will get mandate from AXA and wait for their instruction. Kenneth

From: Joshua Ng [<mailto:joshua@falconair.com.sg>]
Sent: Tuesday, 4 June, 2019 4:23 PM
To: Kenneth Kong (LKKAUTO)
Cc: florence; lynn; francine ng
Subject: Fw: Acknowledgement Your Ref:SLP6137Z Our Ref: S8M012ZF MC/PWS

Resend

Regards
Joshua Ng
Falcon-Air Auto Services Pte Ltd
Tel : 6452 0880

From: Joshua Ng

Sent: Tuesday, May 14, 2019 1:08 PM
To: kenneth kong
Cc: florence ; lynn ; francine ng
Subject: Fw: Acknowledgement Your Ref:SLP6137Z Our Ref: S8M012ZF MC/PWS

Resend

Regards
Joshua Ng
Falcon-Air Auto Services Pte Ltd
Tel : 6452 0880

From: Joshua Ng
Sent: Friday, March 08, 2019 11:57 AM
To: kenneth kong
Cc: Francine Ng ; florence ; lynn
Subject: Re: Acknowledgement Your Ref:SLP6137Z Our Ref: S8M012ZF MC/PWS

Dear kenneth,

Can we settle the case at \$23,800.00?

Regards
Joshua Ng
Falcon-Air Auto Services Pte Ltd
Tel : 6452 0880

From: Florence Loh
Sent: Friday, March 08, 2019 10:18 AM
To: 'Joshua'
Cc: Kenneth Kong ; Francine Ng
Subject: FW: Acknowledgement Your Ref:SLP6137Z Our Ref: S8M012ZF MC/PWS

Hi Joshua,

Please advise.

Florence Loh
Falcon Air Auto Services Pte Ltd
176 Sin Ming Drive #01-06
Sin Ming Autocare
Singapore 575721

Tel: 6452 0880 Fax: 6454 7862

From: Kenneth Kong (LKKAUTO) <KennethKong@lkkauto.com>
Sent: Friday, 8 March 2019 9:26 AM
To: Florence Loh <fa_autoservices@falconair.com.sg>
Subject: RE: Acknowledgement Your Ref:SLP6137Z Our Ref: S8M012ZF MC/PWS

Florence, would like to offer repair sum of \$22,800.00 for this case due to economical value. Kenneth

From: Florence Loh [mailto:fa_autoservices@falconair.com.sg]
Sent: Saturday, 2 March, 2019 12:42 PM
To: Kenneth Kong (LKKAuto)
Cc: 'Joshua'; Francine Ng; Lynn Teo
Subject: FW: Acknowledgement Your Ref:SLP6137Z Our Ref: S8M012ZF MC/PWS

Good morning Kenneth,

Attach estimate, supplementary and photos of the above vehicle for finalise.

Please confirm COR part by part \$25,092.88.

Thank you.

Sending on behalf for Joshua Ng.

Florence Loh
Falcon Air Auto Services Pte Ltd
176 Sin Ming Drive #01-06
Sin Ming Autocare
Singapore 575721

Tel: 6452 0880 Fax: 6454 7862

From: Florence Loh <fa_autoservices@falconair.com.sg>
Sent: Thursday, 15 November 2018 9:02 AM
To: DHAKAL Raghav <raghav.dhakal@axa.com.sg>; Florence Loh <fa_autoservices@falconair.com.sg>
Cc: Claims Service Team (AXA) <cst@axa.com.sg>; Joshua <joshua@falconair.com.sg>
Subject: Re: Acknowledgement Your Ref:SLP6137Z Our Ref: S8M012ZF MC/PWS

Dear Sir/Madam,

Kindly assign survey to AXA in house surveyors.

Thank you.

Florence Loh
Falcon-Air Auto Services Pte Ltd
176 Sin Ming Drive
#01-06/07 Sin Ming AutoCare
Singapore 575721

Tel: 6452 0880 Fax: 6454 7862

From: DHAKAL Raghav
Sent: Wednesday, November 14, 2018 3:49 PM
To: Florence Loh
Subject: Acknowledgement Your Ref:SLP6137Z Our Ref: S8M012ZF MC/PWS

Dear Sir,

Without Prejudice

We want to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list below to conduct the joint pre-repair survey as a Single Joint Expert.

List of our motor surveyors:-

1. Mohd Fadhilah Bin Osman (LBS Automotive Appraisal Pte Ltd)
2. Chris Ang (LBS Automotive Appraisal Pte Ltd)
3. Stan See Chee Seng (LBS Automotive Appraisal Pte Ltd)
4. Ricky Teng/ Elgene Teng (RT Appraisal Pte Ltd)
5. Michael Chong (RT Appraisal Pte Ltd)
6. Elson Teng (RT Appraisal Pte Ltd)
7. Simon Ho/ Mohammed Rasul (LKK Auto Consultants Pte Ltd)
8. Ma Chin Fook/ Adrian Ling/ Chua Weijie (LKK Auto Consultants Pte Ltd)
9. Kenneth Kong/ Marcus Chua/ Hendry Ng (LKK Auto Consultants Pte Ltd)
10. AXA in house surveyors

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert. Meanwhile, please furnish us with estimate quotation in order for our surveyor to complete the pre repair survey.

If there be any injury claims by your client, please combine it in one Letter of Demand in light of one cause of action, save as to costs and expenses.

Please send your reply to the in-charge claim handler who is copied in this email.

Regards
Raghav Dhakal

From: Florence Loh [mailto:fa_autoservices@falconair.com.sg]
Sent: Wednesday, November 14, 2018 2:45 PM
To: SG AXA Insurance SM AXA SGP - Motor Survey <motor.survey@axa.com.sg>; SG AXA Insurance SM Claims Service Team <cst@axa.com.sg>
Cc: Joshua <joshua@falconair.com.sg>
Subject: Accident Involving SLP6137Z and SLF7034H on 13/11/2018

Dear Sir/Madam,

We are assisting vehicle owner SLP 6137Z with third party claim against your insured SLF 7034H .

Attach GIA report and LTA search fee for your perusal.

Please provide a list of the 10 motor surveyor list to us to arrange for survey.

Thank you.

Falcon-Air Auto Services Pte Ltd
176 Sin Ming Drive
#01-06/07 Sin Ming AutoCare
Singapore 575721

Tel: 6452 0880 Fax: 6454 7862