



FALCON - AIR

FALCON - AIR AUTO SERVICES PTE LTD

Co. Reg. No.: 199501140D
GST Reg. No.: 199501140D Page 1 / 6

TAN CHIN HAN AMAS
C/O 176 SIN MING DRIVE #01-06/07
SIN MING AUTOCARE 575721

Attention : Motor Claim Department
Contact : 92774008

Not Noted
Resurvey 84pgm

23 days

Estimate : ES011723

Date : 15/11/2018
Vehicle Num. : SLP 6137Z
Make/Model : HONDA JAZZ-2016/2017
Chassis/Eng# : JHMGK5850HX201110
Accident Date : 13/11/2018
Claim No. :
Reference : TP - AVIVA AGT AXA (SM)
Policy No. : 10835015

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1 PC	BONNET		1,011.70
2.	2 PCS	BONNET RUBBER (FRONT)	25.10	50.20
3.	2 PCS	BONNET RUBBER (SIDE)	24.30	48.60
4.	1 PC	BONNET INSULATOR		186.70
5.	10 PCS	BONNET INSULATOR CLIPS	5.00	50.00
6.	1 PC	BONNET LOCK		137.00
7.	2 PCS	BONNET HINGE	75.00	150.00
8.	2 PCS	HEADLAMP	1,336.50	2,673.00
9.	2 PCS	HEADLAMP RETAINER	45.90	91.80
10.	2 PCS	HEADLAMP PANEL	180.00	360.00
11.	1 PC	RADIATOR GRILLE		508.50
12.	1 PC	RADIATOR GRILLE CHROME MOULDING		118.00
13.	1 PC	RADIATOR GRILLE LOGO		65.00
14.	1 PC	RADIATOR GRILLE EMBLEM (RS)		95.00
15.	1 PC	FRONT BUMPER		695.60
16.	10 PCS	FRONT BUMPER CLIPS	5.00	50.00
17.	2 PCS	FRONT BUMPER SIDE RETAINER	35.40	70.80
18.	1 PC	FRONT BUMPER REINFORCEMENT		353.20
19.	1 PC	LH FOG LAMP		340.00
20.	1 PC	LH FOG LAMP GRILLE		90.30
21.	1 PC	LH FRONT DAY LIGHT		288.20
22.	1 PC	FRONT SUPPORT PANEL		655.90

CONTINUE / ...

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

FALCON - AIR AUTO SERVICES PTE LTD
(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office : Blk 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare S(575721) Tel: 6452-0880 / 6458-0880 Fax: 6454-7862
Branches : Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No 8 Pandan Loop (Blk 1/Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110
Website: www.falconair.com.sg Email: email@falconair.com.sg



FALCON-AIR

TAN CHIN HAN AMAS
C/O 176 SIN MING DRIVE #01-06/07
SIN MING AUTOCARE 575721

Attention : Motor Claim Department

Contact : 92774008

Estimate : ES011723

Date : 15/11/2018
Vehicle Num. : SLP 6137Z
Make/Model : HONDA JAZZ-2016/2017
Chassis/Eng# : JHMGK5850HX201110
Accident Date : 13/11/2018
Claim No. :
Reference : TP - AVIVA AGT AXA (SM)
Policy No. : 10835015

S/N	Quantity	Particular	Unit Price	Amount S\$
23.	1 PC	FRONT SUPPORT PANEL GARNISH		
24.	2 PCS	FRONT FENDER		
25.	2 PCS	FRONT FENDER SHIELD		
26.	16 PCS	FRONT FENDER SHIELD CLIP		
27.	1 PC	AIR DUCT		
28.	1 PC	AIR DUCT HOSE		
29.	2 PCS	AIR GUIDE		
30.	1 PC	AIR CON CONDENSER		
31.	1 PC	AIR CON FAN COWLING		
32.	1 PC	AIR CON FAN BLADE		
33.	1 PC	AIR CON FAN MOTOR		
34.	1 PC	AIR CON LIQUID PIPE		
35.	1 PC	AIR CON SUCTION HOSE		
36.	1 PC	AIR CON DISCHARGE HOSE		
37.	1 PC	RADIATOR		
38.	1 PC	RADIATOR FAN COWLING		
39.	1 PC	RADIATOR FAN BLADE		
40.	1 PC	RADIATOR FAN MOTOR		
41.	2 PCS	RADIATOR TOP MOUNTING		
42.	1 PC	RADIATOR TOP HOSE		
43.	1 PC	INTAKE MANIFOLD		
44.	1 PC	INTAKE MANIFOLD GASKET		
45.	1 PC	WIPER WASHER TANK		
46.	1 PC	WIPER WASHER TANK NECK		

CONTINUE / ...



FALCON - AIR

FALCON - AIR AUTO SERVICES PTE LTD

Co. Reg. No.: 199501140D
GST Reg. No.: 199501140DTAN CHIN HAN AMAS
C/O 176 SIN MING DRIVE #01-06/07
SIN MING AUTOCARE 575721Attention : Motor Claim Department
Contact : 92774008

Estimate : ES011723

Date : 15/11/2018
Vehicle Num. : SLP 6137Z
Make/Model : HONDA JAZZ-2016/2017
Chassis/Eng# : JHMGK5850HX201110
Accident Date : 13/11/2018
Claim No. :
Reference : TP - AVIVA AGT AXA (SM)
Policy No. : 10835015

S/N	Quantity	Particular	Unit Price	Amount S\$	
47.	2 PCS	HORN	65.10	130.20	✓
48.	1 PC	TAILGATE GLASS	<i>Shatter</i>	925.60	✓
49.	1 PC	TAILGATE GLASS MOULDING	<i>nc</i>	181.80	✓
50.	1 PC	TAILGATE	<i>By</i>	1,114.00	✓
51.	1 PC	TAILGATE GARNISH W/LOGO	<i>Chs</i>	353.70	✓
52.	1 PC	TAILGATE EMBLEM (JAZZ)	<i>nc</i>	55.10	✓
53.	1 PC	TAILGATE EMBLEM (RS)	<i>nc</i>	55.10	✓
54.	1 PC	TAILGATE WEATHERSTRIP	<i>ng Div</i>	142.30	✓
55.	1 PC	TAILGATE INNER TRIM	<i>ng Div</i>	298.00	✓
56.	10 PCS	TAILGATE INNER TRIM CLIP	5.00	50.00	✓
57.	2 PCS	TAILGATE REFLECTOR	<i>cut</i> 189.30	378.60	✓
58.	1 PC	TAILGATE LOCK	<i>Ref</i>	227.50	✓
59.	1 PC	TAILGATE INNER HANDLE	<i>Ref</i>	40.70	✓
60.	1 PC	REAR WIPER ARM	<i>Ref</i>	71.20	X
61.	1 PC	REAR WIPER BLADE	<i>Ref</i>	59.50	X
62.	2 PCS	TAILLAMP	<i>c/s Bro</i> 417.30	834.60	✓
63.	4 PCS	TAILLAMP CLIPS	5.00	20.00	✓
64.	2 PCS	TAILLAMP PANEL	175.60	351.20	✓
65.	1 PC	REAR BUMPER	<i>By</i>	692.60	✓
66.	10 PCS	REAR BUMPER CLIPS	5.00	50.00	✓
67.	2 PCS	REAR BUMPER SIDE RETAINER	33.80	67.60	✓
68.	1 PC	RH REAR BUMPER GRILLE	<i>Ref</i>	49.00	✓
69.	1 PC	REAR END PANEL	<i>By</i>	514.00	✓
70.	1 PC	REAR END PANEL GARNISH	<i>ng Div</i>	120.50	✓

CONTINUE / ...

FALCON - AIR AUTO SERVICES PTE LTD
(a subsidiary of Falcon-Air Holdings Pte Ltd)Head Office : Blk 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare S(575721) Tel: 6452-0880 / 6458-0880 Fax: 6454-7862
Branches : Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No 8 Pandan Loop (Blk 1/Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110
Website: www.falconair.com.sg Email: email@falconair.com.sg



FALCON - AIR AUTO SERVICES PTE LTD

Co. Reg. No.: 199501140D
GST Reg. No.: 199501140D

FALCON - AIR

TAN CHIN HAN AMAS
C/O 176 SIN MING DRIVE #01-06/07
SIN MING AUTOCARE 575721

Attention : Motor Claim Department

Contact : 92774008

Estimate : ES011723

Date : 15/11/2018
Vehicle Num. : SLP 6137Z
Make/Model : HONDA JAZZ-2016/2017
Chassis/Eng# : JHMGK5850HX201110
Accident Date : 13/11/2018
Claim No. :
Reference : TP - AVIVA AGT AXA (SM)
Policy No. : 10835015

S/N	Quantity	Particular	Unit Price	Amount S\$
71.	1 PC	REAR COMPARTMENT BOARD		298.20
72.	1 PC	REAR COMPARTMENT SPONGE	cm	188.60
73.	1 PC	REAR COMPARTMENT PANEL		997.00
74.	1 PC	RH REAR CHASSIS	n	710.30
75.	1 PC	RH REAR FENDER	Ar	838.50
76.	1 PC	RH REAR FENDER QUARTER GLASS MOULDING	n	60.10
77.	2 PCS	RH REAR FENDER INNER TRIM	Refurn/cm	285.60
78.	20 PCS	RH REAR FENDER INNER TRIM CLIP	5.00	100.00
79.	1 PC	REAR EXHAUST SILENCER		604.40
80.	2 PCS	REAR EXHAUST SILENCER MOUNTING	35.60	71.20
81.	1 PC	REAR EXHAUST SILENCER HEAT SHIELD		65.90
82.	1 PC	ANTENNA SENSOR		158.10
List TotalS\$:				26,403.50
20.00% Discount S\$:				5,280.70
				21,122.80
SPECIAL NETT ITEMS :				
1.	1 PC	FRONT NUMBER PLATE	nd	45.00
2.	1 PC	TAILGATE SEALANT	n	40.00
3.	1 PC	REAR NUMBER PLATE	n	45.00
4.	2 PCS	REAR BUMPER STICKER	60.00	120.00
5.	1 SET	REVERSE SENSOR	Ar	250.00
				200.00

CONTINUE / ...

FALCON - AIR AUTO SERVICES PTE LTD
(a subsidiary of Falcon-Air Holdings Pte Ltd)Head Office : Blk 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare S(575721) Tel: 6452-0880 / 6458-0880 Fax: 6454-7862
Branches : Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No 8 Pandan Loop (Blk 1/Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110
Website: www.falconair.com.sg Email: email@falconair.com.sg



FALCON - AIR AUTO SERVICES PTE LTD

Co. Reg. No.: 199501140D
GST Reg. No.: 199501140D

FALCON - AIR

TAN CHIN HAN AMAS
C/O 176 SIN MING DRIVE #01-06/07
SIN MING AUTOCARE 575721

Attention : Motor Claim Department

Contact : 92774008

Estimate : ES011723

Date : 15/11/2018
Vehicle Num. : SLP 6137Z
Make/Model : HONDA JAZZ-2016/2017
Chassis/Eng# : JHMGK5850HX201110
Accident Date : 13/11/2018
Claim No. :
Reference : TP - AVIVA AGT AXA (SM)
Policy No. : 10835015

S/N	Quantity	Particular	Unit Price	Amount S\$
6.	1 PC	REAR COMPARTMENT PANEL INSULATOR		280.00
7.	1 PC	RH REAR FENDER QUARTER GLASS SEALANT		40.00
Special Nett Total S\$:				820.00
LABOUR :				
TO FOCUS HEADLAMP				50.00
TO REMOVE/REFIX AIR CON CONDENSER, PIPE				120.00
VACUUM AND TOP UP AIR CON GAS				280.00
TO REMOVE/REFIX TRIMS, ETC TO FACILITATE REPAIRS				50.00
TO CHECK REAR WIRING				120.00
TO REMOVE/REFIX REAR WINDSCREEN GLASS				50.00
TO CONDUCT WATER TEST TO CHECK FOR LEAKAGE				100.00
TO TRANSFER TAILGATE MECHANISM				100.00
TO REMOVE/REFIX RH REAR QUARTER GLASS				480.00
TO CONDUCT CHASSIS ALIGNMENT				50.00
TO REFIX REVERSE SENSOR				280.00
TO REMOVE/REPLACE/RE-ALIGN REAR EXHAUST SYSTEM				400.00
TO REMOVE/REFIX REAR AXLE TO FACILITATE REPAIRS				260.00
TO APPLY BODY SEALANT TO CAR JOINTS				260.00
TO RUSTPROOF ACCIDENT DAMAGE AREA				
TO STRAIGHTEN LH/RH FRONT CHASSIS, LH/RH FRONT WHEEL				
HOUSE, LH/RH FRONT DOOR, LH REAR FENDER, LH REAR				
CHASSIS, LH/RH REAR DOOR, RH ROOF PANEL, CUT-OUT/RE-WELD				

CONTINUE / ...

FALCON - AIR AUTO SERVICES PTE LTD
(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office : Blk 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare S(575721) Tel: 6452-0880 / 6458-0880 Fax: 6454-7862
 Branches : Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No 8 Pandan Loop (Blk 1/Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110
 Website: www.falconair.com.sg Email: email@falconair.com.sg



FALCON - AIR

TAN CHIN HAN AMAS
C/O 176 SIN MING DRIVE #01-06/07
SIN MING AUTOCARE 575721

Attention : Motor Claim Department

Contact : 92774008

Estimate : ES011723

Date : 15/11/2018

Vehicle Num. : SLP 6137Z

Make/Model : HONDA JAZZ-2016/2017

Chassis/Eng# : JHMGK5850HX201110

Accident Date : 13/11/2018

Claim No. :

Reference : TP - AVIVA AGT AXA (SM)

Policy No. : 10835015

S/N	Quantity	Particular	Unit Price	Amount S\$
		FRONT SUPPORT PANEL, RH REAR CHASSIS, RH REAR FENDER, REAR END PANEL, REAR COMPARTMENT PANEL INCLUDING REPLACEMENT OF PARTS		2600 3,600.00
		TO SPRAY PAINT ON BONNET, FRONT BUMPER, FRONT BUMPER REINFORCEMENT, LH/RH FRONT FENDER, FRONT SUPPORT PANEL, LH/RH FRONT DOOR, LH/RH REAR DOOR, LH/RH ROOF PANEL, ROOF PANEL, TAILGATE, REAR BUMPER, REAR END PANEL, REAR COMPARTMENT PANEL, LH/RH REAR FENDER		2600 3,600.00
		Labour Total S\$:		9,800.00

E. & O.E.

Total S\$: 31,742.80

=====

for FALCON AIR AUTO SERVICES PTE LTD

The quotation was prepared from visual inspection. Further materials and labour charges may be required when repair commences. We will advise you accordingly.