Estimated Cost	4	i Agnes of	SMO Bill to:	Dat	e/Time 16/11/18@1.39pm
OD (TP) WS To Inspect Veh at Workshop m of	uicle No: u/s	comfort De	MV7C8 992U	Tel:	SKL7414A G214 B300 .
Policy No:	VALMEIC	01018144		(MIDI	305012
Sum Insured:_			Excess:		
Make of Veh: (Client's Record)				D.C	A. 15/11/2018
		20			
CA / REV /	REP. / REV 2 46pm316/1	24 HRS ^(Mp) Lll& Person Cont	acted Mr- Ji	H ✓ Vehic	O.D. Endorsement:
CA / REV /	REP. / REV 2 AGPM 16/1 Action/Instruct	118 Person Cont		Yehio	
CA / REV /	Action/Instruct 8HD 49	1118 Person Cont ion () Esti 924-003/1/		Yehio Comfort Dela	(D) OUT 10 (Loyeng)
CA / REV / Date/Time 1.	Action/Instruct	ion (\checkmark Esting 24 - $<$ $<$ $<$ $<$ $<$ $<$ $<$ $<$ $<$ $<$	imate Insp:	Confut Dela /KIfa8n	(D) OUT 10 (Loyeng) 2 BOA: 6/7/18

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To:

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place

#05-01/06, Singapore Land Tower

Singapore 048623

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25

Paya Ubi Industrial Park

Singapore 408933

Attn:

CHAN SHU HUI AGNES

Date:

19 Nov 2018

Preliminary Advice

Insured Vehicle No : SKL7414A

TP Vehicle No

: SHD4992U

Accident Date

: 15/11/2018

Make

: HYUNDAI 140

Assignment Date

: 16/11/2018

Date of Inspection : 16/11/2018

Est. Duration of Repair

Inspection At

: COMFORTDELGRO ENGINEERING PTE LTD (HQ)

205 BRADDELL ROAD

: 3.00

SINGAPORE 579701

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear & front o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	3,110.02
Revised Amount	:S\$	1,572.40
Check Items (Estimated)	:S\$	622.88
Total	:S\$	2,195.28

:S\$ Lump Sum Repair

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

to the annual to the same of					coverage.	
let us nave y	our authorisation.					

The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

Other comments:

...CLAIM SUBFOLDER...(New Assignment)

Main 15	Nov 2018						the state of the s		
			16 Nov 2018 13:39 Assign					New A	ssignment Case
Mair	in.	Re	ference		Claim Details		Docume	nts	Show All
LAIM SUBFO	OLDER DET	AILS	Aller a technological females	The same of the sa		[Creat	ed by insurer]		
sured:	ANG WEE	IANG, ID: S85	20268E, Tel: -	+659616086	0, Email: WEE	JIANG@Y	AHOO,COM		
ain laimant;	COMFORT	TRANSPORTATI	ON PTE LTD,	Co. Reg. No	.: 199303821R				
ehicle Reg. o,:	SHD4992	20			Date of Loss		2018 08:00 - :59 nths and 5 Days F	rom LTA Re	g Date (Man Yr)]
laim Type:	TP / CMT	D1805012			Policy/Cover Note No.:	D17MT	PV01018144 (Com	prehensive)
ehicle Reg. lo. (nsured):	SKL7414A				Policy No. (Claimant):				
					Excess:				
	and the second s	Igro Engineerin							ovincercutary
nsurer:							CHAN SHU HUI A	GNES - 63	29 5327]
djuster:	LKK Auto	Consultants Pte	Ltd (HQ) - Tel:	6256-3561	[Final Rpt	t due 27	/11/2018]		
river/Custo ian Insured):	ANG WEE J	IANG (33 / Male)	, NRIC: S8520)268E, Tel:	+6596160860				
SSOCIATED	MAIL REC	CEIVED						View All	Compose Case M
here are no n	nail for this	case.							
ALL ASSOCI	ATED TASI	KS⊟				View	All Search Tasks	Create !	New Task Compl

CMTD1805012/AGC

COMFORTDELGRO ENGINEERING

ComfortDolGro Engineering Pte Ltd 205 Braddell Road Singapore 579701		Our Ref : 305239752 Date : 16/11/18	10
Mainline +65 6383 6280 Facelmille +65 6280 9755		Time of Fax: 0930 HRS	
www.cdge.com.sg	Your Insured : SKL7414A	N	
Company Registration No: 199506048W	Date of Acc: (5/11/18	SOMPO	_
Workshop			
3	of Trages	Attn: Motor Claims Dept.	

SURVEY OF CLIENT'S DAMAGED VEHICLE REG NO SHD4992U 1 The client has engaged us to repair the vehicle and submit claims against the other 59 Loyang Drive Singapore 503969

- party/parties involved in the accident.
- 2 In accordance to the motor claims framework, we hereby request your presence At 59 Loyang Drive, Singapore 508969 to survey our client's damaged vehicle.
- 3 Enclosed, please find:

Dear Sirs

- 1) Our Initial estimate of repairs of the damaged vehicle.
- II) Accident report made by our client.
- 4 I would appreciate it if you could call us to arrange for the survey of the vehicle

Tel no. 62148355 or Hp no. 98240811 >Lim Kwok Eng. Jumani Bin Masudin Tel no. 62148315 or Hp no. 96355305 Tel no. 62148398, or Hp no. 96358546 Llm Tien Siong Chiang Liat Choon Tel no. 62148314 or Hp no. 92966006 Fauzy Bin Mokhtar Tel no: 62148319 or Hp no: 81259176 6214 8316 Tel:

· Larry Ng ·

- 5 If we do not hear from you within the next 48 hours, we shall deem it that you have waived your rights to survey our client's vehicle and we shall proceed to engage Independent surveyor without further reference to you. We henceforth reserve our rights to claim for loss of use and loss of rental during any delayed period of this survey arrangement.
- 6 This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a Motor Surveyor appointed by the Insurance company.
- 7 Thank you.

A member of

Yours faithfully

for Vice President

Crash Repairs & Claims Recovery

Sompo incurance Singapere Ma 1 6 NOV 2018











SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or wilholding of material facts may allow insurance companies to repudiate policy liability.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

Any false reporting may be referred to the Police for investigation.

- This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCI	DENT	STAT	4 - 100	ΕM	п
ACCI	DEN	CHA	300		ы

Date Of Report

15/11/2018 15:11

Date Of Accident

15/11/2018 08:30

Exact Location Of Accident

EDGEDALE PLAIN > PUNGGOL CENTRAL

SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number

SHD4992U

Insured/Policyholder

Country/State of Loss

Name Of Registered Owner

COMFORT TRANSPORTATION PTE LTD

Co Reg No

199303821R

Email Address

FLEETSAFETY@CDGTAXI.COM.SG

Mobile Phone No

Alternative Phone No

OFFICE-65508768

Vehicle Particulars

Manufacturer

HYUNDAI

Model

140

Exact Purpose for which vehicle was being used at

time of accident

Are you claiming under your own insurance policy for repair to your vehicle?

If No. Please state action to be taken

THIRD PARTY

Vehicle Category

TAXI

Insurance Company

Name of Insurance Company

INDIA INTERNATIONAL INSURANCE PTE LTD

Type Of Coverage

THIRD PARTY FIRE AND/OR THEFT

Fleet Policy

YES

Policy Number

MCOM0015

Cover Note Number

Driver

Name of Driver

TAN CHEE KWAN (CHEN ZHIQUAN)

NRIC No Date Of Birth S8123750F

Occupation

01/08/1981 OUTDOOR

Date Of Driving Pass

11/12/2006

Driving Experience

11 YEARS AND 11 MONTHS

Gender

MALE

Mobile Number

(LOCAL) +65-84482209

Fax Number

Contact Number

EMail Address

KEN8181@YAHOO.COM.SG

Address

BLK 192A RIVERVALE DRIVE #02-928

Postcode

541192

Was driver an employee of the Insured's Company

If No, Relationship of the Driver with the Insured

OTHER - TAXI DRIVER

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

CHAIN COLLISION

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

Number of vehicles involved in the accident

Was any body injured in the Accident?

NO

NO

Was any injured conveyed to hospital by ambulance?

NO

Was any other material or property damaged?

YES

I have been approached by unknown person(s)

NO

soliciting/offering accident claims assistance.

Number of Passengers (Including Driver)

2

Passenger 1

NAME:

GENDER:

: FEMALE

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

PLS REFER TO ATTACHED

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

YES

Remarks/ Reasons:

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SKL7414A

Vehicle Make/Model/Colour

Details Of Properties

PRIVATE CAR

Vehicle Category Name of Driver

STEVEN

NRIC/Passport Number

Contact Number

96160860

Address

Postcode

Insurance Company Name

SOMPO INSURANCE SINGAPORE PTE. LTD.

Nature Of Damage

FRT

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

SKR7962C

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

BAO ZHEN

NRIC/Passport Number

Contact Number

98763049

Address

Postcode

Insurance Company Name

Nature Of Damage

RIGHT REAR

No. Of Passenger (Including Driver)

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

- Please report <u>correctly</u> the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance
 Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
 interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

COMFORT TRANSPORTATION PTE LTD CO. REG. NO. 199303821R

Policyholder's Signature Date & Time: Driver's Signature

(If driver is not the policyholder)

Date & Time: 15.11.2018 @ 12:25 Hrs

Reporting Centre Personnel's Signature

Name: Rubbini NRIC/FIN No.:

Sketch Plan Pg. 2

В-	
Along Edgefield Plains Twds Punggol Central. ESCRIBE CIRCUMSTANCES OF THE ACCIDENT On 15.11.2018 at about 08:30 Hrs, I was travelling along Edgefield Plains Central with one female passenger on board. I was travelling on the extreme right lane. Vehicle infront of me cut into memory. Therefore, I applied e-brake. Suddenly, I felt an impact from behind that veh (B) (SKL 7414A) hit my taxi (A) rear portion. Three of us then alighted and exchanged the particulars. I have companicated and photos taken at scene to support my claims. No injury in this accident. A - SHD 4992U. B - SKL 7414A. Mr. Steven. Hp : 9616 0860.	SHD 4992U.
Along Edgefield Plains Twds Punggol Central. ESCRIBE CIRCUMSTANCES OF THE ACCIDENT On 15.11.2018 at about 08:30 Hrs, I was travelling along Edgefield Plains Central with one female passenger on board. I was travelling on the extreme right lane. Vehicle infront of me cut into me manner. Therefore, I applied e-brake. Suddenly, I felt an impact from behind that veh (B) (SKL 7414A) hit my taxi (A) rear portion. Three of us then alighted and exchanged the particulars. I have companicated and photos taken at scene to support my claims. No injury in this accident. A - SHD 4992U. B - SKL 7414A. Mr. Steven. Hp: 9616 0860.	SKL 7414A.
Along Edgefield Plains Twds Punggol Central. On 15.11.2018 at about 08:30 Hrs, I was travelling along Edgefield Plains Central with one female passenger on board. I was travelling on the extreme right lane. Vehicle infront of me cut into me manner. Therefore, I applied e-brake. Suddenly, I felt an impact from behind that veh (B) (SKL 7414A) hit my taxi (A) rear portion. Three of us then alighted and exchanged the particulars. I have companicated and photos taken at scene to support my claims. No injury in this accident. A - SHD 4992U. B - SKL 7414A. Mr. Steven. Hp : 9616 0860.	SKR 7962C.
Along Edgefield Plains Twds Punggol Central. On 15.11.2018 at about 08:30 Hrs, I was travelling along Edgefield Plains Central with one female passenger on board. I was travelling on the extreme right lane. Vehicle infront of me cut into me manner. Therefore, I applied e-brake. Suddenly, I felt an impact from behind that veh (B) (SKL 7414A) hit my taxi (A) rear portion. Three of us then alighted and exchanged the particulars. I have companicated and photos taken at scene to support my claims. No injury in this accident. A - SHD 4992U. B - SKL 7414A. Mr. Steven. Hp : 9616 0860.	
Along Edgefield Plains Twds Punggol Central. On 15.11.2018 at about 08:30 Hrs, I was travelling along Edgefield Plains Central with one female passenger on board. I was travelling on the extreme right lane. Vehicle infront of me cut into me manner. Therefore, I applied e-brake. Suddenly, I felt an impact from behind that veh (B) (SKL 7414A) hit my taxi (A) rear portion. Three of us then alighted and exchanged the particulars. I have companicated and photos taken at scene to support my claims. No injury in this accident. A - SHD 4992U. B - SKL 7414A. Mr. Steven. Hp : 9616 0860.	
On 15.11.2018 at about 08:30 Hrs, I was travelling along Edgefield Plains Central with one female passenger on board. I was travelling on the extreme right lane. Vehicle infront of me cut into me manner. Therefore, I applied e-brake. Suddenly, I felt an impact from behind that veh (B) (SKL 7414A) hit my taxi (A) rear portion. Three of us then alighted and exchanged the particulars. I have companicated and photos taken at scene to support my claims. No injury in this accident. A - SHD 4992U. B - SKL 7414A. Mr. Steven. Hp : 9616 0860.	
On 15.11.2018 at about 08:30 Hrs, I was travelling along Edgefield Plains Central with one female passenger on board. I was travelling on the extreme right lane. Vehicle infront of me cut into me manner. Therefore, I applied e-brake. Suddenly, I felt an impact from behind that veh (B) (SKL 7414A) hit my taxi (A) rear portion. Three of us then alighted and exchanged the particulars. I have companicated and photos taken at scene to support my claims. No injury in this accident. A - SHD 4992U. B - SKL 7414A. Mr. Steven. Hp : 9616 0860.	
On 15.11.2018 at about 08:30 Hrs, I was travelling along Edgefield Plains Central with one female passenger on board. I was travelling on the extreme right lane. Vehicle infront of me cut into me manner. Therefore, I applied e-brake. Suddenly, I felt an impact from behind that veh (B) (SKL 7414A) hit my taxi (A) rear portion. Three of us then alighted and exchanged the particulars. I have companicated and photos taken at scene to support my claims. No injury in this accident. A - SHD 4992U. B - SKL 7414A. Mr. Steven. Hp : 9616 0860.	The state of the s
Central with one female passenger on board. I was travelling on the extreme right lane. Vehicle infront of me cut into me manner. Therefore, I applied e-brake. Suddenly, I felt an impact from behind that veh (B) (SKL 7414A) hit my taxi (A) rear portion. Three of us then alighted and exchanged the particulars. I have companicated and photos taken at scene to support my claims. No injury in this accident. A - SHD 4992U. B - SKL 7414A. Mr. Steven. Hp : 9616 0860.	
I was travelling on the extreme right lane. Vehicle infront of me cut into me manner. Therefore, I applied e-brake. Suddenly, I felt an impact from behind that veh (B) (SKL 7414A) hit my taxi (A) rear portion. Three of us then alighted and exchanged the particulars. I have companicate and photos taken at scene to support my claims. No injury in this accident. A - SHD 4992U. B - SKL 7414A. Mr. Steven. Hp : 9616 0860.	towards Punggol
I was travelling on the extreme right lane. Vehicle infront of me cut into me manner. Therefore, I applied e-brake. Suddenly, I felt an impact from behind that veh (B) (SKL 7414A) hit my taxi (A) rear portion. Three of us then alighted and exchanged the particulars. I have companicate and photos taken at scene to support my claims. No injury in this accident. A - SHD 4992U. B - SKL 7414A. Mr. Steven. Hp : 9616 0860.	
manner. Therefore, I applied e-brake. Suddenly, I felt an impact from behind that veh (B) (SKL 7414A) hit my taxi (A) rear portion. Three of us then alighted and exchanged the particulars. I have companicated and photos taken at scene to support my claims. No injury in this accident. A - SHD 4992U. B - SKL 7414A. Mr. Steven. Hp: 9616 0860.	
manner. Therefore, I applied e-brake. Suddenly, I felt an impact from behind that veh (B) (SKL 7414A) hit my taxi (A) rear portion. Three of us then alighted and exchanged the particulars. I have companicated and photos taken at scene to support my claims. No injury in this accident. A - SHD 4992U. B - SKL 7414A. Mr. Steven. Hp: 9616 0860.	u long in a guddon
that veh (B) (SKL 7414A) hit my taxi (A) rear portion. Three of us then alighted and exchanged the particulars. I have companiaxi and photos taken at scene to support my claims. No injury in this accident. A - SHD 4992U. B - SKL 7414A. Mr. Steven. Hp : 9616 0860.	y latte iii a suddeti
that veh (B) (SKL 7414A) hit my taxi (A) rear portion. Three of us then alighted and exchanged the particulars. I have companiaxi and photos taken at scene to support my claims. No injury in this accident. A - SHD 4992U. B - SKL 7414A. Mr. Steven. Hp : 9616 0860.	d and came to know
Three of us then alighted and exchanged the particulars. I have companies and photos taken at scene to support my claims. No injury in this accident. A - SHD 4992U. B - SKL 7414A. Mr. Steven. Hp : 9616 0860.	
A - SHD 4992U. B - SKL 7414A. Mr. Steven. Hp : 9616 0860.	
A - SHD 4992U. B - SKL 7414A. Mr. Steven. Hp : 9616 0860.	100 00 700
No injury in this accident. A - SHD 4992U. B - SKL 7414A. Mr. Steven. Hp : 9616 0860.	y video fixed in my
No injury in this accident. A - SHD 4992U. B - SKL 7414A. Mr. Steven. Hp : 9616 0860.	
A - SHD 4992U. B - SKL 7414A. Mr. Steven. Hp : 9616 0860.	
B - SKL 7414A. Mr. Steven. Hp : 9616 0860.	
B - SKL 7414A. Mr. Steven. Hp : 9616 0860.	
C - SKR 7962C, Ms. Bao Zhen. Hp : 9876 3049.	

CO. REG. NO. 199303821R

Policyholder's Signature Date & Time

Driver's Signature
(If driver is not the noticeholder)

Ø2

Reporting Centre Personnel's Signature























COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO: SHD 4992U

MAKE

MODEL : HYUNDAI i40

DATE 15/11/2018 15:33

4Sum Sompo

Amount Unit Price Parts Description/ Labour Type Qty S 544.50 Front Bumper Cover Front Bumper Bracket (LH) × 500 \$ 24.60 Front Fender (LH) X May 2 C-1 566.30 1.135.40 SUB TOTAL 227.08 LESS 20% 908.32 DISCOUNTED TOTAL Front Tyre (LH) 😾 Nett 216.00 Labour Charge Panel Beating Spray Painting Charge Tuff Kote 1,050.00 TOTAL LABOUR 553.00 Rear Bumper Rear Bumper Reinforcement \$ 428.40 Rear Bumper Reinforcement Bracket (LH/RH) 160.60 8 80.30 22.00 Rear Bumper Clip 10 pcs 71.20 S Rear Bumper Bracket 35.60 118.40 Rear Bumper Sponge X Rear Bumper Under Cover \$ 228.00 LKK Auto Consultan the SUB TOTAL 1,581.60 316.32 1,265.28 DISCOUNTED TOTAL 135.70 Radinaledged by Price 18 15 to 18. S

16/11/11 15 After Reported 6 Nett Rear Bumper Reverse Sensor Labour Charge Panel Beating Spray Painting Charge Wiring Charge Remove/Refix Reverse Sensor 800.00 3,110.02 ESTIMATE TOTAL This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will

be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

5485.70

OMFORTDELGRO ENGINEERING

, member of COMFORTDELGRO

ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singspork 519701 Mamilite + 65 6383 6280 Facsimile + 65 6260 9755

24 Sepoko Loop Singapore 758155 7 Sungei Kadur Way Singapore 728791 501 Yahun loduntriai Park A Singapore 768732

Date/Time? Ub P6.3F122048 08:55

Page : 1

Team:

ARC Repair TP(CLSO)1

JOB CARD

Sales Order:

TOMER

(R) (P)

MILEAGE

JC NO.: 305239752

COMFORT TRANSPORTATION PTE LTD

7010045

TOMER NO. 383 SIN MING DRIVE

Singapore SINGAPORE 575717

65508755

MAKE:

MODEL

5.11.2518 10:50

E.....F

YR OF MANUD. 09. 2014

REGN NO.: SHD4992U

HYUNDAI

CHASSIS CODE RMHLB41UMEU059614

I - 40

TARGET DATE

COMPLETION DATE/TIME:

OUNT CARD NO.


JOB DESCRIPTION

Accident Date: 15.11.2018

NATURE: 3P 15.11.2018

turned to Service Reception upon collection

LABOR CODE



CKED & PASSED OUT BY:			
SERVICE ADVISOR		-	CUSTOMER'S SIGNATURE
ledgement Slip		** Exit Pass	
No.: SHD4992U	LKE	Vehicle No.: SHD4992U	
f Service Advisor	Signature/Date	Name of Service Advisor	Date

To be kept by Security Guard

ENGINEERING

VEHICLEN	10:	SHD 49924	TYPE OF CLAIN	М:	7P-5	KL 1414A
MODEL		I-40	SURVEY BY	3	LKK	Kalvin Ay
JOB NO		305239752	DATE	:	16/	11/18

SUPPLEMENTARY OF PARTS AND LABOUR COSTS

/No	DESCRIPTION	QTY	ESTIMATE	REMARKS	
1.	Headlamp Assy Lh	1	# 1,388.00	cut	
		-			
		J. J			
-					
-		_			
	1				
-	1	_			
					-
-					
-		TOT	AL: \$0	.00	

COMFORTDELGRO ENGINEERING

our.	Job Ref I	NO:	3032	39752			
ate		¥	21/	11/18		59 Loyar	DelGro Engineering Pte Ltd ng Drive Singapore 508961
IN/	ALIZATIO	ON FOR	RM			Fax: 654	6 8156
0	\$3		ı	_KK		Fax:	
Attn	100	r.	179-14-12-1	VIN ANG			
/eh	icle Reg	No.	SHD4992	U CTPL	- All	_	15.11.18
The	survey a	and estin	nates of the re	pairs of the above-ment	ioned vehicle ar	e as follows:-	
i.			shall bill to:		ОМРО		SKL7414A
2,			amount shall b				
	(a)		Parts after List				
	(b)		Charges	discount			
	(0)			art Repair Cost			Nea
		rotari	or Fait-by-P	art Nepall Oost			
	(c.)	Lumps	um Repair (if a	applicable)	SEEDIN		
			or Lumpsum re Lumpsum Re	epair cost after Less:	20%		\$2,050.00 \$2,050.00
	We s			repairs:	d Confirmed if		
4.	We s	hall trearking da	at the above a	amount as Correct and	d Confirmed if	1701/2009/1/200	
4.	We s 7 wo	hall trea	at the above a	amount as Correct and	d Confirmed if We fina	there is no rep a confirm the es alized amount	
4.	We s 7 woo Than	hall treating dans to the second seco	at the above a ays or your assistar	amount as Correct and	d Confirmed if We find	there is no rep	
4.	We s 7 woo Than Signa	hall trearking dank you fo	at the above a ays or your assistan	amount as Correct and	d Confirmed if We find	there is no reperties confirm the estalized amount anature :	timates and
4.	We s 7 woo Than	hall tre rking da k you fo ature :	at the above a ays or your assistar	amount as Correct and	d Confirmed if We fina	there is no reperties confirm the estalized amount anature :	timates and
5.	We s 7 woo Than Signa Name	hall tre rking da k you fo ature : e :	at the above a ays or your assistar LIM KWOK E 62148316 65468156	amount as Correct and	d Confirmed if We fina	there is no reperties confirm the estalized amount anature :	timates and
5.	We s 7 woo Than Signa Name Tel Fax	hall tre rking da k you fo ature : e :	at the above a ays or your assistar LIM KWOK E 62148316 65468156	amount as Correct and	d Confirmed if We fina	there is no reperties confirm the estalized amount anature :	timates and
5.	We s 7 woo Than Signa Name Tel Fax	hall tre- rking di k you fo ature: e: I Use O	at the above a ays or your assistar LIM KWOK E 62148316 65468156 nly	amount as Correct and	d Confirmed if We find Sig Na Da Document Attached	confirm the esalized amount anature: me: Confirm By	Kaluh 21/11/18
Fo:	We s 7 woo Than Signa Name Tel Fax	hall treerking dealer was the second	LIM KWOK E 62148316 65468156 nly	amount as Correct and	d Confirmed if We find Sig Na Da Document Attached Yes or No	confirm the esalized amount anature: me: Confirm By	Kaluh 21/11/18
1. 2.	We s 7 woo Than Signa Name Tel Fax r Official	hall trearking dalak you for ature:	LIM KWOK E 62148316 65468156 nly	amount as Correct and	Document Attached YES	confirm the esalized amount anature: me: Confirm By	Kaluh 21/11/18
1. 2. 3.	We s 7 woo Than Signa Name Tel Fax Cofficial Rental F Loss of Survey	hall treerking disk you for ature: But I Use O Item Rate P/D Income Fees arch Fees	LIM KWOK E 62148316 65468156 nly Paid	amount as Correct and	Document Attached YES	confirm the esalized amount anature: me: Confirm By	Kaluh 21/11/18
1. 2. 3. 4. 5.	We s 7 woo Than Signa Name Tel Fax Cofficial Rental F Loss of Survey	hall treerking disk you for ature: But I Use O Item Rate P/D Income Fees arch Fee Fees (or, if appli	LIM KWOK E 62148316 65468156 nly Paid	nce. Amount Amount	Document Attached YES	confirm the esalized amount anature: me: Confirm By	Kaluh 21/11/18

LKK Auto Consultants Pte Ltd (Co.Reg. No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

D17MTPV01018144

Engine No:

Chassis No:

Odometer:

CS/SMO18020801/K1QD3N2

D4FDEU475251

684398 km

KMHLB41UMEU059614

Date:

28/11/2018

REFERENCE

Handling

Claimant

Vehicle No:

Date of Loss:

Sompo Insurance Singapore Pte.

Insurer:

Ltd.

SHD4992U

15/11/2018

Insured Vehicle

Policy No:

SKL7414A

No:

Nature of Claim:

TP

Claim No:

CMTD1805012

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SHD4992U

Make & Model:

HYUNDAI 140, 1.7 L CRDI AT ABS AIRBAG 4DR

(A)

Reg. Date: Colour:

10/09/2014 (Man. Year: 2014)

Blue 1685 cc

Engine Capacity: Market Value/New Car

Price:

Sum Insured (S\$):

N/A Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable): Yes Engine Modification:

Yes Footbrake (Serviceable): Pre-accident Condition:

Yes

Handbrake (Serviceable): CONDITION OF TYRES

Front Tyre Size: Front Left Side:

205/60 R16 West Lake 7 mm West Lake 7 mm

Rear Tyre Size: Rear Left Side:

Rear Right Side:

205/60 R16 West Lake 7 mm West Lake 7 mm

Front Right Side: The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,635.70	1,643.25	1,992.45	54.80
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,850.00	930.00	920.00	49.73
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,485.70	2,573.25	2,912.45	53.09
Approved Total (Overridden) (S\$)		2,050.00		
(S\$)	5,485.70	2,050.00	3,435.70	62.63
+ GST 7.00/7.00% (S\$)	384.00	143.50	240.50	62.63
Nett Amount (S\$)	5,869.70	2,193.50	3,676.20	62.63

INSPECTION

Date of Assignment:

16/11/2018

Date Inspected:

16/11/2018 Inspected At:

COMFORTDELGRO ENGINEERING

PTE LTD

59 LOYANG DRIVE SINGAPORE 508969

Estimated Period of Repair:

3.0 days

KALVIN ANG WEI KUN Adjuster:

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Amount

REPAIR DETAILS

Reference

Part Source: MRM-SG

Version: 1.0 (Last Synchronised: 28 Nov 2018)

Parts:

143

HYUNDAI I40 1.7 L CRDI AT ABS AIRBAG 4DR (A) (Catalogue:Merimen Singapore 1.0)

Labour:

Repairer's

(Price-denominated Standard List)

riiii God

Print Code: (Unsubmitted, no print-code for SHD4992U)

Validity:

These estimates are valid only if they contain the print code (above) on all estimate pages, running page

Candition Panairar's

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairers	Amount
1	4	*FRONT BUMPER COVER	Repair	544.50 FL	*-FL
2	1	*FRONT BUMPER BRACKET (LH)	Serviceable	24.60 FL	*-FL
3	1	*FRONT FENDER (LH) *HEADLAMP ASSY LH	Repair Cut	566.30 FL 1,388.00 FL	*- FL *1,388.00 FL
5 6	1	*REAR BUMPER *REAR BUMPER REINFORCEMENT	Deformed Serviceable	553.00 FL 428.40 FL	*553.00 FL *- FL
7 8	2	*REAR BUMPER REINFORCEMENT BRACKET (LH/RH) *REAR BUMPER CLIP	Serviceable Necessary	160.60 FL 22.00 FL	*-FL *22.00FL
9	2	*REAR BUMPER BRACKET	Serviceable		*-FL
10	1	*REAR BUMPER SPONGE	Serviceable	118.40 FL	*-FL
11	1	*REAR BUMPER UNDER COVER	Cut	228.00 FL	*228.00 FL
12	1	*FRONT TYRE (LH)	Serviceable	216.00 FS	*-FS
13	1 anchise	*REAR BUMPER REVERSE SENSOR part. S=SpcNett. L=ListItemDisc.	Serviceable	135.70 FS	*-FS
		Su	ub Total (S\$)	4,456.70	2,191.00
- List Item Discount on L Items 20.00/25.00% (S\$)				821.00	547.75
		Tot	al Parts (S\$)	3,635.70	1,643.25

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			0000000
1	PANEL BEATING	New	900.00	300.00
2	SPRAY PAINTING CHARGE	New	750.00	600.00
3	TUFF KOTE	New	50.00	-
4	WIRING CHARGE	New	30.00	() -
5	REMOVE/REFIX REVERSE SENSOR	New	120.00	30.00
		Gross Labour Cost (S\$)	1,850.00	930.00
	Report was	s unsubmitted during this print-out.		

< END OF ESTIMATES >