

ASS. REC. BY:

REF: CS/FCI18020809/ Avd3

n2

Special Instruction:

Surveyor:

CWS

Adrian

ASSIGNMENT (Office)

From (Person):

Lurene jaw

of

FCI

Date/Time:

16/11/18 @ 2:01pm

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLQ 3649C

Insured:

SHA 0320B

at Workshop m/s:

Success United

Tel:

67461515

of

2 Kaki Bukit Ave 2 # 01-33

Policy No:

Claim No:

D18008061MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

08/11/2018

CA / REV / REP. / REV 24 HRS

(wp)

H.O.D. Endorsement:

Date/Time:

3:53pm 16/11/18

Person Contacted:

Sirina

Vehicle:

IN/OUT

Date/Time

Action/Instruction

(✓)

Estimate

SLQ 3649C - NA / INC18020280/24

DOA: 8/11/18

SHA 0320B - NA / INC18020280/24

DOA: 8/11/18

19/11/18-

Vehicle not in

21/11/18

Informed FCI pending workshop est by email

20/12/18

Adrian confirmed LS \$ 2050 (Red) 2238.08, 507m

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No. SLQ3649C Yr Regn. 2017 JulyType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda VezelC.C. 1496Colour: Blue

A/C: Insured / Std / NI / NA

Sp. Reading: 42645

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: Ru11209102Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 215/60R16R: 215/60R16BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mmR/Bal. 06 mmL/Bal. 06 mmL/Bal. 06 mm

D.O.A.

D.O.I. 20/11/18

Survey held at

Success United.Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time: _____ Action / Instruction

TP 1st Cap.21/12/18 Email preli revised to FCI

RECEIVED 21 DEC 2018

Date/Time, File Pass to?

☐

Preli. Report

11

☐

Final Report

Date/Time, File Return to?

21/12 - typist

Days Of Repair: 4Resurvey No. of Trip: 2

Survey Fee:

Transportation

) S + RS: \$

) Photos

) Others

TOTAL

Report Format: CWSLump Sum / I.B.I. (\$) 2050/-Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)
135
50
50+50
27
312



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D18008061MFSH

Our ref: CS/FCI18020809/Avd3

Date : 21/12/2018

The Motor Claims Department
MS FIRST CAPITAL INSURANCE LTD

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SLO 3649C


We thank you for your instruction on 16/11/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 20/11/2018 at the premises of M/s SUCCESS UNITED PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$4,288.08
Revised Estimate Amount	: S\$2,050.00(LUMP SUM)
"Check" Items Amount	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the rear portion



Comments/Present Status:

Damages Consistent

Yours faithfully,

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	12-11-2018	Our Ref No. D18008061MFSH
Accident Date	08-11-2018	Claim Type. Third Party
Insured Vehicle	SHA0320B	Third Party Vehicle. SLQ3649C
Survey Location	2 KAKI BUKIT AVE 2 #01-33 & #02-29KAKI BUKIT AUTOHUB	
Contact Person.	SIRINA SOON	
Contact No.	67461515/ 67471787	Fax No. 67485015
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	SUCCESS UNITED PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	LURENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
 This is a computer generated letter, no signature required.

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Friday, 21 December 2018 11:18 AM
To: 'CWS Motor Claims'
Cc: 'Lurene Jaw'; SUR
Subject: RE: SURVEY ASSESSMENT - D18008061MFSH/1, SLQ 3649C
Attachments: SLQ 3649C PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SLQ 3649C
Date of survey: 20/11/2018
Number of days : 4 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAUTO)
Sent: Wednesday, 21 November 2018 8:53 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>
Cc: 'Lurene Jaw' <LureneJaw@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18008061MFSH/1, SLQ 3649C

Dear Sir/Madam,

Please be informed that we have inspected the vehicle SLQ 3649C on 20/11/2018 .

We are pending estimate from repairer.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Friday, 16 November 2018 3:55 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Lurene Jaw' <LureneJaw@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18008061MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in the workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]

Sent: Friday, 16 November 2018 2:01 PM

To: ASSIGNMENTS@LKKAUTO.COM

Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Lurene Jaw <LureneJaw@msfirstcapital.com.sg>

Subject: PRI: SURVEY ASSESSMENT - D18008061MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

MS First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



AVG

This email has been checked for viruses by AVG antivirus software.

www.avg.com

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Wednesday, 21 November 2018 8:53 AM
To: 'CWS Motor Claims'
Cc: 'Lurene Jaw'; SUR
Subject: RE: SURVEY ASSESSMENT - D18008061MFSH/1, SLQ 3649C

Dear Sir/Madam,

Please be informed that we have inspected the vehicle SLQ 3649C on 20/11/2018 .

We are pending estimate from repairer.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Friday, 16 November 2018 3:55 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Lurene Jaw' <LureneJaw@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18008061MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in the workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Friday, 16 November 2018 2:01 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Lurene Jaw <LureneJaw@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D18008061MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 8830B

Vehicle Details

Vehicle No.: SLQ3649C
Vehicle to be Exported: Yes
Intended Deregistration Date: 11 Nov 2018
Vehicle Make: HONDA
Vehicle Model: VEZEL 1.5X CVT
Primary Colour: Blue
Manufacturing Year: 2016
Engine No.: L15B4409101
Chassis No.: RU11209102
Maximum Power Output: 96.0 kW (128 bhp)
Open Market Value: \$22,704.00
Original Registration Date: 06 Jul 2017
First Registration Date: 06 Jul 2017
Transfer Count: 0
Actual ARF Paid: \$13,786.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 05 Jul 2027
PARF Rebate Amount: \$10,339.00

Intended COE Rebate Details

COE Expiry Date: 05 Jul 2027
COE Category: A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$42,801.00
COE Rebate Amount: \$34,240.00
Total Rebate Amount: \$44,579.00

The information contained herein is correct as at 10 Nov 2018.

OK

SUCCESS UNITED PTE LTD

2 Kaki Bukit Ave 2, #01-33 / #02-29

Kaki Bukit Autohub, Singapore 417921

Tel No. : 67461515 / 67471787 Fax No. : 67485015

Website : www.successunited.com.sg

Buss. Reg. No. : GST No. 200402570G

MS First Capital Insurance Limited

36 Robinson Road

#16-01 City House

Singapore 068877

Attention : Motor Claim Department

Contact : 65073848 Fax No. : 65073849

Veron.

Estimate : TP18-120

Date : 12/11/2018

Vehicle Num. : SLQ3649C

Make/Model : Honda Vezel-2016

Chassis/Eng# : RU11209102/L15B4409101

Accident Date : 12/11/2018

Claim No. : 018008061MFSH

Reference : SHA320B

Policy No. : (05.07.2019)

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LIST ITEMS :				
1.	1	Rear Boot lid <i>Revised</i>		1,053.70
2.	1	Rear Boot Mechanism lock <i>? new</i>		138.50
3.	1	Rear Boot Weatherstrip		106.80
4.	1	Rear Boot "Vezel" Emblem <i>new</i>		68.20
5.	1	Rear Windscreen Moulding <i>new</i>		96.70
6.	1	Rear End Panel <i>new</i>		365.70
7.	1	Rear Bumper Assy <i>Schomd</i>		680.50

List Total S\$:

20.00% Discount S\$:

2,510.10

502.02

2,008.08

SPECIAL NETT ITEMS :				
1.	1	Reverse Sensor <i>new</i>		280.00
2.	1	Windscreen Sealant <i>new</i>		40.00

Special Nett Total S\$:

320.00

LABOUR :

To remove, rearrange electrical wirings, check lighting

80.00

To remove, instal rear windscreen

200.00

To remove, replace & transfer rear boot lid components.

180.00

To remove, repair and replaced damaged bodyparts, realign bodyworks & where consistent to the accident.

900.00

400

CONTINUE / ...

SUCCESS UNITED PTE LTD

2 Kaki Bukit Ave 2, #01-33 / #02-29
 Kaki Bukit Autohub, Singapore 417921
 Tel No. : 67461515 / 67471787 Fax No. : 67485015
 Website : www.successunited.com.sg
 Buss. Reg. No. : GST No. 200402570G

MS First Capital Insurance Limited
 36 Robinson Road
 #16-01 City House
 Singapore 068877
 Attention : Motor Claim Department
 Contact : 65073848 Fax No. : 65073849

Estimate : TP18-120

Date : 12/11/2018
 Vehicle Num. : SLQ3649C
 Make/Model : Honda Vezel-2016
 Chassis/Eng# : RU11209102/L15B4409101
 Accident Date : 12/11/2018
 Claim No. :
 Reference : SHA320B
 Policy No. : (05.07.2019)

S/N	Quantity	Particular	Unit Price	Amount S\$
		To putty and respray painting on affected areas.	1030	400.00
		Labour Total S\$:		1,960.00

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Ling.
 P/P 20/11/18.
 040mg
 total: 258928
 L/S: 2050.

E. & O.E.

Total S\$: 4,288.08

=====



for SUCCESS UNITED PTE LTD



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FC18020809/Avd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 24-12-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 320B	Veh. Inspected	SLQ 3649C	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18008061MFSH	Excess (\$)	0.00	
Assign From	LURENE	Assign Date	16/11/2018	
2. Vehicle Particulars & Condition				
Make & Model	HONDA VEZEL	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	RU11209102	Colour	BLUE	
Odometer	42645	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	DUNLOP	6 mm	
L/H Front Tyre	215/60 R16	DUNLOP	6 mm	
R/H Rear Tyre	215/60 R16	DUNLOP	6 mm	
L/H Rear Tyre	215/60 R16	DUNLOP	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	08/11/2018	Inspection Date	20/11/2018	
Survey held at	SUCCESS UNITED PTE LTD 2 KAKI BUKIT AVE 2 #01-33 KAKI BUKIT AUTOHUB SINGAPORE 417921			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLQ 3649C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BOOT LID	DENTED	1,053.70	1,053.70
1	REAR BOOT MECHANISM LOCK	NOT NECESSARY	138.50	-
1	REAR BOOT WEATHERSTRIP	NOT NECESSARY	106.80	-
1	REAR BOOT "VEZEL" EMBLEM	NECESSARY	68.20	68.20
1	REAR WINDSCREEN MOULDING	NECESSARY	96.70	96.70
1	REAR END PANEL	TO REPAIR SEE LABOUR	365.70	-
1	REAR BUMPER ASSY	DEFORMED	680.50	680.50
	LESS 20% DISCOUNT		-502.02	-379.82
			2,008.08	1,519.28
SPECIAL NETT ITEMS				
1	REVERSE SENSOR (SN)	NOT NECESSARY	280.00	-
1	WINDSCREEN SEALANT (SN)	NECESSARY	40.00	40.00
			320.00	40.00
LABOUR				
	TO REMOVE,REARRANGE ELECTRICAL WIRINGS,CHECK LIGHTING.		80.00	30.00
	TO REMOVE,REINSTALL REAR WINDSCREEN.		200.00	120.00
	TO REMOVE,REPLACE & TRANSFER REAR BOOT LID COMPONENTS.		180.00	80.00
	TO REMOVE,REPAIR AND REPLACED DAMAGED BODYPARTS,REALIGN BODYWORKS & WHERE CONSISTENT TO THE ACCIDENT.INCLUSIVE OF THE REPAIR OF REAR END PANEL.		900.00	400.00
	TO PUTTY AND RESPRAY PAINTING ON AFFECTED AREAS.		600.00	400.00
	-		-	-
	-		-	-
	-		-	-
			1,960.00	1,030.00
GRAND TOTAL			4,288.08	2,589.28



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,050.00
---	--	--	----------

Report Ref No. CS/FCI18020809/Avd3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.