

ASS. REC. BY:

REF:

CS/FCI18020851/KIVd3/n2

Special Instruction:

Surveyor:

Kalin

ASSIGNMENT (Office)

TWS

From (Person):

Joanne Yong

of

FCI

Date/Time: 16/11/18 4:48pm

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHC6099R

Insured:

SHD 4527 E

at Workshop m/s

Premier Automotive

Tel:

6544 6689

of

23 Chengji south Ave 2 #01-02

Policy No:

Claim No:

D18008174MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

14/11/2018

CA / REV / REP. / REV 24 HRS ^{1up}

26.11.2018

H.O.D. Endorsement:

Date/Time:

9:40am @ 19/11/18

Person Contacted:

Vincent

Vehicle IN /

OUT

Date/Time

Action/Instruction (✓) Estimate

SHC6099R - CC4/ASM18011222/K1j63 DOA: 18/6/18

SHD4527E - CC4/DAT15019059/M1pb3s2 DOA: 8/11/15

27/11/18

Email preli revised to FCI

Signature

Kalua

REF: FCI

ASSIGNMENT

SHC 6099R

22 Aug 2014

From: Date: 26/11/18

Estimated Cost:

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SHC 6099R
at Workshop m/s Premier Automotive
of 23 changi south Ave 2 #01-02

Insured:

Policy No:

Claims No:

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS (up)

Vehicle: IN / OUT

Date: Person Contacted:

Veh No:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp Reading

Eng No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 7 mm

L/Bal. 7 mm

D.O.A. 14/11/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

29/11/18 Continued PIP \$1120 / 3 Pys. (Red 1200, 52M) (No LS)

RECEIVED 29 NOV 2018

Signature
29/11/2018

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

1)

Date/Time, File Return to?

2) 29/11 - typist

Report Format : cws

Lump Sum / I.B.I: (\$) 1120/2

Days Of Repair: 3

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

Survey Fee:

Transportation

) \$ + PC. SI

) Photos

) Others

TOTAL

110

50

50

22

232



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D18008174MFSH

Our ref: CS/FCI18020851/K1vd3

DATE: 27/11/2018

The Motor Claims Department
M/s FIRST CAPITAL INSURANCE LTD

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SHC 6099R


We thank you for your instruction on 16/11/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 26/11/2018 at the premises of M/s PREMIER AUTOMOTIVE SERVICES PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$2,320.00
Revised Estimate Amount	: S\$1,120.00
"Check" Items Amount	: S\$
Book Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the
n/s rear portion



Comments/Present Status:
Damages Consistent

Yours faithfully,

Kalvin Ang
Technical Investigator
Technical Investigation & Reconstructionist (SAE-A)

MOTOR SURVEY ASSIGNMENT

Date	15-11-2018	Our Ref No. D18008174MFSH
Accident Date	14-11-2018	Claim Type. Third Party
Insured Vehicle	SHD4527E	Third Party Vehicle. SHC6099R
Survey Location	23 CHANGI SOUTH AVENUE 2 #01-02	
Contact Person.	VINCENT CHUA	
Contact No.	62148880/ 65546689	Fax No. 62141511
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	PREMIER AUTOMOTIVE SERVICES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	JOANNEY	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Tuesday, 27 November 2018 9:38 AM
To: 'CWS Motor Claims'
Cc: 'Joanne Yong Lai fong'; SUR
Subject: RE: SURVEY ASSESSMENT - D18008174MFSH/1, SHC 6099R
Attachments: SHC 6099R PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SHC 6099R
Date of survey: 26/11/2018
Number of days : 3 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Monday, 19 November 2018 9:41 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Joanne Yong Lai fong' <Joanneyong@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18008174MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in the workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Friday, 16 November 2018 4:48 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Joanne Yong Lai fong <Joanneyong@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D18008174MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



AVG

This email has been checked for viruses by AVG antivirus software.
www.avg.com

Text size + -

Enquire Transaction History**Transaction History Details**

Log Date/Time:	22 Aug 2014 / 09:05:40	Receipt No.:	AACCK001-AX239-140822-000003
Asset Type:	Vehicle	Transaction Amount:	\$62,506.00
Asset ID:	SHC6099R	Channel:	AA Counterless - CYCLE & CARRIAGE KIA PTE LTD
Transaction Type:	01.02 Register New Vehicle (AA)		
Business Transaction Reference No.:	20140822090540677380		

Vehicle No.:	SHC6099R
Vehicle Type:	H10 - Public Transport Taxi (Motor Car)
Vehicle Attachment 1:	Air-Con (Taxi)
Vehicle Attachment 2:	-
Vehicle Attachment 3:	-
Vehicle Scheme:	Taxi (Company)
First Registration Date:	22 Aug 2014
Original Registration Date:	22 Aug 2014
Vehicle Make:	KIA
Vehicle Model:	OPTIMA 1.7(A) DIESEL
Chassis No.:	KNAGM414ME5464902
Engine No.:	D4FDDH308173
Motor No.:	-
Trailer Chassis No.:	-
Propellant:	Diesel
Passenger Capacity:	4
Engine Capacity:	1685
Power Rating:	-
Unladen Weight:	1584
Maximum Laden Weight:	2050
Primary Color:	Silver
Secondary Color:	-
Manufacturing Year:	2013
Open Market Value:	\$19,778.00
Minimum PARF Benefit:	\$7,366.00
PARF Eligibility:	Y
No. of Transfer:	0
Effective Ownership Date/Time:	22 Aug 2014 09:05:40
COE No.:	2014082201001295N
COE Expiry Date:	21 Aug 2022
COE Bid Category:	-
Actual QP/PQP Paid Amount:	\$50,088.00
Lifespan Expiry Date:	21 Aug 2022
Owner ID Type:	Company

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

19-Nov-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6099 R

S/NETT

1 set	n/s door stickers	<i>—</i> <i>nc</i>	\$ 100.00
1 pc	Rear n/s fender sticker	<i>—</i> <i>nc</i>	\$ 60.00
1 pc	Rear bumper top protector	<i>—</i> <i>nc</i>	\$ 80.00 50
	Sundry		\$ <i>nc</i> 50.00 20
	To check rear n/s wheel alignment		\$ 80.00 X 22
	To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.		\$ 180.00 X 22
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the rear n/s door, rear n/s fender, rear bumper, etc		\$ 850.00 500
	To putty and spray painting on rear bumper, rear n/s fender, rear n/s door, rear n/s wheel cover		\$ 800.00 590
	To apply rustproofing on the repaired and replaced panels.		\$ 120.00 X 22
			<u>\$ 2,320.00</u>

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

**THE ABOVE ESTIMATED COST OF REPAIR DO NOT
INCLUDE ANY UNFORESEEN DAMAGES.**

Kaki, AAC
N *26/11/18* *1300h*
3 Pp.
PIP
After Repair photo

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18020851/K1vd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 30-11-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHD 4527E	Veh. Inspected	SHC 6099R
	Policy No.		Coverage (\$)	0.00
	Claim No.	D18008174MFSH	Excess (\$)	0.00
	Assign From	JOANNE YONG	Assign Date	16/11/2018
2. Vehicle Particulars & Condition				
	Make & Model	KIA OPTIMA	c.c	1685
	Engine No.	HIDDEN	Year of Reg.	2014
	Chassis No.	KNAGM414ME5464902	Colour	SILVER
	Odometer	466378	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	205/65 R16	ACHILLES	7 mm
	L/H Front Tyre	205/65 R16	ACHILLES	7 mm
	R/H Rear Tyre	205/65 R16	ACHILLES	7 mm
	L/H Rear Tyre	205/65 R16	ACHILLES	7 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	14/11/2018	Inspection Date	26/11/2018
	Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443		
5a. Remarks				
	A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 6099R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	SET N/S DOOR STICKERS (SN)	NECESSARY	100.00	100.00
1	REAR N/S FENDER STICKER (SN)	NECESSARY	60.00	60.00
1	REAR BUMPER TOP PROTECTOR (SN)	NECESSARY	80.00	50.00
1	SUNDRY (SN)	NECESSARY	50.00	20.00
			290.00	230.00
	LABOUR			
	TO CHECK REAR N/S WHEEL ALIGNMENT.	NOT NECESSARY	80.00	-
	TO DISMANTLE/REFIT THE INNER GARNISHES, INNER LININGS, INNER TRIMS, CUSHION SEAT, CARPET, ETC TO FACILITATE REPAIRS.	NOT NECESSARY	180.00	-
	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS, INCLUDING KNOCK-OUT, STRAIGHTEN, REPAIR, RESHAPE AND ADJUST OF THE REAR N/S DOOR, REAR N/S FENDER, REAR BUMPER, ETC.		850.00	300.00
	TO PUTTY AND SPRAY PAINTING ON REAR BUMPER, REAR N/S FENDER, REAR N/S DOOR, REAR N/S WHEEL COVER.		800.00	590.00
	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS.	NOT NECESSARY	120.00	-
			2,030.00	890.00
	GRAND TOTAL		2,320.00	1,120.00
	RECOMMENDED COST OF REPAIRS			1,120.00

Report Ref No. CS/FCI18020851/K1vd3n2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.