

10/10/2018

ASS. REC. BY:

REF CS3/MSG18015128/T1sb<sup>27</sup>

Ref. Information

SURV. VMT  
- MINN

Tau fitch

ASSIGNMENT (Office)

From (Person):

Monica Chung

of

MSG

Date/Time 19/11/2018

Estimated Cost:

Bill to:

OD / ☒ WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.

SFS 633C

Insured:

FBB 84185

at Workshop n/s

Exotic Car Spray

Tel:

9109 1660

of

81K1002, 2nd merch Lane 3 #01-85

Policy No:

MSD/VM.T/17-987717-WT

Claim No:

MSC/v/18-001104

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A

09/08/2018

CA / REV / REP. / REV 24 HRS

Cup)

Date/Time:

12:44pm @ 20/8/18

Person Contacted:

Sam

H.O.D. Endorsement:

Vehicle

☒ IN ☐ OUT

Date/Time	Action/Instruction (X) Estimate	Do Not Finalize
	SFS 633C-X	
	FBB 84185-X	
	Dismantle: 21/8/2018	
	After repair: 29/8/2018	
06/12/18	Submit HS & 2,700/- @ 6 days ( & 3,750/- Red - 58% )	

*[Signature]*  
6/12/2018  
*[Signature]*

RECEIVED 07 DEC 2018



## Catherine Chong (LKK Auto)

---

**From:** Monica Chung <Monica\_Chung@sg.msig-asia.com>  
**Sent:** Monday, 19 November, 2018 1:15 PM  
**To:** assignments@lkkauto.com  
**Subject:** TP SFS633C DOA-09/08/18      Our Ref: MSC/V/18-001104

Dear Catherine,

We have sent back case for paper adjustment in Merimen.

Thanks.

Regards,

Monica Chung  
Executive, Claims Services (Motor)  
D: +65 6594 2552 | F: +65 6225 7402 | [monica\\_chung@sg.msig-asia.com](mailto:monica_chung@sg.msig-asia.com)



**MSIG**



Insurer Claims  
Team of the Year  
2016

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220

9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | [msig.com.sg](http://msig.com.sg)



A Member of **MS&AD** INSURANCE GROUP

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

## CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	10 Aug 2018		20 Aug 2018 10:38 <a href="#">Edit Adj Rpt</a>	<b>\$50.00</b> <a href="#">Edit Estimates</a>	<b>\$50.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

<a href="#">Main</a>	<a href="#">Reference</a>	<a href="#">Claim Details</a>	<a href="#">Documents</a>	<a href="#">Show All</a>
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

## CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	NUR IMAN BIN RAHMAT, ID: S9831055Z		
Main Claimant:	HOLISTIC HEALTH, Co. Reg. No.: 53153693M		
Vehicle Reg. No.:	SFS633C	Date of Loss:	09/08/2018 23:00 - :59 [134 Months and 3 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / MSC/V/18-001104	Policy/Cover Note No.:	MSD/VMT/17-987717-WTT (Third Party Only) Coverage: 24/11/2017 - 23/11/2018
Vehicle Reg. No. (Insured):	F8884185	Policy No. (Claimant):	
Repairer:	Weng Fatt Motor Engineering (HQ) Bldg 1004 Bukit Merah Lane 3, #01-15, 159720 Bukit Merah - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 21/11/2018]		
Driver/Custodian (Insured):	NUR IMAN BIN RAHMAT (19 / Male), NRIC: S9831055Z		
Adj Asg. Remarks:	SJE DISAGREE Please appoint LKK and contact Mr Vincent Ng @ 9618 7858. Liability 100%		

## ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- MSIG\_5G (19/11/2018): Report Send Back Alerts - SFS633C (TP)

## ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.

15 NOV 2018

**K. K. CHENG & CO**

Advocates & Solicitors  
101 Upper Cross Street #05-21  
People's Park Centre  
Singapore 058357  
Tel: 6227 1272 Fax: 6227 5563

mc

18-00/107

Our Ref: CKK/ck/ACC/10333/18  
Your Ref: FBB 8418S  
(Please quote our reference number when replying)

13 NOV 2018

PDX Intercompany Exchange Pte Ltd



FROM K K CHENG & CO.  
PDX Box No. 8921

**MSIG INSURANCE (SINGAPORE) PTE LTD**  
Singapore

BY PDX: 8173

Attention: Motor Claims Department

Dear Sirs

**HOSLISTIC HEALTH**  
**BLK 168 BISHAN STREET 13 #14-05 SE (570168)**

We are instructed by the above named to claim damages against your insured driver in connection with a road traffic accident on 09.08.2018 at about 11.15pm along Pasir Ris Drive 1 involving our client's vehicle registration number SFS 633C and vehicle FBB 8418S owned by your insured at the material time.

We are instructed that the accident was caused by your insured driver's negligent driving and/or management of your insured's vehicle. As a result of the accident, our client's vehicle was damaged and our client has been put to loss and expense, particulars of which are as follows:-

(1)	costs of repairs	\$6,450.00
(2)	loss of use for 8days @ \$150 per day	\$1,200.00
(3)	additional loss of use for 2days @ \$150 per day (pre-repair inspection)	\$ 300.00
(4)	survey fees	\$ 710.00
(5)	GIA report	\$ 29.00
(6)	LTA search	\$ 8.50
(7)	coloured photographs	\$ 16.00
(8)	photocopying, postages, transport and other incidentals	\$ 50.00
(9)	costs	<u>\$ 900.00</u>
		<u><u>\$9,663.50</u></u>

YQ - upland 5/10  
mc  
15/11/18

**K. K. CHENG & CO**  
**PAGE 2**

A copy each of the following supporting documents is enclosed:

- (1) Plaintiff's GIA report
- (2) GIA report of FBB 8418S
- (3) Repair Bill
- (4) Surveyor's report attached with 63 coloured photographs of our client's damaged vehicle
- (5) Vehicle & Owner Information and Vehicle Owner Particulars
- (6) LTA search

Please note that you or your insured should send to us an acknowledgement of receipt of this letter within 14 days of your receipt of this letter, failing which our client will have no alternative but to commence proceedings against your insured without further notice to you or your insured.

Please also note that if your insured has a counterclaim against our client arising out of the accident, you are also required to send to us a letter giving full particulars of the counterclaim together with all relevant supporting documents within 8 weeks of your receipt of this letter.

Yours faithfully



**CHENG KIM KUAN**  
Encs

c.c. NUR IMAN BIN RAHMAT  
c.c. client  
(Ref: SFS 633C)

## **K. K. CHENG & CO**

Advocates & Solicitors  
101 Upper Cross Street #05-21  
People's Park Centre  
Singapore 058357  
Tel: 6227 1272 Fax: 6227 5563

Our Ref: CKK/ck/ACC/10333/18  
Your Ref: FBB 8418S  
(Please quote our reference number when replying)

13 NOV 2018

BY CERTIFICATE OF POSTING

**NUR IMAN BIN RAHMAT**  
Blk 701 Yishun Avenue 5  
#03-312  
Singapore 760701

Dear Sirs

**HOSLISTIC HEALTH**  
**BLK 168 BISHAN STREET 13 #14-05 SE (570168)**

We are instructed by the above named to claim damages against you in connection with a road traffic accident on 09.08.2018 at about 11.15pm along Pasir Ris Drive 1 involving our client's vehicle registration number SFS 633C and vehicle FBB 8418S owned and driven by you at the material time.

We are instructed that the accident was caused by your negligent driving and/or management of your vehicle. As a result of the accident, our client's vehicle was damaged and our client has been put to loss and expense, particulars of which are as follows:-

(1)	costs of repairs	\$6,450.00
(2)	loss of use for 8days @ \$150 per day	\$1,200.00
(3)	additional loss of use for 2days @ \$150 per day (pre-repair inspection)	\$ 300.00
(4)	survey fees	\$ 710.00
(5)	GIA report	\$ 29.00
(6)	LTA search	\$ 8.50
(7)	coloured photographs	\$ 16.00
(8)	photocopying, postages, transport and other incidentals	\$ 50.00
(9)	costs	<u>\$ 900.00</u>
		<u><b>\$9,663.50</b></u>

A copy each of the following supporting documents is enclosed:

- (1) Plaintiff's GIA report
- (2) GIA report of FBB 8418S
- (3) Repair Bill
- (4) Surveyor's report attached with 63 coloured photographs of our client's damaged vehicle
- (5) Vehicle & Owner Information and Vehicle Owner Particulars
- (6) LTA search

**Please note that if you are insured and you wish to claim under your insurance policy, you should immediately pass this letter and all the enclosed documents to your insurer.**

Please note that you or your insurer should send to us an acknowledgement of receipt of this letter within 14 days of your receipt of this letter, failing which our client will have no alternative but to commence proceedings against you without further notice to you or your insurer.

Please also note that if you have a counterclaim against our client arising out of the accident, you are also required to send to us a letter giving full particulars of the counterclaim together with all relevant supporting documents within 8 weeks of your receipt of this letter.

Yours faithfully



**CHENG KIM KUAN**  
Encs

c.c. MSIG INSURANCE (SINGAPORE) PTE LTD  
c.c. client  
(Ref: SFS 633C)



## Enquire Vehicle & Owner Information ( Vehicle No. SFS633C As At 09 Aug 2018 / 00:00:00 )

### Law Firm Search Details

Search Reason: Insurance claim in relation to traffic accident  
Law Firm Case No.: 10333

### Current Owner Details

Owner ID Type: Business  
Owner ID: 53153693M  
Owner Name: HOLISTIC HEALTH  
Registered Address Type: HDB / HUDC  
Registered Block/House No.: 168  
Registered Street Name: BISHAN STREET 13  
Registered Unit No.: # 14 - 05  
Registered Building Name: -  
Registered Postal Code: 570168

### Current Vehicle Details

Vehicle No.: SFS633C  
Make Description/Model: TOYOTA / COROLLA AXIO 1.5 A  
Insurance Company Name: NTUC INCOME INS CO-OP LTD

> Back to OneMotoring

Bal: 3yrs 10mths.

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type:

Business

Owner ID:

3693M

### Vehicle Details

Vehicle No.:

SF5633C

Vehicle to be Exported:

Yes

Intended De-registration Date:

21 Aug 2018

Vehicle Make:

TOYOTA

Vehicle Model:

COROLLA AXIO 1.5 A

Primary Colour:

Blue

Manufacturing Year:

2007

Engine No.:

1N2C605734

Chassis No.:

NZE1416034514

Maximum Power Output:

81.0 kW (108 bhp)

Open Market Value:

\$11,951.00

Original Registration Date:

06 Jun 2007

First Registration Date:

06 Jun 2007

Transfer Count:

2

Actual ARF Paid:

\$13,147.00

### Intended PARF Rebate Details

PARF Eligibility:

Forfeited

PARF Eligibility Expiry Date:

-

PARF Rebate Amount:

\$0.00

### Intended COE Rebate Details

COE Expiry Date:

05 Jun 2022 ✓

COE Category:

A - Car (1600cc & below)

COE Period(Years):

5

PQP Paid:

\$25,313.00

COE Rebate Amount:

\$19,191.00

Total Rebate Amount:

\$19,191.00

### Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 21 Aug 2018

OK

M.V. \$24,000

6,377.50



toyota corolla axio

Price Range ▾

Depreciation ▾

&gt; 10 year(s) ▾

Vehicle Type ▾



Advanced Search

Home » Used Cars » Car Guru.Com Pte Ltd » Toyota Corolla Axio 1.5A X (COE till 03/2022)

## Resources

Car Buying

Car Selling

Car Ownership

Car Aftermarket

On The Move

Lifestyle

## Car Tyres

WES  
AUST  
EXPERIENCE\*Selected from 501  
apply. Visit us now.

## Toyota Corolla Axio 1.5A X (COE till 03/2022)

Overview Financial Accessories Similar Research Photos Map

Add to Shortlist

Add to Compare

Add a Note

Report Error

More Actions

Share

## Car Details

<b>Price</b>	<b>\$23,800</b>	
<b>Depreciation</b>	\$7,270 /yr	?
<b>Reg Date</b>	16-Mar-2007 (3yrs 3mths 9days COE left)	
<b>Manufactured</b>	2007	?
<b>Mileage</b>	-	
<b>Transmission</b>	Auto	
<b>Engine Cap</b>	1,496 cc	
<b>Road Tax</b>	\$750 /yr	?
<b>Power</b>	81.0 kW (108 bhp) View specs of the Toyota Corolla Axio (2007-2012)	
<b>Curb Weight</b>	1,130 kg	?
<b>Features</b>	Powerful DOHC VVT-i Engine, Smooth CVT Auto Transmission, Dual Airbags, ABS, Super Low Fuel Consumption.	
<b>Accessories</b>	Sports Rims, Black Leather Upholstery, Solar Film, Factory Fitted Audio System, Reverse Camera, Retractable Side Mirrors, Rear Sensors.	
<b>Description</b>	Smooth Engine, Easy To Maintained Unit, Immaculate Condition, Depreciation Is Even Cheaper, Do Not Miss, Bank And In House Loan Available! Trade In Welcome. Call For Appointment For A Test Drive Now Before The Car Is Gone.	
<b>COE</b>	\$24,715	?
<b>OMV</b>	\$13,143	?
<b>ARF</b>	\$14,458	?
<b>Dereg Value</b>	\$16,183 as of today (change)	?
<b>No. of Owners</b>	2	?
<b>Type of Veh</b>	Mid-Sized Sedan	
<b>Category</b>	COE Car	
<b>Availability</b>	Available	

Add to Shortlist

Add to Compare

Add a Note

Posted on: 24-Nov-2018 | Last Updated on: 02-Dec-2018

Tags: Toyota Corolla, toyota corolla, 2007 Toyota Corolla, 2007 toyota corolla, Toyota, Corolla, corolla, Used Toyota



## Seller Information

<b>Company</b>	Car Guru.Com Pte Ltd • dealer's pricelist • 59 vehs sold   35 vehs available	
<b>Address</b>	210 Turf Club Road Lot A7/A8/A9 Search cars nearby this location	
<b>Location</b>	Car Mall @ The Grandstand	
<b>Office No</b>	67639595	
<b>Contact Person(s)</b>	Lawrence Jimmy	92228747 90079944

## Useful Services



Afraid of lemons? Request to have this car evaluated professionally.

Vehicle Evaluation



Find out the market value for your car. Get a free Car Valuation.

Free Valuation

## Upfront Payment

» more Financial info

<b>Transfer Fee</b>	\$25	?
<b>Down Payment</b>	\$7,140 (change)	Maximum 70% Loan ?
<b>t</b>	\$479	?

Compare

**Enquire Vehicle & Owner Information ( Vehicle No. FBB8418S As At 09 Aug 2018 / 00:00:00 )**

Search Reason: Insurance claim in relation to traffic accident  
Law Firm Case No.: 5F5633C/XOTIC

Owner ID Type: Singapore NRIC  
Owner ID: S9831055Z  
Owner Name: NUR IMAN BIN RAHMAT  
Registered Address Type: HDB / HUDC  
Registered Block/House No.: 701  
Registered Street Name: YISHUN AVENUE 5  
Registered Unit No.: # 03 - 312  
Registered Building Name: -  
Registered Postal Code: 760701

Vehicle No.: FBB8418S  
Make Description/Model: YAMAHA / YBR125  
Insurance Company Name: MSIG INSURANCE (SINGAPORE) PTE LTD

**Enquire Vehicle & Owner Information ( Vehicle No. FBB8418S As At 09 Aug 2018 / 00:00:00 )**

Search Reason: Insurance claim in relation to traffic accident  
Law Firm Case No.: SFS633C/XOTIC

Owner ID Type: Singapore NRIC  
Owner ID: S9831055Z  
Owner Name: NUR IMAN BIN RAHMAT  
Registered Address Type: HDB / HUDC  
Registered Block/House No.: 701  
Registered Street Name: YISHUN AVENUE 5  
Registered Unit No.: # 03 - 312  
Registered Building Name: -  
Registered Postal Code: 760701

Vehicle No.: FBB8418S  
Make Description/Model: YAMAHA / YBR125  
Insurance Company Name: MSIG INSURANCE (SINGAPORE) PTE LTD

**SINGAPORE  
POLICE FORCE****PAYMENT****TAX INVOICE**

Invoice No: SPF2018082801000322  
Date/Time: 28/08/2018 17:12:01

Application Paid Via: Visa  
GST Reference No: MG-8400000-5

Transaction Ref No: TP000113767

Service Type	Service Fee	eService Reference No	Unit Price (S\$)	GST (S\$)	Qty	Amount (S\$)
1 Police Document	Search Fee	0050000001919034	14.00	0.00	1	14.00
Total (S\$)						14.00

This is a computer-generated invoice. No signature is required.

Please print a copy of the invoice for your reference.

A FORCE FOR THE NATION



**SINGAPORE  
POLICE FORCE**

## PAYMENT

**TAX INVOICE**

Invoice No: SPF2018083101000240

Date/Time: 31/08/2018 14:07:45

Application Paid Via: Visa

GST Reference No: MG-8400000-5

Transaction Ref No: TP000113767

Service Type	Service Fee	eService Reference No	Unit Price (\$\$)	GST (\$\$)	Qty	Amount (\$\$)
1 Police Document	Document Fee	0050000001919664	16.00	0.00	1	16.00
Total (\$\$)						16.00

This is a computer-generated invoice. No signature is required.

Please print a copy of the invoice for your reference.

A FORCE FOR THE NATION



# SINGAPORE POLICE FORCE

Police Station Of Origin:  
Pasir Ris N.P.C  
1 Pasir Ris Drive 4 #01-01 SINGAPORE  
519457  
Tel No: 1800-5852999

Certified True Copy  
pursuant to Sec. 78 of the  
Evidence Act, Cap 97.



T/20180810/2006

1 of 3

Report No. T/20180810/2006

Suriati Bte Buang (MX)  
Traffic Police  
Date : 06 SEP 2018

## REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 10/08/2018 00:59		Vide Report No.:		Station Diary No.: 14	
<b>Informant's Particulars</b>					
Name of Informant: NUR IMAN BIN RAHMAT			Address: APT BLK 701 YISHUN AVENUE 5 #03-312 SINGAPORE 760701		
ID Type / ID No.: NRIC NO / S9831055Z			Contact No.: Home/Office: Mobile: 96602541		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 19	Date of Birth: 16/09/1998	Type of Informant: Rider		
Race: Malay			Language:		Institution / School Name:
Occupation: National Service Full Time			Driving Licence Information: Class: 2B Date of Expiry:		

## General Information of the Accident

Type of Accident:	Non-Injury	Drink Drive: No	Date/Time of Accident: 09/08/2018 23:15	Type of Location: X-Junction
Location: Junction of Road 1 and Road 2 PASIR RIS STREET 12 PASIR RIS DRIVE 4 X-cross junction at Pasir Ris St 12 towards Pasir Ris Dr 4				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: Two Way		Traffic Control: Traffic Light - Working		Traffic Volume: Light
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

## Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No. of Passenger
FBB8418S	Motorcycle	YAMAHA	YBR125	Red	Seriously Damaged	0
SFS633C	Car				Slightly Damaged	1

## Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
FBB8418S	MSIG INSURANCE (SINGAPORE) PTE. LTD.	MSDTMT17987717	24/11/2017	23/11/2018





**SINGAPORE  
POLICE FORCE**



T/20180810/2006

2 of 3

Report No. T/20180810/2006

Police Station Of Origin:  
Pasir Ris N.P.C  
1 Pasir Ris Drive 4 #01-01 SINGAPORE  
519457  
Tel No: 1800-5852999

**CONTINUATION OF REPORT**

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Rider			
Name	NUR IMAN BIN RAHMAT	ID No.	S9831055Z
Related Vehicle	FBB8418S (Motorcycle)	Contact No.	96602541
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 2B Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	POH ZHONGHAO MARVIN	ID No.	S8131236B
Related Vehicle	SFS633C (Car)	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

**Brief Details.**

On the 09/08/2018 at about 2315hrs, I was the rider of motorcycle bearing registration number, FBB8418S.

While I was riding on the 2nd lane approaching the X-junction of Pasir Ris St 12 x Pasir Ris Dr 4, I noticed a car (SFS633C) which was about to make a right turn from Pasir Ris Dr 4 into Pasir Ris Dr 1. I then sped up and beat red light at the said junction. As the car was about to complete the right turn, the driver suddenly slowed down. Hence, I was not able to avoid the vehicle and collided onto its rear left of the boot. The impact caused me to fall off the bike.

The driver then came out and rendered assistance. I sustained some pain on my right feet, abrasion on the left hand and lower left back but did not activate ambulance as I felt that it was not necessary.

Certified True Copy  
pursuant to Sec. 78 of the  
Evidence Act, Cap 97.

.....  
Suriati Bte Buang (MX)  
Traffic Police  
Date : 06 SEP 2018



**SINGAPORE  
POLICE FORCE**



T/20180810/2006

3 of 3

Police Station Of Origin:  
Pasir Ris N.P.C  
1 Pasir Ris Drive 4 #01-01 SINGAPORE  
519457  
Tel No: 1800-5852999

Report No. T/20180810/2006

**CONTINUATION OF REPORT**

**Sketch Plan**

Informant is not able to provide sketch plan

Certified True Copy  
pursuant to Sec. 78 of the  
Evidence Act, Cap 97.

.....  
Suriati Bte Buang (MX)  
Traffic Police  
Date : 06 SEP 2018

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:  
G /  
Sgt 2 MUHAMMAD IQBAL BIN JUNAIDI

Signature Of Interpreter:  
Not applicable

Officer In Charge Of Case:  
TP / GIA /  
Staff Sgt WONG SIEU LUI  
Contact No.: 65476151

Authentication Stamp  
NP168

Signature Of Informant:

Date/Time:  
10/08/2018 00:59

Classification Of Case:



**SINGAPORE  
POLICE FORCE**

Traffic Police  
10 Ubi Ave 3  
Singapore 408865  
Tel: 65476243/6244  
Fax: 65474749

Date: 6/9/2018

Your Ref: ACC/10333/18

Our Ref: TP000113767/SU  
T/20180809/2118

M/s KK CHENG AND CO  
101 UPPER CROSS STREET  
# 05-21  
PEOPLE'S PARK CENTRE  
SINGAPORE 058357

RECEIVED  
1 SEP 2018

BY: .....

Dear Sir / Madam

**ACCIDENT INVOLVING VEHICLES NO. SFS633C & FBB8418S ON 9/8/2018**

I refer to your e-application on 28/8/2018. I wish to draw to your attention to the item(s) marked "X" hereunder:-

- ☒ Please be informed that Traffic Police will not be investigating into the accident as it is a non-injury case which did not fall within the various categories of exceptions. You may wish to know that this is pursuant to the Non-Injury Accident Reporting Scheme which was implemented on 1 May 1999.
- ☐ This case is still under investigation. The investigation officer is \_\_\_\_\_ Tel: \_\_\_\_\_
- ☐ No action is being taken against anyone in this case. This does not preclude further prosecution should new evidence emerge later. Our findings do not affect insurance and civil claims.
- ☐ Action is being taken against the driver of \_\_\_\_\_ for careless driving.
- ☐ The rider of \_\_\_\_\_ has been issued a warning for careless riding.
- ☐ The driver of \_\_\_\_\_ has accepted the offer of composition on \_\_\_\_\_ for inconsiderate driving.
- ☒ A copy of report No. T/20180810/2006 is attached.
- ☐ There is no report lodged by the driver of \_\_\_\_\_
- ☐ Please be informed that Traffic Police would not be investigating into the accident as it occurred outside Singapore, which was not under our jurisdiction.

Yours faithfully

 **SURIATI BTE BUANG**

for HEAD INVESTIGATION  
TRAFFIC POLICE  
\*delete where inapplicable

# **X-TIC CAR PAINTING SPECIALIST PTE LTD**

Block 1001 Bukit Merah Lane 3, # 01-55, Singapore 159718.

29 October 2018

HOLISTIC HEALTH

C/O Block 1001 Bukit Merah Lane 3

#01-55 / #01 - 85 Singapore 159718

FINAL REPAIR BILL FOR VEHICLE NO. SFS 633 C

Lump Sum Repair \$6,450.00nett



# PRECISION APPRAISAL SERVICES



Insurance Loss Assessors/ Adjusters Cargo Surveyors & Licensed Appraisers  
227 Simei St 4 #06-42 Singapore 520227 Fax: 6444 4886 Company Registration No. 53139926E

**To:**

HOLISTIC HEALTH  
C/O Block 1001 Bukit Merah Lane 3  
#01-55 / #01 - 85 Singapore 159718

**Invoice No.: 181019****DATE : 29 October 2018**

<u>DESCRIPTION</u>		AMOUNT
Vehicle Registration No. : SFS 633 C		\$710.00
Type of Claims : Third Party Claims		
Our Reference No. : PAS/HSHW/181019/TP		
Your Reference No. : -		
Inspection Report Fees : ( including transportation charges & photographs )		
Reinspection Report Fees : -		
Transportation Charges : -		
Additional Photographs : -		
Others ( Specify ) : -		
DOLLARS	SEVEN HUNDRED AND TEN ONLY	TOTAL: \$710.00

**PRECISION APPRAISAL SERVICES**

# PRECISION APPRAISAL SERVICES

Insurance Loss Assessors/ Adjusters Cargo Surveyors & Licensed Appraisers

127 Simei St 4 #06-42 Singapore 520227 Fax: 64444886 Company Registration No. 53139926E



## AUTOMOBILE INSPECTION REPORT

To:

**HOLISTIC HEALTH**

**C/O Block 1001 Bukit Merah Lane 3**

**#01-55 / #01 - 85 Singapore 159718**

### INSURANCE DETAILS

Insured : -  
Policy No. / Claim No. : -  
Sum Insured : -  
Excess Clause : -  
Windscreen Coverage : -  
Type of Claims : Third Party Claims  
Third Party Insurer : -  
Third Party Policy No. : -

### REFERENCE

Assigned By : As above  
Accident Date : 09 August 2018  
Assignment Date : 16 August 2018  
Inspection Date : 16 August 2018  
Our Reference No. : PAS/HSHW/181019/TP

Inspection Report Date : 29 October 2018

Workshop Name :

EXOTIC CAR PAINTING SPECIALIST PTE LTD

Inspection Address :

Block 1001 Bukit Merah Lane 3

#01-55 / #01 - 85 Singapore 159718

### PARTICULARS OF VEHICLE

Registration No. : SF5 633 C  
Make/Model : TOYOTA COROLLA AXIO 1.5 A  
Yr of Manuf/Regn : 2007  
Carrying Capacity : 4Seater  
Chassis No. : NZE1416034514  
Engine No. : 1NZC605734  
Colour : Metallic Blue  
Class : Passenger ( Private - Hire )

Mileage : 169203 Km/h  
Radio/Casette : Fitted  
CD Disc Player : Fitted  
Air Conditioner : Fitted  
Clock : Fitted  
Seat Belt : Fitted  
Wing Mirror Other : Fitted  
Accessories : Fitted

### PRE-ACCIDENT CONDITION (Static Check Only)

Body Work : Good  
Paint Work : Good  
Handbrake : Serviceable  
Footbrake : Serviceable  
Steering : Serviceable  
Any Apparent Eng : None  
Modifications

### VEHICLE VALUE

Market Value : -  
Wreck Value (Part) : -

### TYRE SIZE & CONDITION

Front N/s Size : 205/45R17 80 %  
Make : FALKEN  
Rear N/s size : 205/45R17 80 %  
Make : FALKEN  
Spare Size : 205/45R17 80 %  
Make : FALKEN

Front O/s Size : 205/45R17 80 %  
Make : FALKEN  
Rear O/s Size : 205/45R17 80 %  
Make : FALKEN  
Spare Size :  
Make :  
Jack & Tools : Intact/Missing

Type of Wheel Rims: Alloy

Note: The above percentage % represent the estimated remaining tyre threads.

# PRECISION APPRAISAL SERVICES

Insurance Loss Assessors / Adjusters Cargo Surveyors & Licensed Appraisers

VEHICLE REGISTRATION NO. : SFS 633 C


APPENDIX A



## POINT OF IMPACT

Direction of impact/damage marked (→) (X)

The vehicle sustained impact on its N/s Rear Portion. (see Diagram D)



## GENERAL DESCRIPTION OF DAMAGES

Parts damaged were :

The rear bumper, rear n/s fender and taillamp panel, rear n/s wheel rim and wheel arch, fuel tank cover were dented.

## ADJUSTMENTS & RECOMMENDATIONS

A static inspection was carried out on 16/08/2018 & our report is here with enclosed for your perusal. The Repairs Estimate submitted by M/s EXOTIC CAR PAINTING SPECIALIST PTE LTD as per attached Appraisement Schedule have been revised and scrutinised thoroughly by us & in our opinion, we consider it to be fair and reasonable. The repairer has agreed to effect repairs to the owners satisfaction & to roadworthy condition on an agreed Lump Sum Repair Basis of \$ 6,450.00 after deducting the Policy Excess Clause of \$ NA. As instructed, we have not authorised any of the repairs on your behalf.

	Repairer's		Our	
	Estimate	Amount	Revised	Amount
Spares Parts	6118	35	3996	96
Towing Charges	-		-	
PB Labour Charges	2000	00	1400	00
Others Misc Charges	1830	00	1255	00
Paintwork	1800	00	1400	00
Total	\$ 11748	35	\$ 8051	96

Under normal circumstances, the duration of repairs should not exceed Seven ( 07 ) days excluding Pre - Repair Inspection ( PRI ) / Pre - Repair Survey ( PRS ) & Public Holidays waiting time frame.

Attached photographs taken during inspection Sixty - Three ( 63 ) Photographs.

## SPECIAL REMARKS

1. The inspection was conducted on a 'without prejudice' basis
2. On 21/08/2018, we examined the extent of damages
3. On 28/08/2018, we examined the repaired vehicle.

Yours Faithfully,



T F NG PHILIP FOO  
ACII CAE, AMIMI  
AIAME, AMSAE-A  
Licensed Appraiser/Adjuster

Inspection Report Date: 29 October 2018



VEHICLE REGN NO : SFS 633 C  
 OUR REFERENCE : PAS/HSBW/181019/TP  
 INSPECTION REPORT DATE : 29-Oct-18

# APPRAISEMENT SCHEDULE

CONTINUATION SHEET NO : 1

S/No	Qty	Parts / Labour Descriptions	Remarks / Condition	Repairer's Estimate Amount	Recommendation / Revised Amount
		<u>PARTS SUPPLY - LIST ITEMS</u>		\$ cts	\$ cts
1	1pc	Fuel Tank Cover	Bent/Warped	148.00	148.00
2	1pc	Fuel tank inner garnish	Warped	88.00	88.00
3	1pc	Rear N/s fender	Badly dented	972.40	Repair
4	1pc	Rear bumper	Badly dented	823.60	823.60
5	1pc	Rear bumper side retainer N/s	Bent	131.75	131.75
6	1pc	Rear bumper clips	Necessary	60.00	60.00
7	1pc	Rear N/s fender lower shield	Bent	62.90	62.90
8	1set	Rear N/s fender lower shield clips	Necessary	18.00	18.00
9	1pc	Rear bumper bracket n/s	Bent	141.10	141.10
10	1pc	N/s Taillamp	Cracked	398.00	398.00
11	1pc	N/s Taillamp lower bracket	Bent	53.50	53.50
12	1pc	N/s Taillamp pad	Necessary	20.00	20.00
13	3pcs	N/s Taillamp clips @\$3.3	Necessary	9.90	9.90
14	1pc	Rear suspension wheel hub & bearing	Bent/Warped	294.90	294.90
15	1pc	Rear suspension axle beam	Bent/Warped	1835.00	1835.00
16	1pc	Rear suspension axle beam bushing n/s	Bent	123.25	123.25
17	1pc	Rear suspension axle beam mount bolt n/s	Bent	15.85	15.85
18	1pc	Rear n/s shock absorber	Bent	140.20	140.20
19	1pc	Rear n/s shock absorber coil spring	Bent	122.15	122.15
20	1pc	Rear n/s shock absorber upper support	Bent	20.75	20.75
21	1pc	Rear n/s shock absorber upper bracket	Bent	51.35	51.35
22	1pc	Rear n/s shock absorber bumper	Bent	32.75	32.75
23	1pc	Rear n/s shock absorber top nut	Bent	5.00	5.00
				5568.35	4595.95
		Less: 25% discount		-	1148.99
				5568.35	3446.96
		<u>SPECIAL NETT ITEMS</u>			
1	1pc	Rear N/s wheel rim	Dented/Warped	550.00	550.00
		Total Spare Parts		6118.35	3996.96
		<u>LABOUR &amp; MISC. CHARGES</u>			
1		Remove the necessary affected parts, straighten rear n/s fender and wheel arch, n/s taillamp panel, bootlid and replace parts		2000.00	1400.00
2		Reset wheel alignment ( Twice )		200.00	150.00
3		Putty and Spraypaint ( include rear bumper )		1800.00	1400.00
4		Check electrical		100.00	80.00
5		Tuff Kote		150.00	120.00
6		Remove and refit rear undercarriage parts, both rear shock absorber & stoppers, brake assy to facilitate repair		1200.00	800.00
7		Rewire rear portion		50.00	30.00
8		Remove and refit rear bumper sensors		100.00	60.00
9		Replace rear n/s wheel rim and balancing		30.00	15.00
		Note: Recommended lump sum repair at \$6,450.00 nett.			
		SUB / GRAND TOTAL		11748.35	8051.96

PRECISION APPRAISAL SERVICES

60 days

*[Signature]*



## ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	10 Aug 2018		20 Aug 2018 10:38 <a href="#">Edit Adj Rpt</a>	<b>S\$2,700.00</b> <a href="#">Edit Estimates</a>	<b>S\$2,700.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

**CLAIM SUBFOLDER DETAILS** [Created by insurer]

Insured:	NUR IMAN BIN RAHMAT, ID: S9831055Z		
Main Claimant:	HOLISTIC HEALTH, Co. Reg. No.: S3153693M		
Vehicle Reg. No.:	SFS633C	Date of Loss:	09/08/2018 23:00 - :59 [134 Months and 3 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / MSC/V/18-001104	Policy/Cover Note No.:	MSD/VMT/17-967717-WTT (Third Party Only) Coverage: 24/11/2017 - 23/11/2018
Vehicle Reg. No. (Insured):	F8884185	Policy No. (Claimant):	
		Excess:	
Repairer:	Weng Fatt Motor Engineering (HQ) Blk 1004 Bukit Merah Lane 3, #01-15, 159720 Bukit Merah - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 21/11/2018]		
Driver/Custodian (Insured):	NUR IMAN BIN RAHMAT (19 / Male), NRIC: S9831055Z		
Adj Asg. Remarks:	SJE DISAGREE Please appoint LKK and contact Mr Vincent Ng @ 9618 7858. Liability 100%		

**ASSOCIATED MAIL RECEIVED** [View All](#) [Compose Case Mail](#)

- MSIG\_SG (19/11/2018): Report Send Back Alerts - SFS633C (TP)

































**ALL ASSOCIATED TASKS** [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

**\*SFS633C (MSC/V/18-001104)  
[FBB8418S]**

**TP  
HOLISTIC HEALTH  
Aug 9 2018 11:00PM  
[NUR IMAN BIN RAHMAT]  
Weng Fatt Motor Engineering**

<a href="#">Upload Documents</a> <a href="#">Upload Photos</a> <a href="#">Compose New Letter</a>			<b>View</b> <a href="#">View in Browser</a>	
<b>Assessment Reports</b>			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	M5IG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	17/08/18 15:52	<b>Accident Statement</b> <small>From: SC - Reg. No: FBB8418S, Claimant: NUR IMAN BIN RAHMAT</small>	 Load HTM	
<b>Photos/Images</b>			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	24/08/18 15:35	General View	 Load JPG	<input checked="" type="checkbox"/>
2	24/08/18 15:35	General View	 Load JPG	<input checked="" type="checkbox"/>
3	24/08/18 15:35	General View	 Load JPG	<input checked="" type="checkbox"/>
4	24/08/18 15:35	General View	 Load JPG	<input checked="" type="checkbox"/>
5	24/08/18 15:35	General View	 Load JPG	<input checked="" type="checkbox"/>
6	24/08/18 15:35	General View	 Load JPG	<input checked="" type="checkbox"/>
7	24/08/18 15:35	General View	 Load JPG	<input checked="" type="checkbox"/>
8	24/08/18 15:35	General View	 Load JPG	<input checked="" type="checkbox"/>
9	24/08/18 15:35	General View	 Load JPG	<input checked="" type="checkbox"/>
10	24/08/18 15:35	General View	 Load JPG	<input checked="" type="checkbox"/>
11	24/08/18 15:35	General View	 Load JPG	<input checked="" type="checkbox"/>
12	24/08/18 15:35	General View	 Load JPG	<input checked="" type="checkbox"/>
13	24/08/18 15:35	General View	 Load JPG	<input checked="" type="checkbox"/>
14	24/08/18 15:35	General View	 Load JPG	<input checked="" type="checkbox"/>
15	24/08/18 15:35	General View	 Load JPG	<input checked="" type="checkbox"/>
16	24/08/18 15:35	General View	 Load JPG	<input checked="" type="checkbox"/>
17	24/08/18 15:35	General View	 Load JPG	<input checked="" type="checkbox"/>
18	24/08/18 15:35	General View	 Load JPG	<input checked="" type="checkbox"/>
19	24/08/18 15:35	General View	 Load JPG	<input checked="" type="checkbox"/>
20	24/08/18 15:35	General View	 Load JPG	<input checked="" type="checkbox"/>
21	24/08/18 15:35	General View	 Load JPG	<input checked="" type="checkbox"/>
22	24/08/18 15:35	General View	 Load JPG	<input checked="" type="checkbox"/>
23	24/08/18 15:35	General View	 Load JPG	<input checked="" type="checkbox"/>
24	24/08/18 15:35	General View	 Load JPG	<input checked="" type="checkbox"/>
25	04/09/18 11:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
26	04/09/18 11:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
27	04/09/18 11:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
28	04/09/18 11:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
29	04/09/18 11:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
30	04/09/18 11:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
31	04/09/18 11:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
32	04/09/18 11:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
33	04/09/18 11:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
34	04/09/18 11:24	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
35	04/09/18 11:24	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
36	04/09/18 11:24	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
37	04/09/18 11:24	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
38	04/09/18 11:24	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
39	04/09/18 11:24	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
40	04/09/18 11:24	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
41	04/09/18 11:24	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
42	04/09/18 11:24	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
43	04/09/18 11:24	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
44	04/09/18 11:24	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
45	04/09/18 11:24	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
46	04/09/18 11:24	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
47	04/09/18 11:24	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
48	04/09/18 11:24	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
49	04/09/18 11:24	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
50	04/09/18 11:24	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
51	04/09/18 11:24	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
52	04/09/18 11:24	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
53	04/09/18 11:25	Photo After Spray		<input checked="" type="checkbox"/>
54	04/09/18 11:25	Photo After Spray		<input checked="" type="checkbox"/>
55	04/09/18 11:25	Photo After Spray		<input checked="" type="checkbox"/>
56	04/09/18 11:25	Photo After Spray		<input checked="" type="checkbox"/>
57	04/09/18 11:25	Photo After Spray		<input checked="" type="checkbox"/>
58	04/09/18 11:25	Photo After Spray		<input checked="" type="checkbox"/>
59	04/09/18 11:25	Photo After Spray		<input checked="" type="checkbox"/>
60	04/09/18 11:25	Photo After Spray		<input checked="" type="checkbox"/>
61	04/09/18 11:25	Photo After Spray		<input checked="" type="checkbox"/>
62	04/09/18 11:25	Photo After Spray		<input checked="" type="checkbox"/>
63	04/09/18 11:25	Photo After Spray		<input checked="" type="checkbox"/>
64	04/09/18 11:25	Photo After Spray		<input checked="" type="checkbox"/>
65	04/09/18 11:25	Photo After Spray		<input checked="" type="checkbox"/>
66	04/09/18 11:25	Photo After Spray		<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	17/08/18 14:37	Third Party Accident Report		<input checked="" type="checkbox"/>
2	17/08/18 14:37	SJE DISAGREE - AP LKK		<input checked="" type="checkbox"/>
3	17/08/18 15:46	workshop details		<input checked="" type="checkbox"/>
4	16/11/18 15:21	LOD, LTA SEARCH, POLICE REPORT, REPAIR BILL, SURVEY REPORT		<input checked="" type="checkbox"/>
5	16/11/18 15:21	COLOURED IMAGES		<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	11/12/18 14:12	Colour Photo		<input checked="" type="checkbox"/>
2	11/12/18 14:12	PRS Invoice		<input checked="" type="checkbox"/>

## Documents Checklist

### DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

**Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)****Show Remarks To:** ☐ Handling InsurerNote: Remarks are private unless you show it to other parties.

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18015128/T1SBE2-1

Date: 11/12/2018

## REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	MSD/VMT/17-987717-WTT
Claimant Vehicle No :	SFS633C	Insured Vehicle No :	FBB8418S
Date of Loss:	09/08/2018	Nature of Claim:	TP
		Claim No:	MSC/V/18-001104

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	SFS633C	Engine No:	1NZC605734
Make & Model:	TOYOTA AXIO, 1.5 (A)	Chassis No:	NZE1416034514
Reg. Date:	06/06/2007 (Man. Year: 2007)	Odometer:	169203 km
Colour:	Blue		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	205/45 R17	Rear Tyre Size:	205/45 R17
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,118.35	1,837.69	4,280.66	69.96
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,630.00	1,555.00	4,075.00	72.38
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>11,748.35</b>	<b>3,392.69</b>	<b>8,355.66</b>	<b>71.12</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,700.00</b>		
<b>Nett Amount (S\$)</b>	<b>11,748.35</b>	<b>2,700.00</b>	<b>9,048.35</b>	<b>77.02</b>

## INSPECTION

Date of Assignment:	20/08/2018	
Date Inspected:	20/08/2018 Inspected At:	Exotic Car Spray Painting Specialist Pte Ltd Block 1002 Bukit Merah Lane 3 #01-85 Singapore 159719
Estimated Period of Repair:	6.0 days	

**Adjuster:** MOHD TAUFIKH BIN HAMID

**Manager:** Hiew May Fung

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

## Reference

Part Source:	MRM-SG	Version:	1.0 (Last Synchronised: 11 Dec 2018)
Parts:	143	TOYOTA AXIO 1.5 (A) (Catalogue:Merimen Singapore 1.0)	
Labour:	Repairer's	(Price-denominated Standard List)	
Print Code:	(Unsubmitted, no print-code for SFS633C)		
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page		
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.		

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FUEL TANK COVER	Bent / Warped	148.00 F	*148.00 FL
2	1		*FUEL TANK INNER GARNISH	Not Necessary	88.00 F	*- FL
3	1		*REAR N/S FENDER	Repair	972.40 F	*- FL
4	1		*REAR BUMPER	Badly Dented	823.60 F	*823.60 FL
5	1		*REAR BUMPER SIDE RETAINER N/S	Bent	131.75 F	*131.75 FL
6	1		*REAR BUMPER CLIPS	Necessary	60.00 F	*40.00 FL
7	1		*REAR N/S FENDER LOWER SHIELD	Bent	62.90 F	*62.90 FL
8	1		*SET REAR N/S FENDER LOWER SHIELD CLIPS	Necessary	18.00 F	*10.00 FL
9	1		*REAR BUMPER BRACKET N/S	Bent	141.10 F	*141.10 FL
10	1		*N/S TAILLAMP	Cracked	398.00 F	*398.00 FL
11	1		*N/S TAILLAMP LOWER BRACKET	Not Necessary	53.50 F	*- FL
12	1		*N/S TAILLAMP PAD	Not Necessary	20.00 F	*- FL
13	3		*N/S TAILLAMP CLIPS	Not Necessary	9.90 F	*- FL
14	1		*REAR SUSPENSION WHEEL HUB & BEARING	Distorted	294.90 F	*294.90 FL
15	1		*REAR SUSPENSION AXLE BEAM	Not Necessary	1,835.00 F	*- FL
16	1		*REAR SUSPENSION AXLE BEAM BUSHING N/S	Not Necessary	123.25 F	*- FL
17	1		*REAR SUSPENSION AXLE BEAM MOUNT BOLT N/S	Not Necessary	15.85 F	*- FL
18	1		*REAR N/S SHOCK ABSORBER	Not Necessary	140.20 F	*- FL
19	1		*REAR N/S SHOCK ABSORBER COIL SPRING	Not Necessary	122.15 F	*- FL
20	1		*REAR N/S SHOCK ABSORBER UPPER SUPPORT	Not Necessary	20.75 F	*- FL
21	1		*REAR N/S SHOCK ABSORBER UPPER BRACKET	Not Necessary	51.35 F	*- FL
22	1		*REAR N/S SHOCK ABSORBER BUMPER	Not Necessary	32.75 F	*- FL
23	1		*REAR N/S SHOCK ABSORBER TOP NUT	Not Necessary	5.00 F	*- FL
24	1		*REAR N/S WHEEL RIM	Cut	550.00 FS	*300.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>6,118.35</b>	<b>2,350.25</b>
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	512.56
<b>Total Parts (\$\$)</b>	<b>6,118.35</b>	<b>1,837.69</b>

Report was unsubmitted during this print-out.



## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	REMOVE THE NECESSARY AFFECTED PARTS, STRAIGHTEN REAR N/S FENDER AND WHEEL ARCH, N/S TAILLAMP PANEL, BOOTLID AND REPLACE PARTS	New	2,000.00	600.00
2	RESET WHEEL ALIGNMENT (TWICE)	New	200.00	60.00
3	PUTTY AND SPRAYPAINT (INCLUDE REAR BUMPER)	New	1,800.00	600.00
4	CHECK ELECTRICAL	New	100.00	30.00
5	TUFF KOTE	New	150.00	40.00
6	REMOVE AND REFIT REAR UNDERCARRIAGE PARTS, BOTH REAR SHOCK ABSORBER & STOPPERS, BRAKE ASSY TO FACILITATE REPAIR	New	1,200.00	120.00
7	REWIRE REAR PORTION	New	50.00	30.00
8	REMOVE AND REFIT REAR BUMPER SENSORS	New	100.00	60.00
9	REPLACE REAR N/S WHEEL RIM AND BALANCING	New	30.00	15.00
Gross Labour Cost (\$\$)			<b>5,630.00</b>	<b>1,555.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >