

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHD 4038A

DATE 15/11/2018 15:41

MAKE :

MODEL : HYUNDAI SONATA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Boot Lid			\$ 1,349.50
	Boot Lid Rubber			\$ 110.90
	Boot Lid Lock Upper			\$ 132.10
	Boot Lid Lock Lower			\$ 30.30
	Boot Lid Sonata Plate			\$ 43.60
	Boot Lid Hyundai Plate			\$ 24.20
	Boot Lid 'H' Emblem			\$ 26.10
	Boot Lid CRDI Plate			\$ 22.70
	Boot Lid Lamp (RH)			\$ 230.20
	Rear Bumper			\$ 578.40
	Rear Bumper Reinforcement			\$ 483.30
	Rear Bumper Clip			\$ 22.00
	Rear Bumper Sponge			\$ 137.40
	Rear Bumper Under Cover			\$ 185.80
	Rear Bumper Protector (LH/RH)		\$ 38.00	\$ 76.00
	Tail Lamp (RH)			\$ 344.00
	Rear Panel			\$ 391.80
	Rear Panel Garnish			\$ 95.80
	<i>Rear Fender (RH) x repair</i>			
	SUB TOTAL			\$ 4,284.10
	LESS 20%			\$ 856.82
	DISCOUNTED TOTAL			\$ 3,427.28
	Boot Lid Comfort Logo & Tel No. Sticker			\$ 30.00 Nett
	Rear No. Plate			\$ 25.00 Nett
	Rear Bumper Reverse Sensor			\$ 135.70 Nett
	Rear Bumper Rubber Mat			\$ 50.00 Nett
				\$ 240.70
	Labour Charge			
	Panel Beating			\$ 800.00
	Spray Painting Charge			\$ 900.00
	Wiring Charge			\$ 30.00
	Tuff Kote			\$ 50.00
	Remove/Refix Reverse Sensor			\$ 80.00
	<i>Towing - King dolly \$150.00</i>			
	TOTAL LABOUR			\$ 1,860.00
	ESTIMATE TOTAL			\$ 5,527.98

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.



JOB REQUISITION FOR BREAKDOWN / TOWING SERVICE

Job Requisition

1. Date: <u>15-11-18</u> Time Received: <u>0345</u>	3. Vehicle Type: ☐ Private ☒ Taxi (CTPL/CCPL) ☐ Fleet ☐ STK (Boon Lay)	4. Type of Towing: ☐ Normal Tow ☒ King Dolly ☐ Flat Bed ☐ Crane-up
2. ☐ New ☐ SPARK Kakis Name of Customer : <u>Mr. Ng.</u> Contact No. : <u>87140514</u> Vehicle No. : <u>SHD 4038A</u> Make / Model / Colour : <u>SONATA</u> Email :	5. Nature of Service: ☐ Jumpstart ☐ Recovery ☐ Change Tyre / Battery	6. Parts Replaced/Remarks:

7. Location: <u>218 Geylang Rd.</u>	8. Vehicle Tow - In Workshop: ☐ Smoky Exhaust ☐ Wheel Jammed ☐ Overheating ☐ Steering Faulty ☐ Brake Faulty ☐ Alternator Faulty ☐ Starting Problem ☐ Loss Power ☒ Accident ☐ Engine Stalled ☐ Return Taxi
9. Preferred Workshop: ☐ Braddell ☒ Loyang ☐ Pandan ☐ Sin Ming ☐ Sungei Kadut ☐ Ubi ☐ Senoko ☐ Komoco (UBI / Leng Kee) ☐ Cycle & Carriage (PD) ☐ Others:	

10. Odometer Reading : _____ Fuel Level : <table border="1"><tr><td>F</td><td>1/4</td><td>1/2</td><td>3/4</td><td>E</td></tr></table>	F	1/4	1/2	3/4	E	11. Radio / CD Player ☐ OK ☐ Faulty ☒ Not tested	# : Cracked X : Dented / : Scratched O : Missing Signature of Customer
F	1/4	1/2	3/4	E			

Job Attended

12. Tow Truck / Recovery Van : ☐ VRS ☒ QA ☐ GAO ☐ TZ ☐ YISHUN ☐ OTHERS Name of Driver : <u>Keong</u> Vehicle No. : <u>GBE 2073B</u> Time Dispatch : <u>0345</u> Time of Arrival : <u>0415</u> Time Completed : <u>0445</u>	TOWING
--	--------

Cash Invoice Details (if applicable)

13. Cash Invoice No. :

Customer Acknowledgement

- a. I have been advised to remove all valuable items in my vehicle, including Global Positioning System (GPS), audio compact disk, thumbdrive, carpark coupons, cash cards, spectacles, pen, etc.
- b. I understand that any items left behind are at my own risk and SPARK Car Care™ will not be held liable for such losses.
- c. Surcharge: Towing fee will be levied if the customer decides neither to tow nor proceed with the repairs in SPARK Car Care™.

<u>15.11.18</u> Date	<u>0415</u> Time	 Signature of Customer
-------------------------	---------------------	---------------------------

14. WORKSHOP

Name of Attending Staff/Guard	Date & Time of Arrival	Signature of Attending Staff/Guard
-------------------------------	------------------------	------------------------------------