

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

SGS 8637C
TP/AIG

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

TEL: 64193000

FAX: 64153727

ATTN: Motor Claim Department

WS Ref: TP/AIG/YS

Claim Type: Third Party

Accident Date: 17/11/2018

TP Veh Reg No: SMD3641E

Estimate No: ES1891308/YISHUN

Date: 19 Nov 2018

Policy No: 5019937560-11

Veh Reg No: SGS8637C

Make/Model: HYUNDAI GETZ 1.1 5M

Chassis No: KMHBT51GR7U661486

Engine No: G4HG7231038

Reg. Date: 27/03/2007

Not Authorised

1/1/2018

Resurvey After Paint

9 days

Estimate Repair Cost to Vehicle No :SGS8637C

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
List Price				
1 REAR BUMPER	278.40	1 PC	Bz 278.40	—
2 REAR BUMPER TOP PROTECTOR	124.50	1 PC	Bz 124.50	—
3 REAR BUMPER CLIPS	3.50	6 PCS	na 21.00	—
4 REAR BUMPER REINFORCEMENT	182.10	1 PC	Bz 182.10	—
5 REAR TAILGATE	1,020.90	1 PC	Bz 1,020.90	—
6 TAILGATE EMBLEM (HYUNDAI)	18.00	1 PC	na 18.00	—
7 TAILGATE EMBLEM (GETZ)	20.00	1 PC	na 20.00	—
8 TAILGATE INNER LOCK	65.20	1 PC	na 65.20	—
9 TAILGATE INNER RUBBER	79.50	1 PC	na 79.50	508.50
10 TAILLAMP LH	172.20	1 PC	CM 172.20	—
11 TAILLAMP PANEL	182.10	1 PC	Bz 182.10	—
12 REAR CENTRE PANEL	399.50	1 PC	Bz 399.50	—
13 REAR CENTRE PANEL INNER TOP GARNISH	125.40	1 PC	125.40	?
14 REAR LH FENDER	1,642.60	1 PC	Bz 1,642.60	—
15 REAR LH FENDER INNER GARNISH	139.60	1 PC	139.60	?
16 REAR TOOL BOX	82.96	1 PC	82.96	?
17 REAR SPARE TYRE TOP CUSHION	189.30	1 PC	189.30	?
			4,743.26	
		Less 20%	948.65	3,794.61
Special Net				
18 REVERSE SENSOR	200.00	1 SET	na 200.00	—
19 REAR WINDSCREEN GLASS GUM	40.00	1 PC	na 40.00	—
20 REAR NUMBER PLATE	20.00	1 PC	na 20.00	—
			260.00	260.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

TEL: 64193000

FAX: 64153727

ATTN: Motor Claim Department

WS Ref: TP/AIG/YS

Claim Type: Third Party

Accident Date: 17/11/2018

TP Veh Reg No: SMD3641E

Estimate No: ES1891308/YISHUN

Date: 19 Nov 2018

Policy No: 5019937560-11

Veh Reg No: SGS8637C

Make/Model: HYUNDAI GETZ1.1 5M

Chassis No: KMHBT51GR7U661486

Engine No: G4HG7231038

Reg. Date: 27/03/2007

Estimate Repair Cost to Vehicle No :SGS8637C

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
Labour				
21 REMOVE AND REFIX REAR WINDSCREEN GLASS	120.00	1 LA	120.00	✓
22 REMOVE & REFIX REAR BUMPER ASSY, TAILGATE, REAR LOCK ASSY, TAILLAMPS, CUT, WELD & RENEW REAR PANEL, REAR LH FENDER, TAILLAMP PANEL, TO STRAIGHTEN, KNOCK & REPAIR REAR LH CHASSIS, REAR SPARE TYRE COMPARTMENT & REALIGN THE SAME	1,500.00	1 LA	1,500.00	1300
23 REMOVE & REFIX SEAT, CARPET, TOP ROOF LINING, SAFETY BELT, ETC	120.00	1 LA	120.00	100
24 PUTTY & RESPRAY ON REAR PANEL, REAR BOTH FENDERS, REAR BUMPER, TAILGATE, REAR SPARE TYRE COMPARTMENT & REAR AFFECTED AREAS	1,000.00	1 LA	1,000.00	900
25 RUSTPROOFING	90.00	1 LA	90.00	✓
			2,830.00	2,830.00
			Total	S\$ 6,884.61
			Add GST @ 7%	481.92
			Total Amount Payable	S\$ 7,366.53

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE