

SERVICE ESTIMATE

94457 - C00001
Mr Heah Kwan Seek
88 Surin Avenue

SL: SERVICE SALES - PC

GST Reg.No:M28920628X

Inv.No. : B&P 0 Page 1

Inv.date. : 16/11/2018

WIP No. : 38632

Veh.In/Out:

*Tel.No. : Mobile: 96238490

Reg.No. : SLU1088M

Reg.date : 17/11/2017

Mileage : 0

Chassis No: SALVA2AGXHH245629

Singapore 535656

Closed by : Paul Ong Qing Yong

Svc Consultant :

Remarks : Mr Heah Kwan Seek

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
			1200			2400	✓
802	TO REPLACE FRONT BUMPER, FRT BRACKET, FRT SENSOR, FRT BEAM, REAR BUMPER, REAR SKID PLATE, REAR SENSOR, REAR BEAM, ETC	0	6000.00	0		6,000.00	S
800	TO PUTTY SPRAY PAINT ON FRT BUMPER, REAR BUMPER, ETC	0	3000.00	0		3,000.00	S
802	TO REPLACE REAR EXHAUST	0	1200.00	0		1,200.00	S
280	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	0	486.00	0		486.00	S
	BUMPER - FRONT	1.0 EA	2497.30			2,497.30	S de ✓ 5,247.57
	MOULDING - BUMPER BA LH	1.0 EA	224.70			224.70	S X AN
	MOULDING - BUMPER BA RH	1.0 EA	224.70			224.70	S de ✓ 5,022.23
	COVER - TOW HOOK	1.0 EA	599.70			599.70	S ? } X
	BUMPER BRACKET FRT R	1.0 EA	80.90			80.90	S ? } sum
	BUMPER BRACKET FRT L	1.0 EA	47.50			47.50	S ?
	BUMPER BRACKET FRT R	1.0 EA	46.90			46.90	S ?

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Tan Jiah 97445749
WP
20/11/18 @ 4:20 pm
Resurvey before paint -
5-6 days
sure@lkkauto.com

SERVICE ESTIMATE

94457 - C00001 SL: SERVICE SALES - PC

Mr Heah Kwan Seek
88 Surin Avenue

Singapore 535656

Closed by : Paul Ong Qing Yong
Svc Consultant :
Remarks : Mr Heah Kwan Seek

GST Reg.No:M28920628X

Inv.No. . : B&P 0 Page 2

Inv.date. : 16/11/2018

WIP No. . : 38632

Veh.In/Out:

*Tel.No. . : Mobile: 96238490

Reg.No. . : SLU1088M

Reg.date. : 17/11/2017

Mileage . : 0

Chassis No: SALVA2AGXHH245629

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	BUMPER BRACKET FRT L	1.0 EA	46.90			46.90	S?
	DEFLECTOR - AIR	1.0 EA	112.30			112.30	S?
	DEFLECTOR - AIR	1.0 EA	112.30			112.30	S?
	BUMPER BRACKET FRT C	1.0 EA	398.70			398.70	S?
	WASHER COVER RH EVOQ	1.0 EA	61.30			61.30	S?
	WASHER COVER LH EVOQ	1.0 EA	70.90			70.90	SX
	RADIATOR GRILLE EVO	1.0 EA	863.00			863.00	S?
	BUMPER BEAM FRT EVOQ	1.0 EA	1008.00			1,008.00	S?
	BUMPER - REAR	1.0 EA	2652.50			2,652.50	S de 2,387.25
	HEAT SHIELD REAR EVO	1.0 EA	124.40			124.40	S bf 111.96
	BRACKET - BUMPER MOU	1.0 EA	60.90			60.90	S?
	BRACKET - BUMPER MOU	1.0 EA	68.10			68.10	S? } n/x
	BUMPER BRACKET REAR	1.0 EA	120.40			120.40	S?
	BUMPER BRACKET REAR	1.0 EA	80.40			80.40	S?
	BUMPER MOULDING REAR	1.0 EA	131.20			131.20	S de 118.08
	BUMPER BEAM REAR EVO	1.0 EA	1225.20			1,225.20	S? } n
	MUFFLER - REAR	1.0 EA	1699.80			1,699.80	S? } n

SERVICE ESTIMATE

94457 - C00001 SL: SERVICE SALES - PC

Mr Heah Kwan Seek
88 Surin Avenue

Singapore 535656

Closed by : Paul Ong Qing Yong
Svc Consultant :
Remarks : Mr Heah Kwan Seek

GST Reg.No:M28920628X

Inv.No. . : B&P 0 Page 3
Inv.date. : 16/11/2018
WIP No. . : 38632
Veh.In/Out:
*Tel.No. . : Mobile: 96238490
Reg.No. . : SLU1088M
Reg.date. : 17/11/2017
Mileage . : 0
Chassis No: SALVA2AGXHH245629

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
-------	-------------	----------	-------	-------	-----	--------	---

	EXHAUST CLAMP 65mm E	1.0 EA	87.70			87.70 S	
	BODY PANEL SEALANT X	1.0 EA	883.20			883.20 S	
	ADHESIVE SEALER FL2	1.0 EA	549.10			549.10 S	

Handwritten notes: } 3 } m x

Labour Total 10,686.00
Parts Total 14,078.00
Package Total 0.00

Gross Total. 24,764.00
Net..... 24,764.00
GST @ 7.0% 1,733.48
Total..... 26,497.50
Paid..... 0.00
Please Pay.. 26,497.50

GST: S=StdRated; 0=OutOfScope; Z=ZeroRated

SUPP

SERVICE ESTIMATE

0 - A00005 SL: AXA INSURANCE PTE LTD
 AXA INSURANCE PTE LTD GST Reg.No:M28920628X
 8 SHENTON WAY, Inv.No. . : B&P 0 Page 1
 #27-01 AXA TOWER, Inv.date. : 22/01/2019
 SINGAPORE 068811 WIP No. . : 38632
 Veh.In/Out: 30/11/2018 08/12/2018
 *Tel.No. . : 6338 7288
 Reg.No. . : SLU1088M
 Closed by : Paul Ong Qing Yong Reg.date .. : 17/11/2017
 Svc Consultant : ACC Mileage .. : 13,657
 Remarks : Mr Heah Kwan Seek Chassis No: SALVA2AGXHH245629

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	INTERCOOLER EVOQUE	1.0 EA	1145.60	10		1,031.04	S bt
	LLR006715/RADIATOR F	1.0 EA	1216.10	10		1,094.49	S bt
	WIPER TANK POWERWASH	1.0 EA	154.70	10		139.23	S de
	LAMP - FOG - FRONT	1.0 EA	604.40	10		543.96	S cut
	AIR DEFLECTOR LOWER	1.0 EA	126.90	10		114.21	S de
	COOLANT 1L	2.0 EA	54.20	10		97.56	S re

			Gross Total.	3,020.49
Labour Total	0.00	Net.....	3,020.49	
Parts Total	3,020.49	GST @ 7.0%	211.43	
Package Total	0.00	Total.....	3,231.92	
		Paid.....	0.00	
		Please Pay..	3,231.92	

GST: S=StdRated; O=OutOfScope; Z=ZeroRated