

SERVICE ESTIMATE

94457 - C00001 SL: SERVICE SALES - PC
 Mr Heah Kwan Seek
 88 Surin Avenue

GST Reg.No:M28920628X

Inv.No. . . : B&P 0 Page 1
 Inv.date. . : 16/11/2018
 WIP No. . . : 38632
 Veh.In/Out:

Singapore 535656

*Tel.No. . . : Mobile: 96238490
 Reg.No. . . : SLU1088M
 Reg.date . . : 17/11/2017
 Mileage . . : 0
 Chassis No: SALVA2AGXHH245629

Closed by : Paul Ong Qing Yong
 Svc Consultant :
 Remarks : Mr Heah Kwan Seek

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE FRONT BUMPER,FRT BRACKET,FRT SENSOR,FRT BEAM, REAR BUMPER,REAR SKID PLATE, REAR SENSOR,REAR BEAM,ETC	0	6000.00	0		6,000.00	S
800	TO PUTTY SPRAY PAINT ON FRT BUMPER,REAR BUMPER,ETC	0	3000.00	0		3,000.00	S
802	TO REPLACE REAR EXHAUST	0	1200.00	0		1,200.00	S
280	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	0	486.00	0		486.00	S
	BUMPER - FRONT	1.0 EA	2497.30			2,497.30	S
	MOULDING - BUMPER BA	1.0 EA	224.70			224.70	S
	MOULDING - BUMPER BA	1.0 EA	224.70			224.70	S
	COVER - TOW HOOK	1.0 EA	599.70			599.70	S
	BUMPER BRACKET FRT R	1.0 EA	80.90			80.90	S
	BUMPER BRACKET FRT L	1.0 EA	47.50			47.50	S
	BUMPER BRACKET FRT R	1.0 EA	46.90			46.90	S

SERVICE ESTIMATE

94457 - C00001 SL: SERVICE SALES - PC

Mr Heah Kwan Seek
88 Surin Avenue

Singapore 535656

Closed by : Paul Ong Qing Yong
Svc Consultant :
Remarks : Mr Heah Kwan Seek

GST Reg.No:M28920628X
Inv.No. . : B&P 0 Page 2
Inv.date. : 16/11/2018
WIP No. . : 38632
Veh.In/Out:
*Tel.No. . : Mobile: 96238490
Reg.No. . : SLU1088M
Reg.date. : 17/11/2017
Mileage . : 0
Chassis No: SALVA2AGXHH245629

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	BUMPER BRACKET FRT L	1.0 EA	46.90			46.90	S
	DEFLECTOR - AIR	1.0 EA	112.30			112.30	S
	DEFLECTOR - AIR	1.0 EA	112.30			112.30	S
	BUMPER BRACKET FRT C	1.0 EA	398.70			398.70	S
	WASHER COVER RH EVOQ	1.0 EA	61.30			61.30	S
	WASHER COVER LH EVOQ	1.0 EA	70.90			70.90	S
	RADIATOR GRILLE EVO	1.0 EA	863.00			863.00	S
	BUMPER BEAM FRT EVOQ	1.0 EA	1008.00			1,008.00	S
	BUMPER - REAR	1.0 EA	2652.50			2,652.50	S
	HEAT SHIELD REAR EVO	1.0 EA	124.40			124.40	S
	BRACKET - BUMPER MOU	1.0 EA	60.90			60.90	S
	BRACKET - BUMPER MOU	1.0 EA	68.10			68.10	S
	BUMPER BRACKET REAR	1.0 EA	120.40			120.40	S
	BUMPER BRACKET REAR	1.0 EA	80.40			80.40	S
	BUMPER MOULDING REAR	1.0 EA	131.20			131.20	S
	BUMPER BEAM REAR EVO	1.0 EA	1225.20			1,225.20	S
	MUFFLER - REAR	1.0 EA	1699.80			1,699.80	S

SERVICE ESTIMATE

94457 - C00001 SL: SERVICE SALES - PC

Mr Heah Kwan Seek
88 Surin Avenue

Singapore 535656

Closed by : Paul Ong Qing Yong
Svc Consultant :
Remarks : Mr Heah Kwan Seek

GST Reg.No:M28920628X
Inv.No. . . : B&P 0 Page 3
Inv.date. : 16/11/2018
WIP No. . . : 38632
Veh.In/Out:
*Tel.No. . . : Mobile: 96238490
Reg.No. . . : SLU1088M
Reg.date. : 17/11/2017
Mileage . . : 0
Chassis No: SALVA2AGXHH245629

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	EXHAUST CLAMP 65mm E	1.0 EA	87.70			87.70	S
	BODY PANEL SEALANT X	1.0 EA	883.20			883.20	S
	ADHESIVE SEALER FL2	1.0 EA	549.10			549.10	S

			Gross Total.	24,764.00
Labour Total	10,686.00		Net.....	24,764.00
Parts Total	14,078.00		GST @ 7.0%	1,733.48
Package Total	0.00		Total.....	26,497.50
			Paid.....	0.00
			Please Pay..	26,497.50

GST: S=StdRated; O=OutOfScope; Z=ZeroRated