

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHC 7034X

DATE : 17.11.2018

MAKE :

MODEL : HYUNDAI i40

Chuang

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover <i>X repair</i>			\$ 544.50
	Front Bumper Bracket Top (LH/RH) <i>X su</i>		\$ 22.40	\$ 44.80
	Front Bumper Retainer Mounting <i>X su</i>		\$ 9.20	\$ 18.40
SUB TOTAL				\$ 607.70
LESS 20%				\$ 121.54
DISCOUNTED TOTAL				\$ 486.16
	Front Number Plate <i>/ su</i>			\$ 25.00
	Front No Plate Trim Cover <i>X su</i>			\$ 30.00
TOTAL				\$ 55.00
<i>Labour charge</i> <i>Panel Beating</i> <i>Spray Painting charge</i>				<i>200</i> <i>400</i> <i>300 200</i>
ESTIMATE TOTAL				\$ 541.16
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary items must be resurveyed and is subject to final approval from Insurance Company

ESTIMATE TOTAL

 Signature:
 Date:

REPAIR ESTIMATE*

DATE : 17.11.2018

MODEL : HYUNDAI i40

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

[illegible]