

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/TP/1311/2018/NK
Date	:	17-Nov-18

Kindly arrange for survey.

Your insured vehicle no. **GBB 7622 B**

Lonpac Insurance Bhd

100 Beach Road

#19-00 Shaw Tower

Singapore 189702

Attn: Motor Claims Dept

Fax: 6296 2706

Owner's Name	:	Premium Leasing Pte Ltd
Address	:	9 Leng Kee Road Singapore 159090
Telephone	:	6471 2123
Type of Claim	:	Third Party Claim
Policy No.	:	999994451/100786891-00000
Vehicle No	:	SLJ 1242 S
Model Code	:	Audi A6 3.0 TFSI QUATRRO
Model / Year	:	Nov-16
Engine No	:	CRE148206
Chassis No	:	WAUZZZ4G1HN059739
Mileage	:	-
Date In	:	-
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	15-Nov-18
Place of Accident	:	Pioneer Road direction to Tg Kling Rd

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKL 1242 S

S/N	Nature of Jobs	Estimated Charges
1	To remove and transfer rear parking aid and rear lid kick sensor. Check function.	S/N \$ 360.00 ✓
2	To dismantle and renew rear bumper. Reorganise crash management components. Reinstall all parts removed.	\$ 1,050.00 700
3	To respray rear bumper.	\$ 900.00 700
4	To carry out diagnostic check.	S/N \$ 192.00 ✓
TOTAL LABOUR CHARGES		: <u><u>\$ 2,502.00</u></u>

All charges are not inclusive of GST.

Remarks (OK) = Approved, Remarks (X) = Not approved

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLJ 1242 S

		Damage Parts & Prices	
S/N	Parts Description	S/NETT	REMARKS
1	REAR BUMPER / <i>ee</i>	\$	2,629.00
2	REAR BUMPER STICKY PAD ?	4 \$	20.00
3	REAR BUMPER FIXING PARTS ?	\$	234.00
4	REAR BUMPER SPOILER / <i>GA</i>	\$	707.00
5	REAR BUMPER CLOSING ELEMENT LH / RH ?	2 \$	138.00
6	REAR BUMPER HONEYCOMB GRILLE ?	\$	287.00
7	REAR BUMPER SECURING STRIP ?	\$	191.00
8	CABLE TERMINAL ?	13 \$	84.00
9	TRIM FOR EXHAUST TAIL PIPE LH / RH X <i>na</i>	2 \$	994.00
10	REAR BUMPER CARRIER ?	\$	851.00
11	REAR BUMPER SEAL LH / RH ?	2 \$	24.00
12	REAR BUMPER GUIDE SECTION INNER LH / RH X	2 \$	56.00
13	REAR BUMPER GUIDE SECTION OUTER LH / RH X	2 \$	92.00
14	CONNECTING PIECE X	\$	21.00
15	REAR BUMPER GUIDE PROFILE LH / RH X	2 \$	114.00
16	REAR BUMPER HOLDING STRAP LH / RH X	2 \$	108.00
17	REAR BUMPER SENSOR ?	2 \$	421.00
18	CONTROL UNIT ?	\$	372.00
19	SUNDRIES ?	\$	300.00
TOTAL SPARE PARTS		:	\$ 7,643.00
TOTAL LABOUR CHARGES		:	\$ 2,502.00
GRAND TOTAL		:	\$ 10,145.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : *Guo Qiang - 82880282*
Surveyed Date :
Authorised Date : *3 Days.*
Excess Cost :
Liability : *Before paint photos.*
Remarks : *27/11/18.*

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant