

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHA 7303E

DATE 15/11/2018 14:00

MAKE :

MODEL : HYUNDAI i40

KK/Kalvin L/Sum
L/See EQ

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Rear Bumper ✓			\$ 553.00	
	Rear Bumper Reinforcement ?			\$ 428.40	
	Rear Bumper Reinforcement Bracket (LH/RH) ?		\$ 80.30	\$ 160.60	
	Rear Bumper Clip 10 pcs ✓			\$ 22.00	
	Rear Bumper Bracket ?		\$ 35.60	\$ 71.20	
	Rear Bumper Sponge ?			\$ 103.50	
	Rear Bumper Under Cover ?			\$ 228.00	
	Rear Bumper Reflector Lamp (LH) ✓			\$ 30.60	
	SUB TOTAL			\$ 1,597.30	
	LESS 20%			\$ 319.46	
	DISCOUNTED TOTAL			\$ 1,277.84	
	Rear Bumper Rubber Mat ✓			\$ 50.00	Nett
	Rear Bumper Advertisement Logo ✓			\$ 51.00	Nett
	Rear Fender Advertisement Logo (LH/RH) ✓		\$ 100.00	\$ 200.00	Nett
				\$ 301.00	
	Labour Charge			200	
	Panel Beating			\$ 350.00	
	Spray Painting Charge			\$ 250.00	
				200	
	TOTAL LABOUR			\$ 600.00	
	ESTIMATE TOTAL			\$ 2,178.84	
KK/Kalvin L/Sum 16/11/18 1058h 2 days L/See After Repair photo LKK Auto Consultants hence notify the Repairer of the following: - To resurvey before/after spray painting - To display damaged parts during resurvey - Parts prices are subject to confirmation - Third party survey is on a "Without Prejudice" basis - No illegal modification(s) is allowed - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:					
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					