

ASS. REC. BY:

REF: CS/E6118020893 / Utbn2

Special Instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person):

Yee Pei Li

of

EAT

Date/Time:

19.11.2018 4.06pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLZ 1800Y

Insured:

GBG 9003Y

at Workshop m/s

Fostech Auto

Tel:

6746 5405

of

Blk 1 Kaki Bukit Ave 6 #07-46

Policy No:

Claim No:

GBG9003Y / SL/pl

Sum Insured:

Excess:

Make of Veh:

D.O.A.

16/12/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'Wp'

H.O.D. Endorsement:

Date/Time:

19.11.2018 4.14pm

Person Contacted:

Ninny

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SLZ 1800Y - NA / 11/180039 / HU

DUA: 16/12/2018

GBG 9003Y - X

20/11/18 @

3.12pm informed Steve Lim, we are pending estimate from repairer.

REF:

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

LTA 51001

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

Yr Regn:

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading:

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 28 NOV 2018

Date/Time. File Pass to?



Preli. Report

1) 28/11 Typist



Final Report

Date/Time. File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Invs (\$)



Weekend (\$)

Survey Fee:

Transportation:

) S + PS. Si

) Photos

) Others

TOTAL

350

Report Format :

Lump Sum / I/E: (\$ 2,653.14)

Catherine Chong (LKK Auto)

From: Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>
Sent: Monday, 19 November, 2018 4:06 PM
To: 'admin-d@lkkauto.com'
Cc: SUR (sur@lkkauto.com)
Subject: OI : GBG9003Y / TP : SLZ1800Y/LKK / DOA : 16/11/2018
Attachments: SLZ1800Y - PRS FORM n SAS.pdf

Dear Catherine/Nivitha,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please assist to conduct this survey from **FASTECH AUTO PTE LTD**,

ADDRESS : 1 KAKI BUKIT AVENUE 6
#01-46/48/50 AUTOBAY
SINGAPORE 417883

PERSON TO CONTACT : MR YONG @ 6746 5405

ERGO OFFICER-IN-CHARGE : STEVE LIM

Note: To survey on without prejudice basis. Please note that our insured/insured driver has yet to e-file their SAS for this accident. Please advise the consistency of damages to third party vehicle. Obtain estimate from workshop and inform the repairer in writing, that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Attached is TP's SAS (**note: reports not to be released to any Third Party**). No estimates was provided.

Kindly acknowledge receipt of this email.

Regards,
Yee Pei Li
Claims Assistant (Motor)

ERGO Insurance Pte. Ltd.

5 Temasek Boulevard, #04-01 Suntec Tower Five
Singapore 038985
DID.: +65 6829 9194
Tel.: +65 6829 9199
Fax.: +65 6829 9247

ERGO

www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Tuesday, 20 November 2018 3:12 PM
To: 'Survey Report (ERGO Insurance Pte. Ltd.); 'Steve Lim'
Cc: SUR; assignments
Subject: RE: GBG9003Y / TP : SLZ1800Y/LKK / DOA : 16/11/2018

Dear Steve,

Please be informed that we have inspected the vehicle SLZ 1800Y on 19/11/2018.

We are pending for estimate from repairer.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewse@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Monday, 19 November 2018 4:12 PM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)' <Survey.Report@ergo.com.sg>
Cc: SUR <sur@lkkauto.com>; assignments <assignments@lkkauto.com>
Subject: RE: GBG9003Y / TP : SLZ1800Y/LKK / DOA : 16/11/2018

Dear Pei Li,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Survey Report (ERGO Insurance Pte. Ltd.) [<mailto:Survey.Report@ergo.com.sg>]
Sent: Monday, 19 November, 2018 4:06 PM
To: 'admin-d@lkkauto.com' <admin-d@lkkauto.com>
Cc: SUR (sur@lkkauto.com) <sur@lkkauto.com>
Subject: OI : GBG9003Y / TP : SLZ1800Y/LKK / DOA : 16/11/2018

Dear Catherine/Nivitha,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please assist to conduct this survey from **FASTECH AUTO PTE LTD**,

ADDRESS : 1 KAKI BUKIT AVENUE 6
#01-46/48/50 AUTOBAY

ERGO

Date: 19.11.2018
Our Reference: GBG 9003Y/SL/pl
Your Reference: SLZ 1800Y

To: FASTECH AUTO PTE LTD

Sent via Fax ☐
or
Email ☐ hayly@fastechauto.com.sg

Pre-Repair Survey (PRS) Acknowledgement

Vehicle For Inspection: SLZ 1800Y
Insured's Vehicle: GBG 9003Y
Date Of Accident: 16.11.2018


We acknowledge receipt of your request for PRS on: 19.11.2018

In compliance with "State Courts Practice Directions Amendment No.1 of 2016", do select an assessor from the list below and indicate your selection in the box marked *.

* LKK

AIS	Automobile Inspection Services Pte Ltd	LBS	L.B.S Auto Consultants Pte Ltd
FTA	FormTeam Consultancy Pte Ltd	LKK	LKK Auto Consultants Pte Ltd
IAS	Infiniti Appraisal Service	PS	Priority Services
JPK	JP Knights Pte Ltd	VAC	Vicom Ltd

<input checked="" type="checkbox"/>	Your request for inspection does not have your client's cost of repair estimate, kindly forward a copy.
<input checked="" type="checkbox"/>	Your request for inspection does not have your client's GIA report, kindly forward a copy.
<input type="checkbox"/>	We acknowledge your interest for direct settlement, we will assess & revert soon upon receipt of estimate.
<input checked="" type="checkbox"/>	Our Insured's driver has not reported the accident to us todate.
<input checked="" type="checkbox"/>	Others: <u>OFFICER-IN-CHARGE - STEVE LIM</u>

Prepared by:	<u>Pei Li</u>	6829 9194	<u>claims@ergo.com.sg</u>
Signature:			FAX : 6829 9247

Assessor use only:

Assignment Date: _____
Assignment Time: _____

Remarks:

Workshop use only:

Assessor attended workshop on:

Date: _____
Time: _____
Inspector: _____

☐ Vehicle not available at the appointed date and time.

Kindly acknowledge our Assessor presence for the above job .

Workshop Acknowledgement & Stamp.

Note: Our Inspection is on a without admission to liability basis.



ANNOUNCING Carway as sgCarMart Premium Dealer 2018



Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)

New 5 Years Coe Renewal Honda Stream 1.8A







2.88%p.a Lowest Interest@GV
Cars Financing \$2000
Downpayment Monthly From
\$638
GV Credit Pte Ltd StarAd


[Browse by Category](#)
[Sort by Date Posted](#)

4 vehicles

Nissan Qashqai

[Advanced Search](#)

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Ve
Search Selection	Nissan Qashqai		Any	Any	2018	Any	Any	
	Nissan Qashqai	1.2A DIG-T Premium	\$91,800	\$8,810 /yr	28-Feb-2018	1,197 cc	10,000 km	
Massive Savings Of \$22k From New. No Waiting Time. 5 Years Agent Warranty & Free Service Credit By Tan Chong Motor. Current Faceli Choice Of Colour, Nice Pearl White Effect With A Smooth Finis... Car Buyers Automotive Pte Ltd Posted: 17-Nov-2018 Tags: 2018 Nissan Qashqai, 2018 nissan qashqai, Nissan Qashqai, nissan qashqai, Nissan, Qashqai, qashqai, Used Nissan								
	Nissan Qashqai	1.2A DIG-T Premium	\$96,800	\$9,000 /yr	30-Jun-2018	1,197 cc	5,800 km	
Introducing The 2018 Latest Facelifted Qashqai Premium Purple With Brown Interior. Agent Unit Of Nissan Tan Chong. Comes With 5 Year Agent Warranty. Full Features And Free In Car Front/Rear... Euro Performance Asia Pte Ltd Posted: 06-Nov-2018 Tags: 2018 Nissan Qashqai, 2018 nissan qashqai, Nissan Qashqai, nissan qashqai, Nissan, Qashqai, qashqai, Used Nissan								
	Nissan Qashqai	1.2A DIG-T Premium	\$103,111	\$9,860 /yr	26-Apr-2018	1,197 cc	5,900 km	
High ARF 20201, Only New 2018 Latest Facelifted Qashqai Premium White In Black From Tan Chong Under 5 Years Unlimited Agent Wari 20k Km Free Servicing, Pristine Condition. Black Leather Seat,... Posted: 27-Oct-2018 Tags: 2018 Nissan Qashqai, 2018 nissan qashqai, Nissan Qashqai, nissan qashqai, Nissan, Qashqai, qashqai, Used Nissan								
	Nissan Qashqai	1.2A DIG-T Premium	\$90,998	\$8,720 /yr	27-Feb-2018	1,197 cc	14,000 km	
Be Our Next Happy Client To Owned This Nearly Mint Pre-Owned Vehicle At Most Reasonable And Affordable Price! Full 5 Years Warranty All Accessories To Be Given! Genuine Low Mileage! Condit... Posted: 14-Oct-2018 Tags: 2018 Nissan Qashqai, 2018 nissan qashqai, Nissan Qashqai, nissan qashqai, Nissan, Qashqai, qashqai, Used Nissan								

Save this search criteria, to get email alerts whenever a match is found.

Make Model Price Depreciation Reg Date Eng Cap Mileage Ve

[For old ad](#)
[ed ads](#)
[Compare](#)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	7495J
Vehicle Details	
Vehicle No.:	SLZ1800Y
Vehicle to be Exported:	No
Intended Deregistration Date:	20 Nov 2018
Vehicle Make:	NISSAN
Vehicle Model:	QASHQAI 1.2 DIG-T CVT
Primary Colour:	Silver
Manufacturing Year:	2018
Engine No.:	HRA2585765A
Chassis No.:	SJNFEAJ11U2218282
Maximum Power Output:	85.0 kW (113 bhp)
Open Market Value:	\$20,452.00
Original Registration Date:	27 Mar 2018
First Registration Date:	27 Mar 2018
Transfer Count:	0
Actual ARF Paid:	\$20,633.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	26 Mar 2028
PARF Rebate Amount:	\$15,474.00
Intended COE Rebate Details	
COE Expiry Date:	26 Mar 2028
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$38,000.00
COE Rebate Amount:	\$35,527.00
Total Rebate Amount:	\$51,001.00

The information contained herein is correct as at 20 Nov 2018

OK

Annex D

NOTICE OF REPORTING

[Signature]

This is to confirm that Tan Beng Chiang NRIC/FIN: S0045905D, HP: 96211551 has reported to the Police a non-injury traffic accident which occurred along Ang Mo Kio Avenue 1 on 16/11/2018 at about 1555hrs involving the following vehicles:

[Signature] SLZ 1800Y *[Signature]*
V1) SBZ1800Y (Complainant's vehicle)
V2) GBG9003Y (Other party's vehicle)

BISHAN NPC
20 BISHAN STREET 2
SINGAPORE 579757
TEL: 1800-5529089

[Signature]
SLZ 1800Y *[Signature]*
BISHAN NPC
20 BISHAN STREET 2
SINGAPORE 579757
TEL: 1800-5529089

On the above stated date, time and location, I stopped my car (SBZ1800Y) behind two other cars in the middle lane when the traffic light was red at Li Hwan Drive traffic light junction towards CTE. As I was waiting to move off, a Toyota van (GBG9003Y) suddenly collided on to the back of my vehicle.

After collision, we exchanged our particulars and proceeded on with our journey. I wish to state that no one sustained any injuries. I am lodging this report for insurance claims.

2 If this accident was reported to the Police within 24 hours of its occurrence, then he/she has complied with Sec 84(2) of the Road Traffic Act, Cap 276.

Rank/Name of Issuing Officer: SGT (2) Daron Ho
Date: 16/11/2018 Time: 2119hrs
S/D Ref: eSD 142
Police Post/Unit: Bishan NPC

BISHAN NPC
20 BISHAN STREET 2
SINGAPORE 579757
TEL: 1800-5529089

Original - to be issued to informant
Duplicate - to be submitted to Traffic Police

FASTECH AUTO PTE LTD
1 KAKI BUKIT AVENUE 6
#01-46/48/50
SINGAPORE 417883

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

not Affected
the
P/2# 12653-14
sky.
19/11/18

VEHICLE NO: SLZ 1800Y

QTY	PARTICULAR		
1 PCS	REAR WINDSCREEN W/MOULDING	930.00	nu \$1,855.30
2 PCS	REAR WINDSCREEN INNER SIDE GARNISH @ \$165.00		11 \$330.00 X
1 PCS	TAILGATE	2936.80	Body ID \$3,066.20
1 PCS	TAILGATE OUTER GARNISH	336.00	wopd/ser \$450.00
1 PCS	TAILGATE REAR LOGO		nu \$38.50
1 PCS	TAILGATE GARNISH EMBLEM		nu \$78.50
2 PCS	TAILGATE REFLECTORS @ \$650.00	215.90 x 2 = 431.80	one \$1,300.00
1 PCS	TAILGATE REAR WIPER ARM		11 \$166.00 X
1 PCS	TAILGATE REAR WIPER MOTOR		11 \$966.00 X
1 PCS	TAILGATE INNER LOCK	116.70	twi/jm \$292.00
1 PCS	TAILGATE INNER TRIM BOARD	488.20	Re/cng \$595.30
1 SET	TAILGATE INNER TRIM BOARD CLIPS		nu \$30.00
1 PCS	TAILGATE WEATHERSTRIP		twi \$166.20
1 PCS	TAILGATE REVERSE CAMERA		Shohb \$485.00
2 PCS	TAILGATE LICENCE PLATE LAMPS @ \$53.00		11 \$106.00 X
1 PCS	REAR BUMPER	717.00	12e \$891.00
1 PCS	REAR BUMPER TOW COVER		11 \$22.00 X
2 PCS	REAR BUMPER REFLECTORS @ \$68.00		11 \$136.00 X
2 PCS	REAR BUMPER SIDE RETAINERS @ \$35.00		ms/but \$70.00 12e
1 SET	REAR BUMPER CLIPS		nu \$35.00
1 PCS	REAR BUMPER SPONGE	126.40	to.1 \$185.00
1 PCS	REAR BUMPER REINFORCEMENT	619.20	ID \$721.00
2 PCS	REAR BUMPER REINFORCEMENT BRACKETS @ \$150.00	126 x 2 = 252	ser \$300.00
1 PCS	REAR END PANEL	482.60	Body ID \$720.00
1 PCS	REAR SUPPORT PANEL TOP GARNISH	345.30	det/nu \$408.00
1 PCS	REAR FLOOR PANEL		11 \$1,288.00 X
1 PCS	REAR FLOOR PANEL TOP BOARD		Silc \$622.00 X
2 PCS	REAR FLOOR PANEL TOOLS SPONGES @ \$305.00	295 x 2 = 590	to.1 \$610.00
1 PCS	REAR END PANEL LOCK SENSOR		11 \$265.00 X
1 PCS	REAR FLOOR PANEL TOP BOARD SPONGE		to.1 \$495.00
1 PCS	REAR EXHAUST		11 \$1,122.30 X
2 PCS	REAR EXHAUST MOUNTINGS @ \$60.00		11 \$120.00 X
2 PCS	TAILLAMPS @ \$580.00	323.70 x 2 = 647.40	one \$1,160.00
2 PCS	REAR FENDERS @ \$1150.00		11 \$2,300.00 X
2 PCS	REAR FENDER OUTER PROTECTORS @ \$541.00	481 x 2 = 962	102 def/to.1 \$1,082.00
			\$22,477.30
1 PCS	S.NETT		
1 PCS	REAR LICENCE PLATE W/HOLDER		ser \$50.00 40
1 PCS	REAR WINDSCREEN SEALANT		nu \$50.00 40

1 SET
1 PCS
1 SET

REAR BUMPER REVERSE SENSOR
REAR END PANEL SEALANT
REAR FLOOR PANEL INSULATOR

LABOUR CHARGES:

TO CHECK WIRING
TO DISMANTLE & REPLACING REVERSE SENSOR
TO DISMANTLE & REPLACING REAR WINDSCREEN
TO DISMANTLE & REFIX REAR EXHAUST
TO DISMANTLE & REFIX SEAT, CUSHION UPHOLSTREY
TO SPRAY RUSF PROOFING
TO MOUNT VEHICLE ON CAR O-LINER
LABOUR FOR PANEL BEATING & REPLACING PARTS
TO PUTTY & SPRAY PAINTING

slabk \$280.00 200
ner \$50.00 ✓
n1 \$50.00 X

\$80.00 30
\$80.00 50
\$150.00 120
11 \$150.00 X
\$100.00 80
\$120.00 60
n1 \$380.00 X
\$1,500.00 800
\$1,500.00 1000

TOTAL \$27,017.30

P-11314.60
102

P+10183.64

S.W + 330.00

labour + 2140.00

12653.64



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ERGO INSURANCE PTE LTD			Ref : CS/EGI18020893/Utbn2	
5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER FIVE SINGAPORE 038985			Date : 05-12-2018	
			Code : EGI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBG 9003Y	Veh. Inspected	SLZ 1800Y	
Policy No.		Coverage (\$)	0.00	
Claim No.	GBG9003Y/SL/pl	Excess (\$)	0.00	
Assign From	YEE PEI LI	Assign Date	19/11/2018	
2. Vehicle Particulars & Condition				
Make & Model	NISSAN QASHQAI (A)	c.c	1197	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	SJNFEAJ11U2218282	Colour	SILVER	
Odometer	6301	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R17	BRIDGESTONE	8 mm	
L/H Front Tyre	215/60 R17	BRIDGESTONE	8 mm	
R/H Rear Tyre	215/60 R17	BRIDGESTONE	8 mm	
L/H Rear Tyre	215/60 R17	BRIDGESTONE	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	16/11/2018	Inspection Date	19/11/2018	
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLZ 1800Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR WINDSCREEN W/MOULding	NECESSARY	1,855.30	930.00
2	REAR WINDSCREEN INNER SIDE GARNISH @\$165.00	NOT NECESSARY	330.00	-
1	TAILGATE	BADLY DENTED	3,066.20	2,936.80
1	TAILGATE OUTER GARNISH	WARPED / BENT	450.00	336.00
1	TAILGATE REAR LOGO	NECESSARY	38.50	38.50
1	TAILGATE "QASHQAI" EMBLEM	NECESSARY	78.50	78.50
2	TAILGATE REFLECTORS @\$650.00	CRACKED	1,300.00	431.80
1	TAILGATE REAR WIPER ARM	NOT NECESSARY	166.00	-
1	TAILGATE REAR WIPER MOTOR	NOT NECESSARY	966.00	-
1	TAILGATE INNER LOCK	TWISTED / JAMMED	292.00	116.70
1	TAILGATE INNER TRIM BOARD	DEFORMED / CRACKED	595.30	488.20
1	SET TAILGATE INNER TRIM BOARD CLIPS	NECESSARY	30.00	30.00
1	TAILGATE WEATHERSTRIP	TWISTED	166.20	166.20
1	TAILGATE REVERSE CAMERA	SHORTED	485.00	485.00
2	TAILGATE LICENCE PLATE LAMPS @\$53.00	NOT NECESSARY	106.00	-
1	REAR BUMPER	DENTED / DEFORMED	891.00	717.00
1	REAR BUMPER TOW COVER	NOT NECESSARY	22.00	-
2	REAR BUMPER REFLECTORS @\$68.00	NOT NECESSARY	136.00	-
2	REAR BUMPER SIDE RETAINERS @\$35.00	N/S BENT	70.00	35.00
1	SET REAR BUMPER CLIPS	NECESSARY	35.00	35.00
1	REAR BUMPER SPONGE	TORN	185.00	126.40
1	REAR BUMPER REINFORCEMENT	DENTED	721.00	619.20
2	REAR BUMPER REINFORCEMENT BRACKETS @\$150.00	BENT	300.00	252.00
1	REAR END PANEL	BADLY DENTED	720.00	482.60
1	REAR SUPPORT PANEL TOP GARNISH	DEFORMED / TWISTED	408.00	315.30
1	REAR FLOOR PANEL	TO REPAIR SEE LABOUR	1,288.00	-
1	REAR FLOOR PANEL TOP BOARD	SERVICEABLE	622.00	-
2	REAR FLOOR PANEL TOOLS SPONGES @\$305.00	TORN	610.00	590.00

Report Ref No. CS/EG18020893/Utn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR END PANEL LOCK SENSOR	NOT NECESSARY	265.00	-
1	REAR FLOOR PANEL TOP BOARD SPONGE	TORN	495.00	495.00
1	REAR EXHAUST	TO REPAIR SEE LABOUR	1,122.30	-
2	REAR EXHAUST MOUNTINGS @\$60.00	NOT NECESSARY	120.00	-
2	TAILLAMPS @\$580.00	CRACKED	1,160.00	647.40
2	REAR FENDERS @\$1150.00	TO REPAIR SEE LABOUR	2,300.00	-
2	REAR FENDER OUTER PROTECTORS @\$541.00	DEFORMED / TORN	1,082.00	962.00
	LESS 10% DISCOUNT		-	-1,131.46
			22,477.30	10,183.14
	<u>SPECIAL NETT ITEMS</u>			
1	REAR LICENCE PLATE W/HOLDER (SN)	BENT	50.00	40.00
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	50.00	40.00
1	SET REAR BUMPER REVERSE SENSOR (SN)	SHORTED	280.00	200.00
1	REAR END PANEL SEALANT (SN)	NECESSARY	50.00	50.00
1	SET REAR FLOOR PANEL INSULATOR (SN)	NOT NECESSARY	50.00	-
			480.00	330.00
	<u>LABOUR</u>			
	TO CHECK WIRING.		80.00	30.00
	TO DISMANTLE & REPLACING REVERSE SENSOR.		80.00	50.00
	TO DISMANTLE & REPLACING REAR WINDSCREEN.		150.00	120.00
	TO DISMANTLE & REFIX REAR EXHAUST.	NOT NECESSARY	150.00	-
	TO DISMANTLE & REFIX SEAT,CUSHION UPHOLSTERY.		100.00	80.00
	TO SPRAY RUSF PROOFING.		120.00	60.00
	TO MOUNT VEHICLE ON CAR O-LINER.	NOT NECESSARY	380.00	-
	LABOUR FOR PANEL BEATING & REPLACING PARTS INCLUSIVE OF THE REPAIR OF REAR FLOOR PANEL,REAR EXHAUST AND REAR FENDERS.		1,500.00	800.00
	TO PUTTY & SPRAY PAINTING.		1,500.00	1,000.00
			4,060.00	2,140.00
GRAND TOTAL			27,017.30	12,653.14
RECOMMENDED COST OF REPAIRS				12,653.14

Report Ref No. CS/EGI18020893/Utnb2



Report Ref No. CS/EGI18020893/Utbn2

A handwritten signature in black ink, appearing to read 'Chua'.

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.