

U2 SPRAY PAINTING PTE LTD

Block 25 Kaki Bukit Road 4, #06-43 Synergy @ KB Singapore 417800
HP: 96583371

LZY TRANSPORTATION SERVICES

Bk 25 Kaki Bukit Rd 4
06-43 SYNERGY @KB
Singapore 417800

19th Nov 2018

Accident date: 14th NOV 2018

Estimated repair cost for vehicle no: SJR4072C TOYOTA ALTIS 1.6A '09

S/n	Qty	Items	U/price	Amount
1	1	Rear boot lid Repair		\$850.00 x
2	1	Rear boot lid ALTIS logo		\$54.10 ✓
3	1	Rear boot lid A1.6 logo		\$43.10 ✓
4	1	Rear boot lid emble logo		\$47.70 ✓
5	1	Rear boot lid VVTI logo		\$36.00 ✓
6	1	rear Boot Lid corolla logo		\$45.10 ✓
7	1	Rear boot lid chrome moulding clips		\$15.00 x
8	1	Boot lid chrome moulding		\$292.80 x
9	1	Rear boot lid inner lock		\$323.40 x
10	1	Rear Boot Lid Inner Trim board		\$320.10 x
11	1	Rear Boot Lid Inner Trim board clips		\$50.00 x
12	2	Rear Boot Lid Number Plate Lamp	\$67.10	\$134.20 x
13	1	boot lid plate holder		\$50.00 x
14	2	boot lid lamp	\$320.00	\$640.00 x
15	2	Rear tail lamp	\$425.00	\$850.00 x
16	4	Rear tail lamp clips	\$8.00	\$32.00 x
17	2	Rear tail lamp panel	\$175.40	\$350.80 ✓
18	1	Rear bumper Deformed		\$850.00 985
19	2	Rear Bumper Side holder New	\$73.80	\$147.60 ✓
20	2	Rear bumper bracket Best	\$63.20	\$126.40 ✓
21	2	Rear bumper side reflector New	\$85.00	\$170.00 x
22	1	Rear bumper clips New		\$50.00 30
23	1	Rear end panel Dented		\$560.00 ✓
24	1	Rear end panel top garnish Deformed		\$265.00 ✓
25	1	rear end Panel sealant New		\$120.00 ✓
26	1	Rear spare tire panel top cover New		\$292.80 x
27	1	Front bonnet Dented		\$880.00 ✓

Sheet1

28	2	Front bonnet hinges		\$55.20	\$110.40	X
29	1	Front bonnet lock			\$155.10	X
30	1	Front bonnet inner rubber			\$160.10	X
31	6	Front bonnet inner rubber clips		\$12.90	\$77.40	X
32	1	Front bonnet inner sponge			\$184.20	X
33	1	Front bonnet lock panel	Best		\$161.20	✓
34	2	Front headlamp	cracked	\$750.00	\$1,500.00	✓
35	1	Front grille	cracked		\$290.00	✓
36	1	Front grille emble logo	new		\$89.40	✓
37	1	Front bumper	Detached		\$780.00	455
38	2	Front Bumper Side Bracket	new	\$83.10	\$166.20	78
39	8	Front bumper clips	new	\$12.90	\$103.20	50
40	1	Front bumper reinforcement	Best		\$480.10	285
41	2	front bumper reinforcement bracket	new	\$131.10	\$262.20	X
42	2	Front bumper fog lamp cover	new	\$131.10	\$262.20	X
43	2	front Bumper fog lamp	new	\$180.20	\$360.40	+
44	1	front Bumper lower grille	new		\$280.00	+
45	1	front support panel	Paper		\$780.00	X
46	1	Front air-con condenser	Dented.		\$985.00	✓
47	1	Front radiator	Dented.		\$950.00	✓
48	1	Front radiator fan motor assy	new		\$518.75	X

7703.60
5777.70

Subtotal :- \$16,251.95

S/n	Qty	Items/Nett	U/price	Amount
1	2	Rear bumper reverse sensor	Dented	\$280.00
5	1	Rear Boot Lid Number Plate	new	\$50.00
6	1	Front bumper number plate	Best	\$50.00

250

Subtotal :- \$380.00

Labour charges

To remove & re-fix cushion	\$120.00 60
To remove & re-fix rear windscreen	\$120.00 X
Gum	\$50.00 X
To remove & re-fix front windscreen	\$120.00 X
Gum	\$50.00 X
To remove & refix front air-con condenser, radiator Fan-motor and top up gas	\$250.00 120
WHEEL alignment (computer)	\$120.00 X
To remove & re-fix reverse sensor	\$100.00 50
Tuff kote	\$120.00 60
To Check Wiring System	\$60.00 ✓
Panel beating	\$1,600.00 1400.
Spray painting	\$1,600.00 1400

3150

subtotal:- \$4,310.00

Total:- \$20,941.95

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 9177.70
L/S: GK (Nett Value)
11 Days.

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Business
Owner ID:	4759W

Vehicle Details

Vehicle No.:	SJR4072C
Vehicle to be Exported:	Yes
Intended Deregistration Date:	18 Nov 2018
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS 1.8 AUTO
Primary Colour:	Silver
Manufacturing Year:	2009
Engine No.:	1ZZ4904133
Chassis No.:	MR053ZEE206114390
Maximum Power Output:	97.0 kW (130 bhp)
Open Market Value:	\$20,071.00
Original Registration Date:	23 Jun 2009
First Registration Date:	23 Jun 2009
Transfer Count:	2
Actual ARF Paid:	\$20,071.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	22 Jun 2019
PARF Rebate Amount:	\$10,035.00

Intended COE Rebate Details

COE Expiry Date:	22 Jun 2019
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$7,501.00
COE Rebate Amount:	\$445.00
Total Rebate Amount:	\$10,480.00

The information contained herein is correct as at 18 Nov 2018

OK