

22/03/2002

SS. REC. BY:

REF:

CS/SN1018020928/Kapn2

Special Instruction:

Survivor

Meyman

ASSIGNMENT (Office)

From (Person):

Thelma Chou

of

SMO

Date/Time:

20-11-2018 11:29am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLW 5126A

Insured:

SLP 3518C

at Workshop m/s

Optima Werkz

Tel:

6481 522

of

9A Serangoon North Ave 5

Policy No:

DIBMTPV01009412

Claim No:

CMT01805055

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

15/11/2018

CA / REV / REP. / REV 24 HRS w/p

21-11-2018 @ 2pm

H.O.D. Endorsement:

Date/Time:

20-11-2018 11:30am

Person Contacted:

Lily

Vehicle-IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SLW 5126A - x

SLP 3518C - x

21/11/18 @

2.01pm revised to Thelma Chou via Meyman.

\$1832.72 email & Confirm (Red to 1459.36, 44%)

REF: SMO

Murni

ASSIGNMENT

From:

Date: 21.11.2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SLW 5126A

at Workshop n/s

Optima Werkz

of

9A Serangoon North Ave 5

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

2pm



Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

03 days

Res.: Yes or No

Lum Sum:

1-B.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLW 5126A Yr Regn: 02 18

Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mazda 3

C.C.

1486

Colour:

M. Blue

A/C: Insured / Std / NI / NA

Sp. Reading

8512

T/Radio: Insured / Std / NI / NA

Eng/No:

Ch/No:

JN 63N22A8140161866

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / M/Rim or

Tyre Size:

F:

205/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

9

mm

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

15 / 11 / 18

D.O.I.

21 / 11 / 18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S 1st

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

22/11 Rm pass to Catherine

RECEIVED 22 FEB 2019

Date/Time, File Pass to?



: Preli. Report

1) 22/12 11:48



: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

3

Resurvey No. of Trip:

1

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Report Format:

MER-7P

Lump Sum / I.B.I. (\$

1832.72

250

10

260

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Somp Insurance Singapore Pte. Ltd.
50 Raffles Place
#05-01/06, Singapore Land Tower
Singapore 048623

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Thelma Choo

Date: 22 Nov 2018

Preliminary Advice

Insured Vehicle No : SLP3518C
TP Vehicle No : SLW5126A
Make : MAZDA 3
Date of Inspection : 21/11/2018
Inspection At : OPTIMA WERKZ PTE LTD (HQ)
9A SERANGOON NORTH AVE 5
SINGAPORE 554500

Accident Date : 15/11/2018
Assignment Date : 20/11/2018
Est. Duration of Repair : 3.00

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	3,292.08
Revised Amount	:S\$	1,832.72
Check Items (Estimated)	:S\$	0.00
Total	:S\$	1,832.72

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	16 Nov 2018		20 Nov 2018 11:29 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS			[Created by insurer]
Insured:	YU YIU SUN SUNNY, ID: S2603356Z, Tel: +6596814957, Email: ylusun@singnet.com.sg		
Main Claimant:	PYRO CARS PTE LTD, Co. Reg. No.: 201710328D		
Vehicle Reg. No.:	SLW5126A	Date of Loss:	15/11/2018 15:00 - :59
Claim Type:	TP / CMTD1805055	Policy/Cover Note No.:	D18MTPV01008412 (Comprehensive)
Vehicle Reg. No. (Insured):	SLP3518C	Policy No. (Claimant):	
		Excess:	
Repairer:	Optima Werkz Pte Ltd (HQ) 9A Serangoon North Ave 5, 554500 Serangoon - Tel:		
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Thelma Choo - 6322 4681]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 29/11/2018]		
Driver/Custodian (Insured):	YU YIU SUN SUNNY (57 / Male), NRIC: S2603356Z, Tel: +6596814957		

ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
There are no mail for this case.		

ALL ASSOCIATED TASKS					View All	Search Tasks	Create New Task	Complete	
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Owner ID:

Vehicle Details

Vehicle No.:

Vehicle to be Exported:

Intended Deregistration Date:

Vehicle Make:

Vehicle Model:

Primary Colour:

Manufacturing Year:

Engine No.:

Chassis No.:

Maximum Power Output:

Open Market Value:

Original Registration Date:

First Registration Date:

Transfer Count:

Actual ARF Paid:

Intended PARF Rebate Details

PARF Eligibility:

PARF Eligibility Expiry Date:

PARF Rebate Amount:

Intended COE Rebate Details

COE Expiry Date:

COE Category:

COE Period(Years):

QP Paid:

COE Rebate Amount:

Total Rebate Amount:

Company

0328D

SLW5126A

No

15 Nov 2018

MAZDA

MAZDA3 SEDAN 1.5 AT EU6

Blue

2017

P520454173

JM6BN22ABH0161866

88.0 kW (118 bhp)

\$14,934.00

19 Feb 2018

19 Feb 2018

1

\$14,934.00

Yes

18 Feb 2028

\$11,200.00

18 Feb 2028

A - Car up to 1600cc & 97kW (130bhp)

10

\$42,900.00

\$39,719.00

\$50,919.00

The information contained herein is correct as at 15 Nov 2018

OK

OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143

Tel : +65 6472 1313 Fax : +65 6472 2112

Branch office : 9A Serangoon North Ave 5 Singapore 554500 Tel : +65 6484 9919 Fax : +65 6481 1011

Co. Reg. No. 201212455W

Date: 19 NOVEMBER 2018

Third Party Insurer: SOMPO INSURANCE SINGAPORE

Vehicle No: SLW5126A

SINGAPORE PTE. LTD.

Model: MAZDA 3

Third Party Veh No: SLP3518C

Chassis: JM6BN22A8H0161866
(2018)

Date of Accident: 15 NOVEMBER 2018

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	FRONT BUMPER	1		<i>R</i> \$825.50 <i>X</i>
2	FRONT BUMPER CLIPS	10	\$5.50	<i>nn</i> \$55.00 <i>X</i>
3	FRONT BUMPER SIDE RETAINER LH	1		<i>nn</i> \$18.70 <i>X</i>
4	FRONT HEADLAMP LH	1		<i>cm</i> \$1,019.50 <i>✓</i>
5	FRONT FENDER LH	1		<i>Bn</i> \$333.90 <i>✓</i>
SUB TOTAL				\$2,252.60
LESS 20%				-\$450.52
PARTS TOTAL				\$1,802.08

LABOUR CHARGES:

TO REMOVE & REPLACED WITH PANEL BEATING ALL ACCIDENT PORTION

300
\$700.00

TO PUTTY & SPRAY PAINTING WITH SEALANT ALL ACCIDENT PORTION

400
\$500.00

TO TUFF KOTE / ANTI-RUST

300
\$60.00

TO CHECK WIRING, REPLACED WITH FOCUS HEADLAMP

200
\$80.00

TO DIAGNOSTIC CHECK & RESET MEMORY TO IDENTIFICATION STANDARD

nn \$150.00 *X*

LABOUR TOTAL \$1,490.00

PEI TING TOTAL \$3,292.08

Not Authorized
1.B.1
Resurvey B4 paint 3 days
@1832-72

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary work must be approved and is subject to final approval from LKK Auto Consultants Company

Acknowledged by repairer:

Signature:

Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO18020928/KQBN2

Date: 25/02/2019

REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D18MTPV01008412
Claimant Vehicle No :	SLW5126A	Insured Vehicle No :	SLP3518C
Date of Loss:	15/11/2018	Nature of Claim:	TP
		Claim No:	CMTD1805055

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLW5126A	Engine No:	P520454173
Make & Model:	MAZDA 3, 1.5 SEDAN EU6 (A)	Chassis No:	JM6BN22A8H0161866
Reg. Date:	19/02/2018 (Man. Year: 2017)	Odometer:	8512 km
Colour:	Metallic Blue		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Bridgestone 9 mm	Rear Left Side:	Bridgestone 9 mm
Front Right Side:	Bridgestone 9 mm	Rear Right Side:	Bridgestone 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,802.08	1,082.72	719.36	39.92
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,490.00	750.00	740.00	49.66
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,292.08	1,832.72	1,459.36	44.33
+ GST 7.00/7.00% (S\$)	230.45	128.29	102.16	44.33
Nett Amount (S\$)	3,522.53	1,961.01	1,561.52	44.33

INSPECTION

Date of Assignment:	20/11/2018		
Date Inspected:	21/11/2018	Inspected At:	Optima Werkz Pte Ltd (HQ) 9A Serangoon North Ave 5 Singapore 554500
Estimated Period of Repair:	3.0 days		

Adjuster: KENNETH KONG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 25 Feb 2019)
Parts: 143	MAZDA 3 1.5 SEDAN EU6 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLW5126A)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	825.50 FL	*- FL
2	10		*FRONT BUMPER CLIPS	Not Necessary	55.00 FL	*- FL
3	1		*FRONT BUMPER SIDE RETAINER LH	Serviceable	18.70 FL	*- FL
4	1		*FRONT HEADLAMP LH	Cracked	1,019.50 FL	*1,019.50 FL
5	1		*FRONT FENDER LH	Buckled	333.90 FL	*333.90 FL
Sub Total (S\$)					2,252.60	1,353.40
- List Item Discount on L Items 20.00/20.00% (S\$)					450.52	270.68
Total Parts (S\$)					1,802.08	1,082.72

F=Franchise part, L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE & REPLACED WITH PANEL BEATING ALL ACCIDENT PORTION	New	700.00	300.00
2	TO PUTTY & SPRAY PAINTING WITH SEALANT ALL ACCIDENT PORTION	New	500.00	400.00
3	TO TUFF KOTE/ANTI-RUST	New	60.00	30.00
4	TO CHECK WIRING,REPLACED WITH FOCUS HEADLAMP	New	80.00	20.00
5	TO DIAGNOSTIC CHECK & RESET MEMORY TO IDENTIFICATION STANDARD	New	150.00	0.00
Gross Labour Cost (S\$)			1,490.00	750.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >