

23/03/2007

ASS. REC. BY:

REF:

CS/SMD18020929/R19/bn2

Special Instruction:

Surveyor:

RASHI

ASSIGNMENT (Office)

MAMMEN

From (Person):

Ench Pau Long

of

SMD

Date/Time:

20112018 1123am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLN 8522S

Insured:

SLF 56R.

at Workshop m/s

MOVA

Tel:

6292 3892

of

Bik 1008 Bukit Merah Lane 3 # 01-04

Policy No:

D18MTPV01008085

Claim No:

CMTD1805016

Sum Insured:

Excess:

Make of Veh:

D.O.A.

15/11/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS wpi

23.11.2018 @ 3pm

H.O.D. Endorsement:

Date/Time:

20/11/2018 1142am

Person Contacted:

Nabilah

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SLN 8522S - x

SLF 56R - x

26/11/18 @ 4.14pm visited to Ench Pau Long via Merimen.

Road finalised final fig @ 6997.20, 4 days.

Cred @ 755.30, 10%

Signature: *[Signature]*

REF: SMO

3757F

ASSIGNMENT

From:
 Date: 23/11/2018
 Estimated Cost:
 OD: ☒ TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SLN 8522S
 at Workshop m/s: Mova Automotive
 of BIK 1008, Bkt Merah Lane 3 #01-04
 Insured:
 Policy No:
 Claims No:
 Sum Insured:
 Excess:
 (Client's Record)
 Make of Veh: 3pm owner waiting

<input checked="" type="checkbox"/>	<input type="checkbox"/>
N/S	O/S
<input type="checkbox"/>	<input type="checkbox"/>

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:
 IDAC Accident Rpt: Consistent? : Yes or No
 GIA / PR Seen: Consistent? : Yes or No
 Est. Repairs: 4 days Res.: Yes or No
 Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS ^{up}

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SLN 8522S Yr Regn: 2011 / MAR
 Type: ☒ Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Volvo XC90 2.5T C.C. 2521
 Colour: Black A/C: Insured / Std / NI / NA
 Sp. Reading: 139208 T/Radio: Insured / Std / NI / NA
 Eng/No:
 C/No: 4V1C25
 Gen. Cond: Good / ☒ Fair / Poor / Burnt
 Steering: ☒ In order / Jammed / Leaked / Burnt or
 Brake: ☒ In order / Jammed / Leaked / Burnt or
 Modi: Nil / ☒ Rim / STD A/Rim or
 Tyre Size: F: 235/60R18
 R: .

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Roadstone

Front
 R/Bal. 6 mm
 L/Bal. 6 mm
 D.O.A. 15/11/18
 Survey held at MOVA CBM
 Rear
 R/Bal. 6 mm
 L/Bal. 6 mm
 D.O.I. 23/11/18

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
 N/S FRT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 15 FEB 2019

[Signature]
 14/2/2019

Date/Time, File Pass to?
 1) 15/2 *[Signature]*
 Date/Time, File Return to?

Days Of Repair: 4
 Resurvey No. of Trip: 1

Survey Fee:
 Transportation:
 S + RS:
 Photos:
 Other:

Add Fee:
☐ Site Insp (\$
☐ Interview (\$
☐ Tech. Invs (\$
☐ Weekend (\$

Report Format: MEF-TP
 Lump Sum / I.B.I. (\$) 6993.20

TOTAL

250
10
260

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Sompo Insurance Singapore Pte. Ltd.
50 Raffles Place
#05-01/06, Singapore Land Tower
Singapore 048623

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: GNOH PAU LOONG

Date: 26 Nov 2018

Preliminary Advice

Insured Vehicle No	: SLF56R	Accident Date	: 15/11/2018
TP Vehicle No	: SLN8522S	Assignment Date	: 20/11/2018
Make	: VOLVO XC90	Est. Duration of Repair	: 4.00
Date of Inspection	: 23/11/2018		
Inspection At	: MOVA AUTOMOTIVE PTE LTD (BUKIT MERAH) BLK 1008, #01-04/06/08/94, BUKIT MERAH LANE 3 SINGAPORE 159722		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	7,748.50
Revised Amount	:S\$	6,333.00
Check Items (Estimated)	:S\$	985.50
Total	:S\$	7,318.50

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	16 Nov 2018 Sendback Est	19 Nov 2018 18:01 S\$7,748.50	20 Nov 2018 11:23 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

Show All

CLAIM SUBFOLDER DETAILS

Insured:	TAN LAY SUAN, ID: S1787441A, Tel: +6597685656, Email: MELISSA@SCTIN.COM.SG		
Main Claimant:	HWANG JIUNN WEI, ID: S7813757F		
Vehicle Reg. No.:	SLN8522S	Date of Loss:	15/11/2018 21:00 - :59 [91 Months and 21 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / CMTD1805016	Policy/Cover Note No.:	D18MTPV01008085 (Comprehensive)
Vehicle Reg. No. (Insured):	SLF56R	Policy No. (Claimant):	
		Excess:	
Repairer:	Mova Automotive Pte Ltd (Bukit Merah) Blk 1008, #01-04/06/08/94, Bukit Merah Lane 3, 159722 Bukit Merah - Tel: 62723892/64763333		
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by GNOH PAU LOONG - 63295217]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 29/11/2018]		
Driver/Custodian (Insured):	TAN LAY SUAN (51 / Female), NRIC: S1787441A, Tel: +6597685656		

ASSOCIATED MAIL RECEIVED

View All

Compose Case Mail

There are no mail for this case.



ALL ASSOCIATED TASKS

View All

Search Tasks

Create New Task

Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	3757F
Vehicle Details	
Vehicle No.:	SLN8522S
Vehicle to be Exported:	No
Intended Deregistration Date:	26 Nov 2018
Vehicle Make:	VOLVO
Vehicle Model:	XC90 2.5T A/T ABS D/AB 4WD 5DR TC
Primary Colour:	Black
Manufacturing Year:	2010
Engine No.:	B5254T4462346
Chassis No.:	YV1CZ5957A1566883
Maximum Power Output:	154.0 kW (206 bhp)
Open Market Value:	\$52,080.00
Original Registration Date:	25 Mar 2011
First Registration Date:	25 Mar 2011
Transfer Count:	1
Actual ARF Paid:	\$52,080.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	24 Mar 2021
PARF Rebate Amount:	\$31,248.00
Intended COE Rebate Details	
COE Expiry Date:	24 Mar 2021
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$75,789.00
COE Rebate Amount:	\$16,011.00
Total Rebate Amount:	\$47,259.00

The information contained herein is correct as at 26 Nov 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	16/11/2018 12:22
Date Of Accident	15/11/2018 11:00
Exact Location Of Accident	PUBLIC CARPARK BEHIND SEACARE HOTEL
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLN8522S
Insured/Policyholder	
Name Of Registered Owner	HWANG JIUNN WEI
NRIC No	S7813757F
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97659807
Alternative Phone No	OFFICE-NOPHONE
Vehicle Particulars	
Manufacturer	VOLVO
Model	XC90 2.5T A/T ABS D/AB 4WD 5DR TC
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	
Cover Note Number	

Driver

Name of Driver	HWANG JIUNN WEI
NRIC No	S7813757F
Date Of Birth	21/05/1978
Occupation	INDOOR
Date Of Driving Pass	04/05/1999
Driving Experience	19 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97659807
Fax Number	
Contact Number	OFFICE-NOPHONE
Email Address	NOEMAIL

Address	BLK 395 BUKIT BATOK WEST AVENUE 5 #10-438
Postcode	650395
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLIDED INTO PARKED VEHICLE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLF56R
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	MR ALEX
NRIC/Passport Number	
Contact Number	96310470
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature

Date & Time: 16/11/2018

1235 hrs

Sketch Plan Pg. 1 of 2

Driver's Signature

(If driver is not the policyholder)

Date & Time:



Reporting Centre Personnel's Signature

Name:


NRIC/FIN No.:

SKETCH PLAN

Public carpark behind Seacane Hotel.

A: SW 8522-S

B: SLF 56R



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

LICENSE PLATE: SW 8522-S	ACCIDENT DATE & TIME: 15.11.2018
CONTACT NUMBER: 9765 9807	E-MAIL ADDRESS:
LOCATION: Public carpark behind Seacane Hotel.	
My car A (SW 8522-S) was parked at the above mentioned carpark and car B (SLF 56R) hit my front left area while reversing.	
I was not in the vehicle when incident happen, a note ^{was} by left	
car B on my windscreen by car B owner.	
NOTE: PLEASE NOTE THAT YOUR INSURER MAY HAVE 14 DAYS TIME FRAME FOR YOU TO SUBMIT AN OWN DAMAGE CLAIM UNDER YOUR OWN POLICY. PLEASE CHECK YOUR POLICY FOR MORE INFORMATION	
Please state:	
<input type="checkbox"/> Claim Own Policy <input checked="" type="checkbox"/> Claim Third Party <input type="checkbox"/> Claim OD/TP at other workshop <input type="checkbox"/> Reporting Only	

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time: 16/11/2018

1235 hrs

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:



Main Office : No. 22, Jalan Kilang, Singapore 159419
Tel: 6476 3333 Fax: 6271 5891

Service Centre : Block 1008, Bukit Merah Lane 3,
#01-04/06/08/115, Singapore 159722
Tel: (65) 6476 3333 (8 Lines) Fax: (65) 6270 8314
www.mova.com.sg
GST Reg. No: M2-0088864-2

Mova Spray Centre
2K Oven Spray Painting System

Power-M Automotive Pte Ltd
Specialise in Car Air-con Services,
Car Audio & Hi-Fi System.

Hilton Car Rental Centre
Hilton Auto Trading
Dealing in New/Used Cars, Hire Purchase & Insurance.



TP INSURER:
TAN LAY SUAN

Sompo Insurance Singapore Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:	D18MTPV01008085	Date of Loss:	15/11/2018
Vehicle Reg. No.:	SLN8522S	Driveable?	
Party At Fault:	UNKNOWN		
Driver (Insured):	TAN LAY SUAN		
Make/Model:	VOLVO XC90, 2.5 T ABS AIRBAG (A)	Vehicle Reg. Date:	25/03/2011
Vehicle Colour:	BLACK	Chassis No:	YV1CZ5957A1566883
Engine No:	L15B5461811		
Odometer:	0 KM		
Paint Type:			
List Item Discount:	10.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	4		
Description of Accident/Loss	REFER TO ATTACHED.		
Present Location:	MOVA AUTOMOTIVE PTE LTD (BUKIT MERAH)		

COST OF CLAIMS

	Amount
Parts	6,448.50
Miscellaneous Items	0.00
Labour	1,300.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	7,748.50
+ GST 7.00% (\$\$)	542.40
Nett Amount (\$\$)	8,290.90

This claim is handled by: MONITHA GUNASEKARAN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 19 Nov 2018)

Parts: M1-SUV VOLVO XC90 2.5 T ABS AIRBAG (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLN8522S)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*HEADLAMP LH <i>pho</i>	10.00	0.00	*1,250.00 FL
2	1		*HEADLAMP BRACKET /FRAME LH <i>? Repair</i>	10.00	0.00	*220.00 FL <i>R</i>
3	1		*HEADLAMP CLIPS LH OUTER <i>rec</i>	10.00	0.00	*48.00 FL <i>96</i>
4	1		*FRONT BUMPER <i>de</i>	10.00	0.00	*1,890.00 FL
5	1		*FRONT BUMPER CORNER PAD LH (ROUGH BLACK) <i>sch</i>	10.00	0.00	*350.00 FL
6	1		*FRONT BUMPER BASE <i>? CRK</i>	10.00	0.00	*380.00 FL
7	1		*FRONT BUMPER AIR GRILLE WITH CHROME LH <i>MIS</i>	10.00	0.00	*170.00 FL
8	1		*FRONT BUMPER SIDE RETAINER LH <i>AM</i>	10.00	0.00	*99.00 FL
9	1		*FRONT BUMPER SPONGE <i>? fsc</i>	10.00	0.00	*245.00 FL <i>X</i>
10	10		*FRONT BUMPER CLIPS <i>rec</i>	10.00	0.00	*60.00 FL
11	1		*FRONT FENDER LH <i>ph</i>	10.00	0.00	*1,650.00 FL
12	1		*FRONT FENDER ARCH GARNISH LH <i>de</i>	10.00	0.00	*175.00 FL
13	12		*FRONT FENDER ARCH GARNISH RIVET <i>rec</i>	10.00	0.00	*78.00 FL
14	1		*FRONT FENDER COWLING LH <i>Taken</i>	10.00	0.00	*240.00 FL
15	10		*FRONT FENDER COWLING CLIPS <i>rec</i>	10.00	0.00	*60.00 FL
16	1		*FRONT FENDER BRACE PANEL LH <i>? 44?</i>	10.00	0.00	*250.00 FL
17	1		*FRONT BUMPER REINFORCEMENT - CHECK	10.00	0.00	-
18	1		*FRONT FENDER COWLING UNDER COVER LH - CHECK <i>?</i>	10.00	0.00	-
19	1		*FRONT FOGLAMP - CHECK <i>*?</i>	10.00	0.00	-
20	1		*FRONT WHEELHOUSE PANEL LH - REPAIR	10.00	0.00	-
21	1		*FRONT CHASSISMEMBER LH - REPAIR	10.00	0.00	-
Sub Total (\$\$)						7,165.00
- List Item Discount on L Items (\$\$)						716.50
Total Parts (\$\$)						6,448.50

F=Franchise part, L=ListItemDisc.

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items


There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TO INSPECT FRONT LIGHTING MECHANISM	New 30	60.00
2	TO KNOCK & STRAIGHTEN ON WHEELHOUSE PANEL LH & FRONT CHASSIS MEMBER LH TO REPLACE ITEMS. REALIGN CONNECTION	New 450 400	600.00
3	TO RUST PROOF ON REPAIRED AREAS	New 40	80.00
4	TO SPRAY PAINT ON REPAIRED AREAS	New 400	500.00
5	TO CHECK WHEEL ALIGNMENT	New 17 X	80.00
Gross Labour Cost (S\$)			1,300.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >


 26/11/18
 Paul
 Hy 900/10068
 4 days
 HS
 23/11/18 @ 1520
 Resy after repair



Main Office : No. 22, Jalan Klang, Singapore 159419
Tel: 6476 3333 Fax: 6271 5891

Service Centre : Block 100B, Bukit Merah Lane 3,
#01-04/06/08/115, Singapore 159722
Tel: (65) 6476 3333 (8 Lines) Fax: (65) 6270 8314
www.mova.com.sg
GST Reg. No: M2-0088864-2

Mova Spray Centre
2K Oven Spray Painting System
Power-M Automotive Pte Ltd
Specialise In Car Air-con Services,
Car Audio & Hi-Fi System.
Hilton Car Rental Centre
Hilton Auto Trading
Dealing In New/Used Cars, Hire Purchase & Insurance.



TP INSURER:
TAN LAY SUAN

Sompo Insurance Singapore Pte. Ltd. (HQ)

OK133233

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:	D18MTPV01008085	Date of Loss:	15/11/2018
Vehicle Reg. No.:	✓ SLN8522S	Driveable?	
Party At Fault:	UNKNOWN		
Driver (Insured):	TAN LAY SUAN		
Make/Model:	VOLVO XC90, 2.5 T ABS AIRBAG (A)	Vehicle Reg. Date:	25/03/2011
Vehicle Colour:	BLACK	Chassis No:	YV1CZ5957A1566883
Engine No:	L15B5461811		
Odometer:	0 KM		
Paint Type:			
List Item Discount:	10.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	4		
Description of Accident/Loss	REFER TO ATTACHED.		
Present Location:	MOVA AUTOMOTIVE PTE LTD (BUKIT MERAH)		

COST OF CLAIMS

	Amount
Parts	6,448.50
Miscellaneous Items	0.00
Labour	1,300.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	7,748.50
+ GST 7.00% (\$\$)	542.40
Nett Amount (\$\$)	8,290.90

This claim is handled by: MONITHA GUNASEKARAN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 19 Nov 2018)

Parts: M1-SUV VOLVO XC90 2.5 T ABS AIRBAG (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLN8522S)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*HEADLAMP LH <i>980/</i>	10.00	0.00	*1,250.00 FL
2	1		*HEADLAMP BRACKET / FRAME LH <i>? repair</i>	10.00	0.00	*220.00 FL
3	1	<i>+1 = 2 pcs</i>	*HEADLAMP CLIPS LH OUTER <i>rec</i>	10.00	0.00	48+ *48.00 FL
4	1		*FRONT BUMPER <i>de</i>	10.00	0.00	*1,890.00 FL
5	1		*FRONT BUMPER CORNER PAD LH (ROUGH BLACK) <i>sc</i>	10.00	0.00	*350.00 FL
6	1		*FRONT BUMPER BASE <i>? XLT</i>	10.00	0.00	*380.00 FL
7	1		*FRONT BUMPER AIR GRILLE WITH CHROME LH <i>M/S</i>	10.00	0.00	*170.00 FL
8	1		*FRONT BUMPER SIDE RETAINER LH <i>M/S</i>	10.00	0.00	*99.00 FL
9	1		*FRONT BUMPER SPONGE <i>? X</i>	10.00	0.00	*245.00 FL
10	10		*FRONT BUMPER CLIPS <i>rec</i>	10.00	0.00	*60.00 FL
11	1		*FRONT FENDER LH <i>M</i>	10.00	0.00	*1,650.00 FL
12	1		*FRONT FENDER ARCH GARNISH LH <i>de</i>	10.00	0.00	*175.00 FL
13	12		*FRONT FENDER ARCH GARNISH RIVET <i>rec</i>	10.00	0.00	*78.00 FL
14	1		*FRONT FENDER COWLING LH <i>Taken</i>	10.00	0.00	*240.00 FL
15	10		*FRONT FENDER COWLING CLIPS <i>rec</i>	10.00	0.00	*60.00 FL
16	1		*FRONT FENDER BRACE PANEL LH <i>? Bt</i>	10.00	0.00	*250.00 FL
17	1		*FRONT BUMPER REINFORCEMENT - CHECK <i>? repair</i>	R 10.00	0.00	-
18	1		*FRONT FENDER COWLING UNDER COVER LH - CHECK <i>? repair</i>	R 10.00	0.00	-
19	1		*FRONT FOGLAMP - CHECK <i>? X</i>	R 10.00	0.00	-
20	1		*FRONT WHEELHOUSE PANEL LH - REPAIR	R 10.00	0.00	-
21	1		*FRONT CHASSISMEMBER LH - REPAIR	R 10.00	0.00	-

F=Franchise part, L=Liaison D'sc.

Sub Total (S\$) 6748.00 7,165.00
 - List Item Discount on L Items (S\$) 108 716.50
 Total Parts (S\$) 6073.20 6,448.50

Report was unsubmitted during this print-out.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO INSPECT FRONT LIGHTING MECHANISM	New	30 60.00
2	TO KNOCK & STRAIGHTEN ON WHEELHOUSE PANEL LH & FRONT CHASSIS MEMBER LH. TO REPLACE ITEMS. REALIGN CONNECTION	New	450 600.00
3	TO RUST PROOF ON REPAIRED AREAS	New	40 80.00
4	TO SPRAY PAINT ON REPAIRED AREAS	New	400 500.00
5	TO CHECK WHEEL ALIGNMENT	New	X 80.00
Gross Labour Cost (\$)			920.00 1,300.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

6073.20
 Part : \$ 6748.00
 Labour : \$ 920.00
\$ 7668.00

6993.20
4 days

Paul
 Hy 90010068

4 days

H/S → PBP

23/11/18 @ 1520

Resy after repair
 Before

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO18020929/R1QBN2

Date: 15/02/2019

REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D18MTPV01008085
Claimant Vehicle No :	SLN8522S	Insured Vehicle No :	SLF56R
Date of Loss:	15/11/2018	Nature of Claim:	TP
		Claim No:	CMTD1805016

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLN8522S	Engine No:	B5254T4462346
Make & Model:	VOLVO XC90, 2.5 T ABS AIRBAG (A)	Chassis No:	YV1CZ5957A1566883
Reg. Date:	25/03/2011 (Man. Year: 2010)	Odometer:	139208 km
Colour:	Black		
Engine Capacity:	2521 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/60 R18	Rear Tyre Size:	235/60 R18
Front Left Side:	Roadstone 6 mm	Rear Left Side:	Roadstone 6 mm
Front Right Side:	Roadstone 6 mm	Rear Right Side:	Roadstone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,448.50	6,073.20	375.30	5.82
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,300.00	920.00	380.00	29.23
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	7,748.50	6,993.20	755.30	9.75
+ GST 7.00/7.00% (S\$)	542.40	489.52	52.88	9.75
Nett Amount (S\$)	8,290.90	7,482.72	808.18	9.75

INSPECTION

Date of Assignment:	20/11/2018	Present Location:	Mova Automotive Pte Ltd (Bukit Merah)
Date Inspected:	23/11/2018	Inspected At:	Mova Automotive Pte Ltd (Bukit Merah)
			Blk 1008, #01-04/06/08/94, Bukit Merah
			Lane 3
			Singapore 159722

Estimated Period of Repair: 4.0 days

Adjuster: MOHD RASUL

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 15 Feb 2019)
Parts:	M1-SUV	VOLVO XC90 2.5 T ABS AIRBAG (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLN8522S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*HEADLAMP LH	Broken	1,250.00 FL	*1,250.00 FL
2	1	*HEADLAMP BRACKET /FRAME LH	Repair	220.00 FL	*- FL
3	2	*HEADLAMP CLIPS LH OUTER	Necessary	48.00 FL	*96.00 FL
4	1	*FRONT BUMPER	Deformed	1,890.00 FL	*1,890.00 FL
5	1	*FRONT BUMPER CORNER PAD LH (ROUGH BLACK)	Scratched	350.00 FL	*350.00 FL
6	1	*FRONT BUMPER BASE	Cracked	380.00 FL	*380.00 FL
7	1	*FRONT BUMPER AIR GRILLE WITH CHROME LH	Missing	170.00 FL	*170.00 FL
8	1	*FRONT BUMPER SIDE RETAINER LH	Necessary	99.00 FL	*99.00 FL
9	1	*FRONT BUMPER SPONGE	Serviceable	245.00 FL	*- FL
10	10	*FRONT BUMPER CLIPS	Necessary	60.00 FL	*60.00 FL
11	1	*FRONT FENDER LH	Bent	1,650.00 FL	*1,650.00 FL
12	1	*FRONT FENDER ARCH GARNISH LH	Deformed	175.00 FL	*175.00 FL
13	12	*FRONT FENDER ARCH GARNISH RIVET	Necessary	78.00 FL	*78.00 FL
14	1	*FRONT FENDER COWLING LH	Torn	240.00 FL	*240.00 FL
15	10	*FRONT FENDER COWLING CLIPS	Necessary	60.00 FL	*60.00 FL
16	1	*FRONT FENDER BRACE PANEL LH	Bent	250.00 FL	*250.00 FL
17	1	*FRONT BUMPER REINFORCEMENT - CHECK (NPA)	Repair	-	-
18	1	*FRONT FENDER COWLING UNDER COVER LH - CHECK (NPA)	Repair	-	-
19	1	*FRONT FOGLAMP - CHECK (NPA)	Repair	-	-
20	1	*FRONT WHEELHOUSE PANEL LH - REPAIR (NPA)	Repair	-	-
21	1	*FRONT CHASSISMEMBER LH - REPAIR (NPA)	Repair	-	-

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	7,165.00	6,748.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	716.50	674.80
Total Parts (\$\$)	6,448.50	6,073.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO INSPECT FRONT LIGHTING MECHANISM	New	60.00	30.00
2	TO KNOCK & STRAIGHTEN ON WHEELHOUSE PANEL LH & FRONT CHASSIS MEMBER LH.TO REPLACE ITEMS. REALIGN CONNECTION	New	600.00	450.00
3	TO RUST PROOF ON REPAIRED AREAS	New	60.00	40.00
4	TO SPRAY PAINT ON REPAIRED AREAS	New	500.00	400.00
5	TO CHECK WHEEL ALIGNMENT	New	80.00	0.00
Gross Labour Cost (S\$)			1,300.00	920.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >