

cost plus 10%

AUTO BEST MOTOR SERVICES

BLK 3006 UBI ROAD 1, #01-362, SINGAPORE 408700

Tel: 6756 6932 / 6746 8978 / Fax: 6745 8669 / HP: 9745 6932 (AH CHOE)

To: CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

Estimate For Own Damage Claim

Name of Insured: M/S ISO DELIGHT PTE LTD

Co Reg No.: 200918960G

Policy Number: DMCVSN1816211800

Regn Number: GBH3919P

Vehicle Make & Model: TOYOTA DYNA

Accident Date: 11/NOVEMBER/2018

not authorized
LKR

p/p 3
take photo. After repair
including spare parts.

54.
excess @ 500/-

QTY List Items:

1	Front bumper
1	Front bumper fog lamp - RH
1	Front bumper fog lamp cover <i>MH</i>
2	Front bumper brackets - L/R @ 241.50
1	Front chassis crossmember - CTR
1	Front headlamp - RH
1	Front step garnish - RH
2	Front shock absorbers - L/R @ 189.60
2	Front upper arms - L/R @ 1388.90
2	Front lower arms - L/R @ 757.20
2	Front lower arm ball joints - L/R @ 241.60
1	Front anti roll bar
2	Front anti roll bar links - L/R @ 89.65
2	Front knuckle arms - L/R @ 693.50
2	Front wheel hubs - L/R @ 421.60
2	Front wheel bearings - L/R @ 190.65
1	Front steering rack assy
1	Front steering rack universal joint
1	Front steering rack crossmember
2	Engine mountings @ 155.60
1	Gear box mounting
1	Radiator assy
1	Radiator bottom hose
1	Radiator fan cowling
1	Air intercooler
2	Rear shock absorbers - L/R @ 189.60
1	Rear leaf spring - RH
1	Rear leaf spring "U" bolt bracket - RH
1	Rear axle housing
1	Rear wheel hub shaft - RH
2	Rear wheel hub shaft oil seals @ 112.60
2	Rear wheel hub shaft bearings @ 166.50

	Amount \$
<i>no/2011</i>	561.60
<i>320</i>	341.65
<i>mes</i>	110.43
<i>11</i>	483.00 <i>x</i>
<i>11</i>	645.50 <i>x</i>
<i>11</i>	740.63 <i>x</i>
	281.90 <i>?</i>
<i>ols but</i>	379.20 <i>12C</i>
	2,777.80 <i>?</i>
<i>ols but</i>	1,514.40 <i>12C</i>
	483.20 <i>?</i>
	415.00 <i>?</i>
	179.30 <i>?</i>
	1,387.00 <i>?</i>
	843.20 <i>?</i>
	381.30 <i>?</i>
	3,481.65 <i>?</i>
	321.60 <i>?</i>
<i>no/2011</i>	2,245.63
	311.20 <i>?</i>
	162.60 <i>?</i>
	2,119.50 <i>?</i>
	142.20 <i>?</i>
	281.90 <i>?</i>
	1,232.56 <i>?</i>
	379.20 <i>?</i>
	761.90 <i>?</i>
	186.50 <i>?</i>
<i>su</i>	4,352.23 <i>x</i>
<i>na</i>	435.23 <i>x</i>
<i>na</i>	225.20 <i>?</i>
<i>11</i>	333.00 <i>x</i>

Regn Number: GBH3919P

Vehicle Make & Model: TOYOTA DYNA

- 1 Rear propeller shaft
- 1 Rear wheel guard - RH
- 1 Rear exhaust silencer box

11 1,203.56 x
 2 261.90 x
 2 961.50 x

Sub - Total 30,924.17
 Less 25% 7,731.04
 Total List 23,193.13

Special Nett Items:

- 1 Front no. plate
- 1 Front wheel rim - RH
- 1 Front tyre - RH
- 1 bot Power steering fluid
- 1 bot Brake fluid
- 1 bot Radiator coolant
- 1 Rear wheel rim - RH
- 2 Rear tyres - RH @ 180
- 1 tin Gear oil

301 40.00 14
 250.00?
 240.00?
 50.00?
 40.00?
 65.00?
 180.00?
 360.00?
 120.00?

Total Special Nett 1,345.00

Labour Charges:

- Towing charges
- To check front electrical wiring
- To remove, refix front undercarriage
- To remove, refix rear undercarriage
- To check wheel alignment
- To remove, refix engine parts
- To apply putty, sand, respray painting & etc
- Panel beating, cut, weld, remove & replacing above parts

300.00 ? 341
 50.00 20
 650.00 350
 450.00 300
 120.00 60
 250.00 ?
 450.00 200
 600.00 300

Total Labour 2,870.00

ESTIMATE PARTS AND LABOUR GRAND TOTAL \$ 27,408.13

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: