2203/2002 ASS, REC. BY	REF	cs/TMI180	Naza Kled	30 Epecial Instruction	n:
Surveyor:	MIVII	ASSIGNME	NT (Office)	J~ F	
From (Person	Zheng Henyang			Date/Time:	20/11/18 @ gam
Estimated Cos	t:		Bill to:		
OD/TP W	STTP RES / OD RES / EV	A/INV/MV7CS	3	•	
To Inspect Ve	hicle No:	SHA 1813P		nsured: SIV	v 8259D
at Workshop i	n/s	comfort De	laro	Tel: 62	14 8300
of	Ę	sa Loyena D	Dive		
Policy No:	MH000848	, ,	Claim No: _ M	1805883	
Sum Insured:			Excess:		
Make of Veh: (Client's Record				D.O.A	18/11/2018
CA / REV /	REP. / REV 24 HRS	<b>(P</b> )		H O D Fee	orsement:
	·22am@20/11/18 P		yumani	Vehicle(IN)	OUT
Date/Time	Action/Instruction (			ruge consist	ency
	SHA (813P - CC	1711 1702038	8/Rlea3a	2' 20	A: 14/10/17
	SJW 8259D-CC3	-1M118016=	398/Klrd3		: 7/9/18
	-		13.1		

260

TOTAL

# ...CLAIM SUBFOLDER...(New Assignment)

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	A	tj Submitted	Ins Auth'ed	Status	
	19 Nov 2018 17:26 Sendback Est	19 Nov 2018 17:59 <b>\$\$6,633.42</b>	20 Nov 2018 09:01 Assign					New As	signment Case
P	1ain	Referen	nce	Cla	im Details		Documents		Show All
LAIM SU	SFOLDER DETA	ILS							
nsured:	CTPL, Co. Re	eg. No.: 199303821	R						
1ain Ilaimant:	CTPL								
/ehicle Reg. No.:	SHA1813P			ı	Date of Loss	18/11/2018 [ <b>0</b> Days From	23:00 - :59 m LTA Reg Date (M	an Yr)]	
Claim Type:	TP				Policy/Cover Note No.:				
/ehicle Reg. Vo. Insured):	SJW8259D				Policy No. (Claimant):				
					Excess:	S\$0.00			
epairer:	ComfortDelG	iro Engineering Pt	e Ltd (Loyang)	59 Loyang	g Drive, 508	969 Loyang - T	el: 6214 8300		
landling nsurer:		Insurance Singa						26416]	
djuster:	LKK Auto Co	nsultants Pte Ltd	(HQ) - Tel: 6256	5-3561	[Final Rp	due 29/11/	2018]		
Adj Asg. Remarks:	OUR INSD HA	VE NOT REPORT TH	E ACCIDENT, PLS	S. CHECK C	CONSISTENC	Y OF THE DAM	IAGE. THKS		
ASSOCIAT	ED MAIL RECE	IVED					View	V All Com	pose Case Ma
here are n	o mail for this cas	se.							
ALL ASSO	CIATED TASKS	Θ				View All	Search Tasks C	reate New Tas	sk Comple
Due Date	Priority	Type Task Grou	p Subject	Handle	er Assio	ned By	Completed On	Created	On Don
Due Date	1.1.01167	The man area		200000000					

# OMFORTDELGRO ENGINEERING

member of ComfortDelgro

### ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579701 Mainline - 65 6383 6280 Facsumie - 65 6280 9755

Workshops 59 Lovanor Drive Singapore 508969

24 Sencko Loop Singapore 755156 7 Sungel Kadur Way Singapore 725791 201 Value Industrial Dark A Singapore 768733

Date/Time20101993172018 11:48

Page : 1

ARC Repair TP(CLSO)1	JOB CARD	Sales Order:	JC NO.: 305240656
		REGN NO.: SHA1813P	MILEAGE
7010045	LTD	MAKE: HYUNDAI	FUEL EF
383 SIN MING DRIVE Singapore SINGAPORE 575717		MODEL IONIQ(G2)	8.11.2018 23:50
65508755 (O)		YR OF MANU 03.07.2018	TARGET DATE
D NO.		CHASSIS CODE KMHC851CVJU103363	COMPLETION DATE/TIME:
	COMFORT TRANSPORTATION PTE 7010045 383 SIN MING DRIVE Singapore SINGAPORE 575717 65508755 (0)	COMFORT TRANSPORTATION PTE LTD 7010045 383 SIN MING DRIVE Singapore SINGAPORE 575717 65508755 (O)	COMFORT TRANSPORTATION PTE LTD 7010045 383 SIN MING DRIVE Singapore SINGAPORE 575717 65508755 (O)  REGN NO.: SHA1813P  MAKE: HYUNDAI  MODEL IONIQ(G2) 1  YR OF MANU 03.07.2018  CHASSIS CODE RMMC851CVJU103363

JOB DESCRIPTION


Accident Date: 18.11.2018

NATURE: 3P 18.11.2018

S/NO

LABOR CODE

1 ...



			CUSTOMER'S SIGNATURE	
	Exit Pass			
CHIANG	Vehicle No.:	SHA1813P		
Signature/Date	Name of Service To be kept by \$		Date	
	Signature/Date	CHIANG  Vehicle No.:  Signature/Date  Name of Service	Exit Pass  CHIANG  Vehicle No.: SHA1813P  Signature/Date Name of Service Advisor	CHIANG  Vehicle No.: SHA1813P  Signature/Date Name of Service Advisor  Date

#### SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver,
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

<ol><li>By the lodgement of this report to the insurers, you hereby consaforesaid.</li></ol>	sent to the archiving of this report at the centre and to copies of the report being made available
	ACCIDENT STATEMENT
Date Of Report	19/11/2018 10:28
Date Of Accident	18/11/2018 23:50
Exact Location Of Accident	SHEARES LINK T JUNCTION OF BAYFRONT AVE.
Country/State of Loss	SINGAPORE
	DETAILS OF OWN VEHICLE
Vehicle Registration Number	SHA1813P
Insured/Policyholder	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768
Vehicle Particulars	
Manufacturer	HYUNDAI
Model	IONIQ HYBRID
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI
Insurance Company	
Name of Insurance Company	INDIA INTERNATIONAL INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT

Fleet Policy YES

Policy Number MCOM0015

Cover Note Number

#### Driver

Name of Driver TAN KOK CHIEW NRIC No S1284619C Date Of Birth 03/10/1958 Occupation OUTDOOR Date Of Driving Pass 29/02/1980

**Driving Experience** 38 YEARS AND 8 MONTHS

Gender MALE

Mobile Number (LOCAL) +65-94389986

Fax Number

Contact Number

EMail Address NOEMAIL

BLK 493C TAMPINES STREET 43 Address

#09-302 522493

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own

Postcode

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

COLLISION - HEAD TO REAR

OTHER - TAXI DRIVER

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles involved in the accident

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by ambulance?

NO

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

3

NAME:

: MALE

Passenger 2

Passenger 1

GENDER: NAME:

GENDER:

: MALE

**Details of Police Action** 

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

REFER ATTACHED

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

YES

Remarks/ Reasons:

Was there any audio recorded?

NO

**DETAILS OF OTHER VEHICLE PROPERTY 1** 

Vehicle Registration Number Vehicle Make/Model/Colour

SJW8259D

**Details Of Properties** 

PRIVATE CAR

Vehicle Category Name of Driver

PARAMASIVAM SELVARAYAR

NRIC/Passport Number

S7568763Z

Contact Number

92489077

Address

Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

FRONT

#### Sketch Plan Pg. 1

#### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
- 7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s)
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

COMFORT TRANSPORTATION PTE LTD CO. REG. NO. 199303821R

Policyholder's Signature Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No .:

GIARIAC SketchPlanForm, V3

Baybrow ave SKETCH PLAN DESCRIBE CIRCUMSTANCES OF THE ACCIDENT et edocat 5350 hrs A Was bay front into 40 Stop Was Maht Crossing Second pedestrian ew Came Vehicle A back and Sustain damage DECLARATION I/We declare the foregoing particulars are true in every respect. COMFORT TRANSPORTATION PTE LTD CO. REG. NO. 199303821R

Driver's Signature

Date & Time:

(If driver is not the policyholder)

Policyholder's Signature

GIARMC SketchPlanForm\_V3


Date & Time:

Page 5 of 18

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:











## ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

59 Loyang Drive Singapore 508969 Tel: 6214 8300

TP INSURER:

Tokio Marine Insurance Singapore Ltd (HQ)

CTPL

Singapore

Chiems

PARTICULARS OF CLAIM

Claim Type:

THIRD PARTY

Ref. No:

18/11/2018

Policy No: Vehicle Reg. No.:

.:

SHA1813P

Driveable?

Date of Loss:

YES

Party At Fault:

UNKNOWN

010 0 0 10 192N

Make/Model:

HYUNDAI AE IONIQ HEV DCT SR, 1.6 (A) Vehicle Reg. Date: 18/11/2018

Vehicle Colour:

BLUE

Gen Condition:

**EXCELLENT** 

Engine No:

G4LEJU045565

Chassis No:

KMHC851CVJU103363

Odometer:

37979 KM

Paint Type:

List Item Discount:

20.00 %

Total Loss?

NO

Est. Duration of

Repair (day)

4

Present Location:

COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)

COST OF CLAIMS		Amount
Parts		4,628.42
Miscellaneous Items		10.00
Labour		1,995.00
Paintwork Labour		0.00
Towing		0.00
	Gross Total (S\$)	10761.50 6,633.42
	+ GST 7.00% (S\$)	464.34
	Nett Amount (S\$)	7,097.76

This claim is handled by: JUMANI BIN MASUDIN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source:

(Last Synchronised: 19 Nov 2018)

Parts:

N/A

HYUNDAI AE IONIQ HEV DCT SR 1.6 (A) (Model not available in database)

Labour:

Repairer's

(Price-denominated Standard List)

Print Code: ComfortDelGro Engineering Pte Ltd/SHA1813P/19/11/2018 17:59

Validity:

These estimates are valid only if they contain the print code (above) on all estimate pages, running page

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*BOOT LID	20.00	0.00	*2,480.40 FL
2	1		*BOOT LID LOCK × 5th	20.00	0.00	*224.00 FL
3	1		*BOOT LID HEMBLEM	20.00	0.00	*47.90 FL
4	1		BOOT LID II EIVIBLEIVI	20.00	0.00	*28.00 FL
5	1		*EMBLEM HYBRID	20.00	0.00	*24.30 FL
6	1		*EMBLEM IONIQ	20.00	0.00	*31.30 FL
7	1		*EMBLEM -SYMBOL MARK	20.00	0.00	*28.00 FL
8	1		*BOOT LID LAMP LH X	20.00	0.00	*794.40 FL
9	1		*REAR BUMPER Public	20.00	0.00	*459.40 FL
10	1		*REAR BUMPER REINFORCEMENT *5**	20.00	0.00	*294.80 FL
11	2		*REAR BUMPER REINFORCEMENT BRACKET LH/RH X544	20.00	0.00	*276.20 FL
12	1		*REAR BUMPER CENTRE MOULDING ASSY	20.00	0.00	*451.25 FL
13	1		*REAR BUMPER LOWER CENTRE MOULDING ASSY	20.00	0.00	*270.10 FL
14	1		*REAR BUMPER SIDE BRACKET LH / /*	20.00	0.00	*33.10 FL
15	10		*REAR BUMPER COVER CLIPS	20.00	0.00	*22.00 FL
16	1		*REAR BUMPER UNDER CENTRE	20.00	0.00	*53.85 FL
17	1		*REAR BUMPER REFLECTOR LAMP LH	20.00	0.00	*31.90 FL
18	1		*REAR BUMPER SIDE UNDER LH	20.00	0.00	*27.50 FL
19	1		*BOOTLID COMFORT LOGO & TEL NO STICKER	0	0.00	*30.00 FS
20	1		*REAR BUMPER REVERSE SENSOR + , ~	0	0.00	*135.70 FS
F=Fra	nchise	part. S=SpcN	lett_L=ListItemDisc.			
			Sub Total (S\$)			5,744.10
			- List Item Discount on L Items (S\$)			1,115.68
			Total Parts (S\$)			4,628.42

ComfortDelGro Engineering Pte Ltd/SHA1813P/19/11/2018 17:59. Not valid without Reference section. Generated using Merimen e-Claims IEAS

Catima	taa ar	Minan	llaneous	14
Esilina	IPS OF	INVISCE	Hanenis	mame

No		Particulars		Amount	
<u>Mis</u>	cellar 1	OD/TP Case (Insurer)		10.00	/
			Sub Total (S\$)	10.00	

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labo	our Items		600
1	PANEL BEATING	New	800.00
2	SPRAY PAINTING	New	900.00 60
3	WIRING	New	50.00 20
4	TUFF KOTE	New	50.00 2
5	REMOVE/REFIX REVERSE SENSOR	New	120.00 3
6	TOWING FEE	New	75.0060
		Gross Labour Cost (S\$)	1,995.00

ComfortDelGro Engineering Pte Ltd/SHA1813P/19/11/2018 17:59. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Co = tants person notify
the Repairer of the following:
The Repairer of the followin

## ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

59 Loyang Drive Singapore 508969 Tel: 6214 8300

## (SUPPLEMENTARY)

TP INSURER:

Tokio Marine Insurance Singapore Ltd (HQ)

CTPL

Singapore

PARTICUL	ARS OF	CLAIM
----------	--------	-------

Claim Type:

THIRD PARTY

Ref. No:

Policy No:

MH000848

Date of Loss:

18/11/2018

Vehicle Reg. No.:

SHA1813P UNKNOWN Driveable?

YES

Party At Fault: Make/Model:

HYUNDAI AE IONIQ HEV DCT

Vehicle Reg.

18/11/2018

Vehicle Colour:

SR, 1.6 (A)

Date:

EXCELLENT

T : N

BLUE

Gen Condition:

EXCELLENT

Engine No: Odometer: G4LEJU045565 37979 KM Chassis No:

KMHC851CVJU103363

Paint Type:

List Item Discount:

20.00 %

Total Loss?

NO

Est. Duration of

Repair (day)

4

Present Location:

COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)

COST OF CLAIMS		Amount
Parts		3,888.08
Miscellaneous Items		0.00
Labour		240.00
Paintwork Labour		0.00
Towing		0.00
	Gross Total (S\$)	4,128.08
	+ GST 7.00% (S\$)	288.97
	Nett Amount (S\$)	4,417.05
	+ Previous Estimates (S\$)	7,097.76
	Claim Total (S\$)	11,514.81

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR	DETAI	LS

Reference

Part Source: (Last Synchronised: 07 Dec 2018)

Parts:

N/A

HYUNDAI AE IONIQ HEV DCT SR 1.6 (A) (Model not available in database)

Labour:

Repairer's

(Price-denominated Standard List)

Print Code: ComfortDelGro Engineering Pte Ltd/SHA1813P/07/12/2018 11:42

Validity:

These estimates are valid only if they contain the print code (above) on all estimate pages, running page

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

## Estimates on Parts

Qty	Part No.	Particulars	%Disc	%Depr	Amount
1		*BUMPER TOWING CAP	20.00	0.00	*51.60 FL *
1		PANEL ASSY QTR OUTER LH	20.00	0.00	*3,556.20 FL *
1		*EXTENSION ASSY QTR OUTER LH	20.00	0.00	*208.30 FL
1		*PANEL ASSY BACK But	20.00	0.00	*532.00 FL *
1		*TAIL LAMP -COMB LH / C+	20.00	0.00	*512.00 FL
nchise	part. L=ListItem	Disc			
		Sub Total (S\$)			4,860.10
		- List Item Discount on L Items (S\$)			972.02
		Total Parts (S\$)			3,888.08
	1 1 1 1	1 1 1 1	1 *BUMPER TOWING CAP 1 *PANEL ASSY QTR OUTER LH 1 *EXTENSION ASSY QTR OUTER LH 1 *PANEL ASSY BACK 1 *TAIL LAMP -COMB LH nchise part. L=ListItemDisc.  Sub Total (S\$) - List Item Discount on L Items (S\$)	1 *BUMPER TOWING CAP 20.00 1 *PANEL ASSY QTR OUTER LH 20.00 1 *EXTENSION ASSY QTR OUTER LH 20.00 1 *PANEL ASSY BACK 20.00 1 *TAIL LAMP -COMB LH 20.00 nchise part. L=ListItemDisc.  Sub Total (S\$) - List Item Discount on L Items (S\$)	1 *BUMPER TOWING CAP 20.00 0.00 1 *PANEL ASSY QTR OUTER LH 20.00 0.00 1 *EXTENSION ASSY QTR OUTER LH 20.00 0.00 1 *PANEL ASSY BACK 20.00 0.00 1 *TAIL LAMP -COMB LH 20.00 0.00 1 *TAIL LAMP -COMB LH 20.00 0.00  Sub Total (\$\$) - List Item Discount on L Items (\$\$)

ComfortDelGro Engineering Pte Ltd/SHA1813P/07/12/2018 11:42. Not valid without Reference section. Generated using Merimen e-Claims IEAS

## Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

### Estimates on Labour

No	Particulars	Lab.Type	Amount	
Lab	our Items		/00	
1	RENOVE/REFIX REAR WINDSCREEN GLASS	New	120.00	
2	REMOVE/REFIX REAR UPHOLSTERY	New	120.00	50
		Gross Labour Cost (S\$)	240.00	

ComfortDelGro Engineering Pte Ltd/SHA1813P/07/12/2018 11:42. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

### LKK Auto Consultants hence notify the Repairer of the following:

- . To resurvey before/after spray painting
- . To display damaged part(s) during resourcey
- . Parts prices are subject to confirmation
- . Third party survey is on a "Without Prejudice" basis
- . No illegal modification(s) is allowed
- Supplementary item(s) must be recurveyed and is subject to final approval from incurance Company

Acknowledged by Repairer

Signature:

Date:

COMFORTDELGRO ENGINEERING

Our Jo	ob Ref	No :	3	05240656				ENGINEERING
Date		1	7	07/12/18			59 Lo	ortDelGro Engineering Pte Ltd yang Drive Singapore 508969 5546 8156
FINAL	IZATI	ON FO	RM				, uni	
То	:			LKK			Fax:	
Attn				KALVIN				
Vehic	le Reg	No.	: SHA18	13P		_		18/11/2018
				e repairs of the above	-mentio	ed vehicle	are as follows	:-
1.	The re	epair jo	b shall bill t	o:	ток	IO		SJW8259D
2.	The fi	nalized	amount sh	all be:				
	(a)	Spare	Parts after	List discount				\$ 6745.00
	(b)	Labou	r Charges					\$1490.00
		Total	for Part-By	-Part Repair Cost				\$ 8235.00
	(c.)	Total	for Lumpsu	(if applicable) m repair cost after Les Repair cost	ss:			1
<ul><li>3.</li><li>4.</li></ul>	We sl		at the abov	for repairs:	and Co		rking days.	ply from you within 7
5.			or your assis	stance.			confirm the e alized amount	estimates and
	Signa	iture :				Sig	nature:	//
	Name	:	CHIANG			Na	me :	Kalm
	Tel	:	62148314			Da	te :	10/12/8
	Fax	2	65468156	8				
For O	fficial	Use O	nlv					
		Item		Amount		Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Re	ental R	ate P/D	ay			YES		
2. Lo	ss of I	ncome	Paid			N		
3. St	ırvey F	ees						
5. Me of	edical l	rch Fee Fees (o if appli	n behalf	7.49				
Rema	arks:							

### COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 07.12.2018

Time: 11:51:02

Page: 1

COMPANY: THIRD PARTY'S CLAIMS (CAS)

CUSTOMER: 7010045

ADDRESS: COMFORT TRANSPORTATION PTE LTD

383 SIN MING DRIVE

SINGAPORE SINGAPORE 575717

65508755

JOB NO REGN NO MILEAGE

: 305240656 : SHA1813P : 0000000000

MAKE

: HYUNDAI

MODEL

: IONIQ(G2) : 03.07.2018

DATE OF REGN DATE/TIME IN

: 18.11.2018 23:50

ACCIDENT DATE : 18.11.2018

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

## RT REQUISITION

0001 04-01-0104-2256-G	IONIQ PANEL ASSY-TAIL GAT 1 2,480.40 20.00 1,984.32
0002 04-01-0104-2271-G	IONIQ EMBLEM-IONIQ 1 31.30 20.00 25.04
0003 04-01-0104-2270-G	IONIQ EMBLEM-HYBRID 1 24.30 20.00 19.44
0004 04-01-0104-2282-G	IONIQVC COVER-RR BUMPER# 1 459.40 20.00 367.52
0005 04-01-0104-2533-G	IONIQV2 MOULDING ASSY-RR 1 451.25 20.00 361.00
0006 04-01-0104-0851-G	IONIQVC REFLECTOR/REFLEX 1 31.90 20.00 25.52
0007 28-01-0103-0005-A	(I40/SONATA)REAR BOOT LOG 1 15.00 2.00- 15.00
0008 28-01-0103-0006-A	(I40/SONATA)REAR BOOT TEL 1 15.00 0.20 15.00
0009 04-01-0101-0111-G	HYUNDAI BUMPER COVER CLIP 10 L 22.00 20.00 17.60
0010 04-01-0104-2531-G	IONIQVC BRACKET ASSY-RR B 1 33.10 20.00 26.48
0011 04-01-0104-2544-G	IONIQVC CAP-RR HOOK 1 51.60 20.00 41.28
0012 04-01-0104-0576-G	IONIQVC PANEL ASSY-QUARTE 1 3,556.20 20.00 2,844.96
0013 04-01-0104-0710-G	IONIQVC EXTENSION ASSY-QT 1 208.32 20.00 166.66

### COMFORTDELGRO ENGINEERING PTE LTD

Date: 07.12.2018 Time: 11:51:02

Page: 2

REPAIR ESTIMATE

COMPANY: THIRD PARTY'S CLAIMS (CAS)

CUSTOMER: 7010045

ADDRESS: COMFORT TRANSPORTATION PTE LTD

383 SIN MING DRIVE

SINGAPORE SINGAPORE 575717

65508755

JOB NO

: 305240656

REGN NO

: SHA1813P

MILEAGE

: 0000000000

MAKE

: HYUNDAI

MODEL

: IONIQ(G2)

DATE OF REGN

: 03.07.2018

DATE/TIME IN

: 18.11.2018 23:50

ACCIDENT DATE : 18.11.2018

#### JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

0014 04-01-0104-2346-G IONIQ PANEL ASSY-BACK 1 532.00 20.00 425.60

04-01-0104-2395-G IONIQ LAMP ASSY-REAR COMB 1 513.45 20.00 410.76

512

SUB-TOTAL : 6,746.18

#### JOB NATURE

0000 L	PANEL BEATING	600.00
0001 23-502	SPRAYPAINT ON AFFECTED AREA	600.00
0002 17-01	CHECK ALL LIGHTING	20.00
0003 20-00	TUFF COAT ON AFFECTED PARTS.	20.00
0004 20-22	REMOVE/REFIX REVERSE SENSOR	30.00
0005 23-01	TOWING FEE	60.00

6 20-06-210R

REMOVE & REPLACE REAR W/SCREEN.

#### COMFORTDELGRO ENGINEERING PTE LTD

Date: 07.12.2018 Time: 11:51:02

Page: 3

REPAIR ESTIMATE

COMPANY: THIRD PARTY'S CLAIMS (CAS)

CUSTOMER: 7010045

ADDRESS: COMFORT TRANSPORTATION PTE LTD

383 SIN MING DRIVE

SINGAPORE SINGAPORE 575717

65508755

JOB NO

: 305240656

REGN NO

: SHA1813P

MILEAGE

: 0000000000

MAKE

: HYUNDAI

MODEL DATE OF REGN

: IONIQ(G2) : 03.07.2018

DATE/TIME IN

: 18.11.2018 23:50

ACCIDENT DATE : 18.11.2018

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

DATE:

0007 20-204 REMOVE/REFIX UPHOLSTERY ASST REPAIR

200.00 50

SUB-TOTAL : 1,650.00

TOTAL : 8,396.18

AUTHORISED: YES / NO

MVA NAME & SIGNATURE

DATE:

SURVEYOR NAME & SIGNATURE

Merimen e-Claims Page 1 of 1

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

LAIM SUE	BFOLDER TRACK	ING								
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Subi	mitted	Ins Auth'ed	Status		
Main	19 Nov 2018 17:26 Sendback Est	19 Nov 2018 17:59 <b>\$\$6,633.42</b>	20 Nov 2018 09:01 Edit Adj Rpt	S\$8,235.00 Edit Estimates	S\$8,23! View R	1		Pending for Report Cancel Ca		
Supp #1	07 Dec 2018 11:32	07 Dec 2018 11:42 <b>5\$4,128.08</b>	07 Dec 2018 11:42				(Combined)	Combined	with Main e Suppl.	
	Main	Refer	rence	Claim Deta	ils	$\Gamma$	Documents		Show All	
CLATM S	UBFOLDER DETA	ILS								
Insured:		eg. No.: 19930382	1R							
Main Claimant:	CTPL	•								
Vehicle Re No.:	SHA1813P	).		Date of L	oss: 18/11/2018 23:00 - :59 [4 Months and 15 Days From LTA Reg D		A Reg Date (N	Reg Date (Man Yr)]		
Claim Typ	e: <b>TP</b> / M1805	8883		Policy/Co Note No.		er MH000848 (Third Party Only) Coverage: 26/07/2018 - 25/07/2019		2019	9	
Vehicle Re No. (Insured):	SJW8259D			Policy No (Claiman						
				Excess:		750.00				
Repairer:	ComfortDelC	iro Engineering F	te Ltd (Loyang)	59 Loyang Drive, 5	08969 Loy	ang - Te	1: 6214 8300			
Handling Insurer:	100-00-00-00-00-00-00-00-00-00-00-00-00-						y Tay - 65926413]			
Adjuster:	29/11/2018		I (HQ) - Tel: 6256	-3561 [Handled	by KALVII	N ANG I	WEI KUN ] [Fin	al Rpt due		
Adj Asg. Remarks:	OUR INSD HA	VE NOT REPORT T	HE ACCIDENT, PLS	CHECK CONSIST	NCY OF TH	HE DAMA	AGE. THKS			
ASSOCIA	TED MAIL RECE	IVED					View Al	Compos	e Case Mail	
There are	no mail for this ca	se.								
ALL ASS	OCIATED TASKS	8			View A	II Se	arch Tasks Creat	e New Task	Complete	
Due Da		Type Task Gr	oup Subject	Handler A	signed By	, (	Completed On	Created Or	Done?	

Merimen e-Claims Page 1 of 2

### **Claim Documents**

SHA1813P (M1805883)

[SJW8259D]

TP

CTPL

Nov 18 2018 11:00PM

[CTPL]

ComfortDelGro Engineering Pte Ltd

Ass	essment Reports		1 per p	page 🔻	<b>V</b>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)		Thumbnail	Print
1	19/11/18 17:59	Repairer Estimates	0	Load HTM	
2	07/12/18 11:42	Repairer Estimates Suppl. #1	0	Load HTM	
Pho	otos/Images		3 per p	page 🔻	~
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Prin
1	20/11/18 18:46	General View	0	Load JPG	~
2	20/11/18 18:46	General View	0	Load JPG	<b>V</b>
3	20/11/18 18:46	General View	0	Load JPG	~
4	20/11/18 18:46	General View	Ð	Load JPG	V
5	20/11/18 18:46	General View	0	Load JPG	V
6	20/11/18 18:46	General View	Ð	Load JPG	~
7	20/11/18 18:46	General View	0	Load JPG	V
8	20/11/18 18:46	General View	0	Load JPG	V
9	20/11/18 18:46	General View	0	Load JPG	~
10	20/11/18 18:46	General View	0	Load JPG	<b>V</b>
11	20/11/18 18:46	General View	0	Load JPG	V
12	20/11/18 18:46	General View	0	Load JPG	V
13	20/11/18 18:46	General View	O	Load JPG	~
14	20/11/18 18:46	General View	Ð	Load JPG	V
15	20/11/18 18:46	General View	0	Load JPG	~
16	20/11/18 18:46	General View	0	Load JPG	V
17	20/11/18 18:46	General View	0	Load JPG	V
18	20/11/18 18:46	General View	0	Load JPG	<b>V</b>
19	20/11/18 18:46	General View	0	Load JPG	V
20	20/11/18 18:46	General View	O	Load JPG	V
21	20/11/18 18:46	General View	0	Load JPG	V
22	20/11/18 18:46	General View	0	Load JPG	V
23	20/11/18 18:46	General View	0	Load JPG	V
24	20/11/18 18:46	General View	Ð	Load JPG	<b>V</b>
25	20/11/18 18:46	General View	0	Load JPG	V
26	20/11/18 18:46	General View	0	Load JPG	V
27	20/11/18 18:46	General View	Ð	Load JPG	V
28	20/11/18 18:46	General View	0	Load JPG	V
29	20/11/18 18:46	General View	0	Load JPG	<b>V</b>
30	20/11/18 18:46	General View	0	Load JPG	V
31	20/11/18 18:46	General View	0	Load JPG	V
32	20/11/18 18:46	General View	0	Load JPG	<b>V</b>
33	20/11/18 18:46	General View	0	Load JPG	V

Merimen e-Claims Page 2 of 2

Ass	essment Reports		1 per	page 🔻	V
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)		Thumbnail	Print
34	20/11/18 18:46	General View	0	Load JPG	V
35	20/11/18 18:46	General View	0	Load JPG	V
36	20/11/18 18:46	General View	0	Load JPG	<b>V</b>
37	20/11/18 18:46	General View	0	Load JPG	~
38	20/11/18 18:46	General View	0	Load JPG	V
39	20/11/18 18:46	General View	0	Load JPG	~
40	20/11/18 18:46	General View	0	Load JPG	<b>V</b>
41	23/11/18 17:34	Reinspection Photo	0	Load JPG	<b>V</b>
42	23/11/18 17:34	Reinspection Photo	0	Load JPG	<b>V</b>
43	23/11/18 17:34	Reinspection Photo	0	Load JPG	V
44	23/11/18 17:34	Reinspection Photo	0	Load JPG	~
45	23/11/18 17:34	Reinspection Photo	0	Load JPG	~
46	23/11/18 17:34	Reinspection Photo	0	Load JPG	~
47	23/11/18 17:34	Reinspection Photo	0	Load JPG	~
48	23/11/18 17:34	Reinspection Photo	0	Load JPG	V
49	23/11/18 17:34	Reinspection Photo	0	Load JPG	<b>V</b>
50	23/11/18 17:34	Reinspection Photo	0	Load JPG	V
51	23/11/18 17:34	Reinspection Photo	0	Load JPG	<b>V</b>
52	28/11/18 17:22	Reinspection Photo	0	Load JPG	V
53	28/11/18 17:22	Reinspection Photo	0	Load JPG	V
54	28/11/18 17:22	Reinspection Photo	0	Load JPG	<b>V</b>
55	28/11/18 17:22	Reinspection Photo	0	Load JPG	~
56	28/11/18 17:22	Reinspection Photo	0	Load JPG	V
57	28/11/18 17:22	Reinspection Photo	0	Load JPG	<b>V</b>
58	28/11/18 17:22	Reinspection Photo	0	Load JPG	~
59	28/11/18 17:22	Reinspection Photo	0	Load JPG	V
60	28/11/18 17:22	Reinspection Photo	0	Load JPG	<b>V</b>
61	28/11/18 17:22	Reinspection Photo	0	Load JPG	~
62	28/11/18 17:22	Reinspection Photo	0	Load JPG	<b>V</b>
Doc	umentation		1 per	page 🔻	<b>✓</b>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Braddell)		Thumbnail	Print
1	19/12/18 10:01	LOD, Invoice, LOR, Mileage Record, LA, LTA Search Fee	0	Load PDF	-
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)		Thumbnail	Print
1	19/11/18 18:00	E-filed GIA report	0	Load PDF	-
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	21/12/18 09:36	Supplementary	0	Load PDF	

## **Documents Checklist**

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
			^
			~
Show Remarks To: Repairer Handling Insurer Note: Remarks are private unless you show it to other parties.			

### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25. Pava Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS/TMI18020934/K1SD3E2

Date:

21/12/2018

REFERENCE

Handling Insurer: Tokio Marine Insurance Singapore Ltd

Policy No:

MH000848

Claimant Vehicle

SHA1813P

Insured Vehicle No:

SJW8259D

No: Date of Loss:

18/11/2018

Nature of Claim:

TP

Claim No: M1805883

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No:

**SHA1813P** 

Make & Model:

HYUNDAI AE IONIQ HEV DCT SR, 1.6 (A)

Engine No:

G4LEJU045565

37979 km

Reg. Date:

03/07/2018 (Man. Year: 2018)

Chassis No: Odometer:

KMHC851CVJU103363

Colour: Engine Capacity: Blue

1580 cc

Market Value/New Car Price: N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Excellent

Yes

Steering (Serviceable): Engine Modification:

Yes Footbrake (Serviceable): No Pre-accident Condition:

Yes Good

Handbrake (Serviceable):

CONDITION OF TYRES Front Tyre Size:

195/65 R15

Rear Tyre Size:

195/65 R15

Front Left Side:

Nexen 7 mm

Rear Left Side: Rear Right Side: Nexen 7 mm Nexen 7 mm

Nexen 7 mm Front Right Side: The above values represent the remaining tyre treads depth

Repairer's	Adjuster's	Difference	Diff %
8,516.50	6,745.00	1,771.50	20.80
10.00	10.00	0.00	0.00
2,235.00	1,480.00	755.00	33.78
0.00	0.00	0.00	
0.00	0.00	0.00	
10,761.50	8,235.00	2,526.50	23.48
753.31	576.45	176.86	23.48
11,514.81	8,811.45	2,703.36	23.48
	8,516.50 10.00 2,235.00 0.00 0.00 10,761.50 753.31	8,516.50 6,745.00 10.00 10.00 2,235.00 1,480.00 0.00 0.00 10,761.50 8,235.00 753.31 576.45	8,516.50     6,745.00     1,771.50       10.00     10.00     0.00       2,235.00     1,480.00     755.00       0.00     0.00     0.00       0.00     0.00     0.00       10,761.50     8,235.00     2,526.50       753.31     576.45     176.86

INSPECTION

Date of Assignment:

20/11/2018 Present Location:

ComfortDelGro Engineering Pte Ltd

(Loyang)

Date Inspected:

20/11/2018 Inspected At:

ComfortDelGro Engineering Pte Ltd

(Loyang)

59 Loyang Drive Singapore 508969

Estimated Period of Repair:

6.0 days

KALVIN ANG WEI KUN Adjuster:

Manager:

Hiew May Fung

## REPAIR DETAILS

Referen	ce	
Part Source	:	(Last Synchronised: 21 Dec 2018)
Parts:	N/A	HYUNDAI AE IONIQ HEV DCT SR 1.6 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted	, no print-code for SHA1813P)
Validity:		tes are valid only if they contain the print code (above) on all estimate pages, running page the END OF ESTIMATES marker on the last estimate page
Further Info	: Items/values	not in reference catalogue are prefixed with an asterisk *.

## Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*BOOT LID	Bent	2,480.40 FL	*2,480.40 FL
2	1	*BOOT LID LOCK	Serviceable	224.00 FL	*- FL
3	1	*BOOT LID HANDLE ASSY TAIL GATE RELEASE	Serviceable	47.90 FL	*- FL
4	1	*BOOT LID H EMBLEM	Not Necessary	28.00 FL	*- FL
5	1	*EMBLEM HYBRID	Necessary	24.30 FL	*24.30 FL
6	1	*EMBLEM IONIQ	Necessary	31.30 FL	*31.30 FL
7	1	*EMBLEM -SYMBOL MARK	Not Necessary	28.00 FL	*- FL
8	1	*BOOT LID LAMP LH	Serviceable	794.40 FL	*- FL
9	1	*REAR BUMPER	Deformed	459.40 FL	*459.40 FL
10	1	*REAR BUMPER REINFORCEMENT	Serviceable	294.80 FL	*-FL
11	2	*REAR BUMPER REINFORCEMENT BRACKET LH/RH	Serviceable	276.20 FL	*- FL
12	1	*REAR BUMPER CENTRE MOULDING ASSY	Necessary	451.25 FL	*451.25 FL
13	1	*REAR BUMPER LOWER CENTRE MOULDING ASSY	Serviceable	270.10 FL	*- FL
14	1	*REAR BUMPER SIDE BRACKET LH	Cracked	33.10 FL	*33.10 FL
15	10	*REAR BUMPER COVER CLIPS	Necessary	22.00 FL	*22.00 FL
16	1	*REAR BUMPER UNDER CENTRE	Repair	53.85 FL	*-FL
17	1	*REAR BUMPER REFLECTOR LAMP LH	Cracked	31.90 FL	*31.90 FL
18	1	*REAR BUMPER SIDE UNDER LH	Repair	27.50 FL	*- FL
19	1	*BOOTLID COMFORT LOGO & TEL NO STICKER	Necessary	30.00 FS	*30.00 FS
20	1	*REAR BUMPER REVERSE SENSOR	Serviceable	135.70 FS	*-FS
Sup	pleme	ntary #1			
21	1	*BUMPER TOWING CAP	Missing	51.60 FL	*51.60 FL
22	1	*PANEL ASSY QTR OUTER LH	Buckled	3,556.20 FL	*3,556.20 FL
23	1	*EXTENSION ASSY QTR OUTER LH	Cracked	208.30 FL	*208.30 FL
24	1	*PANEL ASSY BACK	Bent	532.00 FL	*532.00 FL
25	1	*TAIL LAMP -COMB LH	Cut	512.00 FL	*512.00 FL
F=Fra	anchise	part. S=SpcNett. L=ListItemDisc.			
			Sub Total (S\$)		8,423.75
		- List Item Discount on L Items 2	2,087.70	1,678.75	
			Total Parts (S\$)	8,516.50	6,745.00

Report was unsubmitted during this print-out.

Decemended	Missellanseus	140000
Recommended	Miscellaneous	items

10.00	10.00
10.00	10.00
	100000000000000000000000000000000000000

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	PANEL BEATING	New	800.00	600.00
2	SPRAY PAINTING	New	900.00	600.00
3	WIRING	New	50.00	20.00
4	TUFF KOTE	New	50.00	20.00
5	REMOVE/REFIX REVERSE SENSOR	New	120.00	30.00
6	TOWING FEE	New	75.00	60.00
Sup	plementary #1			
Lab	our Items			
7	RENOVE/REFIX REAR WINDSCREEN GLASS	New	120.00	100.00
8	REMOVE/REFIX REAR UPHOLSTERY	New	120.00	50.00
		Gross Labour Cost (S\$)	2,235.00	1,480.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >