

REF: NS/INC18020943/Nqber

REF: NS/INC18020943/Nqber

TAX/11/18/2071

Surveyor: NA2

# ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: 9MC68097

Policy No. 5095103893 20-10-2017

Claims No. MT/1020313-03

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 2 days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: SHC 4756R Yr Regn: 1 APR 2016

Type: M.Car / M.Cycle / BUS / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: MYTIA PERUS C.G. 1,798

Colour: MARONN A/C: Insured / Std / NI / NA

Sp. Reading: 340,505 T/Radi: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: JTDEN36U905767760

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65/R15

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or FALKEN (R), Achilles CF)

Front R/Bal. 6 mm

R/Bal. 5 mm

L/Bal. 6 mm

L/Bal. 5 mm

D.O.A. 16/11/18 D.O.I. 19/11/18

Survey held at SMART WOODLANDS

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

SMART WOODLANDS REAR O/S

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Reverse Shocks Working
	SHC 4756R - NJM / INC18020151 / Tyl
	SHC68097 - C03 / MSC16014559 / Hlvbm2
31/5/19	FINALIZED Lump sum REPAIR \$1050.00 / 2 Days
	CRAD \$ 4411.51 (81%)
	RECEIVED 30 MAY 2019

Date/Time, File Pass to?

1) 30/5/19 Maise

Date/Time, File Return to?

2)

Report Format: TP

Lump Sum / I.B.I. (\$) 1050

Days Of Repair: 2

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee: 160

Transportation:

Add Fee: Site Insp (\$ ) S + RS - SI

Interview (\$ ) Photos

Tech. Invs (\$ ) Others

Weekend (\$ )

TOTAL

160
160

TP Claims against NTUC Income: Follow-Through Survey

Date : 06/05/2019

S/No	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.
1	MT/1041958-002	COMFORT TRANSPORTATION PTE LTD	SHC 8955G	SLH 2238J
2	MT/1042268-002	COMFORT TRANSPORTATION PTE LTD	SHC 2230D	XD 7779K
3	MT/1042493-002	COMFORT TRANSPORTATION PTE LTD	SHD 3252D	SBP 3006G
4	MT/1042595-002	COMFORT TRANSPORTATION PTE LTD	SHC 2767Y	GW 6100B
5	MT/1020313-003	SMRT TAXIS PTE LTD	SHC 4756R	SHC 6809J

eBaoTech

GeneralClaim

Hello, NAC\_PAYA\_UBI\_800601

[Change Language](#)[Change Password](#)[Log Out](#)[My Desktop](#)[Notice of Loss](#)

## Policy Query

Policy No.	<input type="text"/>	Date of Accident	<input type="text" value="16/11/2018 13:49"/>
Vehicle No.(For Motor)	<input type="text" value="SHC6809J"/>	Certificate Number	<input type="text"/>

Select	Policy No.	Certificate Number	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
<input type="radio"/>	5095103893		PREMIER TAXIS PTE. LTD.	200304975H	GFT	Third Party	SHC6809J	SHC6809J	20/10/2017	

## Case Details

Case Reference Number : TAX/11/18/2071  
 Type of Repair : Accident Repair  
 Vehicle Registration Number : SHC4756R

Company Type : SMRT Taxis Pte Ltd  
 Estimation ID : EST-4578-ID  
 Assigned By : Kok Wah Wong

Insurance Company Name : NTUC Income  
 Insurance Co-operative Ltd  
 Accident Date and Time : 16/11/2018 03:54 PM  
 Vehicle Age(In Months) : 31

## Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

## Estimation Details

### Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation							Surveyor Approval			
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	
One Time Key In	Main			BUMPER REAR	1	458.60	458.60	25.00	343.95	Replace	1	343.95	Replace	✓ CRK
One Time Key In	Main			BUMPER CLIPS	10	1.61	16.10	25.00	12.08	Replace	10	12.08	Replace	✓ NRC
One Time Key In	Main			PIXEL STICKER	2	60.00	120.00	0.00	120.00	Replace	2	120.00	Replace	✓ NRC
One Time Key In	Main			BUMPER REINFORCEMENT REAR	1	205.70	205.70	25.00	154.27	Replace	0	0	Check	? X SVC
One Time Key In	Main			ARM SUB-ASSY, RR BUMPER RH	1	139.60	139.60	25.00	104.70	Replace	0	0	Check	? X SVC
One Time Key In	Main			SENSOR REVERSE	1	180.00	180.00	0.00	180.00	Replace	0	0	Not Give	✓ X SVC
One Time Key In	Main			BUMPER SIDE RETAINER RR/RH	1	94.80	94.80	25.00	71.10	Replace	1	71.10	Replace	✓ CRK
One Time Key In	Main			BUMPER SEAL, RR RH	1	65.70	65.70	25.00	49.28	Replace	0	0	Check	? X SVC
One Time Key In	Main			BUMPER LIP COVER RR/RH	1	118.10	118.10	25.00	88.57	Replace	0	0	Check	? X SVC
One Time Key In	Main			END PANEL	1	602.10	602.10	25.00	451.58	Replace	0	0	Check	? X SVC
									Total Spare Part Cost	2,292.85				
											Surveyor Total	547.13		
									Lump Sum Discount (%)	20.00	Lump Sum Dis (%)	20		
									Final Spare Part Cost	1,834.28	Final Sur Total	437.70		

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation							Surveyor Approval			
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	
One Time Key In	Main			SEALANT SIKAFLEX	1	37.00	37.00	0.00	37.00	Replace	0	0	Check	? XNN
One Time Key In	Main			DUCT ASSY, QUARTER	1	70.40	70.40	25.00	52.80	Replace	0	0	Check	? XSUL
One Time Key In	Main			FENDER RR/RH	1	766.80	766.80	25.00	575.10	Replace	0	0	Not Give	XSUL
One Time Key In	Main			STICKER DECAL SMRT	1	7.80	7.80	0.00	7.80	Replace	0	0	Not Give	XNN
One Time Key In	Main			STICKER DECAL 6555 8888	1	21.60	21.60	0.00	21.60	Replace	0	0	Not Give	XNN
One Time Key In	Main			TAIL LAMP BRACKET, RH	1	30.70	30.70	25.00	23.02	Replace	0	0	Check	? XSUL
									Total Spare Part Cost	2,292.85	Surveyor Total	547.13		
									Lump Sum Discount (%)	20.00	Lump Sum Dis (%)	20		
									Final Spare Part Cost	1,834.28	Final Sur Total	437.70		

#### Labour's Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TO REPAIR RH REAR PORTION	507.00	200	
Total:		507.00	200.00	

#### Spray Cost Detail


S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TO REPSRAY REAR BUMPER	378.00	200	
2	TO RESPRAY BUMPER BEAM	180.00	0	CHECK XNN
3	TO RESPRAY REAR PANEL	180.00	0	CHECK 100
4	TO RESPRAY REAR FENDER RH	378.00	0	NN
Total:		1,116.00	200.00	

#### Other Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
Total:		460.00	60.00	

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	40	
2	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0	NN
3	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	20	
4	TO WASH AND VACUUM	60.00	0	NN
5	TO REPLACE SUNDRY PARTS	100.00	0	NN
<b>Total:</b>		<b>460.00</b>	<b>60.00</b>	

## Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	1,834.28	437.70
Total Labour Cost	507.00	200.00
Total Spray Painting	1,116.00	200.00
Other	460.00	60.00
Overall Total	3,917.28	897.70
Lump Sum Repair Option	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Lump Sum Total	3,900.00	900.00
Surveyor Approved Amount		900.00
No of Repair Days*	5	2
Remarks	-	LUMP SUM REPAIR. 2 DAYS. CHECK ITEMS PHOTOS. AFTER REPAIR PHOTOS.
Surveyor Name		Naz
Signature		

Survey Date

19/11/2018

Save

Clear

HAZ LKK

19/11/18

LIS

2 DAYS

CHECK ITEMS PHOTOS

AFTER REPAIR PHOTOS

**LKK Auto Consultants** hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) allowed
- Supplemental work(s) must be resurveyed and is subject to approval from insurance Company

Acknowledged by Repairer

Signature

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	17/11/2018 11:12
Date Of Accident	16/11/2018 23:55
Exact Location Of Accident	TELOK BLANGAH DRIVE
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHC4756R
<b>Insured/Policyholder</b>	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	198905369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-80000000

### Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

### Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18090213MFSH
Cover Note Number	

### Driver

Name of Driver	SOH WAH SIONG
NRIC No	S6909362J
Date Of Birth	15/03/1969
Occupation	OUTDOOR
Date Of Driving Pass	22/05/1991
Driving Experience	27 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-80000000
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	623
Postcode,	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

MY TAXI WAS PARKED INSIDE THE PARKING LOT NO.73 (TB29) AND I WAS RESTING INSIDE MY TAXI WITH MY ENGINE OFF WHEN THE SILVER CAB SHC6809J FROM BEHIND SUDDENLY HIT ONTO THE REAR RIGHT PORTION OF MY TAXI.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHC6809J
Vehicle Make/Model/Colour	SILVERCAB
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	KADIR BIN A RAHMAN
NRIC/Passport Number	S0065567H
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	



SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature  
Date & Time:


Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:





Section A - Accident Details

Registration Number	SHC4756R
Case Reference Number	TAX/11/18/2071
Registration Date	1/4/2016
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	SOH WAH SIONG
Type of Accident	Others
Accident Date and Time	16/11/2018 11:54 PM
Accident Reported Date and Time	17/11/2018 11:12 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24098781
Special Instruction to ARC, if any	SILVER CAB - NTUC - LKK
Prepared Date and Time	18/11/2018 9:32 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	



Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$845.00	\$400.00
Total Spray Cost	\$1,298.00	\$300.00
Total Spare Part Cost	\$1,834.28	\$547.13
Total Other Cost	\$460.00	(\$197.13)
<b>TOTAL COST</b>	<b>\$4,435.28</b>	<b>\$1,050.00 (L/S)</b>
Lump Sum Total	\$3,900.00	\$0.00
Number of Repair Days	5.0	2.0
Prepared / Adjusted By	Kim Ming Chin	Naz (LKK) / NTUC
ARC / Surveyor Sign Off Date	18/11/2018 9:48 PM	19/11/2018 12:12 PM
Signature		
Remarks	LUMP SUM REPAIR. 2 DAYS. CHECK ITEMS PHOTOS. AFTER REPAIR PHOTOS.	

## Section C - Quotation and Accident Invoice Details

Quotation Number	QN-1904-0479	Invoice Number	
Quotation Date	29.04.2019	Invoice Date	
Invoice Amount		Prepared Date	

## Section D - Details of Repair Estimates

## Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	\$338.00	\$200.00
TO REPAIR RH REAR PORTION	\$507.00	\$200.00
Total Labour	\$845.00	\$400.00

## Part 2 - Spray Painting &amp; Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR PANEL	\$180.00	\$100.00
TO RESPRAY REAR BUMPER	\$378.00	\$200.00
TO RESPRAY BUMPER BEAM	\$180.00	\$0.00
TO RESPRAY REAR PANEL	\$180.00	\$0.00
TO RESPRAY REAR FENDER RH	\$378.00	\$0.00
Total Spray Painting & Panel Beating	\$1,296.00	\$300.00

## Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Lump Sum Adjustment by Surveyor	\$0.00	(\$257.13)
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$40.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$0.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$20.00
TO WASH AND VACUUM	\$60.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
Total Other Costs	\$460.00	(\$197.13)

## Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52159-47905	BUMPER REAR	1.00	\$458.60	25.00	\$343.95	Replace	Replace
		52161-16010	BUMPER CLIPS	10.00	\$1.61	25.00	\$12.08	Replace	Replace
			PIXEL STICKER	2.00	\$60.00	0.00	\$120.00	Replace	Replace
		52023-12240	BUMPER REINFORCEMENT REAR	0.00	\$205.70	0.00	\$0.00	Replace	Check
		52015-47050	ARM SUB-ASSY, RR BUMPER RH	0.00	\$139.60	0.00	\$0.00	Replace	Check
			SENSOR REVERSE	0.00	\$180.00	0.00	\$0.00	Replace	Not Given
		52575-47020	BUMPER SIDE RETAINER RR/RH	1.00	\$94.80	25.00	\$71.10	Replace	Replace
		52591-47021	BUMPER SEAL, RR RH	0.00	\$65.70	0.00	\$0.00	Replace	Check
		76087-47020	BUMPER LIP COVER RR/RH	0.00	\$118.10	0.00	\$0.00	Replace	Check
		58307-47060	END PANEL	0.00	\$602.10	0.00	\$0.00	Replace	Check

		SEALANT SIKAFLEX	0.00	\$37.00	0.00	\$0.00	Replace	Check	X
	62940-16060	DUCT ASSY, QUARTER	0.00	\$70.40	0.00	\$0.00	Replace	Check	Y
	61604-47090	FENDER RR/RH	0.00	\$766.80	0.00	\$0.00	Replace	Not Given	X
		STICKER DECAL SMRT	0.00	\$7.80	0.00	\$0.00	Replace	Not Given	Y
		STICKER DECAL 6555 8888	0.00	\$21.60	0.00	\$0.00	Replace	Not Given	Y
	52562-47010	TAIL LAMP BRACKET, RH	0.00	\$30.70	0.00	\$0.00	Replace	Check	X
Total				\$2,860.51		\$547.13			

NN  
SUL  
SUL  
NN  
NN  
SUL

Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

547.13  
+ 400.00  
+ 360.00

1307.13

- 20%

1045.70

4/5 \$1050/- / 2 REPAIR DAYS

5576

CONFIRMED LUMP SUM REPAIR \$1,050.00 / 2 DAYS.

NAZ UKK  
H

5461.51

315119

VEGA ENGINEERING PTE LTD	
Accident Case Number	74X/11/18/2071
Vehicle No	SHC 4756.R
Vehicle Model	TOYOTA PRIUS
Date of Collection	20/11/18
Date of Request	20/11/18
Number of Days to Extend	2 DAYS

### REQUEST FOR SUPPLYMENT PARTS

S/N	Number photos	Part Description	Quantity	Unit Price
1	478, 79, 80, 81	To Repair End panel		\$200.00
2		To Respray End panel		\$180.00
3				
4				
5				
6				
7				
8				

I. (Name) CHIA  
(Position) ADVISOR

<<<Please submit photographs for damaged parts>>>

Do solemnly and sincerely declare that:- Supplementary Parts are raised for replacement for the aforesaid vehicle.

*CHIA*

Signature of person making this declaration

[To be signed in front of an authorised witness]

I acknowledge that this declaration is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to the damages of perjury.

Acknowledge By	ARC Executive / Supervisor / SA	
Approval By	Surveyor / In-house Staff	
Parts Ordering	SMRT Store / Contractor Supply / Form 22 / WOC	Form 22 / PO / WOC / Reservation / Number
Photo Submitted		Date of submission

For SMRT Staff





## National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18020943/Nqbe2

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSESINGAPORE  
189556

Date: 09-05-2019



Code: INC4

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 6809J	Veh. Inspected	SHC 4756R
Policy No.	5095103893	Coverage (\$)	0.00
Claim No.	MT/1020313-003	Excess (\$)	0.00
Assign From		Assign Date	19/11/2018

### 2. Vehicle Particulars & Condition

Make & Model	TOYOTA PRIUS	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	JTDKN36U905767760	Colour	MAROON
Odometer	340505	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		

### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	ACHILLES	6 mm
L/H Front Tyre	195/65 R15	ACHILLES	6 mm
R/H Rear Tyre	195/65 R15	FALKEN	5 mm
L/H Rear Tyre	195/65 R15	FALKEN	5 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.
--

### 5. General Information

Accident Date	16/11/2018	Inspection Date	19/11/2018
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	2 Working Days
-------------------------------------	----------------

**National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

**ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 4756R**

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	BUMPER REAR (DISC 25%)	CRACKED	458.60	343.95
10	BUMPER CLIPS @\$1.61 (DISC 25%)	NECESSARY	16.10	12.08
1	BUMPER SIDE RETAINER RR/RH (DISC 25%)	CRACKED	94.80	71.10
2	PIXEL STICKER @\$60.00 (SN)	NECESSARY	120.00	120.00
1	BUMPER REINFORCEMENT REAR	SERVICEABLE	205.70	-
1	ARM SUB-ASSY, RR BUMPER RH	SERVICEABLE	139.60	-
1	SENSOR REVERSE	SERVICEABLE	180.00	-
1	BUMPER SEAL, RR RH	SERVICEABLE	65.70	-
1	BUMPER LIP COVER RR/RH	SERVICEABLE	118.10	-
1	END PANEL	SERVICEABLE	602.10	-
1	DUCT ASSY, QUARTER	SERVICEABLE	70.40	-
1	FENDER RR/RH	SERVICEABLE	766.80	-
1	TAIL LAMP BRACKET, RH	SERVICEABLE	30.70	-
1	SEALANT SIKAFLEX	NOT NECESSARY	37.00	-
1	STICKER DECAL SMRT	NOT NECESSARY	7.80	-
1	STICKER DECAL 6555 8888	NOT NECESSARY	21.60	-
			2,935.00	547.13
<b><u>LABOUR</u></b>				
PANEL BEATING & BODY WORK.			845.00	400.00
SPRAY PAINT.			1,296.00	300.00
TO APPLY RUST-PROOFING ON AFFECTED AREA.			100.00	40.00
TO CHECK WIRING AND SYSTEM FUNCTION.		NOT NECESSARY	80.00	-
TO TEST AND REFIX REVERSE SENSOR SYSTEM.			120.00	20.00
TO WASH AND VACUUM.		NOT NECESSARY	60.00	-
TO REPLACE SUNDRY PARTS.		NOT NECESSARY	100.00	-
			2,601.00	760.00
<b>GRAND TOTAL</b>			<b>5,536.00</b>	<b>1,307.13</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)</b>				<b>1,050.00</b>

Report Ref No. NS/INC18020943/Nqbe2



Report Ref No. NS/INC18020943/Nqbe2

**MUHAMMAD NAZRIL BIN ABDULLAH**

**Automotive Assessor**

A handwritten signature in black ink, appearing to be "K.K. LAU".

**K.K.LAU CPT(RET)**

**BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE**

**REGD Auto Consultant-SAE, Licensed Appraiser**

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

**No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.**