

REF: NS/INC18020946/Nq62  
 TAX/11/18/2072

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured: FBL 4379U  
 Policy No. 5094911659-01 181018 - 171079  
 Claims No. MT/1070164-002  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

Veh No: SHB 5296A Yr Regn: 10 OCT 2017  
 Type: M.Car / M.Cycle / BUS / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or \_\_\_\_\_  
 Make: TOYOTA PRIUS c.c. 1,798  
 Colour: MAROON A/C: Insur. d / Std / NI / NA  
 Sp. Reading: 101,812 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: JTDKB3FU103572527  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: Inorder / Jammed / Leaked / Burnt or  
 Brake: Inorder / Jammed / Leaked / Burnt or  
 Mod: Nil / S/Rim / STD A/Rim or  
 Tyre Size: F: 195/65/R15  
 R: 11  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or YOKO CR, FALKEN CF  
 Front \_\_\_\_\_ Rear \_\_\_\_\_  
 R/Bal. 5 mm R/Bal. 5 mm  
 L/Bal. 5 mm L/Bal. 5 mm  
 D.O.A. 17/11/18 U.O.I. 19/11/18  
 Survey held at SMART WELD AND I  
 Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or  
REAR O/S  
 The UIC / Chassis frame / Body Structure affected due to collision.

(Policy Condition)  
 Remark: The veh had commenced its repair at the time of inspection.  

N/S	O/S

 Bal. or Market Value: \_\_\_\_\_ x  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No  
 Est. Repairs: 4 days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No  
 CA / REV / REP. / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Date / Time	Action / Instruction
	FRONT SENSORS working INC PTP
	SHB 5296A - NS/INC18020946/Rq62 DA: 14/01/2016
	FBL 4379U - NA/INC18020946/BL DA: 17/11/2018
10/4/19	FINALIZED PART BY PART REPAIR \$2743.60 / 4 Days (Red to 50% 40, 65%)
	RECEIVED 1 APR 2019

Date/Time, File Pass to?  Preli: Report  
 1) 11/4 train  Final Report  
 Date/Time, File Return to? \_\_\_\_\_  
 2) \_\_\_\_\_  
 Report Format: TP  
 Lump Sum / I.B.I. (\$) 2743.60  
 Days Of Repair: 4  
 Resurvey No. of Trip: 3  
 Add Fee:  Site Insp (\$ \_\_\_\_\_) S + RS. SI  
 Interview (\$ \_\_\_\_\_) Photos  
 Tech. Invs (\$ \_\_\_\_\_) Others  
 Weekend (\$ \_\_\_\_\_)  
 Survey Fee: \_\_\_\_\_  
 Transportation: \_\_\_\_\_  
 TOTAL



eBaoTech

General Claim

Hello, NAC\_PAYA\_UBI\_800601

[Change Language](#)[Change Password](#)[Log Out](#)My Desktop  
Notice of Loss

## Policy Query

Policy No.  Date of Accident   
 Vehicle No.(For Motor)  Certificate Number

Select	Policy No.	Certificate Number	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
<input type="radio"/>	5094911659-01		ABDUL SAMAD BIN HAJI ABDUL HAMID	S1595216D	GMC	Third Party, Fire & Theft	FBL4379U	FBL4379U	18/10/2018	17/10/2019

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	19/11/2018 09:00
Date Of Accident	17/11/2018 08:20
Exact Location Of Accident	LOYANG AVE TOWARDS PIE
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHB5296A
<b>Insured/Policyholder</b>	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	198905369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-80000000
<b>Vehicle Particulars</b>	
Manufacturer	TOYOTA
Model	PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI
<b>Insurance Company</b>	
Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18090213MFSH
Cover Note Number	
<b>Driver</b>	
Name of Driver	LIM YEOW SUN
NRIC No	S0092707D
Date Of Birth	01/02/1952
Occupation	OUTDOOR
Date Of Driving Pass	13/06/1973
Driving Experience	45 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-80000000
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address 11  
 Postcode  
 Was driver an employee of the Insured's Company NO  
 If No, Relationship of the Driver with the Insured OTHER - HIRER  
 Vehicle Registration Number of Driver's Own Vehicle -  
 -  
 Insurance Company of Driver's Own Vehicle -  
 -

**General Information of the Accident**

Type Of Accident COLLISION - HEAD TO REAR  
 Weather Conditions RAINING  
 Road Surface WET

**Other Information**

Was any foreign vehicle involved in this accident? NO  
 Number of vehicles involved in the accident  
 Was any body injured in the Accident? NO  
 Was any injured conveyed to hospital by ambulance? NO  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (Including Driver) 2  
 Passenger 1  
 NAME: : ZUNIGA JEFFREY  
 GENDER: : MALE

**Details of Police Action**

Was the accident reported to the police? YES  
 If Yes, Please state which Police Station  
 Police Station Name PASIR RIS NEIGHBOURHOOD POLICE CENTRE  
 Police Station Address ROAD: 1 PASIR RIS DRIVE 4 , POSTCODE: 519457 , COUNTRY: SINGAPORE  
 Police Station Contact TEL NO: 1800-5852999 - FAX NO: 65855261  
 Was notice of intended Prosecution given? NO  
 If Yes, against whom?

**Circumstances of Accident**

REFER TO POLICE REPORT - T/20181117/2017

**Attachment(s)**

Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? YES  
 Remarks/ Reasons: FILE TOO BIG  
 Was there any audio recorded? NO

**Details of Witness 1**

Name ZUNIGA JEFFREY  
 Phone Number  
 Email Address

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number FBL4379U  
 Vehicle Make/Model/Colour  
 Details Of Properties  
 Vehicle Category MOTORCYCLE

Name of Driver

ABDUL SAMAD BIN HAJI ABDUL HAMID

NRIC/Passport Number

S1595216D

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)



SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature  
Date & Time:

*6*

Driver's Signature  
(if driver is not the policyholder)  
Date & Time:

*[Signature]*  
17/11/2018

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



**SINGAPORE  
POLICE FORCE**



T/20181117/2017

Police Station Of Origin:  
Pasir Ris N.P.C  
1 Pasir Ris Drive 4 #01-01 SINGAPORE  
519457  
Tel No: 1800-5852999

1 of 4

Report No. T/20181117/2017

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 17/11/2018 09:37	Vide Report No.:	Station Diary No.: 24
--	------------------	--------------------------

**Informant's Particulars**

Name of Informant: LIM YEOW SUN		Address: APT BLK 253 PASIR RIS STREET 21 #05-237 SINGAPORE 510253	
ID Type / ID No.: NRIC NO / S0092707D		Contact No.:	
Nationality: SINGAPORE CITIZEN		Home/Office:	Mobile: 97543124
Email:		Type of Informant: Driver	
Sex: Male	Age: 66	Date of Birth: 01/02/1952	Type of Informant: Driver
Race: Chinese		Language:	Institution / School Name:
Occupation: Taxi driver		Driving Licence Information: Class: 3	Date of Expiry:

**General Information of the Accident**

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 17/11/2018 08:20	Type of Location: Straight Road
Location: Along Road 1 LOYANG AVENUE  Along Loyang Avenue towards PIE				
Weather: Raining		Road Surface: Wet	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control:	Traffic Volume: Heavy	
Type of Collision: Between Moving Vehicles - Head To Rear			Anyone conveyed by ambulance: No	

**Details of Vehicle Involved**

Vehicle No.	Type	Make	Model	Color	Condition	No. of Passenger
FBL4379U	Motorcycle				Seriously Damaged	0
SHB5296A	TAXI	TOYOTA	PRIUS	Maroon	Slightly Damaged	1

**Details of Person Involved**

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE  
POLICE FORCE**



T/20181117/2017

Police Station Of Origin:  
Pasir Ris N.P.C  
1 Pasir Ris Drive 4 #01-01 SINGAPORE  
519457  
Tel No: 1800-5852999

2 of 4

Report No. T/20181117/2017

## CONTINUATION OF REPORT

Rider:			
Name	ABDUL SAMAD BIN HAJI ABDUL HAMID	ID No.	S1595216D
Related Vehicle	FBL4379U (Motorcycle)	Contact No.	98192342
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	Slight
Driver:			
Name	LIM YEOW SUN	ID No.	S0092707D
Related Vehicle	SHB5296A (TAXI)	Contact No.	97543124
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Passenger/Witness:			
Name	ZUNIGA JEFFREY	ID No.	G5217057K
Related Vehicle	SHB5296A (TAXI)	Contact No.	81288962
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

**Brief Details.**

On 17/11/2018 at about 0820hrs I was travelling along Loyang Avenue towards PIE on the 3rd lane in my SMRT Taxi bearing the plate number SHD5296A when a vehicle in front of me reverse as the road was heavy and he wanted to change lane causing me to apply the emergency brake. A motorcycle bearing the plate number FBL4379U hit the rear of my taxi causing my right tail light to be broken and dent on the bumper. The motorcycle also suffered damages and the motorcycle was unable to start. The rider suffered pain on his right leg. Me and my passenger was not injured. No TP or ambulance at scene. There is an in car camera in my vehicle.



**SINGAPORE  
POLICE FORCE**

Police Station Of Origin:  
Pasir Ris N.P.C  
1 Pasir Ris Drive 4 #01-01 SINGAPORE  
519457  
Tel No: 1800-5852999



T/20181117/2017

3 of 4

Report No. T/20181117/2017

CONTINUATION OF REPORT



**SINGAPORE  
POLICE FORCE**



T/20181117/2017

Police Station Of Origin:  
Pasir Ris N.P.C  
1 Pasir Ris Drive 4 #01-01 SINGAPORE  
519457  
Tel No: 1800-5852999

4 of 4

Report No. T/20181117/2017

**CONTINUATION OF REPORT**

**Sketch Plan**

Informant is not able to provide sketch plan

**IMPORTANT:** Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: G / Sgt 2 MUHAMMAD SYAZWAN BIN SHAIBANI	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 17/11/2018 09:37
Officer In Charge Of Case: TP / AEIT / Sr Staff Sgt ONG YONG HOCK Contact No.: 65476436	Classification Of Case:
Authentication Stamp NP168	 SINGAPORE POLICE FORCE SIGNATURE

> [Back to OneMotoring](#)

### Enquire Transfer Fee

**Vehicle Details**

Vehicle No.: SHB5296A  
 Vehicle Type: H10 - Public Transport Taxi (Motor Car)  
 Vehicle Attachment 1: Air-Con (Taxi)  
 Vehicle Scheme: Taxi (Company)  
 Vehicle Make: TOYOTA  
 Vehicle Model: PRIUS HYBRID 1.8 CVT  
 Chassis No.: JTDKB3FU103572577  
 Propellant: Petrol-Electric  
 Engine No.: 2ZRS096291  
 Motor No.: 1NMS096291  
 Engine Capacity: 1798 cc  
 Power Rating: 53.0 kW  
 Maximum Power Output: 90.0 kW ( 120 bhp)  
 Maximum Laden Weight: 1790 kg  
 Unladen Weight: 1375 kg  
 Year Of Manufacture: 2017  
 Original Registration Date: 10 Oct 2017  
 Lifespan Expiry Date: 09 Oct 2025  
 COE Category: A - Car up to 1600cc & 97kW (130bhp)  
 PQP Paid: \$34,052.00  
 COE Expiry Date: 09 Oct 2025  
 Road Tax Expiry Date: 09 Oct 2019  
 PARF Eligibility Expiry Date: 09 Oct 2025  
 Inspection Due Date: 09 Oct 2019  
 Intended Transfer Date: 16 Apr 2019  
 CO2 Emission: 87.00 (g/km)  
 CEV/VES Rebate Utilised Amount: \$27,610.00  
 CO Emission: -  
 HC Emission: -  
 NOx Emission: -  
 PM Emission: -

Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use [Enquire Road Tax Payable](#) for fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

**Amount Payable**

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
<b>Total Amount Payable :</b>			<b>25.00</b>

**Message**

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

You may print this page for reference.

OK

Print



## Case Details

Case Reference Number : TAX/11/18/2072  
 Type of Repair : Accident Repair  
 Vehicle Registration Number : SHB5296A

Company Type : SMRT Taxis Pte Ltd  
 Estimation ID : EST-4580-ID  
 Assigned By : Kok Wah Wong

Insurance Company Name : NTUC Income Insurance Co-operative Ltd  
 Accident Date and Time : 17/11/2018 12:20 AM  
 Vehicle Age(In Months) : 13

## Documents / Photographs

[View Documents / Photographs](#) Total Documents: 1

## Estimation Details

### Spare Part's Cost Detail

BOM Type	Coating Type	Portion	Material Number	SMRT Recommendation						Surveyor Approval				
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	
One Time Key In	Main			COVER, RR BUMPER ASSY	1	423.90	423.90	25.00	317.92	Replace	1	317.92	Replace	/CRK
One Time Key In	Main			PAD, RR BUMPER, RH & LH , 1	2	3.80	7.60	25.00	5.70	Replace	2	5.70	Replace	/NEC
One Time Key In	Main			PAD, RR BUMPER, RH & LH , 2	2	3.80	7.60	25.00	5.70	Replace	2	5.70	Replace	/NEC
One Time Key In	Main			PAD, RR BUMPER, RH & LH , 3	2	3.80	7.60	25.00	5.70	Replace	2	5.70	Replace	/NEC
One Time Key In	Main			SEAL, RR BUMPER ARM, RH & LH	2	11.00	22.00	25.00	16.50	Replace	0	0	Check	? X SUC
One Time Key In	Main			RETAINER, RR BUMPER, RH	1	112.70	112.70	25.00	84.53	Replace	0	0	Not Give	X SUC
One Time Key In	Main			PIXEL STICKER	2	60.00	120.00	0.00	120.00	Replace	2	120.00	Replace	/NEC
One Time Key In	Main			LENS & BODY ASSY, RR BUMPER, RH	1	486.80	486.80	10.00	438.12	Replace	1	438.12	Replace	/CRK
One Time Key In	Main			LENS & BODY, REAR COMBINATION LAMP, RH	1	438.10	438.10	10.00	394.29	Replace	1	394.29	Replace	/CRK
One Time Key In	Main			SEAL, RR BUMPER, RH	1	85.20	85.20	25.00	63.90	Replace	0	0	Check	? X SUC
One Time Key In	Main			GUARD, RR BUMPER, LOWER	1	558.30	558.30	25.00	418.72	Replace	1	418.72	Replace	/SCR
One Time Key In	Main			COVER, GUARD RR BUMPER LOWER	1	14.80	14.80	25.00	11.10	Replace	0	0	Not Give	X SUC
One Time Key In	Main			PAD, RR BUMPER, CTR	3	2.20	6.60	25.00	4.95	Replace	3	4.95	Replace	/NEC
Total Spare Part Cost									3,713.71		Surveyor Total	1,724.82		
Lump Sum Discount (%)									0.00		Lump Sum Dis (%)	0		
Final Spare Part Cost									3,713.71		Final Sur Total	1,724.82		

BOM Type	Coating Type	Portion	Material Number	SMRT Recommendation							Surveyor Approval			
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	
One Time Key In	Main			SENSOR REVERSE	1	180.00	180.00	0.00	180.00	Replace	0	0	Not Givn	X SUC
One Time Key In	Main			REAR BUMPER REINFORCEMENT	1	318.80	318.80	25.00	239.10	Replace	0	0	Check	? X SUC
One Time Key In	Main			FILLER, RR BUMPER, RH	1	119.90	119.90	25.00	89.93	Replace	1	0	Repair	XR
One Time Key In	Main			COVER, REAR FLOOR UNDER, RH	1	169.50	169.50	25.00	127.13	Replace	0	0	Check	? X SUC
One Time Key In	Main			RETAINER, OUTSIDE, RH & LH	1	3.30	3.30	25.00	2.47	Replace	1	2.47	Replace	XNN NFE
One Time Key In	Main			END PANEL SUB-ASSY, BODY LOWER BACK	1	629.80	629.80	25.00	472.35	Replace	0	0	Check	? X SUC
One Time Key In	Main			SEALANT SIKAFLEX	1	37.00	37.00	0.00	37.00	Replace	0	0	Check	? XNN
One Time Key In	Main			PANEL SUB-ASSY, FENDER REAR RH	1	824.80	824.80	25.00	618.60	Replace	0	0	Not Givn	X SUC
One Time Key In	Main			DUCT ASSY, QUARTER VENT, RH & LH	1	65.00	65.00	25.00	48.75	Replace	0	0	Check	? X SUC
One Time Key In	Main			CLIPS PIECE, FRT & RR BUMPER	10	1.50	15.00	25.00	11.25	Replace	10	11.25	Replace	NFE
Total Spare Part Cost									3,713.71	Surveyor Total		1,724.82		
Lump Sum Discount (%)									0.00	Lump Sum Dis (%)		0		
Final Spare Part Cost									3,713.71	Final Sur Total		1,724.82		

**Labour's Cost Detail**

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TO REPAIR RH REAR PORTION	676.00	628.00	300
Total:		676.00	676.00	

**Spray Cost Detail**

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TO REPSRAY REAR BUMPER	378.00	200	
2	TO RESPRAY BUMPER BEAM	180.00	0	CHECK
3	TO RESPRAY FILLER RR BUMPER RH	180.00	50	
4	TO RESPRAY REAR PANEL	180.00	0	CHECK
5	TO TOUCH UP FRONT FENDER RH	378.00	0	CHECK
Total:		1,296.00	250.00	

Other Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	40	
2	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	30	
3	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	20	
4	TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR	120.00	0	NN
5	TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00	30	
6	TO WASH AND VACUUM	60.00	0	NV
7	TO REPLACE SUNDRY PARTS	100.00	0	NN
<b>Total:</b>		<b>700.00</b>	<b>120.00</b>	

Summary

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Total Spare Part Detail	3,713.71	1,724.82
Total Labour Cost	676.00	676.00
Total Spray Painting	1,296.00	250.00
Other	700.00	120.00
<b>Overall Total</b>	<b>6,385.71</b>	<b>2,770.82</b>
Lump Sum Repair Option		
Lump Sum Total	0.00	2,770.82
Surveyor Approved Amount		2,770.82
No of Repair Days*	6	3
Remarks	.	PART BY PART REPAIR, 3 DAYS. CHECK ITEMS PHOTOS, BEFORE PAINT PHOTOS.
Surveyor Name		Naz
Signature		

Save Clear

Survey Date



*Handwritten signature*  
19/11/2018  
20/11/18

NAZ LEX  
19/11/18  
P/R  
3 DAYS  
CHECK ITEMS PHOTOS  
BEFORE PAINT PHOTOS

- LKK Auto Consultants** hereby notify the Repairer of the following:
- To resurvey before/after spray painting
  - To display damaged parts during resurvey
  - Parts prices are subject to confirmation
  - Third party survey is on a "Without Prejudice" basis
  - No illegal modifications is allowed
  - Supplementary items must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer  
Signature:  
Date:

Section A - Accident Details	
Registration Number	SHB5296A
Case Reference Number	TAX/11/18/2072
Registration Date	10/10/2017
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	LIM YEOW SUN
Type of Accident	Head to Rear
Accident Date and Time	17/11/2018 8:20 AM
Accident Reported Date and Time	17/11/2018 11:18 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24098780
Special Instruction to ARC, if any	TP
Prepared Date and Time	18/11/2018 9:56 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	



Toyota

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$976.00	\$500.00
Total Spray Cost	\$1,476.00	\$350.00
Total Spare Part Cost	\$3,762.46	\$1,773.60
Total Other Cost	\$700.00	\$120.00
<b>TOTAL COST</b>	<b>\$6,914.46</b>	<b>\$2,743.60 (P/P)</b>
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	8.0	4.0
Prepared / Adjusted By	Kim Ming Chin	Naz (LKK) / NTUC
ARC / Surveyor Sign Off Date	18/11/2018 10:18 PM	19/11/2018 11:59 AM
Signature		
Remarks	Initial estimates = 6 days Request number of days to extend 2 days	PART BY PART REPAIR. 3 DAYS. CHECK ITEMS PHOTOS. BEFORE PAINT PHOTOS.



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd  
 60 Woodlands Industrial Park E4, Singapore 757706  
 FAX Number 83695592  
 Estimator Telephone Number: 86662623  
 Accident Report's Number: 86662672

Date Generated : 10/04/2019  
 User ID : PehSuan

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-1904-0157	Invoice Number	
Quotation Date	10.04.2019	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR REAR END PANEL	\$300.00	\$200.00
TO REPAIR RH REAR PORTION	\$676.00	\$300.00
<b>Total Labour</b>	<b>\$976.00</b>	<b>\$500.00</b>

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR PANEL	\$180.00	\$100.00
TO RESPRAY REAR BUMPER	\$378.00	\$200.00
TO RESPRAY BUMPER BEAM	\$180.00	\$0.00
TO RESPRAY FILLER RR BUMPER RH	\$180.00	\$50.00
TO RESPRAY REAR PANEL	\$180.00	\$0.00
TO TOUCH UP FRONT FENDER RH	\$378.00	\$0.00
<b>Total Spray Painting &amp; Panel Beating</b>	<b>\$1,476.00</b>	<b>\$350.00</b>

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$40.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$30.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$20.00
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	\$120.00	\$0.00
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	\$120.00	\$30.00
TO WASH AND VACUUM	\$60.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
<b>Total Other Costs</b>	<b>\$700.00</b>	<b>\$120.00</b>

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52159479 13	COVER, RR BUMPER ASSY	1.00 ✓	\$423.90	25.00	\$317.93	Replace	Replace ✓
		52462470 30	PAD, RR BUMPER, RH & LH, 1	2.00 ✓	\$3.80	25.00	\$5.70	Replace	Replace ✓
		52462470 20	PAD, RR BUMPER, RH & LH, 2	2.00 ✓	\$3.80	25.00	\$5.70	Replace	Replace ✓
		52462470 10	PAD, RR BUMPER, RH & LH, 3	2.00 ✓	\$3.80	25.00	\$5.70	Replace	Replace ✓
		52191470 30	SEAL, RR BUMPER ARM, RH & LH	0.00	\$11.00	0.00	\$0.00	Replace	Check X
		52575470 40	RETAINER, RR BUMPER, RH	0.00	\$112.70	0.00	\$0.00	Replace	Not Given X
			PIXEL STICKER	2.00	\$60.00	0.00	\$120.00	Replace	Replace ✓
		81581470 10	LENS & BODY ASSY, RR BUMPER, RH	1.00	\$486.80	10.00	\$438.12	Replace	Replace ✓

✓ R K  
 ✓ NEC  
 ✓ NEC  
 ✓ NEC  
 X SVL  
 X SVL  
 ✓ NEC  
 ✓ C&C

1177.20



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd  
 60 Woodlands Industrial Park E4, Singapore 757705  
 FAX Number : 63685502  
 Estimator Telephone Number : 68602023  
 Accident Reporting Number : 68602672

Date Generated : 10/04/2019  
 User ID : PohDuan

	81551472 81	LENS & BODY, REAR COMBINATION LAMP, RH	1.00	\$438.10	10.00	\$394.29	Replace	Replace	✓	CRK
	52591470 50	SEAL, RR BUMPER, RH	0.00	\$85.20	0.00	\$0.00	Replace	Check	X	SUL
	52453470 10	GUARD, RR BUMPER, LOWER	1.00	\$558.30	25.00	\$418.73	Replace	Replace	✓	SCR
	52169470 20	COVER, GUARD RR BUMPER LOWER	0.00	\$14.80	0.00	\$0.00	Replace	Not Given	X	SUL
	52461470 10	PAD, RR BUMPER, CTR	3.00	\$2.20	6.60	\$4.95	Replace	Replace	✓	NEC
		SENSOR REVERSE	0.00	\$180.00	0.00	\$0.00	Replace	Not Given	X	SUL
	52023470 30	REAR BUMPER REINFORCEMENT	0.00	\$318.80	0.00	\$0.00	Replace	Check	X	SUL
	52565479 00	FILLER, RR BUMPER, RH	1.00	\$119.90	100.00	\$0.00	Replace	Repair	X	NR
	58398470 50	COVER, REAR FLOOR UNDER, RH	0.00	\$169.50	0.00	\$0.00	Replace	Check	X	SUL
	75392352 20	RETAINER, OUTSIDE, RH & LH	1.00	\$3.30	25.00	\$2.48	Replace	Replace	✓	NEC
	58307470 90	END PANEL SUB-ASSY, BODY LOWER BACK	0.00	\$629.80	0.00	\$0.00	Replace	Check	X	SUL
		SEALANT SIKAFLEX	0.00	\$37.00	0.00	\$0.00	Replace	Check	X	XNN
	61601471 50	PANEL SUB-ASSY, FENDER REAR RH	0.00	\$824.80	0.00	\$0.00	Replace	Not Given	X	SUL
	62940470 10	DUCT ASSY, QUARTER VENT, RH & LH	0.00	\$65.00	0.00	\$0.00	Replace	Check	X	XSUL
	52161160 10	CLIPS PIECE, FRT & RR BUMPER	10.00	\$1.50	15	\$11.25	Replace	Replace	✓	NEC
Total				\$4,554.00		\$1,724.85				

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
		62940470 10	DUCT ASSY, QUARTER VENT, RH & LH	1.00	\$65.00	25.00	\$48.75	Replace	Replace
Total					65.00		48.75		

1773.60 -  
 + 500.00 -  
 + 470.00 -  
 -----  
 2743.60 -

7860.30

7771

FINALIZED PART BY PART REPAIR \$ 2743.60 / 4 DAYS.

NAZUK  
 10/14/19

Contractor:	WEGA ENGINEERING PTE LTD		
Accident Case Number	7AX/11/18/2072	Date of Collection	20/11/18
Vehicle No	S17B 5296A	Date of Request	21/11/18
Vehicle Model	TOYOTA PRIUS 4	Number of Days to Extend	2 DAYS. 1 DAY

**REQUEST FOR SUPPLYMENT PARTS**

S/N	Number photos	Part Description	Quantity	Unit Price
1	4185	Duct Assy Quarter Vent RH		\$ 65.00 / DEF
2	4182, 83, 84, 85	To Repair Rear Bnd Panel		\$ 300.00 \$200
3		To Respray Rear Bnd Panel		\$ 180.00 \$100
4				
5				
6				
7				
8				

<<<Please submit photographs for damaged parts>>>

I. (Name) CHIA

(Position) ADVISOR

. NAZ LKIC

Do solemnly and sincerely declare that:- Supplementary Parts are raised for replacement for the aforesaid vehicle.

*Chia*

Signature of person making this declaration

(To be signed in front of an authorised witness)

I acknowledge that this declaration is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to the damages of perjury.

Acknowledge By	ARC Executive / Supervisor / SA	
Approval By	Surveyor / In-house Staff	
Parts Ordering	SMRT Store / Contractor Supply / Form 22 / WOC	Form22 / PO / WOC / Reservation / Number
Photo Submitted		Date of submission

For SMRT Staff



# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18020946/Nqbs2	
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556	Date: 16-04-2019
Code: INC4	



### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	FBL 4379U	Veh. Inspected	SHB 5296A
Policy No.	5094911659-01	Coverage (\$)	0.00
Claim No.	MT/1020164-002	Excess (\$)	0.00
Assign From		Assign Date	19/11/2018

### 2. Vehicle Particulars & Condition

Make & Model	TOYOTA PRIUS	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JTDKB3FU103572577	Colour	MAROON
Odometer	101812	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		

### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65R15	FALKEN	5 mm
L/H Front Tyre	195/65R15	FALKEN	5 mm
R/H Rear Tyre	195/65R15	YOKOHAMA	5 mm
L/H Rear Tyre	195/65R15	YOKOHAMA	5 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.  
DAMAGES SEE DETAILS.

### 5. General Information

Accident Date	17/11/2018	Inspection Date	19/11/2018
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **4 Working Days**



# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 5296A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	COVER, RR BUMPER ASSY (DISC 25%)	CRACKED	423.90	317.93
2	PAD, RR BUMPER, RH & LH, 1 @ \$3.80 (DISC 25%)	NECESSARY	7.60	5.70
2	PAD, RR BUMPER, RH & LH, 2 @ \$3.80 (DISC 25%)	NECESSARY	7.60	5.70
2	PAD, RR BUMPER, RH & LH, 3 @ \$3.80 (DISC 25%)	NECESSARY	7.60	5.70
1	GUARD, RR BUMPER, LOWER (DISC 25%)	SCRATCHED	558.30	418.73
3	PAD, RR BUMPER, CTR @ \$2.20 (DISC 25%)	NECESSARY	6.60	4.95
1	RETAINER, OUTSIDE, RH & LH (DISC 25%)	NECESSARY	3.30	2.48
10	CLIPS PIECE, FRT & RR BUMPER @ \$1.50 (DISC 25%)	NECESSARY	15.00	11.25
1	DUCT ASSY, QUARTER VENT, RH & LH (DISC 25%)	DEFORMED	65.00	48.75
1	LENS & BODY ASSY, RR BUMPER RH (DISC 10%)	CRACKED	486.80	438.12
1	LENS & BODY, REAR COMBINATION LAMP, RH (DISC 10%)	CRACKED	438.10	394.29
2	PIXEL STICKER @ \$60.00 (SN)	NECESSARY	120.00	120.00
1	SEAL, RR BUMPER ARM, RH & LH	SERVICEABLE	11.00	-
1	RETAINER, RR BUMPER, RH	SERVICEABLE	112.70	-
1	SEAL, RR BUMPER, RH	SERVICEABLE	85.20	-
1	COVER, GUARD RR BUMPER LOWER	SERVICEABLE	14.80	-
1	SENSOR REVERSE	SERVICEABLE	180.00	-
1	REAR BUMPER REINFORCEMENT	SERVICEABLE	318.80	-
1	COVER, REAR FLOOR UNDER, RH	SERVICEABLE	169.50	-
1	END PANEL SUB-ASSY, BODY LOWER BACK	SERVICEABLE	629.80	-
1	PANEL SUB-ASSY, FENDER REAR RH	SERVICEABLE	824.80	-
1	DUCT ASSY, QUARTER VENT, RH & RH	SERVICEABLE	65.00	-
1	SEALANT SIKAFLEX	NOT NECESSARY	37.00	-
1	FILLER, RR BUMPER, RH	TO REPAIR SEE LABOUR	119.90	-
			<b>4,708.30</b>	<b>1,773.60</b>
<b>LABOUR</b>				
PANEL BEATING & BODYWORK. INCLUSIVE OF THE REPAIR OF FILLER, RR BUMPER, RH.			976.00	500.00
SPRAY PAINT.			1,476.00	350.00

Report Ref No. NS/INC18020946/Nqbs2



# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO APPLY RUST-PROOFING ON AFFECTED AREA.		100.00	40.00
	TO CHECK WIRING AND SYSTEM FUNCTION.		80.00	30.00
	TO TEST AND REFIX REVERSE SENSOR SYSTEM.		120.00	20.00
	TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	NOT NECESSARY	120.00	-
	TO INSPECT RR LIGHTING, MECHANISM & WATER TEST RR LIGHTING FOR LEAKAGE.		120.00	30.00
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
	TO REPLACE SUNDRY PARTS.	NOT NECESSARY	100.00	-
			3,152.00	970.00
<b>GRAND TOTAL</b>			<b>7,860.30</b>	<b>2,743.60</b>
<b>RECOMMENDED COST OF REPAIRS (CONFIRMED)</b>				<b>2,743.60</b>

Report Ref No. NS/INC18020946/Nqbs2

MUHAMMAD NAZRIL BIN ABDULLAH

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.