

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

19 NOV 2018

ESTIMATE

Estimate No. : b1 49169
Date Estimated : 19/11/2018
Prepared By : Gary Poh Chai Hoon

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -
Ong Mei-Lynn (Wang Meilin)
83 Shelford Road

Singapore 288523

- ACCOUNT - 121
AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKL8300M	VE51099	26/06/2018	218i-C	0

DESCRIPTION

VALUE

Replace rear bumper panel and attachments, bootlid, etc
to knock out dents caused by the accident

1700 2,550.00

Spray paint rear bumper panel, boot lid, tail panel.

1730 2,666.00

To supply rear emboss number plate.

66 83.00

To check electrical wiring systems and lightings at the
rear section for proper function.

150 177.00

To remove old PDC assembly, replace damaged parts and
reconnect to new bumper including conduct checks for
proper function.

150 177.00

To carry out body cavity preservation.
(Per panel).

100 118.00

Sundries.

? 150.00

Total Labour 1: 5,921.00

DESCRIPTION

QTY

PRIC

VALUE

BOOTLID

1 1,136.15

61 1,136.15

SET MOUNTS PDC SENSOR REAR

1 58.60

nei 58.60

REAR BUMPER CARRIER

1 394.90

? 394.90

REAR BUMPER CENTRE GUIDE

1 41.45

? 41.45

LH SIDE GUIDE FOR BUMPER

1 49.05

? 49.05

RH SIDE GUIDE FOR BUMPER

1 49.05

? 49.05

REAR BUMPER TRIM STRIP (LINE SPORT)

1 88.75

cm 88.75

REAR BUMPER PANEL PRIMED (BASIS)

1 980.25

de 980.25

RR FLAP TOWING EYE PRIMED

1 38.95

RY 38.95

EMBLEM ADHERED REAR 218i

1 64.10

nei 64.10

TRUNK LID GASKET

1 125.45

? 125.45

DECOUPLING RING PDC TORQUE CONVERTE

4 5.05

nei 20.20

ULTRASONIC SENSOR BLACK

4 236.85

? 947.40

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 49169
Date Estimated : 19/11/2018
Prepared By : Gary Poh Chai Hoon

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKL8300M	VE51099	26/06/2018	218i-C	0

Total Parts : 3,994.30

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time 22/11/18 9:50am Excess S\$ _____

Surveyor's Name Taufik Sign _____

Surveyor's Tel 97495749 Authorised Yes / No _____

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PIML Yes / No

Surveyor's E-mail taufik@lkkauto.com

No. of Working Days Recommend 5-6 days



Labour 1	:	5,921.00
Parts	:	3,994.30
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	694.07
Grand Total	:	10,609.37

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **