anvelor -	Marcis	ASSIGN	MENT (Office)		
From (Person):	Yel Peili	of	EGL	D	ate/Time: 20.112018 1206pm
Estimated Cost			Bill to:		1
OD TP WS To Inspect Veh		RESTEVATINVIM PC 7333M	V / CS	Insured:	XE 8558U
at Workshop m	/s	Think One		Tel:	908 81188
of	1	40. 18 Defu	Ave 2	_	
Policy No:	Man Parallel Comment of the Comment		Claim No:	XE 8558	u /SL/pl
Sum Insured:			Excess:		r my
Make of Veh: (Client's Record)				D	.O.A. 31.102018
CA / REV /	REP. / REV 24	Contract of the Contract of th	38113018 G	10.30cm	H.O.D. Endorsement:
Date/Time:	20112018 130pm	Person Contac	ted: Kwen	Vel	hicle IN / QUT
Date/Time	Action/Instruction	on (V) Estin	note.		
	PC -1338m -	NA/INC18010 A			DCA : 0906 2018
	XE 855SU -	X X	64 1 44	(11.19), essere	
27/11/18	@ 17:54		of PA to	PU L	Via enail.
-					

ASC	OGNMEN!
Date: 26/11/18	Vehille PC 7333M YEROGE & 18
Estimated Cost:	Type: M.Car / M.Cycle: Bus / Van / Lorry / Taxi / Prime Mover /
OD / WS / TP RES / OD RES / EVA / INV / MV	Truck/Trailer of 22/1/19/4 //9
To Inspect Vehicle No: PC 7333M	Make: Yutong 266/191/c.c 6690
at Workshop m/s. Think One Autocare	Colour Wite Trees A/C: Insured/Std/NI/NA
No.18 Defu Ave 2	Sp.Reading [643] T/Radio: Insured / Std / NI / NA
Insured	Eng/No.
Policy No.	cino LZYTBTE6XJ102063,
Claims No.	Gen. Cong. Good / Fair / Poor / Burnt
Sum Insured: Excess:	Steering: Inorder / Jammed / Leaked / Burnt. or
(Člient's Record)	Brake: Inorder / Jammed / Leaked / Burnt or
Make of Veh: 10-30am - 11am	Modi: NH S/Rim / STD A/Rim or
	Tyre Size: F: [[R 2 2 - 5
(Policy Condition)	R:
Remark. The veh had commenced its N/S 0/S	
repair at the time of inspection.	TOYOTYOKO OF Pouble CSIA
Bal. or Market Value:	Front Rear
IDAC Accident Rport: Consistent? Yes or No	R/Bal. 6 mm R/Bal. 6/6 mm
GIA / PR Seen: Consistent? ; Yes or No	L/Bal. 6 mm L/Bal. 6 6 mm
Est Repairs:	D.O.A. 31/10/18 D.O.I. 26/11/18
Lum Sum: 20 % 3 Val.: Yes or No	Survey held at
CA / REV / REP. / 24 HRS 149)	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
Vehicle: IN / C	OUT OF STATE
Date: Person Contacted:	. The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction	winds bearen
14/14/18 2/5 \$ 4000 Confirmed	· 0/0. [Ga 21.
14/12/18 Continued 218 \$ 4.00	- 36%) 3 days with Marcus
(\$ 24,396 30 - Red.	- 86%.
REC	EIVED 1 4 DEC 2018.
1,12	
	2
Date/Time File Pass to? : Prefi. Report	Days Of Repair:
1) Typist : Final Report	Resurvey No. of Trip: Survey Fee:
Date/Time, File Return to?	
2) Add	Fee: Site Insp (\$) _S+RS,_SI .
3	Tech Invs (\$) others
Report Format :	Weekend (\$ 350
Lump Sum / I.B.I: (\$ 4.00/- 4/5)	L Tributoria

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: XE8558U/SL/pl

Date: 27 November 2018

Our Ref: CS/EGI18020954/Usb

The Motor Claims Department ERGO INSURANCE PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO. PC 7333M .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 26/11/2018 at the premises of M/s Think One Autocare Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	28,396.30	
Revised Estimate Amount	: S\$	9,082.90	
"Check" Items Amount	: S\$	-	
Market Value	: S\$	-	
LTA Reimbursement Value	: <u>S\$</u>	-	
Nett Value	: <u>S\$</u>	2	

Description of Damage:

The vehicle sustained damages at the front o/s portion.

nearside from

Comments/ Present Status:

Damages Consistent. Repair days: 3 Days

Yours faithfully, Marcus Chua Automotive Assessor

ERGO

ate:	20.11.20	018		Sent via Fax		
ır Reference:	XE 8558	U/SL/pl				
ur Reference:	DC 7224M			or		
ur nererence.				Email		
	THINK	ONE AUTOCARE PTE	LTD	L	karentan@thinkone.com.sg	
re-Repair Su	irvey (PRS) Acknowledgement				
ehicle For Insp		PC 7333M				
sured's Vehicl	e:	XE 8558U	3-3-0 Mi			
ate Of Accider	nt:	31.10.2018				
		your request for PRS on:	19.11.2018	3		
		Courts Practice Directions A			et an assessor from	
e list below a	nd indicate	your selection in the box n	narked *.	*	·UKK	
AIS	Automobi	le Inspection Services Pte Ltd	LBS	L.B.S Auto Consi	ultants Pte Ltd	
FTA		n Consultancy Pte Ltd	LKK	LKK Auto Consul	Itants Pte Ltd	
IAS	Infiniti Ap	praisal Service	PS	Priority Services		
JPK	JP Knights	Pte Ltd	VAC	Vicom Ltd		
	OFFICE	r Interest for direct settlement has not reported the accident t R-IN-CHARGE - STEVE L	o us todate.	6829 93		
Signature:	1 3	800.			FAX: 6829 9247	
Assessor use or Assignment Dat Assignment Tim Remarks:	te:		Date: Time Inspector: Vehicle not av	nded workshop on:	ointed date and time.	
			Workshop Ac	knowledgement &	Stamp. nout admission to liability basis.	

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

wner ID Type:	Company
Owner ID:	6025N
/ehicle Details	
'ehicle No.:	PC7333M
ehicle to be Exported:	No
ntended Deregistration Date:	26 Nov 2018
/ehicle Make:	YUTONG
/ehicle Model:	ZK6119H AUTO
Primary Colour:	Multi-Colour
Manufacturing Year:	2018
Engine No.:	ISB67E6C29022315096
Chassis No.:	LZYTBTE6XJ1020634
Maximum Power Output:	*
Open Market Value:	\$144,538.00
Original Registration Date:	10 Aug 2018
First Registration Date:	10 Aug 2018
Fransfer Count:	0
Actual ARF Paid: Intended PARF Rebate Details	\$7,227.00
PARF Eligibility:	No
PARF Eligibility Expiry Date:	2
PARF Rebate Amount:	\$0.00
COE Expiry Date:	09 Aug 2028
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$30,889.00
COE Rebate Amount:	\$29,975.00
Total Rebate Amount:	\$29,975.00

The information contained herein is correct as at 26 Nov 2018

ОК

Shirley Hiew (LKK Auto)

From:

Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>

Sent:

Tuesday, 27 November 2018 5:54 PM

To:

'Survey Report (ERGO Insurance Pte. Ltd.)' SUR; assignments; Admin-D (LKKAuto)

Cc: Subject:

RE: XE8558U / TP : PC7333M/LKK / DOA : 31/10/2018

Attachments:

PC 7333M - Preli Advise.pdf

Dear Pei Li,

Enclosed preliminary revised of vehicle PC 7333M.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: <u>Sur@lkkauto.com</u> | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]

Sent: Tuesday, 20 November 2018 1:33 PM

To: 'Survey Report (ERGO Insurance Pte. Ltd.)' <Survey.Report@ergo.com.sg>
Cc: SUR <sur@lkkauto.com>; assignments <assignments@lkkauto.com>

Subject: RE: XE8558U / TP: PC7333M/LKK / DOA: 31/10/2018

Dear Pei Li,

Thank you for the assignment.

Please be informed that vehicle currently not in the workshop, repairer will arrange.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Survey Report (ERGO Insurance Pte. Ltd.) [mailto:Survey.Report@ergo.com.sg]

Sent: Tuesday, 20 November, 2018 12:06 PM

To: 'admin-d@lkkauto.com' <admin-d@lkkauto.com>

Cc: SUR (sur@lkkauto.com) <sur@lkkauto.com>

Subject: OI: XE8558U / TP: PC7333M/LKK / DOA: 31/10/2018

Dear Catherine/Nivitha,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company LKK AUTO CONSULTANTS PTE LTD to be the "Single Joint Expert".

Please assist to conduct this survey from THINK ONE AUTOCARE PTE LTD,

ADDRESS

: NO 18 DEFU AVENUE 2

SINGAPORE 539522

PERSON TO CONTACT

: KAREN TAN @ 9128 8488 / 6844 3300

ERGO OFFICER-IN-CHARGE

: STEVE LIM

Note: To survey on WITHOUT PREJUDICE basis. Please advise the consistency of damages to third party vehicle and inform the repairer in writing, that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Attached are estimate, insured and third party's SAS (note: reports not to be released to any Third Party).

Kindly acknowledge receipt of this email.

Regards, Yee Pei Li Claims Assistant (Motor)

ERGO Insurance Pte. Ltd.

5 Temasek Boulevard, #04-01 Suntec Tower Five Singapore 038985

DID: +65 6829 9194 Tel: +65 6829 9199 Fax: +65 6829 9247

ERGO

www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers

Catherine Chong (LKK Auto)

From:

Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>

Sent:

Tuesday, 20 November, 2018 12:06 PM

To:

'admin-d@lkkauto.com'

Cc:

SUR (sur@lkkauto.com)

Subject:

Attachments:

OI : XE8558U / TP : PC7333M/LKK / DOA : 31/10/2018 XE8558U - SAS.pdf; PC7333M - SAS.pdf; PC7333M - ESTIMATE.pdf; PC7333M - PRS

FORM.pdf

Dear Catherine/Nivitha,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please assist to conduct this survey from THINK ONE AUTOCARE PTE LTD,

ADDRESS

: NO 18 DEFU AVENUE 2

SINGAPORE 539522

PERSON TO CONTACT

: KAREN TAN @ 9128 8488 / 6844 3300

FRGO OFFICER-IN-CHARGE

: STEVE LIM

Note: To survey on WITHOUT PREJUDICE basis. Please advise the consistency of damages to third party vehicle and inform the repairer in writing, that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Attached are estimate, insured and third party's SAS (note: reports not to be released to any Third Party).

Kindly acknowledge receipt of this email.

Regards, Yee Pei Li Claims Assistant (Motor)

ERGO Insurance Pte. Ltd.

5 Temasek Boulevard, #04-01 Suntec Tower Five Singapore 038985

DID.: +65 6829 9194 Tel.: +65 6829 9199 Fax: +65 6829 9247



www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers

Think One Autocare Pte Ltd No.18 Defu Avenue 2 Singapore 539522

Tel: 6844 3300 Fax: 6842 4988

No Qty	Parts Description		timated ts Price
1 1	Front bumper complete assy	\$	3,800.00
2 1	Front bumper right bracket 17	S	175.00
3 1	Front panel assy	\$	8,900.00
3 1 4 1	Front centre logo 4 7	\$	250.00
5 1	Front right headlamp	S	1,013.00
	Front right bumper lower fog lamp \(\square\) 7	\$	280.00
6 1 7 1	Front windscreen glass assy Front windscreen glass top moulding 335	\$	8,175.00
	Front windscreen glass top moulding 315	S	606.00
8 1 9 1	Front wiper assy	\$	708.00
	/-	\$ 2	3,907.00
	Less 10%	\$	2,390.70
		\$ 2	1,516.30
	Special Nett Items	0	90.00
1 1	Front no plate	5	80.00
2 1se	Front no plate t Front panel sticker	- 5	350.00
			430.00
	Total Parts	\$ 2	1,946.30

Not Adhul P-9

Work Aller Mps
Take phother Mps
26/11/15 1/5 \$ 4000/

3 day.

Think One Autocare Pte Ltd No.18 Defu Avenue 2 Singapore 539522

Tel: 6844 3300 Fax: 6842 4988

PC7333M Yutong ZK6119H

No	Description		Labour Charges	
1	Labour for panel beating, cut, weld, straighten front right affected area and replace front right damaged parts.	S	2,500.00	4
2	To putty and spray painting front right portion.	\$	2,500.00	35
3	To check wiring and focus front headlamp.	\$	50.00	×
4	To apply anti rust proofing to front right affected area.	18	250.00	X
	To remove and install front windscreen glass to facilitate the repair.	S	800.00	40
6	To remove and install front wiper assy.	\$	350.00	X
	Total labour :	S	6,450.00	

Total parts: \$ 21,946.30

Total labour : \$ 6,450.00

Total repair cost: \$ 28,396.30

LKK Auto Consultants hence notify the Repairer of the following:

- . To resurvey before/after spray painting
- . To display damaged part(s) during resurvey
- . Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis.
- No illegal mudification(s) is allowed.
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Intern	nationale Des Experts En Autom	nobile
ERG	INSURANCE PT	E LTD	Ref : CS/EGI180209	54/Usbn2
#04-0	MASEK BOULEVA 11 SUNTEC TOWE APORE 038985		Date: 18-12-2018 Code: EGI	
1.		Policy Particul	ars :- THIRD PARTY CLA	IM
	Insured Veh.	XE 8558U	Veh. Inspected	PC 7333M
	Policy No.		Coverage (\$)	0.00
	Claim No.	XE8558U/SL/pl	Excess (\$)	0.00
	Assign From	YEE PEI LI	Assign Date	20/11/2018
2.		Vehicle P	articulars & Condition	一种是一种企业人
	Make & Model	YUTONG ZK6119H	c.c	6690
	Engine No.	HIDDEN	Year of Reg.	2018
	Chassis No.	LZYTBTE6XJ1020634	Colour	WHITE / GREEN
	Odometer	16431	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3.		Cor	nditions of Tyres	
		Size	Make	Balance
	R/H Front Tyre	11 R22.5	DOUBLE COIN	6 mm
	L/H Front Tyre	11 R22.5	DOUBLE COIN	6 mm
	R/H Rear Tyre	11 R22.5 (D)	DOUBLE COIN	6/6 mm
	L/H Rear Tyre	11 R22.5 (D)	DOUBLE COIN	6/6 mm
4.			ription of Damages	
	THE VEHICLE SU	STAINED DAMAGES AT TH	E FRONT O/S PORTION.	
	DAMAGES SEE D	DETAILS.		
5.		Ge	neral Information	
	Accident Date	31/10/2018	Inspection Date	26/11/2018
	Survey held at	THINK ONE AUTOCARE P	TE LTD	
		NO.18 DEFU AVENUE 2 SINGAPORE 539522		
5a.			Remarks	
	A)THE INSPECTI	ON WAS CONDUCTED ON A	A"WITHOUT PREJUDICE" BA NS, WE HAVE NOT AUTHOR	ISIS. ISED REPAIRS.
5b.			mate Days of Repair	

3 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. PC 7333M

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER COMPLETE ASSY	NOT NECESSARY	3,800.00	-
1	FRONT BUMPER RIGHT BRACKET	NOT NECESSARY	175.00	
1	FRONT PANEL ASSY	TO REPAIR SEE LABOUR	8,900.00	
1	FRONT CENTRE LOGO	NOT NECESSARY	250.00	1
1	FRONT RIGHT HEADLAMP	NOT NECESSARY	1,013.00	
1	FRONT RIGHT BUMPER LOWER FOG LAMP	NOT NECESSARY	280.00	5.
1	FRONT WINDSCREEN GLASS ASSY	DENTED / WARPED	8,175.00	3,980.00
1	FRONT WIPER ASSY	TO REPAIR SEE LABOUR	708.00	82
1	FRONT WINDSCREEN GLASS TOP MOULDING	NECESSARY	606.00	315.00
	LESS 10% DISCOUNT		-2,390.70	-429.50
			21,516.30	3,865.50
	SPECIAL NETT ITEMS			
1	FRONT NO PLATE (SN)	NOT NECESSARY	80.00	9
1	SET FRONT PANEL STICKER (SN)	NOT NECESSARY	350.00	
			430.00	
	LABOUR			Interviews
	LABOUR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN FRONT RIGHT AFFECTED AREA AND REPLACE FRONT RIGHT DAMAGED PARTS. INCLUSIVE OF THE REPAIR OF FRONT PANEL ASSY AND FRONT WIPER ASSY.		2,500.00	480.00
	TO PUTTY AND SPRAY PAINTING FRONT RIGHT PORTION.		2,500.00	300.00
	TO CHECK WIRING AND FOCUS FRONT HEADLAMP.	NOT NECESSARY	50.00	9
	TO APPLY ANTI RUST PROOFING TO FRONT RIGHT AFFECTED AREA.	NOT NECESSARY	250.00)
	TO REMOVE AND INSTALL FRONT WINDSCREEN GLASS TO FACILITATE THE REPAIR.		800.00	400.00
	TO REMOVE AND INSTALL FRONT WIPER ASSY.	NOT NECESSARY	350.00	
			6,450.00	1,180.00
	GRAND TOTAL		28,396.30	5,045.50

Report Ref No. CS/EGI18020954/Usbn2



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS	4,000.00
(TO ITS PRE-ACCIDENT CONDITION)	

Report Ref No. CS/EGI18020954/Usbn2

CHUA KANG SENG Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES: This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.