

## CITY CAB PTE LTD

## REPAIR ESTIMATE\*

VEHICLE NO : SHB 3557K

DATE 20/11/2018 9:35

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Rear Bumper ✓			\$ 553.00	
	Rear Bumper Clip 10 pcs ✓			\$ 22.00	
	Rear Bumper Bracket ?		\$ 35.60	\$ 71.20	
	Rear Bumper Sponge ?			\$ 103.50	
	<b>SUB TOTAL</b>			<b>\$ 749.70</b>	
	<b>LESS 20%</b>			<b>\$ 149.94</b>	
	<b>DISCOUNTED TOTAL</b>			<b>\$ 599.76</b>	
	Rear Bumper Advertisement Logo ✓			\$ 50.00	Nett
	Rear Fender Advertisement Logo (LH/RH) ✓		\$ 100.00	\$ 200.00	Nett
				<b>\$ 250.00</b>	
	<b>Labour Charge</b>				
	Panel Beating			\$ <del>350.00</del> <sup>200</sup>	
	Spray Painting Charge			\$ <del>250.00</del> <sup>200</sup>	
	Wiring Charge			\$ <del>50.00</del> <sup>20</sup>	
	Remove/Refix Reverse Sensor			\$ <del>80.00</del> <sup>20</sup>	
	<b>TOTAL LABOUR</b>			<b>\$ 730.00</b>	
	<b>ESTIMATE TOTAL</b>			<b>\$ 1,579.76</b>	
<p><i>Ka hi 1004</i></p> <p><i>20/11/18 1315h</i></p> <p><i>2 Reps.</i></p> <p><i>L/S</i></p> <p><i>After Repair photo</i></p> <div data-bbox="828 1281 1356 1732"> <p>LKK Auto Centre's 4 points notify the Repairer as following:</p> <ul style="list-style-type: none"> <li>• To resurvey before repair or spray painting</li> <li>• To display damaged part(s) during resurvey</li> <li>• Parts prices are subject to confirmation</li> <li>• Third party survey is on a "Without Prejudice" basis</li> <li>• No illegal modification(s) is allowed</li> <li>• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company</li> </ul> <p>Acknowledged by Repairer</p> <p>Signature: _____</p> <p>Date: _____</p> </div> <p>This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.</p>					