

Please arrange to survey vehicle at
8 KAKI BUKIT AVENUE 4 - GATE 2
#07-48 PREMIER @ KAKI BUKIT
SINGAPORE 415875

ABWIN 論輝

Date : 20/11/2018
TP Vehicle No. : SKH- 424-M
To : AXA INSURANCE SINGAPORE PTE LTD
Attn : Motor Claim Department

Jay.

LINDA LIAO
ABWIN SERVICE PTE LTD
DID: 67139417
Fax: 67139415
HP: 97519596

Owner : MUHAMAD IMRAN BIN ABDUL HAMID
NTUC INCOME INSURANCE CO-OPERATIVE LTD
Certificate No. : 5097166076
Vehicle No. : SKS-2392-A
Make & Model : HONDA ODYSSEY ABSOLUTE 2.4 CVT

Accident Date: 18/11/2018

RC1 1039201

ESTIMATED REPAIR COST DETAILS

QTY	DESCRIPTION	REPAIR AMOUNT	SURVEYOR APP.
<u>List Item</u>			
1	TAILATE Disturbed	\$1,100.30	✓
1	TAILGATE LOCK Dmgd	\$189.00	✓
1	TAILGATE EMBLEM "ODYSSEY" New	\$280.00	✓
1	TAILGATE LOGO New	\$35.80	✓
1	TAILGATE INNER TRIMBOARD New	\$265.30	✓
1	TAILGATE REFLECTOR RH } Canceled	\$398.60	✓
1	TAILGATE REFLECTOR LH } Canceled	\$398.60	✓
1	TAILLAMP RH } New Nec	\$856.80	+
1	TAILLAMP LH } New Nec	\$856.80	+
1	REAR NUMBER PLATE GARNISH cut	\$350.00	✓
1	REAR NUMBER PALTE GARNISH CHROME cut	\$350.00	✓
1	REAR BUMPER Deformed	\$580.20	✓
1	REAR BUMPER RETAINER RH } New	\$35.00	✓
1	REAR BUMPER RETAINER LH } New	\$35.00	✓
1	REAR BUMPER REFLECTOR RH } New	\$55.80	+
1	REAR BUMPER REFLECTOR LH } New	\$55.80	+
1	REAR BUMPER REFLECTOR CHRMOE RH } New	\$120.80	+
1	REAR BUMPER REFLECTOR CHRMOE LH } New	\$120.80	+
10	REAR BUMPER CLIPS New	\$50.00	✓
1	RH CORNER PANEL GARNISH } New	\$165.80	+
1	LH CORNER PANEL GARNISH } New	\$165.80	+
1	REAR END PANEL Repair	\$485.90	✓
1	REAR END PANEL TOP GARNISH New	\$165.00	✓
10	REAR END PANEL TOP GARNISH CLIPS New	\$50.00	+
1	SPARE TYRE PANEL Repair	\$450.60	+
1	SPARE TYRE PANEL BOARD New	\$478.90	+
1	SPARE COMPARTMENT New	\$1,850.90	+
1	REAR WINDSCREEN MOULDING New	\$250.60	✓
Sub Total		\$10,198.10	

Tailgate lock Sensor 78 ✓ Dmgd.

4131.10

3304.88

Date : 20/11/2018
 TP Vehicle No. : SKH- 424-M
 To : AXA INSURANCE SINGAPORE PTE LTD
 Attn : Motor Claim Department

LINDA LIAO
 ABWIN SERVICE PTE LTD
 DID: 67139417
 Fax: 67139415
 HP: 97519596

Owner : MUHAMAD IMRAN BIN ABDUL HAMID
 NTUC INCOME INSURANCE CO-OPERATIVE LTD
 Certificate No. : 5097166076
 Vehicle No. : SKS-2392-A
 Make & Model : HONDA ODYSSEY ABSOLUTE 2.4 CVT

Accident Date: 18/11/2018

ESTIMATED REPAIR COST DETAILS

QTY	DESCRIPTION	REPAIR AMOUNT	SURVEYOR APP.
	Discount 20% on Parts	(\$2,039.62)	
		\$8,158.48	

Special Nett

1	REAR WINDSCREEN SEALANT <i>new</i>	\$65.00	✓
1	REAR END PANEL SEALANT <i>new</i>	\$65.00	✓
1	REAR BUMPER REVERSE SENSOR <i>new</i>	\$400.00	✓
1	REAR NUMBER PLATE & CASEING <i>beat</i>	\$65.00	✓
	Sub Total	\$595.00	

Labour & Misc

TO STRAIGHTEN AND PANEL BEAT ACCIDENT AREAS	\$1,800.00	600
TO SPRAY PAINT ON AFFECTED AREAS	\$1,800.00	600
TO CHECK WIRING AND FOCUS TAILLAMP	\$250.00	30
TO REMOVE & INSTALL REAR WINDSCREEN	\$180.00	120
TO TRANSFER & INSTALL TAILGATE FITTING	\$250.00	120
TO INSTALL REVERSE SENSOR & CHECK FUNCTIONALITY	\$150.00	60
Sub Total	\$4,430.00	

Sub Total \$13,183.48
 GST 7% \$922.84
 Total \$14,106.33

Adrian Lij 96893735.
P/P 20/11/18. total: 4964.88
05 days. (P/P)