

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

20-Nov-18

ESTIMATE REPAIR BILL FOR TOYOTA ALTIS REGN NO: SLR 559 T

Sundry	\$ 50.00 20
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$ 180.00 50
To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the rear o/s door, rear o/s fender, rear bumper	\$ 1,000.00 600
To putty and spray painting on rear bumper, rear o/s fender, rear o/s door	\$ 600.00 540
To apply rustproofing on the repaired and replaced panels.	\$ 150.00 X
	<hr/>
	\$ 1,980.00

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Kalish (LKK)

20/11/18 1010 hrs

3 Reps.

PIP

After Rep. p ltr.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: