



Prime Auto Claims Service Pte Ltd

GST Reg. No : 201606560M
6 Benoi Place Singapore 629927
Tel: 6861 0908 Fax: 6515 2948

Date: 20.11.2018

AXA Insurance Singapore Pte Ltd
8 Shenton Way #27-01/02
AXA Tower
Singapore 068811

Attn: Motor Claims Dept

RE: ESTIMATED COST OF REPAIR TO VEHICLE SKU7367E TOYOTA ESQUIRE 2.0 (2014)

To supply

1) 1pc	Rear bumper	\$	1,388.50 <i>over</i>
2) 1set	Rear bumper clip	\$	30.00 <i>over</i>
3) 1pc	Rear bumper left side reflector	\$	72.50 <i>over</i>

Sub total Parts	\$	1,491.00
Less:25% discount	\$	(372.75)
	\$	1,118.25

L/charges

1)	To remove rear bumper. Replace rear bumper & the above parts. Align & adjust rear bumper.	\$	250.00
2)	To putty, respray painting rear bumper. To polish.	\$	300.00

Sub total L/charges	\$	550.00
Estimated Grand Total	\$	1,668.25

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Tanfer 97495749
WP
20/11/18 5pm
Resurvey after repair
62 days
sur@lkkauto.com