

ISS200

INS. CASE OWNER:

Peter

CC / AXA1802

4 ASM

0967, T. 06/18

LKK:

IDAC:

Surveyor:

MTM

DOE:

20/11/18

Date / Time:

20/11/18

Registered in Merimen:

Pre-assign / CCU / FTE:



Insured Vehicle No.:

XD 7716S

Name of Insured:

Hinh Phong LOGISTIC PTE

Insured Tel No.:

HP:

Excess Sec II :SS

\$1000

D.O.A.:

15/11/18

Is driver the owner? (YES / NO)

(YES / NO)

Nature of Accident:

AVS 12

If NO, Driver Name / Age:

YANK MANDU

Driver Tel No.:

(V/L- YES / NO)

Claim No.:

88MU13CN/82462

Policy No.:

01569774

Make / Model:

NO TRUCKS

Place of Accident:

TWAS AVE 18 ATNAS

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

(YES / NO)

(YES / NO)

Insured Liability: %

Final ? Yes / No

XB 97554



INSRS:
WSP:
Tel:
Liability:
RMKS:

*SM
Shang*



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/Time	STAGE	DATE / PIC
<i>20/11/18</i>	Non-Reporting ltr (1st):	
	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call OI:	<i>EMAIL 8.1.19</i>
	After call ltr to OI:	
	Documentation Check List:	Handler Typist
	Notification ltr (if non-pickup)	<input type="checkbox"/>
	After call ltr to OI:	<input checked="" type="checkbox"/>
	Authorisation To Act:	<input checked="" type="checkbox"/>
	Release Voucher:	<input checked="" type="checkbox"/>
	Final Repair Bill:	<input checked="" type="checkbox"/>
	Car Rental Invoice:	<input type="checkbox"/>
	Towing Invoice:	<input type="checkbox"/>
	LTA / GIA:	<input checked="" type="checkbox"/>
	Medical Bill:	<input type="checkbox"/>
	PIR:	<input type="checkbox"/>
	Mandate/Reject Instruction:	<input checked="" type="checkbox"/>
	LOD:	<input checked="" type="checkbox"/>
	Payment Breakdown Form:	<input type="checkbox"/>
	Post-Repair Photos:	<input type="checkbox"/>
	Others:	<input type="checkbox"/>

PRELIMINARY ADVICE Date/Time: Sent By:

FINALIZATION Date/Time: Confirm with: Repair Cost: *45* \$57,950 (8 days) Reduction: *45* % Email Call

FINAL SETTLEMENT Date/Time: *13.3.19* Confirm with: *SUSAN* Email Call Final Liability: % 100 (Agreed / Assessed) BOLA S/N No.: NIL

Repair Cost: *0/67* \$5,506.50 *OLD HIT STATIONARY TP.* Loss of Rental (LOR): \$5 - (days) Loss of Use (LOU): \$5 1,500.00 (\$ 150 x 10 days) Loss of Income (LOI): \$5 - (\$ x days)

LOR only LOU only LOR + LOU LOR + LO [Tick only one] GI/ALTA Search \$50.00 Medical: \$5 - Disbursement: \$5 - (e.g. Tow/ Independent) Legal Cost \$5 -

Total: \$5 10,008.50 Global Sum \$5: 9,400 (AXA APPROVAL) 1) Claim status: Normal/Reject/Private Settle 2) Report Format: *TP* 3) Survey fee: *350*

FINAL PAYMENT Date/Time: *13.3.19* Confirm with: *SUSAN* Email Call

Payee 1: \$5 9,400.00 Name 1: *SIN STEEL ENGINEERING SERVICES*

Payee 2: (Strike if N.A.) \$5 Name 2: Payee 3: (Strike if N.A.) \$5 Name 3:

COPY SENT
20/11/18



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM18020967/eb3

8 SHENTON WAY #24-01
AXA TOWERS SINGAPORE 068811

Date : 20-11-2018



Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	XD 7716S	Veh. Inspected	XB 9355Y
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	20/11/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	15/11/2018	Inspection Date	
Survey held at	SIN SHENG ENGINEERING SERVICES 3 TECH PARK CRESCENT TUAS TECK PARK SINGAPORE 638129		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

SIN SHENG ENGINEERING SERVICES

3 TECH PARK CRESCENT

SINGAPORE 638129

Tel No. : 6863-9595 Fax No. : 6863-6477

E-Mail : sinsheng1981@gmail.com

Buss. Reg. No. : 312029/00D

KIM EE LOGISTICS (PTE) LTD

10 Tanjong Penjuru

Singapore 609037

ACCOUNTS: MS ALICE

Attention : Motor Claim Department

Contact : 6533 3555 Fax No. : 6261-9074

Estimate : ES002666

Date : 19/11/2018

Vehicle Num. : XB9355Y

Make/Model : NISSAN CKB-2004

Chassis/Eng# : CKB45ABT00416/PF6167570C

Accident Date : 15/11/2018

Claim No. :

Reference : XD7716S

Policy No. : VFX/P1366890

S/N	Quantity	Particular	Unit Price	Amount S\$
		LIST ITEMS :		
1.	1	FRONT BUMPER		2,467.35 <i>bt</i>
2.	1	BUMPER BRACKET, RHS		295.80 <i>bt</i>
3.	1	BUMPER CORNER, RHS		185.20 <i>de</i>
4.	1	BUMPER PROTECTOR RH		175.20 <i>cut</i>
5.	1	BUMPER SPOTLAMP <i>photo</i>		295.40 <i>RN</i>
6.	1	SIDE LAMP		245.40 <i>ave</i>
7.	1	HEAD LAMP RH		943.20 <i>ave</i>
8.	1	HEADLAMP BEZEL		346.20 <i>mis</i>
9.	2	HEADLAMP BEZEL COVER	35.20	70.40 <i>mis</i>
10.	1	DUCT, FR BUMPER AIR GUIDE, CTR, RH		195.20 <i>de</i>
11.	1	CORNER PANEL, RHS		468.20 <i>ave</i>
12.	1	CORNER VANE		368.40 <i>ave</i>
13.	1	FRONT GRILLE		853.10 <i>Ry</i>
14.	1	STEP, UPPER		395.10 <i>bt</i>
15.	1	STEP GARNISH, BIG		568.20 <i>ave</i>
16.	1	STEP GARNISH, SMALL		395.20 <i>de</i>
17.	1	STEP BRACKET		698.50 <i>bt</i>
18.	1	STEP		293.50 <i>bt</i>
19.	1	COVER WHEELHOUSE RH		398.20 <i>de</i>
20.	1	UPPER FENDER		785.20 <i>ave</i>
21.	1	FENDER GARNISH		245.10 <i>RN</i>
22.	1	PILLAR, RHS		953.20 <i>bt</i>
23.	1	SIDE SILL PANEL		853.50 <i>Ry</i>

CONTINUE / ...

SIN SHENG ENGINEERING SERVICES

3 TECH PARK CRESCENT

SINGAPORE 638129

Tel No. : 6863-9595 Fax No. : 6863-6477

E-Mail : sinsheng1981@gmail.com

Buss. Reg. No. : 312029/00D

KIM EE LOGISTICS (PTE) LTD

10 Tanjong Penjuru

Singapore 609037

ACCOUNTS: MS ALICE

Attention : Motor Claim Department

Contact : 6533 3555 Fax No. : 6261-9074

Estimate : ES002666

Date : 19/11/2018

Vehicle Num. : XB9355Y

Make/Model : NISSAN CKB-2004

Chassis/Eng# : CKB45ABT00416/PF6167570C

Accident Date : 15/11/2018

Claim No. :

Reference : XD77165

Policy No. : VFX/P1366890

S/N	Quantity	Particular	Unit Price	Amount S\$
24.	1	FRONT DOOR, RH		2,936.50 <i>Ry</i>
25.	1	DOOR SIGNAL LAMP, RH		175.20 <i>ca</i>
26.	<i>2</i>	DOOR HINGE	245.20 ✓	490.40 <i>bt</i>
27.	1	UD LOGO		195.20 <i>ry</i>
List Total S\$:				16,292.05
25.00% Discount S\$:				4,073.01

				12,219.04
LABOUR :				<i>900</i>
TO PANEL BEAT/REPAIR RH BODY				1,200.00
TO DISMANTLE/REPLACE ABOVEMENTIONED PARTS				
SPRAY PAINTING				<i>800.</i>
TO APPLY NEW LOGO				950.00
LOSS OF USE : 10 DAYS @ \$ 250/DAY				150.00 <i>100</i>
Labour Total S\$:				-----
				2,300.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SIN SHENG ENGINEERING SERVICES

Total S\$: 14,519.04

=====

Tanjiloh 92495149
 -wp
 20/11/18 @ 1730
 Resurvey after repair
 8 days.
 sue@lkkauto.com

◀ Service Request Details

Claim
S8M013CN

Reference
None ✎

Loss Date
November 15, 2018

Request Date
November 20, 2018

Due Date
November 27, 2018

Vendor Name
LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss
Third Party Vehicle Damage

Services
Pending verification - Direct Settlement

*20.11.2018 @ 7:26am
Susan Wehin
Taufik.*

Actions

Next Step
Agree to perform service

Vehicle Information

Incident Vehicle Registration #
XB9355Y

Make
TPVD NISSAN

Catherine Chong (LKK Auto)

From: sinsheng engineeringservices <sinsheng1981@gmail.com>
Sent: Monday, 19 November, 2018 3:27 PM
To: SG AXA Insurance SM AXA SGP - Motor Survey
Subject: Accident Involving XB9355Y with XD7716S on 15/11/2018
Attachments: XB9355Y - Singapore Accident Statement.pdf; XB9355Y_PRI.pdf; XB9355Y_TP search fee.pdf

Categories: Pragati

Dear Officer Incharge,

We are repairer of motor vehicle XB9355Y . Enclosed Accident Statement and LTA search fee for your attention please. Kindly assist to arrange for the Pre-Repair Inspection to be conducted within two (2) workings days upon received this email.

Kindly let us have your list of 10 norminated surveyors to conduct the Single-Joint Inspection.

Kindly assist to revert the liability issue or offer if direct settlement is in order

Thank You

Regards

Susan

Sin Sheng Engineering Services

3 Tech Park Crescent

Tuas Tech Park

Singapore 638129

Tel: 6863 9595

Fax: 6863 6477



MANDATE REQUEST FOR S8M013LN

Type

🔗 Question

Message

Liability: Insured hit stationary third party vehicle. Spoken to insured and he aware that his NCD is affected and AXA to settle at best. Settlement: Repair Cost : \$8,506.50 (w/GST) Loss of Use: \$1,500.00 (10days x \$1500) LTA : \$2.00 Total: \$10,008.50 Immediate Advice with Mandate uploaded for your easy reference. Please kindly let us have your approval / instruction if any. Thank you - Asher Sng (15/02/2019)

Reply



Please proceed DS with below revised quantum

Type

🔗 Question

Message

COR \$8200 (lump sum inclusive of GST); LOU: \$1200 (\$120/day x 10days); LTA Search: \$2. Total: \$9402

Reply

**THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)**

Vehicle No:	XD 7716S (Insd veh)	Model:	NISSAN CKB45
	XB 9355Y (TP veh)		
Date of Accident:	15/11/2018		

Global Sum Settlement	:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
Repair Estimate	:	\$	15,535.37
Final Repair Cost	:	\$	8,506.50
Loss of Use	:	\$	1,500.00
Rental (if any)	:	\$	10 days at \$150.00 per day
LTA / GIA Search Fee	:	\$	2.00

Others: : \$

Final Settlement Sum (GLOBAL SUM) : \$ 9,400.00

Is Third Party Workshop GIA Registered? YES NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability ____ 100 ____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: _____
 BOLA Liability: _____ (%) Assessed Liability (*): _____ (%)
 * Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown		
1)	SIN SHENG ENGINEERING SERVICES	: \$ 9,400.00

NUR SHAQILAH BTE ABDOL
WAHAB

12/04/2019
Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM18020967/T1eb3s2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811
ATTN: PETER WANG

Date : 12-04-2019



Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	XD 7716S	Veh. Inspected	XB 9355Y
Policy No.	P1569374	Coverage (\$)	0.00
Claim No.	S8M013CN	Excess (\$)	0.00
Assign From	PETER WANG	Assign Date	20/11/2018

2. Vehicle Particulars & Condition

Make & Model	NISSAN CKB45	c.c	12503
Engine No.	HIDDEN	Year of Reg.	2004
Chassis No.	CKB45ABT00416	Colour	BLUE
Odometer	844015	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	10.00-R20	SUMO	8 mm
L/H Front Tyre	10.00-R20	SUMO	8 mm
R/H Rear Tyre	10.00-R20 (D)	SUMO	8/8 mm
L/H Rear Tyre	10.00-R20 (D)	SUMO	8/8 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	15/11/2018	Inspection Date	20/11/2018
Survey held at	SIN SHENG ENGINEERING SERVICES 3 TECH PARK CRESCENT TUAS TECK PARK SINGAPORE 638129		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **8 Working Days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. XB 9355Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER (CONSISTENT)	BENT	2,467.35	2,467.35
1	BUMPER BRACKET, RHS (CONSISTENT)	BENT	295.80	295.80
1	BUMPER CORNER, RHS (CONSISTENT)	DEFORMED	185.20	185.20
1	BUMPER PROTECTOR RH (CONSISTENT)	CUT	175.20	175.20
1	BUMPER SPOTLAMP (CONSISTENT)	NOT NECESSARY	295.40	-
1	SIDE LAMP (CONSISTENT)	CRACKED	245.40	245.40
1	HEAD LAMP RH (CONSISTENT)	CRACKED	943.20	943.20
1	HEADLAMP BEZEL (CONSISTENT)	MISSING	346.20	346.20
2	HEADLAMP BEZEL COVER @ \$35.20 (CONSISTENT)	MISSING	70.40	70.40
1	DUCT, FR BUMPER AIR GUIDE, CTR, RH (CONSISTENT)	DEFORMED	195.20	195.20
1	CORNER PANEL, RHS (CONSISTENT)	CRACKED	468.20	468.20
1	CORNER VANE (CONSISTENT)	CRACKED	368.40	368.40
1	FRONT GRILLE (CONSISTENT)	TO REPAIR SEE LABOUR	853.10	-
1	STEP, UPPER (CONSISTENT)	BENT	395.10	395.10
1	STEP GARNISH, BIG (CONSISTENT)	CRACKED	568.20	568.20
1	STEP GARNISH, SMALL (CONSISTENT)	DEFORMED	395.20	395.20
1	STEP BRACKET (CONSISTENT)	BENT	698.50	698.50
1	STEP (CONSISTENT)	BENT	293.50	293.50
1	COVER WHEELHOUSE RH (CONSISTENT)	DEFORMED	398.20	398.20
1	UPPER FENDER (CONSISTENT)	CRACKED	785.20	785.20
1	FENDER GARNISH (CONSISTENT)	NOT NECESSARY	245.10	-
1	PILLAR, RHS (CONSISTENT)	BENT	953.20	953.20
1	SIDE SILL PANEL (CONSISTENT)	TO REPAIR SEE LABOUR	853.50	-
1	FRONT DOOR, RH (CONSISTENT)	TO REPAIR SEE LABOUR	2,936.50	-
1	DOOR SIGNAL LAMP, RH (CONSISTENT)	CRACKED	175.20	175.20
2	DOOR HINGE @ \$245.20 (CONSISTENT)	BENT 1PC ONLY	490.40	245.20
1	UD LOGO (CONSISTENT)	NECESSARY	195.20	195.20

Report Ref No. CC4/ASM18020967/T1eb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 25% DISCOUNT		-4,073.01	-2,715.81
			12,219.04	8,147.44
	LABOUR			
	TO PANEL BEAT / REPAIR RH BODY. TO DISMANTLE / REPLACE ABOVE MENTIONED PARTS. INCLUSIVE OF THE REPAIR OF FRONT GRILLE, SIDE SILL PANEL AND FRONT DOOR, RH.		1,200.00	900.00
	SPRAY PAINTING.		950.00	800.00
	TO APPLY NEW LOGO.		150.00	100.00
			2,300.00	1,800.00
	GRAND TOTAL		14,519.04	9,947.44
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				7,950.00

Report Ref No. CC4/ASM18020967/T1eb3s2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.