

Mon 17/12 @ 10am
S&R

SF1185Z

BMW Dealer

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

20 NOV 2018

ESTIMATE

Estimate No. : b1 49160
Date Estimated : 19/11/2018
Prepared By : Han Kwan Yong

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -

Teo Puay Yong
Blk 171 Gangsa Road
#06-28

Singapore 670171

- ACCOUNT - 40000

Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SFT185Z	NP42899	30/07/2012	320iA/4	0

DESCRIPTION

To replace front bumper & attachments including to knock out dented area caused by the accident

850 1,275.00

To respray front bumper

934 1,038.00

To check electrical wiring systems at the front section for proper function including adjustments of headlights.

150 177.00

To supply front emboss number plate.

66 83.00

Sundries.

? 80.00

Total Labour 1: 2,653.00

DESCRIPTION

RIVET
FRONT SHOCK ABSORBER
PARTIALLY OPEN GRID RH
INSERT AIR INTAKE CENTER
FRT BUMPER TRIM PRIMED (SRA)
FLAP TOWING EYE PRIMED
FRT RH GRILLE (BASIS)
LICENCE PLATE BASE (ECE)

QTY	PRIC	VALUE
10	0.50	5.00
1	42.20	42.20
1	68.30	68.30
1	97.90	97.90
1	1,007.30	1,007.30
1	43.25	43.25
1	98.80	98.80
1	69.25	69.25

Total Parts : 1,432.00

Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401559W GST Reg. No M2-0020081-x



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : **b1 49160**
Date Estimated : **19/11/2018**
Prepared By : **Han Kwan Yong**

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SFT185Z	NP42899	30/07/2012	320iA/4	0

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. Claim No.

Date & Time 17/12/2017 Excess S\$

Surveyor's Name Tan Sign [Signature]

Surveyor's Tel 9249544 Authorised Yes / No

Authorised Date wp Time

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No

Surveyor's E-mail Tan@pml.com

No. of Working Days Recommend 03 days

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Labour 1	:	2,653.00
Parts	:	1,432.00
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	285.95
Grand Total	:	4,370.95

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **