SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as <u>truthful and accurate</u> as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid

aforesaid.	
	ACCIDENT STATEMENT
Date Of Report	19/11/2018 09:37
Date Of Accident	16/11/2018 08:00
Exact Location Of Accident	BEDOK RESERVOIR ROAD
Country/State of Loss	SINGAPORE
	DETAILS OF OWN VEHICLE
Vehicle Registration Number	SBS6324C
Insured/Policyholder	
Name Of Registered Owner	TOWER TRANSIT SINGAPORE PTE LTD
Co Reg No	201419417K
Email Address	SHARIFAH@TOWERTRANSIT.SG
Mobile Phone No	
Alternative Phone No	OFFICE-68171747
Vehicle Particulars	
Manufacturer	MERCEDES-BENZ
Model	CITARO 0530-6.4 D (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	BUS
Insurance Company	
Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	D-17089154MFBP
Cover Note Number	
Driver	

Driver

Name of Driver
ONG LUAY KIONG
Passport No/FIN
F7127461Q
Date Of Birth
31/12/1972
Occupation
OUTDOOR
Date Of Driving Pass
Driving Experience
S YEARS AND 2 MONTHS
Gender
MALE

_ .. .

Mobile Number (LOCAL) +65-98888888

Fax Number
Contact Number

EMail Address NOEMAIL

Address 21 BULIM DRIVE

Postcode

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own Vehicle

Insurance Company of Driver's Own Vehicle

-

NO

NO

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR

Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles involved in the accident

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by

ambulance?

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

Number of Passengers (Including Driver) 10

Details of Police Action

Was the accident reported to the police?

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

If Yes, against whom?

Circumstances of Accident

REFER TO ATTACHED STATEMENT.

Attachment(s)

Are accident photos available for attachment? NOT AVAILABLE DUE TO CIRCUMSTANCES OF ACCIDENT

Was there any video captured by Car Camera? NO Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number PC2808T

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category BUS

Name of Driver MUHAMMAD BIN MAJENI

NRIC/Passport Number S8326009B

Contact Number

Address Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s)
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my Instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (I) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature Date & Time:

Driver's Signature

(If driver is not the policyholder) Date & Time: 16

11

2018

Reporting Centre Personnel's Signature

NRIC/FIN No.:

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT I bc: 10715 (ONG LUAY KIONG) reported had an accident with a private bus 8c 2808 T. SBS 6324c was stationary at buy. Stop picking up pagerangers - Pc 2808T hit ses 6324c from the back No injuries reported All passengers self-alighted at the bus stop. Damage sustained by sR3 6324c is dented engine cover, cracked rear bumpur and damaged rear right		Sketch Plan #2 Bus Stop (84621)
DESCRIBE CIRCUMSTANCES OF THE ACCIDENT I bc: 10715 (ONG LURY KIONG) reported had an accident with a private bus PC 2808T. SBS 6324C was stationary at bus: Stop picking up prograngers - PC 2808T hit sBS 6324C from the back. No injuries reported All passengers sulf-alighted at the bus stop. Damage sustained by sBS 6324C is dented engine cover, cracked reare bumper and damaged rear right signal light. Damaged sustained by private bus is shattered		SKETCH PLAN
DESCRIBE CIRCUMSTANCES OF THE ACCIDENT I bc: 10715 (ONG LURY KIONG) reported had an accident with a private bus PC 2808T. SBS 6324C was stationary at bus: Stop picking up prograngers - PC 2808T hit sBS 6324C from the back. No injuries reported All passengers sulf-alighted at the bus stop. Damage sustained by sBS 6324C is dented engine cover, cracked reare bumper and damaged rear right signal light. Damaged sustained by private bus is shattered	/	SBS 6324€ □1
DESCRIBE CIRCUMSTANCES OF THE ACCIDENT 1 bc:10715 (ONG LURY KIONSE) reported had an accident with a private bus PC 2808T. SBS 6324C was stationary at buy: Stop picking up prograngers - PC 2808T hit sBS 6324C from the back. No injuries reported. All passengers self-alighted at the bus stop. Damage sustained by sBS 6324C is dented engine cover, cracked gears bumper and damaged rear right signal light. Damaged sustained by private bus is shattered		100
DESCRIBE CIRCUMSTANCES OF THE ACCIDENT 1 bc:10715 (ONG LURY KIONSE) reported had an accident with a private bus PC 2808T. SBS 6324C was stationary at buy: Stop picking up prograngers - PC 2808T hit sBS 6324C from the back. No injuries reported. All passengers self-alighted at the bus stop. Damage sustained by sBS 6324C is dented engine cover, cracked gears bumper and damaged rear right signal light. Damaged sustained by private bus is shattered		
DESCRIBE CIRCUMSTANCES OF THE ACCIDENT 1 bc:10715 (ONG LURY KIONSE) reported had an accident with a private bus PC 2808T. SBS 6324C was stationary at buy: Stop picking up prograngers - PC 2808T hit sBS 6324C from the back. No injuries reported. All passengers self-alighted at the bus stop. Damage sustained by sBS 6324C is dented engine cover, cracked gears bumper and damaged rear right signal light. Damaged sustained by private bus is shattered		2806
I be: 10715 (ONG LUAY KIONG) reported had an accident with a private bus PC 2808T. SBS 6324C was stationary at bus: Stop picking up participants. PC 2808T hit ses 6324c from the back. No injuries reported. All passengers suf-alighted at the bus stop. Damage sustained by sB3 6324c is dented engine cover, cracked near bumper and damaged rear right signal light. Damaged sustained by private bus is shattered		180 X
I be: 10715 (ONG LUAY KIONG) reported had an accident with a private bus PC 2808T. SBS 6324C was stationary at bus: Stop picking up participants. PC 2808T hit ses 6324c from the back. No injuries reported. All passengers suf-alighted at the bus stop. Damage sustained by sB3 6324c is dented engine cover, cracked near bumper and damaged rear right signal light. Damaged sustained by private bus is shattered		
I be: 10715 (ONG LUAY KIONG) reported had an accident with a private bus PC 2808T. SBS 6324C was stationary at bus: Stop picking up participants. PC 2808T hit ses 6324c from the back. No injuries reported. All passengers suf-alighted at the bus stop. Damage sustained by sB3 6324c is dented engine cover, cracked near bumper and damaged rear right signal light. Damaged sustained by private bus is shattered		BN 8 (1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 -
I be: 10715 (ONG LUAY KIONG) reported had an accident with a private bus PC 2808T. SBS 6324C was stationary at bus: Stop picking up participants. PC 2808T hit ses 6324c from the back. No injuries reported. All passengers suf-alighted at the bus stop. Damage sustained by sB3 6324c is dented engine cover, cracked near bumper and damaged rear right signal light. Damaged sustained by private bus is shattered		
of private bus PC 2808T. SBS 6324C was stationary at buy; stop picking up participars. PC 2808T hit sBS 6324C from the back. No injuries reported. All passengers self-alighted at the bus stop. Damage sustained by sRS 6324C is dented engine cover, cracked near bumper and damaged rear right signal light. Damaged sustained by private bus is shottered		DESCRIBE CIRCUMSTANCES OF THE ACCIDENT
Stop picking up parexengers - PC 28087 hit ses 6324c from the back No injuries reported. All passengers self-alighted at the bus stop. Damage sustained by sess 6324c is dented engine cover, cracked near bumper and damaged rear right signal light. Damaged sustained by private bus is shattered		1
at the bus' stop. Damage sustained by sps 6324c is dented engine cover, cracked near bumper and damaged rear right signal light. Damaged sustained by private bus is shattered		1 bc:10715 (ONG LURY KIONSE) reported had an accident with
engine cover, cracked near brumper and damaged near right signal light. Damaged sustained by private buy is shattered		1 bc:10715 (ONG LURY KIONS) reported had an accident with a private bus PC 2808T. SBS 6324C was stationary at bug:
signal light. Domaged sustained by private bus is shattered		I be: 10715 (ONG LURY KIONG) reported had an accident with a private bus PC 2808T. SBS 6324C was stationary at buy: Stop picking up pagesangers - PC 2808T hit sBS 6324C from the back No injuries reported. All passengers self-alighted
		I bc:10715 (ONG LUAY KIONG) reported had an accident with a private bus PC 2808T. SBS 6324C was stationary at buy: Stop picking up pagesengers - PC 2808T hit sBS 6324C from the back. No injuries reported. All passengers self-alighted at the bus stop. Damage sustained by SBS 6324C is dented
wind screwn.		I be: 10715 (ONG LURY KIONG) reported had an accident with a private bus PC 2808T. SBS 6324C was stationary at buy: Stop picking up partengers. PC 2808T hit sBS 6324C from the back. No injuries reported. All passengers self-alighted at the bus stop. Damage sustained by SBS 6324C is dented engine cover, cracked near bumper and damaged rear right
		I be: 10715 (ONG LURY KIONG) reported had an accident with a private bus PC 2808T. SBS 6324C was stationary at buy: Stop picking up pagesengers. PC 2808T hit sBS 6324C from the back. No injuries reported. All passengers suf-alighted at the bus stop. Damage sustained by SBS 6324C is dented engine cover, cracked sears bumper and damaged rear right

DECLARATION I/We declare the foregoing particulars are true in every respect. 10715 Policyholder's Signature Date & Time: Driver's Signature (If driver is not the policyholder) Reporting Centre Personnel's Signature Name: 15.30 pm NRIC/FIN No .: Date & Time:

Page 4 of 4