

HO BENG TRADING

Block 3020A Ubi Road 1 # 01-33 Singapore 408714
 Tel : (65) 69664526 HP: 92712214 Fax: (65) 69664526
 Email : chris_chanbebe@hotmail.com

ORCHID THAI CATERING
 BLOCK 3020A UBI ROAD 1
 # 01-33
 Singapore 408714

TPEQ

Xiao Tony

20th NOV 2018

Accident date: 09th NOV 2018
 Estimated repair cost for vehicle no: GBH1613J TOYOTA HIACE '18

S/n	Qty	Items	U/price	Amount
1	1	Rear Boot Lid		\$2,500.10
2	1	Rear boot lid 70 KM logo		\$35.00
3	1	Rear boot lid embie logo		\$66.10
4	1	Rear boot lid inner lock		\$509.10
5	1	Rear boot lid inner rubber		\$329.10
6	1	Rear boot lid inner trim board		\$540.10
7	10	Rear boot lid inner trim board clips	\$12.90	\$129.00
8	1	Rear boot lid centre moulding		\$209.10
9	2	Rear boot lid number plate garnish		\$166.40
10	1	Rear boot lid number plate		\$50.00
11	2	Rear tail lamp	\$352.20	\$704.40
12	1	Rear bumper		\$520.10
13	1	Rear bumper reverse sensor		\$380.00
14	2	Rear bumper side bracket	\$121.25	\$242.50
15	10	Rear bumper clips	\$12.90	\$129.00
16	1	Rear end panel outer		\$580.15
17	1	Rear end panel inner		\$568.10
18	1	Rear End Panel Top Garnish		\$209.10
19	6	Rear End Panel Top garnish clips	\$12.90	\$77.40
20	1	Rear Exhaust		\$858.00

Tailgate Advertisement Stickers
 New

Subtotal :- \$8,802.75

684.2
 513.15
 S.N: 455

Labour charges

To remove & re-fix rear windscreen.

\$120.00 X

Gum

\$50.00 X

To remove & re-fix rear reverse sensor

~~\$100.00~~ 50

To remove & re-fix cushion

\$120.00 X

To Check Wiring System

~~\$60.00~~ 30

Tuff kote

980

\$120.00 X

Panel beating

~~\$800.00~~ 300

Spray painting

~~\$800.00~~ 600

Subtotal :- \$2,170.00

Total:- \$10,972.75

total: 1475
L/S: 1150.
030mgs.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: