

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SFV 2818 H

S/N	Nature of Jobs	Estimated Charges
1	To remove and transfer front wire harness for headlights, horns , outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00 ✓ X
2	To dismantle and renew front bumper, lhs front fender and lhs headlight. Re-organise crash management components. Reinstall all parts removed.	\$ 1,800.00 500 1000
3	To respray front bumper and lhs front fender.	\$ 1,500.00 550 1000
4	To carry out diagnostic check.	S/N \$ 192.00 ✓
TOTAL LABOUR CHARGES		: \$ <u>3,972.00</u>