

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/1313/2018/GW
Date : 19-Nov-18

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Ng Kok Wah
Address : Blk 9, Tampines St 86, #12-37

Telephone : HP +65 96190345
Type of Claim : Own Damage Claims
Policy No. : 1800061529
Vehicle No : **SFV 2818 H**
Model Code : A4 Sedan 2.0 TFSI
Model / Year : Jun-18
Engine No : CVK 060539
Chassis No : WAUZZZF40JA159718
Mileage : -
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 15-Nov-18
Place of Accident : Along West Coast Road

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SFV 2818 H

S/N	Nature of Jobs	Estimated Charges
1	To remove and transfer front wire harness for headlights, horns , outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00 ✓
2	To dismantle and renew front bumper, lhs front fender and lhs headlight. Re-organise crash management components. Reinstall all parts removed.	\$ 1,800.00 1000
3	To respray front bumper and lhs front fender.	\$ 1,500.00 1000
4	To carry out diagnostic check.	S/N \$ 192.00 ✓
TOTAL LABOUR CHARGES		: \$ 3,972.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SFV 2818 H .

		<u>Damage Parts & Prices</u>	
<u>S/N</u>	<u>Parts Description</u>	<u>S/NETT</u>	<u>REMARKS</u>
1	FRONT BUMPER <i>Repair</i>	\$ 1,902.00	X.
2	FRONT BUMPER FIXING PARTS	\$ 245.00	X
3	FRONT BUMPER SECURING STRIP	\$ 30.00	X
4	FRONT BUMPER CLOSING ELEMENT	\$ 180.00	X
5	FRONT BUMPER AIR GUIDE-LH	\$ 73.00	X
6	FRONT BUMPER AIR GUIDE GRILLE-LH	\$ 118.00	X
7	FRONT BUMPER AIR GUIDE SECTION-LH	\$ 31.00	X
8	FRONT SENSOR	\$ 211.00	X
9	FRONT FENDER-LH <i>Dented</i>	\$ 665.00	✓
10	FRONT FENDER ATTACHMENT PARTS-LH ?	\$ 45.00	?
11	FRONT FENDER CLOSING ELEMENT-LH <i>me</i>	\$ 44.00	✓
12	FRONT FENDER BRACKET-LH ?	\$ 31.00	?
13	FRONT FENDER BRACKET DEFORMATION ELEMENT-LH <i>me</i>	\$ 43.00	✓
14	FRONT FENDER BRACE-LH ?	\$ 103.00	?
15	FRONT WHEEL HOUSING LINER-LH	\$ 215.00	X
16	WHEEL HOUSING LINER ATTACHMENT PARTS <i>2 me</i>	\$ 78.00	X
17	FRONT WHEEL SPOILER-LH	\$ 63.00	X
18	FRONT WHEEL SPOILER END PLATE-LH <i>2 me</i>	\$ 30.00	X
19	FRONT STONE CHIP GUARD <i>3 me</i>	\$ 44.00	✓
20	FRONT FENDER COVER	\$ 27.00	✓
SUB-TOTAL SPARE PARTS		\$ 4,178.00	

* quoted wrongly

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SFV 2818 H

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
21	FRONT FENDER TOP COVER <i>me</i>	\$ 20.00	✓
22	LED HEADLIGHT-LH <i>3 me</i>	\$ 5,973.00	+
23	LED HEADLIGHT LIFT CYLINDER-LH	\$ 184.00	✓
24	SUNDRIES ?	\$ 300.00	?
TOTAL SPARE PARTS		:	\$ 10,655.00
TOTAL LABOUR CHARGES		:	\$ 3,972.00
GRAND TOTAL		:	\$ 14,627.00

* quoted wrongly

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name

Surveyed Date

Authorised Date

Excess Cost

Liability

Remarks

: Adrian Lim
: 20/11/18
:
:
:
:
: Authorized Repairs, 04 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant