

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

19-Nov-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHB 8561 P

1 pc	Rear o/s fender <i>X ngs</i>	\$ 1,205.00
1 pc	Rear o/s fender inner shield <i>X</i>	\$ 120.00
1 pc	Rear windscreen moulding <i>X</i>	\$ 87.00
1 pc	Rear o/s door <i>/</i>	\$ 765.00
1 pc	Rear o/s wheel cover <i>X</i>	\$ 116.00
		\$ 2,293.00
		Less 10%
		\$ 229.30
		\$ 2,063.70

S/NETT

1 pc	Rear o/s fender sticker <i>/</i>	\$ 60.00
1 set	o/s door sticker <i>/</i>	\$ 100.00
1 set	Rear o/s fender inner shield clips <i>X</i>	\$ 28.00
Sundry		\$ 50.00 20
To check rear o/s wheel alignment		\$ 80.00 X
To dismantle and refit the rear windscreen		\$ 120.00 X
To dismantle and refit the inner component of rear o/s door into new shell door		\$ 120.00 50
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs		\$ 180.00 50
To labour charge for dismantle and renew the accident damaged parts. To heat/weld, cut-off the rear o/s fender. Including knock-out, straighten, repair, reshape and adjust of the same		\$ 950.00 400
To putty and spray painting on rear bumper, rear o/s fender, rear o/s door		\$ 600.00 360
To apply rustproofing on the repaired and replaced panels.		\$ 120.00 30
		\$ 4,471.70

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)
THE ABOVE ESTIMATED COST OF REPAIR DO NOT
INCLUDE ANY UNFORESEEN DAMAGES.

Kalin 10/11/18
19/11/18 1345h.
4 Bp.
4s
After Repair photo