

# PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02  
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511  
CO. REG:200707743D GST REG:200707743D

19-Nov-18

## ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6672 K

1 pc	Front n/s door @ \$791.00	X repair	\$	791.00
2 pcs	Front n/s door hinges @ \$34.00	X	\$	68.00
1 pc	n/s mirror assy @ \$590.00	X repair	\$	590.00
			\$	1,449.00
			Less 10%	\$ 144.90
			\$	1,304.10

### S/NETT

1 set	n/s door stickers @ \$100.00	✓		\$100.00
	Sundry		\$	<del>50.00</del> 20
	To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.		\$	<del>180.00</del> X
	To dismantle / refit the inner components of the front n/s door into new shell door		\$	<del>150.00</del> X
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the same, etc		\$	<del>650.00</del> 200
	To putty and spray painting on front n/s door, n/s side mirror		\$	<del>400.00</del> 230
	To apply rustproofing on the repaired and replaced panels.		\$	<del>120.00</del> X
			\$	2,954.10

( ALL THE REPAIR COSTS ARE SUBJECTED TO GST )

**THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.**

*Kalina (LKK)*  
*M*  
*19/11/18*  
*2 Pys*  
*4/5*  
*After Repair photo.*

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: