

BH AUTO SERVICES PTE LTD

Blk 1, Sector C, Sin Ming Industrial Estate #01-111 / 113 / 115 / 117 Singapore 575636
Tel: 6559 8944 / Fax: 6269 2404

ATTN : MOTOR CLAIMS DEPARTMENT
EQ INSURANCE COMPANY LTD
5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEX SINGAPORE 069110
TEL : 6223 9433

DATE : 15/11/2018
PAGE : 1 OF 2

Not Withheld
Resurvey B4 paint

ACCIDENT REPAIR ON : SME2800P
MODEL : MERCEDES BENZ GLC250 4MATIC
POLICY NO : GA392375/1
CHASSIS NO : WDC2539462V104812
YEAR OF MANUFACTURE : 2018
DATE / TIME OF ACCIDENT : 10/11/2018@12:20HRS
LOCATION : ALONG OASIA HOTEL NOVENA CAR PARK
THIRD PARTY VEHICLE NO : SLM27M

REPLACEMENT OF PARTS		QUANTITY	UNIT PRICE	AMOUNT
1	FRONT HEADLAMP LH	1	<i>wa</i>	\$ 2,932.00
2	FRONT HEADLAMP LOWER BRACKET LH	1		\$ 172.00
3	FRONT BUMPER	1	<i>Bu</i>	\$ 1,293.00
4	FRONT BUMPER SIDE RETAINER LH	1		\$ 65.00
5	FRONT BUMPER INNER BRACKET CENTRE	1		\$ 185.00
6	FRONT BUMPER LOWER CHROME GARNISH	1	<i>ka</i>	\$ 558.00
7	FRONT BUMPER FOG LAMP COVER LH	1		\$ <i>su</i> 64.00
8	FRONT BUMPER PARKING SENSOR LH	2	\$ 178.00	\$ 356.00
9	FRONT BUMPER LOWER SPOILER	1	<i>Di</i>	\$ 274.00
10	FRONT FENDER WHEEL ARCH GARNISH LH	1	<i>Wd/ka</i>	\$ 215.00
11	FRONT FENDER INNER SHIELD LH	1		\$ <i>su</i> 172.00
SUB TOTAL				\$ 6,286.00
LESS 10%				\$ (628.60)
PARTS TOTAL				\$ 5,657.40

SPECIAL NETT ITEMS		QUANTITY	UNIT PRICE	AMOUNT
1	FRONT HEADLAMP CLIPS LH	3	\$ 5.00	\$ 15.00
2	FRONT BUMPER CLIPS	10	\$ 7.00	\$ <i>ka</i> 70.00
3	FRONT BUMPER RIVET	10	\$ 7.00	\$ 70.00
4	FRONT BUMPER LOWER SPOILER CLIPS	10	\$ 5.00	\$ <i>ka</i> 50.00
5	FRONT FENDER WHEEL ARCH GARNISH CLIPS LH	6	\$ 5.00	\$ <i>ka</i> 30.00
6	FRONT FENDER INNER SHIELD CLIPS LH	6	\$ 5.00	\$ <i>ka</i> 30.00
PARTS TOTAL				\$ 265.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

ACCIDENT REPAIR ON : SME2800P
 MODEL : MERCEDES BENZ GLC250 4MATIC
 POLICY NO : GA392375/1
 CHASSIS NO : WDC2539462V104812
 YEAR OF MANUFACTURE : 2018
 DATE / TIME OF ACCIDENT : 10/11/2018@12:20HRS
 LOCATION : ALONG OASIA HOTEL NOVENA CAR PARK
THIRD PARTY VEHICLE NO : SLM27M

DATE : 15/11/2018
PAGE : 2 OF 2

LABOUR CHARGES FOR FRONT LEFT PORTION		AMOUNT
1	PROVIDE SKILL LABOUR TO REMOVE ALL DAMAGED PARTS, PANEL BEAT, CUT AND WELD IF NECESSARY AND ALIGN ALL PANEL AND REINSTALL ALL DAMAGED PARTS.	\$ 400.00
2	PROVIDE SKILL LABOUR AND MATERIAL TO PUTTY ALL DAMAGED PARTS AND PANEL AND TO RESPRAY WITH 2K PAINT WITH OVEN SPRAY BOOTH FACILITIES.	\$ 300.00
3	REMOVE AND REPLACE FRONT BUMPER PARKING SENSOR TO FACILITATE REPAIR	\$ 50.00
4	TUFF KOTE AND ANTI RUST COATING ALL REPLACE AND REPAIR PARTS.	\$ 80.00
5	DISCONNECT, CHECK, RESET AND DIAGNOSTIC ELECTRICAL SYSTEM WIRING, HARNESS, WIRE SOCKETS AND ETC. REMOVE AND REINSTALL DAMAGED PARTS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	\$ 250.00
LABOUR TOTAL		\$ 1,080.00

2501
 ✓
 ✓
 X
 ?

TOTAL PARTS & LABOUR	\$ 7,002.40
GST 7%	\$ 490.17
GRAND TOTAL	\$ 7,492.57
ESTIMATE REPAIR DURATION	4 DAYS

3 days

YOURS SINCERELY



ESTIMATOR : KIT
 TEL : 8405 4058
 FAX : 6269 2404
 EMAIL : karkit.ngai@bhauto.com.sg

SURVEY ATTENDED BY :

NAME	Kenneth
COMPANY	LCIC
DATE	19/11/18
TIME	10.35am
TEL	96910663
EMAIL	