

QUOTATION

合合車廠私人有限公司 HUP HUP WORKSHOP PTE. LTD.

27-A, JURONG PORT ROAD, #01-29, SINGAPORE 619101

TEL: 6265 5270, 6261 3407, 6265 1966 FAX: 6261 8456

Business Regn. / GST Regn. No. 19-8004325-G

Date: 19/11/2018

M/s LONPAC INSURANCE BHD

VEHICLE NO. SV 1625A

MAKE Volkswagen 1300 CC

Our Ref: HHW/TP 2400/2018

Your Ref:

- | | | |
|-------|----------------------------|--|
| 1 pc | Front bumper | |
| 1 pc | Front bumper top bar | |
| 2 pcs | Front bumper brackets | |
| 2 pcs | Front bumper side brackets | |
| 2 pcs | Front bumper centre guard | |

bt ✓
3000.00

Labour charge to knock, repair front LH fender, front centre panel, bonnet, front bumper interior parts; dismantle, align, replace front bumper assy.

600
1000.00

Spray paint on bonnet, front LH fender, front centre panel.

600
1000.00

=====

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

合合車廠私人有限公司
HUP HUP WORKSHOP PTE. LTD.

Taufik

Authorized Signature

Taufik 97495749
-wp

22/11/18 @ 1230

Resurvey new parts.
sure@lkkauto.com.
5 days.

N.B.: Estimate does not include 7% GST