

ASS. REC. BY:

REF: CS/MSG180209901 Ng d3st Special Instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person):

Irene Tan

of

MSG

Date/Time: 20/11/18 @ 4:07pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

FBK 2832X

Insured:

SJS 20604

at Workshop m/s:

Bike Production

Tel:

6392 2555

of

610 Serangoon Road

Policy No: AB0443952 QMX

Claim No:

576332

Sum Insured:

Excess:

Make of Veh:

D.O.A. 13/11/2018

(Client's Record)

21/11/18

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 5pm @ 20/11/18

Person Contacted:

Wendy

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	FBK 2832X - X
	SJS 20604 - X
20/11/18 @ 2:30pm	revised to Irene Tan via Messenger.

REF:

REF:

Surveyor: NAZ

MSIG

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: FRE 2832X Yr Regn: 16 JUN 2015

Type: M.Car / M.Cycle / BUS / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: YAMAHA R3 A8J C.C. 321

Colour: BLUE A/C: Insured / Std / NI / NA

Sp. Reading: 38,860 T/Radip: Insured / Std / NI / NA

Eng/No: _____

C/No: 4MH3RA071000003537

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 120/70 R17

R: 140/70 R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front _____ Rear _____

R/Bal. 5 mm R/Bal. 6 mm

L/Bal. _____ mm L/Bal. _____ mm

D.O.A. 13/11/18 D.O.I. 21/11/18

Survey held at BIKE PRODUCTION

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

22/11/18 FINALIZED LUMP SUM REPAIR \$3900.00 / 3 DAYS
(Red \$4502.50, 54%)

RECEIVED 30 JAN 2019

MSIG L/S

28/12/2018

Date/Time, File Pass to?

☐ : Preli Report
☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 3

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐ : Site Insp (\$ _____) \$ + R/S \$ _____

☐ : Interview (\$ _____) Photos

☐ : Tech. Invs (\$ _____) Others

☐ : Weekend (\$ _____)

TOTAL

Report Format: OVER-TP

Lump Sum / I.B.I. (\$) 3900

150
10

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	14 Nov 2018		20 Nov 2018 16:07 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	RONALDO ROBANGSA, ID: S8471946C			
Main Claimant:	ABDUL RAHMAN BIN AHMAD BAJURI, ID: S8107227B			
Vehicle Reg. No.:	FBK2832X	Date of Loss:	13/11/2018 15:00 - :59 [40 Months and 28 Days From LTA Reg Date (Man Yr)]	
Claim Type:	TP / 576332	Policy/Cover Note No.:	A80443952QMX (Comprehensive) Coverage: 29/09/2018 - 28/09/2019	
Vehicle Reg. No. (Insured):	SJS2060U	Policy No. (Claimant):		
		Excess:	S\$500.00	
Repairer:	Bike Production Pie Ltd (HQ) 610 SERANGOON ROAD, 218216 Serangoon - Tel: 63922555			
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 21/11/2018]			
Driver/Custodian (Insured):	LYDIAWATI BINTE MOHD ROSHID (), NRIC: S8337560D, Tel: +6591145672			
Adj Asg. Remarks:	LIABILITY 100% AGAINST OI ASSIGN LKK AUTO CONSULTANTS CONTACT MR KWAN @ 63922555			

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Irene Tan Gek Ing

Date: 22 Nov 2018

Preliminary Advice

Insured Vehicle No	: SJS2060U	Accident Date	: 13/11/2018
TP Vehicle No	: FBK2832X	Assignment Date	: 20/11/2018
Make	: YAMAHA YZF-R3	Est. Duration of Repair	: 3.00
Date of Inspection	: 21/11/2018		
Inspection At	: BIKE PRODUCTION PIE LTD (HQ) 610 SERANGOON ROAD SINGAPORE 218216		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	8,405.00
Revised Amount	:S\$	4,442.50
Check Items (Estimated)	:S\$	630.00
Total	:S\$	5,072.50

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	14/11/2018 12:10
Date Of Accident	13/11/2018 15:10
Exact Location Of Accident	BLK 463C SEMBAWANG DRIVE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBK2832X
Insured/Policyholder	
Name Of Registered Owner	ABDUL RAHMAN BIN AHMAD BAJURI
NRIC No	S8107227B
Email Address	LYNN.BMT@GMAIL.COM
Mobile Phone No	(LOCAL) +65-92322360
Alternative Phone No	OFFICE-92322360

Vehicle Particulars

Manufacturer	YAMAHA
Model	YZF-R3-321CC ABS

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? **YES**

If No, Please state action to be taken

Vehicle Category	MOTORCYCLE
------------------	------------

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1800117469
Cover Note Number	

Driver

Name of Driver	ABDUL RAHMAN BIN AHMAD BAJURI
NRIC No	S8107227B
Date Of Birth	27/02/1981
Occupation	INDOOR
Date Of Driving Pass	26/07/2011
Driving Experience	7 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-92322360
Fax Number	
Contact Number	OFFICE-92322360
Email Address	LYNN.BMT@GMAIL.COM

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

B 14/11/2018
 Policyholder's Signature
 Date & Time: 1

Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

Nx
 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	7227B
Vehicle Details	
Vehicle No.:	FBK2832X
Vehicle to be Exported:	No
Intended Deregistration Date:	22 Nov 2018
Vehicle Make:	YAMAHA
Vehicle Model:	YZF-R3 ABS
Primary Colour:	Blue
Manufacturing Year:	2015
Engine No.:	H402E0010078
Chassis No.:	MH3RH071000003537
Maximum Power Output:	-
Open Market Value:	\$4,972.00
Original Registration Date:	16 Jun 2015
First Registration Date:	16 Jun 2015
Transfer Count:	3
Actual ARF Paid:	\$746.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	15 Jun 2025
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$5,800.00
COE Rebate Amount:	\$3,808.00
Total Rebate Amount:	\$3,808.00

The information contained herein is correct as at 22 Nov 2018

OK

BIKE PRODUCTION PTE LTD

610, Serangoon Road S(218216)

Tel: 63922555, 62995177 Fax: 62975400

ROC/ GST Reg No.: 200007407G

Date: 14 Nov 2018

ASSESSMENT FOR REPAIR: YAMAHA YZF-R3 ABS - FBK2832X

Chassis No.: MH3RH071000003537

Engine No.: H402E0010078

Qty**Description****Estimate**

1 pc	Front mudguard		\$195.00	✓ SCR
1 pc	Right fork assy	(big outer tube only) Fork	\$495.00	✓ SCR
1 pc	Front cowling		\$285.00	✓ SCR
1 pc	Right mirror		\$135.00	✓ SCR
1 pc	Right black cover		\$125.00	✓ SCR
1 pc	Steering bridge		\$295.00	X SVL
2 pcs	Steering bearing @ \$45.00		\$90.00	X SVL
1 pc	Steering stem		\$305.00	X SVL
1 pc	Right fuel tank cover		\$325.00	✓ SCR
1 pc	Right fuel tank emblem		\$50.00	✓ NEC
1 pc	Right fairing		\$345.00	✓ SCR
1 pc	Right fairing inner black		\$205.00	? ✓ SCR
1 pc	Right fairing emblem		\$85.00	X NO emblem
1 pc	Right slider		\$145.00	✓ SCR
1 pc	Right engine cover		\$455.00	X R ✓ CRK
1 pc	Right engine cover gasket		\$65.00	✓ NEC
1 pc	Right lower cover		\$205.00	✓ SCR
1 pc	Right footrest		\$95.00	X SVL ✓ SCR
1 pc	Right footrest holder		\$175.00	X SVL ✓ BT
1 pc	Brake pedal		\$85.00	X SVL ✓ BT
1 pc	Balancer right		\$45.00	X SVL
1 pc	Handle bar right		\$195.00	X SVL
1 pc	Brake lever		\$65.00	✓ SCR
1 pc	Exhaust		\$1,650.00	✓ SCR X SVL change to original exhaust.
1 pc	Rear right cover		\$285.00	✓ SCR
1 pc	Rear footrest holder right		\$175.00	✓ SCR
1 pc	Rear footrest right		\$75.00	✓ SCR

Less discount 10%

Special nett items

1 pc	Front sport rim		\$480.00	X SVL
1 pc	Front number plate		\$20.00	X NN
1)	Towing charges @ \$30		\$100.00	(show receipt)
2)	Replace, realign and adjust above damaged parts, check wiring and lighting system		\$700.00	200
3)	To replace and balance front and rear wheel rim		\$120.00	X NN
4)	To knock, straighten chassis & body balancing		\$450.00	200 X NN
5)	To remove/refit, replace (if damage) check and straighten front fork tubes.		\$180.00	X NN
6)	Spray painting		\$250.00	150

Date: 14 Nov 2018

(DISMANTLE MARKING)

ASSESSMENT FOR REPAIR: YAMAHA YZF-R3 ABS - FBK2832X

Chassis No.: MH3RH071000003537

Engine No.: H402E0010078

Qty	Description	Estimate
1 pc	Front mudguard	\$195.00 /scr
1 pc	Right fork assy	\$495.00 fork outer tube (scr)
1 pc	Front cowlings	\$285.00 /scr
1 pc	Right mirror	\$135.00 /scr
1 pc	Right black cover	\$125.00 /scr
1 pc	Steering bridge	\$295.00 x svc
2 pcs	Steering bearing @ \$45.00	\$90.00 x svc
1 pc	Steering stem	\$305.00 x svc
1 pc	Right fuel tank cover	\$325.00 /scr
1 pc	Right fuel tank emblem	\$50.00 /scr
1 pc	Right fairing	\$345.00 /scr
1 pc	Right fairing inner black	\$205.00 ? /scr
1 pc	Right fairing emblem	\$85.00 x no emblem
1 pc	Right slider	\$145.00 /scr
1 pc	Right engine cover	\$455.00 x R /scr
1 pc	Right engine cover gasket	\$65.00 /scr
1 pc	Right lower cover	\$205.00 /scr
1 pc	Right footrest	\$95.00 x svc /scr
1 pc	Right footrest holder	\$175.00 x svc /BT
1 pc	Brake pedal	\$85.00 x svc /BT
1 pc	Balancer right	\$45.00 x svc
1 pc	Handle bar right	\$195.00 x svc
1 pc	Brake lever	\$65.00 /scr
1 pc	Exhaust	\$1,650.00 /scr
1 pc	Rear right cover	\$285.00 /scr
1 pc	Rear footrest holder right	\$175.00 /scr
1 pc	Rear footrest right	\$75.00 /scr
		\$5,960.00
		\$596.00
		\$5,364.00
	<u>Special nett items</u>	
1 pc	Front sport rim	\$480.00 x svc
1 pc	Front number plate	\$20.00 x NN
1)	Towing charges	60 to \$100.00 (shown above)
2)	Replace, realign and adjust above damaged parts, check wiring and lighting system	\$200.00 200
3)	To replace and balance front and rear wheel rim	\$120.00 x NN
4)	To knock, straighten chassis & body balancing	\$450.00 200 x NN
5)	To remove/refit, replace (if damage) check and straighten front fork tubes.	\$180.00 x NN
6)	Spray painting	\$250.00 /
		150

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	14 Nov 2018		20 Nov 2018 16:07 Edit Adj Rpt	S\$3,900.00 Edit Estimates	S\$3,900.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	RONALDO ROBANGSA, ID: S8471946C		
Main Claimant:	ABDUL RAHMAN BIN AHMAD BAJURI, ID: S8107227B		
Vehicle Reg. No.:	FBK2832X	Date of Loss:	13/11/2018 15:00 - :59 [40 Months and 28 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 576332	Policy/Cover Note No.:	A80443952QMX (Comprehensive) Coverage: 29/09/2018 - 28/09/2019
Vehicle Reg. No. (Insured):	SJS2060U	Policy No. (Claimant):	
		Excess:	S\$500.00
Repairer:	Bike Production Pie Ltd (HQ) 610 SERANGOON ROAD, 218216 Serangoon - Tel: 63922555		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Muhammad Nazril Bin Abdullah] ... [Final Rpt due 20/12/2018]		
Driver/Custodian (Insured):	LYDIAWATI BINTE MOHD ROSHID (), NRIC: S8337560D, Tel: +6591145672		
Adj Asg. Remarks:	LIABILITY 100% AGAINST OI ASSIGN LKK AUTO CONSULTANTS CONTACT MR KWAN @ 63922555		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***FBK2832X (576332)**

[SJS2060U]

TP

ABDUL RAHMAN BIN AHMAD BAJURI

Nov 13 2018 3:00PM

[RONALDO ROBANGSA]

Bike Production Pie Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View
[View in Browser](#)

Assessment Reports

No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	1 per page	Thumbnail	Print
1	20/11/18 09:38	Accident Statement From: SC - Reg. No: SJS2060U, Claimant: RONALDO ROBANGSA		Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	22/11/18 14:37	Adjuster Immediate Advice		Load HTM	

Photos/Images

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	3 per page	Thumbnail	Print
1	06/12/18 09:49	General View		Load JPG	☒
2	06/12/18 09:49	General View		Load JPG	☒
3	06/12/18 09:49	General View		Load JPG	☒
4	06/12/18 09:49	General View		Load JPG	☒
5	06/12/18 09:49	General View		Load JPG	☒
6	06/12/18 09:49	General View		Load JPG	☒
7	06/12/18 09:49	General View		Load JPG	☒
8	06/12/18 09:49	General View		Load JPG	☒
9	06/12/18 09:49	General View		Load JPG	☒
10	06/12/18 09:49	General View		Load JPG	☒
11	06/12/18 09:49	General View		Load JPG	☒
12	06/12/18 09:49	General View		Load JPG	☒
13	06/12/18 09:49	General View		Load JPG	☒
14	06/12/18 09:49	General View		Load JPG	☒
15	06/12/18 09:49	General View		Load JPG	☒
16	06/12/18 09:49	General View		Load JPG	☒
17	06/12/18 09:49	General View		Load JPG	☒
18	06/12/18 09:49	General View		Load JPG	☒
19	06/12/18 09:49	General View		Load JPG	☒
20	06/12/18 09:49	General View		Load JPG	☒
21	06/12/18 09:49	General View		Load JPG	☒
22	06/12/18 09:49	General View		Load JPG	☒
23	06/12/18 09:49	General View		Load JPG	☒
24	06/12/18 09:49	General View		Load JPG	☒
25	06/12/18 09:49	General View		Load JPG	☒
26	06/12/18 09:49	General View		Load JPG	☒
27	06/12/18 09:49	General View		Load JPG	☒
28	06/12/18 09:49	General View		Load JPG	☒
29	06/12/18 09:49	General View		Load JPG	☒
30	06/12/18 09:49	General View		Load JPG	☒

Assessment Reports			1 per page ▼	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
31	06/12/18 09:50	General View	 Load JPG	☒
32	06/12/18 09:50	General View	 Load JPG	☒
33	06/12/18 09:50	General View	 Load JPG	☒
34	06/12/18 09:50	General View	 Load JPG	☒
35	06/12/18 09:50	General View	 Load JPG	☒
36	06/12/18 09:50	General View	 Load JPG	☒
37	06/12/18 09:50	General View	 Load JPG	☒
38	06/12/18 09:50	General View	 Load JPG	☒
39	06/12/18 09:50	General View	 Load JPG	☒
40	06/12/18 09:50	General View	 Load JPG	☒
41	06/12/18 09:50	General View	 Load JPG	☒
42	06/12/18 09:50	General View	 Load JPG	☒
43	06/12/18 09:50	General View	 Load JPG	☒
44	06/12/18 09:50	General View	 Load JPG	☒
45	06/12/18 09:50	General View	 Load JPG	☒
46	06/12/18 09:50	General View	 Load JPG	☒
47	06/12/18 09:50	General View	 Load JPG	☒
48	06/12/18 09:50	General View	 Load JPG	☒
49	06/12/18 09:50	General View	 Load JPG	☒
50	06/12/18 09:50	General View	 Load JPG	☒
51	06/12/18 09:50	General View	 Load JPG	☒
52	06/12/18 09:50	General View	 Load JPG	☒
53	06/12/18 09:50	General View	 Load JPG	☒
54	22/01/19 15:15	Dismantled Parts	 Load JPG	☒
55	22/01/19 15:15	Dismantled Parts	 Load JPG	☒
56	22/01/19 15:15	Dismantled Parts	 Load JPG	☒
57	22/01/19 15:15	Dismantled Parts	 Load JPG	☒
58	22/01/19 15:15	Dismantled Parts	 Load JPG	☒
59	22/01/19 15:15	Dismantled Parts	 Load JPG	☒
60	22/01/19 15:15	Dismantled Parts	 Load JPG	☒
61	22/01/19 15:15	Dismantled Parts	 Load JPG	☒
62	22/01/19 15:15	Dismantled Parts	 Load JPG	☒
63	22/01/19 15:15	Dismantled Parts	 Load JPG	☒
64	22/01/19 15:15	Dismantled Parts	 Load JPG	☒
65	22/01/19 15:15	Dismantled Parts	 Load JPG	☒
66	22/01/19 15:15	Dismantled Parts	 Load JPG	☒
67	22/01/19 15:15	Dismantled Parts	 Load JPG	☒
68	22/01/19 15:15	Dismantled Parts	 Load JPG	☒
69	22/01/19 15:15	Dismantled Parts	 Load JPG	☒
70	22/01/19 15:15	Dismantled Parts	 Load JPG	☒
71	22/01/19 15:15	Dismantled Parts	 Load JPG	☒
72	22/01/19 15:15	Dismantled Parts	 Load JPG	☒
73	22/01/19 15:15	Dismantled Parts	 Load JPG	☒
74	22/01/19 15:15	Dismantled Parts	 Load JPG	☒
75	22/01/19 15:15	Dismantled Parts	 Load JPG	☒
76	22/01/19 15:15	Dismantled Parts	 Load JPG	☒
77	22/01/19 15:15	Dismantled Parts	 Load JPG	☒
78	22/01/19 15:15	Dismantled Parts	Load JPG	☒

Assessment Reports			1 per page ▼	✓
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
79	22/01/19 15:15	Dismantled Parts	Load JPG	✓
80	22/01/19 15:15	Dismantled Parts	Load JPG	✓
Documentation			1 per page ▼	✓
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	20/11/18 09:38	FBK2832X GIA REPORT From: SC - Reg. No: SJS2060U, Claimant: RONALDO ROBANGSA	Load PDF	
2	20/11/18 14:28	PRI ASSIGN LKK	Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	30/01/19 16:58	SUPPLEMENTARY	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST			Reset	Save	Print
There are no document checklists configured.					

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer
 Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18020990/NQD3S2
Date: 30/01/2019

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	A80443952QMX
Claimant Vehicle No :	FBK2832X	Insured Vehicle No :	SJS2060U
Date of Loss:	13/11/2018	Nature of Claim:	TP
		Claim No:	576332

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBK2832X	Engine No:	H402E0010078
Make & Model:	YAMAHA YZF-R3, 321cc ABS	Chassis No:	MH3RH071000003537
Reg. Date:	16/06/2015 (Man. Year: 2015)	Odometer:	38860 km
Colour:	Blue		
Engine Capacity:	321 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	120/70 R17	Rear Tyre Size:	140/70R17
Front Left Side:	Bridgestone 5 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,256.50	4,448.00	2,808.50	38.70
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,920.00	410.00	1,510.00	78.65
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,176.50	4,858.00	4,318.50	47.06
Approved Total (Overridden) (S\$)		3,900.00		
(S\$)	9,176.50	3,900.00	5,276.50	57.50
+ GST 7.00/7.00% (S\$)	642.36	273.00	369.36	57.50
Nett Amount (S\$)	9,818.86	4,173.00	5,645.86	57.50

INSPECTION

Date of Assignment:	20/11/2018	
Date Inspected:	21/11/2018	Inspected At: Bike Production Pie Ltd (HQ) 610 SERANGOON ROAD Singapore 218216
Estimated Period of Repair:	3.0 days	

Adjuster: Muhammad Nazril Bin Abdullah

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but

any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 30 Jan 2019)	
Parts:	N/A	YAMAHA YZF-R3 321cc ABS (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBK2832X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT MUDGUARD	Scratched	195.00 FL	*195.00 FL
2	1		*RIGHT FORK ASSY (FORK OUTER TUBE ONLY)	Scratched	495.00 FL	*250.00 FL
3	1		*FRONT COWLING	Scratched	285.00 FL	*285.00 FL
4	1		*RIGHT MIRROR	Scratched	135.00 FL	*135.00 FL
5	1		*RIGHT BLACK COVER	Scratched	125.00 FL	*125.00 FL
6	1		*STEERING BRIDGE	Serviceable	295.00 FL	*- FL
7	2		*STEERING BEARING	Serviceable	90.00 FL	*- FL
8	1		*STEERING STEM	Serviceable	305.00 FL	*- FL
9	1		*RIGHT FUEL TANK COVER	Scratched	325.00 FL	*320.00 FL
10	1		*RIGHT FUEL TANK EMBLEM	Necessary	50.00 FL	*50.00 FL
11	1		*RIGHT FAIRING	Scratched	345.00 FL	*340.00 FL
12	1		*RIGHT FAIRING INNER BLACK	Scratched	205.00 FL	*170.00 FL
13	1		*RIGHT FAIRING AMBLEM	Not Necessary	85.00 FL	*- FL
14	1		*RIGHT SLIDER	Scratched	145.00 FL	*100.00 FL
15	1		*RIGHT ENGINE COVER	Cracked	455.00 FL	*350.00 FL
16	1		*RIGHT ENGINE COVER GASKET	Necessary	65.00 FL	*25.00 FL
17	1		*RIGHT LOWER COVER	Scratched	205.00 FL	*170.00 FL
18	1		*RIGHT FOOTREST	Scratched	95.00 FL	*95.00 FL
19	1		*RIGHT FOOTREST HOLDER	Bent	175.00 FL	*130.00 FL
20	1		*BRAKE PEDAL	Bent	85.00 FL	*85.00 FL
21	1		*BALANCER RIGHT	Serviceable	45.00 FL	*- FL
22	1		*HANDLE BAR RIGHT	Serviceable	195.00 FL	*- FL
23	1		*BRAKE LEVER	Scratched	65.00 FL	*65.00 FL
24	1		*EXHAUST	Scratched	1,650.00 FL	*900.00 FL
25	1		*REAR RIGHT COVER	Scratched	285.00 FL	*250.00 FL
26	1		*REAR FOOTREST HOLDER RIGHT	Scratched	175.00 FL	*140.00 FL
27	1		*REAR FOOTREST RIGHT	Scratched	75.00 FL	*75.00 FL
28	1		*FRONT SPORT RIM	Serviceable	480.00 FS	*- FS
29	1		*FRONT NUMBER PLATE	Not Necessary	20.00 FS	*- FS
30	1		*LOWER RIGHT FAIRING BRACKET	Bent	85.00 FL	*50.00 FL
31	1		*WATER PUMP OUTER ASSEMBLY	Scratched	295.00 FL	*220.00 FL
32	1		*CLUTCH AXLE ASSEMBLY	Broken	330.00 FL	*270.00 FL
33	1		*RIGHT FAIRING STICKER	Scratched	75.00 FL	*75.00 FL
34	1		*ENGINE OIL	Necessary	30.00 FS	*30.00 FS
35	1		*COOLANT	Necessary	35.00 FS	*35.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	8,000.00	4,935.00
- List Item Discount on L Items 10.00/10.00% (\$)	743.50	487.00
Total Parts (\$)	7,256.50	4,448.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING CHARGES.	New	100.00	60.00
2	REPLACE, REALIGN AND ADJUST ABOVE DAMAGED PARTS, CHECK WIRING AND LIGHTING SYSTEM.	New	700.00	200.00
3	TO REPLACE AND BALANCE FRONT AND REAR WHEEL RIM.	New	120.00	0.00
4	TO KNOCK, STRAIGHTEN CHASSIS & BODY BALANCING.	New	450.00	0.00
5	TO REMOVE / REFIT, REPLACE (IF DAMAGE) CHECK AND STRAIGHTEN FRONT FORK TUBES.	New	180.00	0.00
6	SPRAY PAINTING.	New	250.00	150.00
7	RESET METER.	New	120.00	0.00
Gross Labour Cost (\$\$)			1,920.00	410.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >