

BIKE PRODUCTION PTE LTD

610, Serangoon Road S(218216)

Tel: 63922555, 62995177 Fax: 62975400

ROC/ GST Reg No.: 200007407G

Date: 14 Nov 2018

ASSESSMENT FOR REPAIR: YAMAHA YZF-R3 ABS - FBK2832X

Chassis No.: MH3RH071000003537

Engine No.: H402E0010078

Qty

Description

Estimate

1 pc	Front mudguard		\$195.00	SCR
1 pc	Right fork assy (fork tube only)	fork \$295	\$495.00	fork outer tube (SCR)
1 pc	Front cowling	\$2.50	\$285.00	SCR
1 pc	Right mirror		\$135.00	SCR
1 pc	Right black cover		\$125.00	SCR
1 pc	Steering bridge		\$295.00	X SVC
2 pcs	Steering bearing @ \$45.00		\$90.00	X SVC
1 pc	Steering stem		\$305.00	X SVC
1 pc	Right fuel tank cover	\$320	\$325.00	SCR
1 pc	Right fuel tank emblem		\$50.00	NEC
1 pc	Right fairing	\$340	\$345.00	SCR
1 pc	Right fairing inner black	\$170	\$205.00	? SCR
1 pc	Right fairing emblem		\$85.00	X no emblem
1 pc	Right slider	\$100	\$145.00	SCR
1 pc	Right engine cover	\$350	\$455.00	X R SCR
1 pc	Right engine cover gasket	\$25	\$65.00	NEC
1 pc	Right lower cover	\$170	\$205.00	SCR
1 pc	Right footrest		\$95.00	X SVC SCR
1 pc	Right footrest holder	\$130	\$175.00	X SVC BT
1 pc	Brake pedal		\$85.00	X SVC BT
1 pc	Balancer right		\$45.00	X SVC
1 pc	Handle bar right		\$195.00	X SVC
1 pc	Brake lever		\$65.00	SCR
1 pc	Exhaust	\$900	\$1,650.00	SCR X SVC change to original exhaust
1 pc	Rear right cover	\$250	\$285.00	SCR
1 pc	Rear footrest holder right	\$140	\$175.00	SCR
1 pc	Rear footrest right		\$75.00	SCR

Less discount 10%

Special nett items

1 pc	Front sport rim		\$480.00	X SVC
1 pc	Front number plate		\$20.00	X NN
1)	Towing charges @ \$30	\$60	\$100.00	(show receipt)
2)	Replace, realign and adjust above damaged parts, check wiring and lighting system		\$700.00	200
3)	To replace and balance front and rear wheel rim		\$120.00	X NN
4)	To knock, straighten chassis & body balancing		\$450.00	200 X NN
5)	To remove/refit, replace (if damage) check and straighten front fork tubes.		\$180.00	X NN
6)	Spray painting		\$250.00	

7)

Reset meter

\$120.00 x ~~AM~~

Total Estimate

\$7,784.00

8405

Note: The above estimate is subjected to the prevailing GST of 7%

\$410

9176-50

For Bike Production Pte Ltd

NAZ LKK

21/11/18

L/S

3 DAYS

CHECK ITEMS PHOTO

AFTER REPAIR PHOTO


 22/11/18

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SUPPLEMENTARY ITEMS

1. LOWER RIGHT FAIRING BRACKET	\$50	\$85	✓ BT
2. WATER PUMP OUTER ASSEMBLY	\$220	\$295	✓ KR
3. CLUTCH AXLE ASSEMBLY	\$270	\$330	✓ BEK
4. RIGHT FAIRING STICKER	\$	75	✓ SCR
	\$615	785	
		706.50	

SUPPLEMENTARY SPECIAL NETT ITEMS

1. ENGINE OIL	\$30	✓ NEC
2. COOLANT	\$35	✓ NEC
	\$65	

PARTS	\$ 4,870
LESS 10%	\$ 4,383
s/NETT	\$ 65
LABOUR	\$ 410
TOTAL	\$ 4,858
LESS 20%	\$ 3,886.40
L/S TOTAL	\$ 3,900.00

Page 2

/ 3 DAYS