

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/1322/2018/JT
Date : 20-Nov-18

Kindly arrange for survey.

Your insured vehicle no. SJS 1156 J.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Mark Poh Geong Yeow
Address : 25 Woodleigh Close
#02-03
Singapore 357920
Telephone : HP +65 9738 1374
Type of Claim : Third Party Claim
Policy No. : PNPV2018-00013488
Vehicle No : **SCK 303 H**
Model Code : Audi A6 C7 2.0 TFSI Mu
Model / Year : Nov-13
Engine No : CDN 364484
Chassis No : WAUZZZ4G3EN037947
Mileage : -
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 17-Nov-18
Place of Accident : Along PIE/Changi Airport just before Sims Exit

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SCK 303 H

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To repair rhs rear door and rhs rear fender.	\$ 900.00	750.
2	To respray rhs rear door, rhs sill panel trim and rhs rear fender.	\$ 2,300.00	1650.
3	To renew rhs rear rim and carry out wheel alignment.	S/N \$ 280.00	✓
4	To reapply paint coating for affected area.	S/N \$ 450.00	✓ \$
TOTAL LABOUR CHARGES		: \$ 3,930.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SCK 303 H

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	1 SET OF CLIP ATTACHMENT PARTS <i>not on</i>	\$ 91.00	X
2	1 SET OF ADHESIVE TAPE ATTACHMENT PARTS <i>not on</i>	\$ 14.00	X
3	RUBBER VALVE <i>not on</i>	4 \$ 12.00	X
4	REAR RHS RIM <i>ht</i>	TBC	✓
5	SUNDRIES ?	\$ 300.00	7
TOTAL SPARE PARTS CHARGES		\$ 417.00	
TOTAL LABOUR CHARGES		\$ 3,930.00	
GRAND TOTAL		\$ 4,347.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Ling
Surveyed Date : 05/12/18
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 04 Days

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant