55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

#### **Telefax**

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183

Reference : PA/TP/1322/2018/JT

**Date** : 20-Nov-18

Kindly arrange for survey.

Your insured vehicle no. SJS 1156 J.

#### AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way #07-16 AIG Building Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Mark Poh Geong Yeow Address : 25 Woodleigh Close

#02-03

Singapore 357920

 Telephone
 : HP +65 9738 1374

 Type of Claim
 : Third Party Claim

 Policy No.
 : PNPV2018-00013488

 Vehicle No.
 : SCK 202 H

Vehicle No : SCK 303 H

Model Code : Audi A6 C7 2.0 TFSI Mu Model / Year : Nov-13

Engine No : CDN 364484

Chassis No : WAUZZZ4G3EN037947

Mileage : Date In : Liability : Excess Cost : -

Estimated By : Johnny Boo / Allan Wu

Accident Date : 17-Nov-18

Place of Accident : Along PIE/Changi Airport just before Sims Exit

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

### **Telefax**

## Estimated Labour Charges for Accident Vehicle SCK 303 H.

S/N	Nature of Jobs		Estimated Charges		
1	To repair RHS rear door and RHS rear fender. To remove RHS sill panel to faciliate respray of trim.		\$	1,400.00	
2	To rspray RHS rear door, RHS sill panel trim and RHS rear fender.		\$	2,500.00	
3	To renew RHS rear rim and carry out wheel alignment.	S/N	\$	280.00	
4	To carry out diagnostic check.	S/N	\$	192.00	
	TOTAL LABOUR CHARGES	:	\$	4,372.00	

All charges are not inclusive of GST.

Remarks (OK) = Approved, Remarks (X) = Not approved

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

### Telefax

## Material List for Accident Vehicle Regn No. SCK 303 H.

			<b>Damage Parts &amp; Prices</b>				
S/N	Parts Description		S	NETT	<u>RE</u> MARKS		
1	Sill panel attachement parts - RHS		\$	91.0	0		
2	Sill panel trim adhesive tape - RHS		\$	14.0	0		
3	Rear rim - RHS		TBO	-			
4	Sundries		\$	300.0	0		
	TOTAL SPARE PARTS	:	\$	405.0	0		
	TOTAL LABOUR CHARGES	:	\$	4,372.0	0_		
	GRAND TOTAL	:	\$	4,777.00	0		

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

#### **Telefax**

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.

Should we require further labour charges and spare parts in the

progress of repair, we shall inform you accordingly.

For inspection of vehicle, please refer to Ms Norah Khai at

Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo Allan Wu

Body Repair Manager Claims Consultant