

BMW Dealer

Performance Motors LimitedA member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
64796601 (AfterSales)
64796624 (Motorrad)

Survey & repair

1/ NOV 2018



26.11 @ 10am

GST REG. NO : M2 - 0020081 - X

E S T I M A T EEstimate No. : b1 49063
Date Estimated : 10/11/2018
Prepared By : Chua Kee Sin

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -Matthew Thomas Chin
47 Hume Avenue
#09-08

Singapore 598748

- ACCOUNT - 40000Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKJ9523R	J720416	30/05/2013	316iA/4	0

DESCRIPTION

Replacing rear left door

850 1,275.00

Painting left rear door

796 885.00

To carry out body cavity preservation.
(Per panel).

100 118.00

To supply and install rear left window glass quoter
solar film.

361 425.00

Sundries.

? 150.00

To transfer lock mechanism from old to new door including
conduct checks on new door power window system for proper
function. (1 door).

451 531.00

Total Labour 1: **3,384.00**DESCRIPTION

REAR LH DOOR

QTY	PRIC	VALUE
1	1,267.50	dd 1,267.50

Abdichtung B

1 4.60 ne 4.60

SEALING STRIP

1 20.60 ne 20.60

RR LH DOOR OUTER DUCT COVER (GLANZS

1 111.90 ne 111.90

REAR LH DOOR INNER WERTHERSTRIP

1 71.70 ne 71.70

REAR DOOR WEATHERSTRIP

1 140.70 ne 140.70

RR LH DOOR WINDOW FRAME COVER

1 73.25 ? 73.25

LH EXTERIOR COVER WINDOW GUIDE WEB

1 61.75 ? 61.75

REAR LH SIDE WINDOW FIXED

1 171.70 ne 171.70

Seal

1 17.35 ne 17.35

REAR LH DOOR WINDOW GUIDE

1 124.40 124.40

(DG) CLEANER R1 (100ML)

1 26.15 ne 26.15

(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)

1 131.55 ne 131.55

(DG/SL) GLASS PRIMER 30ML (VP206)

1 27.85 ne 27.85

Total Parts : **2,251.00**

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : **b1 49063**
Date Estimated : **10/11/2018**
Prepared By : **Chua Kee Sin**

Page No. : **2 of 5**

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKJ9523R	J720416	30/05/2013	316iA/4	0

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time 28/11/18 4:40 PM Excess S\$ _____

Surveyor's Name Tayfun Sign Tayfun

Surveyor's Tel 97495744 Authorised Yes / No

Authorised Date WP Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No

Surveyor's E-mail Tayfun@khanh.com

Working Days Recommend 4 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Labour 1	:	3,384.00
Parts	:	2,251.00
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	394.45
Grand Total	:	6,029.45

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **