

ASS. REC. BY:

REF: 23/MSG18020999/ Dvd3

Special Instruction:

Surveyor:

Bryan

ASSIGNMENT (Office)

From (Person):

Pauline Thom

of

MSG

Date/Time:

20/11/18 4:20pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHA 1797C

Insured:

SLM 1776C

at Workshop m/s

800n Hook Motor

Tel:

65425119

of

Blk 10, AMK Ind. Park 2A # 01-05/06

Policy No:

A29069766MKF

Claim No:

576379

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

19/11/2018

21/11/18

H.O.D. Endorsement:

CA / REV / REP. / REV 24 HRS

up

Date/Time:

4:41pm @ 20/11/18

Person Contacted:

Lynn

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SHA 1797C - CS3 / FCI 18017393 / R / CD 3s 2

D.O.A: 22/09/18

SLM 1776C - NA / AIG 17022712 / 14

D.O.A: 02/11/2017

21/11/18

Send preli revised via merimen

REF:

ASSIGNMENT

CBE Dec 2024

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop no:

of

Insured

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

48

days:

Res.: Yes or No

Lum Sum:

20

%

3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No: BHA 1797C

V Regn: 2015 Dec

Type: M/Gar / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai I40

CC: 1685

Colour:

Blue

A/C

Insured / Std / Nil / NA

Sp Reading:

357998

T/Radio: Insured / Std / Nil / NA

Eng No:

D4FDGU699770

Ch No:

KMHLB41UMHU097687

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Insured / Jammed / Leaked / Burnt or

Brake: Insured / Jammed / Leaked / Burnt or

Modi: Nil / SRim / STD A/Rim or

Tyre Size:

F:

205/60 R16

R:

— 11 —

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Camper

Front

Rear

R/Bal.

S

mm

R/Bal.

S

mm

L/Bal.

S

mm

L/Bal.

S

mm

D.O.A.

19/11/2018

D.O.A.

21/11/2018

Survey held at

Chunni Amk

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Body y O/S Rev

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

NSIG SLM 1776C

10/2/18

Jinay + 15 11000/- with 8 days Jm (Recd 8946.88, 45%)

RECEIVED 11 DEC 2018

Date/Time, File Pass to?



Prel. Report

D)



Final Report

Date/Time, File Return to?

D)

n/12 - typist

Days Of Repair:

8

Resurvey No. of Trip:

2

Survey Fee:

Transportation

S + RS \$

Photos

Others

TOTAL

200
10

210

Report Format :

merimen

Lump Sum / L.B.f. (\$)

11,000/-

Add Fee:



Site Insp. (\$)



Interview (\$)



Tech. Invs (\$)



Weekend (\$)

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Pauline Tham

Date: 27 Nov 2018

Preliminary Advice

Insured Vehicle No	: SLM1776C		
TP Vehicle No	: SHA1797C	Accident Date	: 19/11/2018
Make	: HYUNDAI I40	Assignment Date	: 20/11/2018
Date of Inspection	: 21/11/2018	Est. Duration of Repair	: 7.00
Inspection At	: SOON HOCK MOTOR PTE LTD (HQ) BLK 10 ANG MO KIO INDUSTRIAL PARK 2A, #01-05/06 AMK AUTOPOINT SINGAPORE 568047		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s rear portion and o/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	19,946.88
Revised Amount	:S\$	13,872.96
Check Items (Estimated)	:S\$	0.00
Total	:S\$	13,872.96

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	19 Nov 2018		20 Nov 2018 16:20 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	GRAB RENTALS PTE LTD, Co. Reg. No.: 201617200G			
Main Claimant:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R			
Vehicle Reg. No.:	SHA1797C	Date of Loss:	19/11/2018 08:00 - :59 [22 Months and 21 Days From LTA Reg Date (Man Yr)]	
Claim Type:	TP / 576379	Policy/Cover Note No.:	A29069766MKF (Comprehensive) Coverage: 01/02/2018 - 31/01/2019	
Vehicle Reg. No. (Insured):	SLM1776C	Policy No. (Claimant):		
		Excess:		
Repairer:	Soon Hock Motor Pte Ltd (HQ) Blk 10 Ang Mo Kio Industrial Park 2A, #01-05/06 AMK Autopoint, 568047 Ang Mo Kio - Tel: 64836016			
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Pauline Tham - 6594 2545]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 21/11/2018]			
Driver/Custodian (Insured):	ONG POH SENG SIMPSON (), NRIC: S8207273Z, Tel: +6594500924			
Adj Asg. Remarks:	OI GRAB. Liability 100%.			

ASSOCIATED MAIL RECEIVED
[View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS
[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Veron Chen (LKKAuto)

From: Pauline Tham <pauline_tham@sg.msig-asia.com>
Sent: Saturday, 8 December 2018 12:38 PM
To: SUR
Subject: Yref : SLM1776C, OREF ; 576379

Dear Janice/Catherine,

Please let us have the finalised report soon.

Thanks.

Pauline Tham

Senior Executive, Claims Services, Motor

D: +65 6594 2545 | F: +65 6225 7402 | pauline_tham@sg.msig-asia.com



MSIG



Insurer Claims
Team of the Year
2016

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

MCD618149665 / ComfortDelGro Engineering Pte Ltd - Layan
 ENTRY DATE & TIME: 19/11/2018 15:40
 SUBMITTED BY: Catherine Por Moy Juan

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 19/11/2018 15:40
 Date Of Accident 19/11/2018 08:50
 Exact Location Of Accident UPPER CROSS ST TOWARDS CTE
 Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SHA1797C
 Insured/Policyholder
 Name Of Registered Owner COMFORT TRANSPORTATION PTE LTD
 Co Reg No 199303821R
 Email Address FLEETSAFETY@CDGTAXI.COM.SG
 Mobile Phone No
 Alternative Phone No OFFICE-65508768
 Vehicle Particulars
 Manufacturer HYUNDAI
 Model I40
 Exact Purpose for which vehicle was being used at time of accident
 Are you claiming under your own insurance policy for repair to your vehicle? NO
 If No, Please state action to be taken THIRD PARTY
 Vehicle Category TAXI
 Insurance Company
 Name of Insurance Company MS FIRST CAPITAL INSURANCE LTD
 Type Of Coverage THIRD PARTY FIRE AND/OR THEFT
 Fleet Policy YES
 Policy Number D-18088936MFSH
 Cover Note Number
 Driver
 Name of Driver LEE CHONG HENG
 NRIC No S0826793F
 Date Of Birth 15/10/1952
 Occupation OUTDOOR
 Date Of Driving Pass 24/12/1973
 Driving Experience 44 YEARS AND 10 MONTHS
 Gender MALE
 Mobile Number (LOCAL) +65-98198978
 Fax Number
 Contact Number
 Email Address LEECHONGHENG1510@YAHOO.COM

Address 557 #02-1892 ANG MO KIO AVENUE 10
Postcode 560557
Was driver an employee of the Insured's Company NO
If No, Relationship of the Driver with the Insured OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle -
Vehicle -
Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident COLLISION - MAJOR/MINOR RD
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Number of vehicles involved in the accident
Was any body injured in the Accident? NO
Was any injured conveyed to hospital by ambulance? NO
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
If Yes, Please state which Police Station
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

SEE ATTACH.

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? YES
Remarks/ Reasons: -
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLM1776C
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage FRT
No. Of Passenger (Including Driver)

SKETCH PLAN**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by Interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


COMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 199303821R

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time: 19.11.2018 @ 12:35 Hrs

Reporting Centre Personnel's Signature
Name: *Rubini*
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 19.11.2018 at about 08:50 hrs, I was travelling along Upper Cross St towards CTE with no passenger on board.

I was travelling straight. Suddenly, veh (B) (SLM 1776C) dashed out from the slip road from my right and hit my taxi (A) whole right portion. This causes my taxi (A) to sustain damages on whole right portion.

I have company video fixed in my taxi and photos taken at scene to support my claims.

Veh (B) (SLM 1776C). Male driver.

No injury in this accident.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 199303821R

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time: 19.11.2018 @ 12:35 Hrs

Reporting Centre Personnel's Signature
Name: Rubbini
NRIC/FIN No.:

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Fender With Housing (RH) Distorted		2020.00	\$ 4,736.80 ✓
	Rear Fender Inner Lining (RH) S/L			\$ 169.30 X
	Rear Windscreen Moulding H/L			\$ 28.30 X ✓
	Rear Door (RH) S/L			\$ 2,201.10 ✓
	Rear Door Rubber (RH) H/L			\$ 280.50 ✓
	Rear Door Gear/Regulator (RH) Z crank			\$ 242.80 Z ✓
	Rear Door Power Motor (RH) H/L			\$ 158.60 X
	Front Door (RH) S/L			\$ 2,256.40 ✓
	Front Door Rubber H/L			\$ 290.50 ✓
	Front Door Gear / Regulator (RH) Z crank			\$ 250.60 Z ✓
	Front Door Power Motor, RH H/L			\$ 296.40 X
	Door Centre Pillar Outer (RH) Distorted			\$ 2,527.80 ✓
	Rocker Panel Outer Garnish (RH) distorted			\$ 341.40 ✓
	Rear Tyre Rim (RH) Z distorted			\$ 325.30 Z ✓
	Rear Wheel Hub-Cap (RH) Cnt			\$ 107.10 ✓
	Rear Wheelbearing ING & Hub Z Done			\$ 362.00 Z ✓
	Rear Trailing Arm (RH) Z distorted			\$ 192.00 Z ✓
	Rear Assist (RH) Z distorted			\$ 145.70 Z ✓
	Rear Shock Absorber (RH) Z distorted			\$ 276.30 Z ✓
	Rear Shock Absorber Mounting (RH) H/L			\$ 81.30 X
	Rear Crossmember Z distorted			\$ 1,021.50 Z ✓
	Stabilizer Bar Z distorted			\$ 199.60 Z ✓
	Stabilizer Link Z distorted			\$ 85.90 Z ✓
	Rear Upper Arm (RH) Z distorted			\$ 335.75 Z ✓
	Rear Lower Arm (RH) Z distorted			\$ 353.80 Z ✓
	Rear Knuckle Arm (RH) Z distorted			\$ 545.60 Z ✓
	SUB TOTAL		14389.95	\$ 17,812.35
	LESS 20%		11511.96	\$ 3,562.47
	DISCOUNTED TOTAL			\$ 14,249.88
	Rear Windscreen Sealant H/L			\$ 46.00 Nett ✓
	Rear Door Comfortelgro & Apps Sticker (RH) H/L			\$ 80.00 Nett ✓
	Front Door Coloured Comfort Logo (RH) H/L			\$ 75.00 Nett ✓
	Rear Tyre (RH) S/L			\$ 216.00 Nett X
			151.00	\$ 417.00
			201.00	

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Labour Charge			\$ 1,800.00
	Panel Beating			\$ 1,250.00
	Spray Painting Charge			\$ 50.00
	Wiring Charge			\$ 100.00
	Tuff Kote			\$ 50.00
	Towing Charge			\$ 150.00
	Remove/Refix Cushion & Upholstery Rear			\$ 120.00
	Remove/Refix Rear Windscreen Glass			\$ 120.00
	Remove/Refix Reverse Sensor			\$ 240.00
	Transfer of Door		\$ 120.00	\$ 200.00
	Remove/Refix Undercarriage (RR)			\$ 120.00
	Rear Wheel Alignment			\$ 200.00
	Re-set Rear ABS System			\$ 400.00
	Re-set Frt & Rear Power Window System		\$ 200.00	\$ 480.00
	Diagnostic & Resetting To Erase Fault Code			
	TOTAL LABOUR		2160.00	\$ 5,280.00
	ESTIMATE TOTAL			\$ 19,946.88
	21/11/18 NA Anthony L/Sume Ryan LKK Auto		1387296 4S 11000/-	
	LKK Auto Consultants hence notify the Repairer of the following:			
	To resurvey before/after spray painting			
	To display damaged part(s) during resurvey			
	Parts prices are subject to confirmation			
	Third party survey is on a "Without Prejudice" basis			
	No illegal modification(s) is allowed			
	Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company			
	Acknowledged by Repairer			
	Signature:			
	Date:			
	This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.			

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

NAME
ADDRESS

Home Tel.:

VIN:

Registration: SHA 1797 C

Technician:

Mileage: 357999

Time Printed 21.11.18 3:31 PM

HYUNDAI I40

Front : Left

Actual	BEFORE	Specified Range
-0°17'		-3°00' 3°00'
3°39'		-0°19' 5°41'
-0°21'		-1°30' 1°30'
13°16'		
12°59'		

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	BEFORE	Specified Range
-0°39'		-3°00' 3°00'
3°59'		-0°19' 5°41'
0°05'		-1°30' 1°30'
13°37'		
12°58'		

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	BEFORE	Specified Range
0°22'		-3°00' 3°00'
-0°19'		-3°00' 3°00'
-0°21'		-3°00' 3°00'
-0°16'		-3°00' 3°00'

Rear : Left

Actual	BEFORE	Specified Range
0°57'		-3°30' 2°30'
0°20'		-1°30' 1°30'

Camber
Toe

Rear : Right

Actual	BEFORE	Specified Range
4°45'		-3°30' 2°30'
5°49'		-1°30' 1°30'

Rear

Cross Camber
Total Toe
Thrust Angle

Actual	BEFORE	Specified Range
-3°48'		-3°00' 3°00'
6°09'		-3°00' 3°00'
-2°45'		-3°00' 3°00'

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18020999/DVD3N2

Date: 11/12/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	A29069766MKF
Claimant Vehicle No :	SHA1797C	Insured Vehicle No :	SLM1776C
Date of Loss:	19/11/2018	Nature of Claim:	TP
		Claim No:	576379

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHA1797C	Engine No:	D4FDGU699770
Make & Model:	HYUNDAI I40, 1.7 L CRDI AT ABS AIRBAG 4DR (A)	Chassis No:	KMHLB41UMHU097687
Reg. Date:	29/12/2016 (Man. Year: 2016)	Odometer:	357998 km
Colour:	Blue		
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60R16	Rear Tyre Size:	205/60R16
Front Left Side:	Campeon 5 mm	Rear Left Side:	Campeon 5 mm
Front Right Side:	Campeon 5 mm	Rear Right Side:	Campeon 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	14,666.88	11,712.96	2,953.92	20.14
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,280.00	2,160.00	3,120.00	59.09
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	19,946.88	13,872.96	6,073.92	30.45
Approved Total (Overridden) (S\$)		11,000.00		
(S\$)	19,946.88	11,000.00	8,946.88	44.85
+ GST 7.00/7.00% (S\$)	1,396.28	770.00	626.28	44.85
Nett Amount (S\$)	21,343.16	11,770.00	9,573.16	44.85

INSPECTION

Date of Assignment: 20/11/2018

Date Inspected: 21/11/2018 Inspected At:

CHUNNI MOTOR WORK PTE LTD
BLK 10 ANG MO KIO IND. PARK 2A,
#03-19 AMK AUTOPOINT
SINGAPORE 568047

Estimated Period of Repair: 8.0 days

Adjuster: BRYAN TANI

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 11 Dec 2018)
Parts:	143	HYUNDAI I40 1.7 L CRDI AT ABS AIRBAG 4DR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHA1797C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR FENDER RH	Dented	4,736.80 FL	*2,020.00 FL
2	1		*REAR FENDER INNER LINING RH	Serviceable	169.30 FL	*- FL
3	1		*REAR WINDSCREEN MOULDING	Necessary	28.30 FL	*28.30 FL
4	1		*REAR DOOR RH	Buckled	2,201.10 FL	*2,201.10 FL
5	1		*REAR DOOR RUBBER RH	Necessary	280.50 FL	*280.50 FL
6	1		*REAR DOOR GEAR/REGULATOR RH	Cracked	242.80 FL	*242.80 FL
7	1		*REAR DOOR POWER MOTOR RH	Not Necessary	158.60 FL	*- FL
8	1		*FRONT DOOR RH	Buckled	2,256.40 FL	*2,256.40 FL
9	1		*FRONT DOOR RUBBER	Necessary	290.50 FL	*290.50 FL
10	1		*FRONT DOOR GEAR/REGULATOR RH	Cracked	250.60 FL	*250.60 FL
11	1		*FRONT DOOR POWER MOTOR RH	Not Necessary	296.40 FL	*- FL
12	1		*DOOR CENTRE PILLAR OUTER RH	Dented	2,527.80 FL	*2,527.80 FL
13	1		*ROCKER PANEL OUTER GARNISH RH	Distorted	341.40 FL	*341.40 FL
14	1		*REAR TYRE RIM RH	Distorted	325.30 FL	*325.30 FL
15	1		*REAR WHEEL HUP-CAP RH	Cut	107.10 FL	*107.10 FL
16	1		*REAR WHEELBEARING ING & HUB	Damaged	362.00 FL	*362.00 FL
17	1		*REAR TRAILING ARM RH	Distorted	192.00 FL	*192.00 FL
18	1		*REAR ASSIST RH	Distorted	145.70 FL	*145.70 FL
19	1		*REAR SHOCK ABSORBER RH	Distorted	276.30 FL	*276.30 FL
20	1		*REAR SHOCK ABSORBER MOUNTING RH	Not Necessary	81.30 FL	*- FL
21	1		*REAR CROSSMEMBER	Distorted	1,021.50 FL	*1,021.50 FL
22	1		*STABILIZER BAR	Distorted	199.60 FL	*199.60 FL
23	1		*STABILIZER LINK	Distorted	85.90 FL	*85.90 FL
24	1		*REAR UPPER ARM RH	Distorted	335.75 FL	*335.75 FL
25	1		*REAR LOWER ARM RH	Distorted	353.80 FL	*353.80 FL
26	1		*REAR KNUCKLE ARM RH	Distorted	545.60 FL	*545.60 FL
27	1		*REAR WINDSCREEN SEALANT	Necessary	46.00 FS	*46.00 FS
28	1		*REAR DOOR COMFORTDELGRO & APPS STICKER RH	Necessary	80.00 FS	*80.00 FS
29	1		*FRONT DOOR COLOURED COMFORT LOGO RH	Necessary	75.00 FS	*75.00 FS
30	1		*REAR TYRE (RH)	Serviceable	216.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	18,229.35	14,590.95
- List Item Discount on L Items 20.00/20.00% (S\$)	3,562.47	2,877.99
Total Parts (S\$)	14,666.88	11,712.96

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,800.00	800.00
2	SPRAY PAINTING CHARGE	New	1,250.00	800.00
3	WIRING CHARGE	New	50.00	30.00
4	TUFF KOTE	New	100.00	40.00
5	TOWING CHARGE	New	50.00	-
6	REMOVE/REFIX CUSHION & UPHOLSTERY REAR	New	150.00	80.00
7	REMOVE/REFIX REAR WINDSCREEN GLASS	New	120.00	80.00
8	REMOVE/REFIX REVERSE SENSOR	New	120.00	-
9	TRANSFER OF DOOR	New	240.00	120.00
10	REMOVE/REFIX UNDERCARRIAGE (RR)	New	200.00	150.00
11	REAR WHEEL ALIGNMENT	New	120.00	60.00
12	RE-SET REAR ABS SYSTEM	New	200.00	-
13	RE-SET FRT & REAR POWER WINDOW SYSTEM	New	400.00	-
14	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE	New	480.00	-
Gross Labour Cost (S\$)			5,280.00	2,160.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >