

22/03/2002

ASS. REC. BY:

REF:

CS/FCL18021005/Bvber

Special Instruction:

Survivor

ASSIGNMENT (Office)

From (Person):

CWS May Chua

of

FCL

Date/Time:

20/11/2018 5:16pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SMA 5587G

Insured:

SHC 8990D

at Workshop m/s

N-51 Automotiv

Tel:

Ah Yong / Ah Ken

of

Blk 2 Kaki Bukit Ave 2 #01-77

8482 0051

Policy No:

Claim No:

D18008235MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A.

17/11/2018

(Client's Record)

21-11-2018

CA / REV / REP. / REV 24 HRS 'WP'

H.O.D. Endorsement:

Date/Time:

20-11-2018 5:30pm

Person Contacted:

Melody

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SMA 5587A - X

SHC 8990D - CS/FCL16017246 / U/vb328

D.O.A. 07/09/2016

22/11/18

Informed FCI pending est from repairer by email

28/12/18

@ 25:20pm Mr Lim Confirmed LS \$7700 with Mr Koh

CRed 7604.79, 50/9

Autohub

Autohub

REF: TCI

ASSIGNMENT

From: Date: 21.11.2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SMA 5587G
at Workshop m/s N-51 Automotive
of 2 Kaki Bukit Ave 2 #0417

Insured:

Policy No.

Claims No.


Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS 'WP'

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SMA 5587G Yr Regn: 13/6/2018

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: TOYOTA PRIUS C.C 1797

Colour: BLACK A/C: Insured / Std / NI / NA

Sp. Reading: 40615 T/Radio: Insured / Std / NI / NA

Eng/No: 22R0B81238

C/No: JTD353E496J027979

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/60/16

R: 205/60/16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 17/11/18 D.O.I. 21/11/18

Survey held at N51 Automotive

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	MV 25.05.12
	PV 25.06.12
	NV 26.30.12
28/12/18	Email preli. revised to FCI
RECEIVED 20 DEC 2018	

Date/Time. File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time. File Return to?

2) 28/12 - typist

Report Format: CWS

Lump Sum / I.B.I: (\$ 7700)

Days Of Repair: 5

Resurvey No. of Trip: 2

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

Survey Fee:

Transportation: S + RS SI

Photo: 181

Other: 21/11/19

TOTAL

5x15
1704.75
50
50+50
68
463

MOTOR SURVEY ASSIGNMENT

Date	20-11-2018	Our Ref No. D18008235MFSH
Accident Date	17-11-2018	Claim Type. Third Party
Insured Vehicle	SHC8990D	Third Party Vehicle. SMA5587A
Survey Location	2 KAKI BUKIT AVENUE 2 #01-18 KAKI BUKIT AUTOHUB	
Contact Person.	MELODY CHIN	
Contact No.	68420051/ 67440510	Fax No. 67410510
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	N-51 AUTOMOTIVE PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	MAY CHUA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Friday, 28 December 2018 3:28 PM
To: 'CWS Motor Claims'
Cc: 'May Chua Hui Chin'; SUR
Subject: RE: SURVEY ASSESSMENT - D18008235MFSH/1, SMA 5587A
Attachments: SMA 5587G PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SMA 5587G
Date of survey: 21/11/2018
Number of days :5 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAUTO)
Sent: Thursday, 22 November 2018 3:20 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>
Cc: 'May Chua Hui Chin' <maychua@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18008235MFSH/1, SMA 5587A

Dear Sir/Madam,

Please be informed that we have inspected the vehicle SMA 5587A on 21/11/2018.

We are pending estimate from repairer.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Tuesday, 20 November 2018 5:31 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'May Chua Hui Chin' <maychua@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18008235MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]

Sent: Tuesday, 20 November, 2018 5:16 PM

To: ASSIGNMENTS@LKKAUTO.COM

Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; May Chua Hui Chin <maychua@msfirstcapital.com.sg>

Subject: PRI: SURVEY ASSESSMENT - D18008235MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

MS First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D18008235MFSH

Our ref: CS/FCI18021005/Bvb

Date: 28/12/2018

The Motor Claims Department
M/s: MS FIRST CAPITAL INSURANCE LTD

WITHOUT PREJUDICE

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SMA 5587G


We thank you for your instruction on 20/11/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 21/11/2018 at the premises of M/s N-51 AUTOMOTIVE PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$15,304.79
Revised Estimate Amount	: S\$7,700.00 (LUMP SUM)
"Check" Items Amount	: S\$
Booked Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the front portion and n/s body



Comments/Present Status:

Damages Consistent

Yours faithfully,

LIM TEOW GUAN
Asst. Automotive Assessor

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Thursday, 22 November 2018 3:20 PM
To: 'CWS Motor Claims'
Cc: 'May Chua Hui Chin'; SUR
Subject: RE: SURVEY ASSESSMENT - D18008235MFSH/1, SMA 5587A

Dear Sir/Madam,

Please be informed that we have inspected the vehicle SMA 5587A on 21/11/2018.

We are pending estimate from repairer.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Tuesday, 20 November 2018 5:31 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'May Chua Hui Chin' <maychua@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18008235MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Tuesday, 20 November, 2018 5:16 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; May Chua Hui Chin <maychua@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D18008235MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	7200G
Vehicle Details	
Vehicle No.:	SMA5587G
Vehicle to be Exported:	No
Intended Deregistration Date:	21 Nov 2018
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS PLUS (AUTO)
Primary Colour:	Black
Manufacturing Year:	2018
Engine No.:	2ZR0B81238
Chassis No.:	JTDZS3EU90J027979
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$27,507.00
Original Registration Date:	13 Jun 2018
First Registration Date:	13 Jun 2018
Transfer Count:	0
Actual ARF Paid:	\$20,510.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	12 Jun 2028
PARF Rebate Amount:	\$15,382.00
Intended COE Rebate Details	
COE Expiry Date:	12 Jun 2028
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$45,289.00
COE Rebate Amount:	\$43,297.00
Total Rebate Amount:	\$58,679.00

The information contained herein is correct as at 21 Nov 2018

OK

Dep 9010/yr

751/mth

MV 75K

PV 58,679.00

NV 36,300/2

Chin

21/11/18

- 2018 / 2019 Kia Cerato K3 / Forte (BD Series)
- TOC under police investigation - Criminal Defamation
- Multimillion-Dollar Civil Suits against 3 Workers...

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#) [Advertiser Login](#) [Ways of Selling](#)

Mazda CX5 2.5 Luxury Pristine Condition.



Very Well Maintained,
Immaculate Condition 19 Inch
Sports Rims.
Direct Owner StarAd

HIN LUNG AUTO
HoBee Group
One Stop Car Hub
Finance, Insurance, Workshop
New and Used Cars
30 years of car sale

Browse by Category ▼

Sort by Date Posted ▼ 100 results/page ▼

7 vehicles

Toyota Prius

Advanced Search

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Toyota Prius		Any	Any	2018	Any	Any	Any	All
	Toyota Prius	Hybrid 1.8A S	\$98,777	\$9,050 /yr	09-Oct-2018	1,797 cc	23 km	Hatchback	Available
Fuel Type: Petrol-Electric Grab Driver Welcome High Loan Available, 2018 New Model Prius, Vitas Ready, Deliver Immediate, High Accessories With GPS, IRoad Recording Camera, High Trade In Your Existing Car, 5 Years Or 130,000Km ... HTS Motor Posted: 14-Nov-2018 Tags: 2018 Toyota Prius, 2018 toyota prius, Toyota Prius, toyota prius, Toyota, Prius, prius, Used Toyota									
	Toyota Prius	Hybrid 1.8A S	\$96,800	\$9,010 /yr	15-Aug-2018	1,797 cc	3 km	Hatchback	Available
Fuel Type: Petrol-Electric Grab Driver Welcome High Loan Available, 2018 New Model Prius, Vitas Ready, Deliver Immediate, High Accessories With GPS, IRoad Recording Camera, High Trade In Your Existing Car, 5 Years Or 130,000Km ... HTS Motor Posted: 14-Nov-2018 Tags: 2018 Toyota Prius, 2018 toyota prius, Toyota Prius, toyota prius, Toyota, Prius, prius, Used Toyota									
	Toyota Prius	Alpha Hybrid 1.8A S	\$106,800	\$10,380 /yr	09-Feb-2018	1,797 cc	11,400 km	MPV	Available
Fuel Type: Petrol-Electric Elegant Black, 7 Seaters MPV, Almost Brand New, Low Fuel Consumption With Hybrid, Low Maintenance Cost, Very Well Maintained, With Warranty, Drive Away With Minimum Down Payment, Flexible In House Loa... Prime Motor & Leasing Posted: 12-Oct-2018 Tags: 2018 Toyota Prius, 2018 toyota prius, Toyota Prius, toyota prius, Toyota, Prius, prius, Used Toyota									
	Toyota Prius	Alpha Hybrid 1.8A S	\$105,800	\$10,270 /yr	12-Feb-2018	1,797 cc	7,700 km	MPV	Available
Fuel Type: Petrol-Electric Elegant Blue, 7 Seaters MPV, Almost Brand New, Low Fuel Consumption With Hybrid, Low Maintenance Cost, Very Well Maintained, With Warranty, Flexible In-house Loan Packages Available. Prime Motor & Leasing Posted: 03-Oct-2018 Tags: 2018 Toyota Prius, 2018 toyota prius, Toyota Prius, toyota prius, Toyota, Prius, prius, Used Toyota									
	Door Visor 2015 to 2016 Toyota Alphard Injection Door Visor More info about this product								
	Toyota Prius	Alpha Hybrid 1.8A S	\$105,800	\$10,270 /yr	09-Feb-2018	1,797 cc	25 km	MPV	Available
Fuel Type: Petrol-Electric Almost Brand New Condition, 7 Seaters MPV With 3 Years Warranty, Low Deposit, In House Loan Available, High Trade In. Prime Motor & Leasing Posted: 23-Sep-2018 Tags: 2018 Toyota Prius, 2018 toyota prius, Toyota Prius, toyota prius, Toyota, Prius, prius, Used Toyota									

Compare [1]

Select used cars to **Compare** or **Add to Alert**

Shortlist [1]

 Toyota Prius Hybrid 1.8A S
15-Aug-2018

To compare cars, select from the search results.

To compare cars, select from the search results.

To compare cars, select from the search results.

Add to Shortlist
Compare Now
Clear All

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	17/11/2018 19:38
Date Of Accident	17/11/2018 12:00
Exact Location Of Accident	CAIRNHILL NEAR BIDDEFORD ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMA5587G
Insured/Policyholder	
Name Of Registered Owner	GRAB RENTALS PTE LTD
Co Reg No	201617200G
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-66550005

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS PLUS (AUTO)
Exact Purpose for which vehicle was being used at time of accident	HIRE & REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	A29069766MKF
Cover Note Number	

Driver

Name of Driver	YAP HOCK GUAN
NRIC No	S1723922H
Date Of Birth	03/02/1965
Occupation	OUTDOOR
Date Of Driving Pass	14/08/1984
Driving Experience	34 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98572315
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address	NIL
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : P1 GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I was driving on the right side of the road , when suddenly I felt a big impact from my left side . I realised that a blue taxi from the left lane came into my lane and wanted to go to Biddeford road. No injury involved. We exchange particulars.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	RETRIEVING
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHC8990D
Vehicle Make/Model/Colour	HYUNDAI / COMFORT TAXI
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	RAHIM B MAHON
NRIC/Passport Number	S1333843D
Contact Number	84945152
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

Sketch Plan

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
 4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of insurance companies.
 5. Any false reporting may be referred to the Police for investigation.
 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available application by interested parties.
 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)**
- I understand, acknowledge, agree and consent that:
- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


VERIFIED BY AJAX MARS
REPORTING OFFICER
Mohammad Azaly Bin Abdullah

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre
Personnel

Sketch Plan



ACCIDENT STATEMENT (2000 characters)

I was driving on the right side of the road , when suddenly I felt a big impact from my left side . I realised that a blue taxi from the left lane came into my lane and wanted to go to Biddeford road.

No injury involved.

We exchange particulars.

Taxi Voucher No.:

DECLARATION

We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -
MOHAMMAD AZALY BIN ABDULLAH

MARS Officer



Registered Owner or Driver's Signature

Job Complete Date/Time

17 November 2018 at 3:54 PM

Date/Time:

17 November 2018 at 3:54 PM

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

Atte Mr. Lim

(62584315)

GRAB RENTALS PTE LTD
 18 SIN MING LANE #01-08 MIDVIEW CITY
 SINGAPORE 573960

ESTIMATE

Repair Code : CLM14905

Date in : 17/11/2018

Vehicle Num. : SMA5587G

Model : TOYOTA PRIUS PLUS (AUTO)

Chassis/Eng# : JTDZS3EU90J027979/2ZR0B81238

Contact : 66550005 98572315

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
FRONT BUMPER	1	781.10	585.36 781.10 DD
FRONT BUMPER AIR GRILLE LH	1	178.45	178.45 CR
FRONT BUMPER DAYLIGHT LH	1	972.85	910.20 972.85 BR
FRONT BUMPER SIDE BRACKET LH	1	171.10	171.10 NN
FRONT BUMPER SIDE LOCK CLIPS	6	9.50	57.00 } NE
FRONT BUMPER SIDE LOCK CLIPS HOLDER	6	12.90	77.40 }
FRONT BUMPER SIDE RETAINER L/R @ 102.00	2	132.25	2,04.00 264.50 NE
FRONT BUMPER UPPER RUBBER SEAL	1	174.45	174.45 NE
FRONT LH DOOR	1	1218.20	✓ 1,218.20 DD
FRONT LH DOOR BLACK FRAME STICKER	1	121.30	✓ 121.30 NE
FRONT LH DOOR VERTICAL GARNISH	1	151.30	✓ 151.30 NE
FRONT LH DOOR WEATHER STRIP	1	205.20	205.20 NN
FRONT LH FENDER	1	731.35	✓ 731.35 DD
FRONT LH FENDER 'HYBRID' EMBLEM	1	121.10	121.10 NE
FRONT LH FENDER BRACKET	1	172.45	86.50 172.45 NN
FRONT LH FENDER INNER SHIELD	1	259.45	160.00 259.45 TN
FRONT LH FENDER VERTICAL SHIELD	1	97.00	97.00 NI
FRONT LH HEADLAMP	1	2721.10	2,530.00 2,721.10 BR

*** This is a computer-generated document which requires no signature.***

page 1

Sabrina@N51.com.sg

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200616038C

GST Registration No. : 200616038C

GRAB RENTALS PTE LTD

18 SIN MING LANE #01-08 MIDVIEW CITY

SINGAPORE 573960

ESTIMATE

Repair Code : CLM14905

Date in : 17/11/2018

Vehicle Num. : SMA5587G

Model : TOYOTA PRIUS PLUS (AUTO)

Chassis/Eng# : JTDZS3EU90J027979/2ZR0B81238

Contact : 66550005 98572315

FRONT LH HEADLAMP LOWER BRACKET	1	172.45	172.45	NN
FRONT LH KNUCKLE ARM	1	485.00	✓ 485.00	BT
FRONT LH KNUCKLE BEARING	1	517.00	65.00 517.00	JM
FRONT LH LOWER ARM	1	435.00	435.00	} NN
FRONT LH LOWER BALL JOINT	1	127.00	127.00	
FRONT LH SHOCK ABSORBER	1	375.00	375.00	BT
FRONT LH SHOCK ABSORBER TOP MOUNTING	1	151.00	151.00	NN
FRONT LH SPORT RIM HUB CAP	1	378.30	100.00 378.30	SCI
FRONT LH STABILIZER LINK	1	117.00	117.00	NN
FRONT LH TIE ROD END	1	93.00	93.00	NN
ROCKER LH GARNISH	1	947.00	722.50 947.00	DD
STEERING RACK & PINION	1	1580.00	1,580.00	NN
		Subtotal before discount	13,853.05	
Percentage discount 25%			2007.28 3,463.26	
		Sub-total 1	6021.83 10,389.79	
FRONT BUMPER CLIPS - SET	1	50.00	40 50.00	NEC
FRONT LH DOOR INNER TRIM BOARD CLIPS - SET	1	50.00	50.00	NN
FRONT LH DOOR VERTICAL GARNISH CLIPS - SET	1	20.00	20.00	NEC

*** This is a computer-generated document which requires no signature.***

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200616038C

GST Registration No. : 200616038C

GRAB RENTALS PTE LTD

18 SIN MING LANE #01-08 MIDVIEW CITY

SINGAPORE 573960

Contact : 66550005 98572315

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

ESTIMATE

Repair Code : CLM14905

Date in : 17/11/2018

Vehicle Num. : SMA5587G

Model : TOYOTA PRIUS PLUS (AUTO)

Chassis/Eng# : JTDZS3EU90J027979/2ZR0B81238

FRONT LH FENDER INNER SHIELD CLIPS - SET	1	50.00	40 50.00 NE
FRONT LH FENDER VERTICAL SHIELD CLIPS - SET	1	40.00	40.00 NN
FRONT LH SPORT RIM	1	1555.00	1,250.00 1,555.00 CUT
FRONT LH TYRE	1	400.00	400.00 NN
ROCKER LH GARNISH CLIPS - SET	1	60.00	60.00 NE
Subtotal before discount		1410.00	2,225.00
Percentage discount 0%			0.00
Sub-total 2		1410.00	2,225.00
Parts-total		7431.83	12,614.79

LABOUR

To remove, reinstall electrical wiring harness, check lighting. (to FR)	60.00
To remove, reinstall window glass. (to FR)	60.00 80.00
To remove, change front suspension parts, absorber, lower arm, knuckle arm, wheel bearing, bearing hub, drive shaft, anti-roll bar, top-arm and steering rack and pinion.	150.00 350.00 X
To road test driving, check and resetting wheel alignments system.	60.00 100.00
To remove, reinstall roof top trim upholstery, cushion scat, trim garnish, trim liner carpet. (to FR)	100.00 NN
To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	700.00 1,050.00
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	600.00 850.00
To apply anti-rust chemical on repaired and replaced panel.	60.00 100.00
Labour Total	1690.00 2,690.00
Parts & Labour Total	9121.83 15,304.79

Repair days 5



T.Grim

20/11/18

*** This is a computer-generated document which requires no signature.***

L/S 7,100/2



N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200616038C

GST Registration No. : 200616038C

Att Mr. Lim

(6284315)

GRAB RENTALS PTE LTD

18 SIN MING LANE #01-08 MIDVIEW CITY

SINGAPORE 573960

ESTIMATE

Repair Code : CLM14905

Date in : 17/11/2018

Vehicle Num. : SMA5587G

Model : TOYOTA PRIUS PLUS (AUTO)

Chassis/Eng# : JTDZS3EU90J027979/2ZR0B81238

Contact : 66550005 98572315

Parts and Labour Assessment

Description of part	Qty	Unit Price	Amount
FRONT BUMPER	1	781.10	585.36 781.10 DD✓
FRONT BUMPER AIR GRILLE LH	1	178.45	178.45 CR✓
FRONT BUMPER DAYLIGHT LH	1	972.85	910.20 972.85 BR✓
FRONT BUMPER SIDE BRACKET LH	1	171.10	171.10 NN✓
FRONT BUMPER SIDE LOCK CLIPS	6	9.50	57.00 } NEC✓
FRONT BUMPER SIDE LOCK CLIPS HOLDER	6	12.90	77.40 } ✓
FRONT BUMPER SIDE RETAINER L/R @ 102.00	2	132.25	2.04.00 264.50 NEC✓
FRONT BUMPER UPPER RUBBER SEAL	1	174.45	174.45 NEC✓
FRONT LH DOOR	1	1218.20	✓ 1,218.20 DD✓
FRONT LH DOOR BLACK FRAME STICKER	1	121.30	✓ 121.30 NEC✓
FRONT LH DOOR VERTICAL GARNISH	1	151.30	✓ 151.30 NEC✓
FRONT LH DOOR WEATHER STRIP	1	205.20	205.20 NN✓
FRONT LH FENDER	1	731.35	✓ 731.35 DD✓
FRONT LH FENDER 'HYBRID' EMBLEM	1	121.10	121.10 NEC✓
FRONT LH FENDER BRACKET	1	172.45	86.50 172.45 NN✓
FRONT LH FENDER INNER SHIELD	1	259.45	160.00 259.45 TN✓
FRONT LH FENDER VERTICAL SHIELD	1	97.00	97.00 NN✓
FRONT LH HEADLAMP	1	2721.10	2,530.00 2,721.10 BR✓

*** This is a computer-generated document which requires no signature. ***

page 1

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200616038C

GST Registration No. : 200616038C

(24820057)
KOH

GRAB RENTALS PTE LTD

18 SIN MING LANE #01-08 MIDVIEW CITY

SINGAPORE 573960

ESTIMATE

Repair Code : CLM14905

Date in : 17/11/2018

Vehicle Num. : SMA5587G

Model : TOYOTA PRIUS PLUS (AUTO)

Chassis/Eng# : JTDZS3EU90J027979/2ZR0B81238

Contact : 66550005 98572315

FRONT LH HEADLAMP LOWER BRACKET	1	172.45	172.45	
* FRONT LH KNUCKLE ARM	1	✓ 485.00	485.00	
* FRONT LH KNUCKLE BEARING	1	65.00 517.00	517.00	
FRONT LH LOWER ARM	1	435.00	435.00	
FRONT LH LOWER BALL JOINT	1	127.00	127.00	
* FRONT LH SHOCK ABSORBER	1	375.00	375.00	
FRONT LH SHOCK ABSORBER TOP MOUNTING	1	151.00	151.00	
* FRONT LH SPORT RIM HUB CAP	1	175.80 378.30	378.30	NNX
FRONT LH STABILIZER LINK	1	117.00	117.00	NNX
FRONT LH TIE ROD END	1	93.00	93.00	NNX
ROCKER LH GARNISH	1	947.00	722.50 947.00	DD✓
* STEERING RACK & PINION	1	1580.00	1580.00	NNX
Subtotal before discount			13,853.05	
Percentage discount 25%			3,463.26	
Sub-total 1			10,389.79	
FRONT BUMPER CLIPS - SET	1	50.00	40 50.00	NNX
FRONT LH DOOR INNER TRIM BOARD CLIPS - SET	1	50.00	50.00	NNX
FRONT LH DOOR VERTICAL GARNISH CLIPS - SET	1	20.00	20.00	NNX

*** This is a computer-generated document which requires no signature. ***

page 2

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200616038C

GST Registration No. : 200616038C

GRAB RENTALS PTE LTD

18 SIN MING LANE #01-08 MIDVIEW CITY

SINGAPORE 573960

Contact : 66550005 98572315

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

ESTIMATE

Repair Code : CLM14905

Date in : 17/11/2018

Vehicle Num. : SMA5587G

Model : TOYOTA PRIUS PLUS (AUTO)

Chassis/Eng#: JTDZS3EU90J027979/2ZR0B81238

FRONT LH FENDER INNER SHIELD CLIPS - SET	1	50.00	50.00	NEE
FRONT LH FENDER VERTICAL SHIELD CLIPS - SET	1	40.00	40.00	NNX
FRONT LH SPORT RIM	1	1555.00	1,250.00	1,555.00 CUT
FRONT LH TYRE	1	400.00	400.00	NNX
ROCKER LH GARNISH CLIPS - SET	1	60.00	60.00	NEE
Subtotal before discount			2,225.00	
Percentage discount 0%			0.00	
Sub-total 2			2,225.00	
Parts-total			12,614.79	

LABOUR

To remove, reinstall electrical wiring harness, check lighting. (to FR)	60.00
To remove, reinstall window glass. (to FR)	60.00 80.00
To remove, change front suspension parts, absorber, lower arm, knuckle arm, wheel bearing, bearing hub, drive shaft, anti-roll bar, top-arm and steering rack and pinion.	150.00 350.00
To road test driving, check and resetting wheel alignments system.	60.00 100.00
To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)	100.00 NNX
To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	700.00 1,050.00
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	600.00 850.00
To apply anti-rust chemical on repaired and replaced panel.	60.00 100.00
Labour Total	2,690.00
Parts & Labour Total	15,304.79

Repair days 5

TGLim

20/11/18

*** This is a computer-generated document which requires no signature.***

page 3

Mr. Lim 62584315

Work Order: R002009
 N: SMA5587G
 Technician: 111
 Mileage: 40614
 Date: 21.11.18 10:29



SMA5587G

Toyota : Prius + / Prius V : with 205/60R16 Tire : ZVW40R-AWXEBQ : 2012-

Front : Left

Actual	Before	Specified Range
0°00'		-0°55' 0°35'
		4°52' 6°22'
-1°33'		-0°01' 0°11'

Camber ✓
 Caster ✓
 Toe ✓
 SAI
 Included Angle
 Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
-0°33'		-0°55' 0°35'
		4°52' 6°22'
0°11'		-0°01' 0°11'

Front

Cross Camber
 Cross Caster
 Cross SAI
 Total Toe
 Cross Turn Diff.

Actual	Before	Specified Range
0°33'		-0°45' 0°45'
		-0°45' 0°45'
-1°22'		-0°02' 0°22'

Too much toe out

Rear : Left

Actual	Before	Specified Range
-1°47'		-1°54' -0°54'
0°15'		-0°05' 0°13'

Camber ✓
 Toe

Rear : Right

Actual	Before	Specified Range
-1°25'		-1°54' -0°54'
-0°11'		-0°05' 0°13'

Rear

Cross Camber
 Total Toe
 Thrust Angle

Actual	Before	Specified Range
-0°22'		-0°30' 0°30'
0°04'		-0°09' 0°25'
0°13'		

REMARK:
 L/H/F MISALIGNMENT

904-25 Kaki Bukit Autohub
2 Kaki Bukit Avenue 2
Singapore 417921

Tel: 67412848 / 67477946

62564315
Att. Mr. Lim
(after)

Work Order: R002614
VIN: SMA5587G
Technician: LBB
Mileage: 48846
Date: 22.11.18 15:56



Toyota : Prius + / Prius V : with 205/60R16 Tire : ZVN48R-ANDGBQ : 2012-

Front: Left

Actual	Before	Specified Range
0°01'	0°03'	-0°55' 0°35'
5°17'	5°17'	-0°52' 0°22'
0°04'	-0°38'	-0°01' 0°11'
12°06'	12°04'	
12°07'	12°07'	

Camber
Caster
Toe
SAI

Included Angle
Turning Angle Diff.

Front: Right

Actual	Before	Specified Range
-0°13'	-0°07'	-0°55' 0°35'
5°39'	5°39'	-0°52' 0°22'
0°05'	-0°45'	-0°01' 0°11'
12°28'	12°22'	
12°18'	12°18'	

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	Before	Specified Range
0°14'	0°10'	-0°45' 0°45'
-0°22'	-0°22'	-0°45' 0°45'
-0°23'	-0°15'	
0°09'	-1°23'	-0°02' 0°22'

Rear: Left

Actual	Before	Specified Range
-1°55'	-1°56'	-1°54' -0°54'
0°08'	0°08'	-0°05' 0°13'

Camber
Toe

Rear: Right

Actual	Before	Specified Range
-1°19'	-1°19'	-1°54' -0°54'
-0°06'	-0°05'	-0°05' 0°13'

Rear

Cross Camber
Total Toe
Thrust Angle

Actual	Before	Specified Range
-0°35'	-0°37'	-0°35' 0°35'
0°03'	0°03'	-0°05' 0°25'
0°07'	0°07'	

cut



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18021005/Bvbe2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 03-01-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 8990D	Veh. Inspected	SMA 5587G	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18008235MFSH	Excess (\$)	0.00	
Assign From	MAY CHUA	Assign Date	20/11/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PRIUS	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	JTDZS3EU90J027979	Colour	BLACK	
Odometer	40615	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/60 R16	YOKOHAMA	6 mm	
L/H Front Tyre	205/60 R16	YOKOHAMA	6 mm	
R/H Rear Tyre	205/60 R16	YOKOHAMA	6 mm	
L/H Rear Tyre	205/60 R16	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY AND FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	17/11/2018	Inspection Date	21/11/2018	
Survey held at	N-51 AUTOMOTIVE PL 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMA 5587G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	DENTED	781.10	585.36
1	FRONT BUMPER AIR GRILLE LH	CRACKED	178.45	178.45
1	FRONT BUMPER DAYLIGHT LH	BROKEN	972.85	910.20
1	FRONT BUMPER SIDE BRACKET LH	NOT NECESSARY	171.10	-
6	FRONT BUMPER SIDE LOCK CLIPS @\$9.50	NECESSARY	57.00	57.00
6	FRONT BUMPER SIDE LOCK CLIPS HOLDER @\$12.90	NECESSARY	77.40	77.40
2	FRONT BUMPER SIDE RETAINER L/R @\$132.25	NECESSARY	264.50	204.00
1	FRONT BUMPER UPPER RUBBER SEAL	NECESSARY	174.45	174.45
1	FRONT LH DOOR	DENTED	1,218.20	1,218.20
1	FRONT LH DOOR BLACK FRAME STICKER	NECESSARY	121.30	121.30
1	FRONT LH DOOR VERTICAL GARNISH	NECESSARY	151.30	151.30
1	FRONT LH DOOR WEATHERSTRIP	NOT NECESSARY	205.20	-
1	FRONT LH FENDER	DENTED	731.35	731.35
1	FRONT LH FENDER 'HYBRID' EMBLEM	NECESSARY	121.10	121.10
1	FRONT LH FENDER BRACKET	NOT NECESSARY	172.45	-
1	FRONT LH FENDER INNER SHIELD	TORN	259.45	160.00
1	FRONT LH FENDER VERTICAL SHIELD	NOT NECESSARY	97.00	-
1	FRONT LH HEADLAMP	BROKEN	2,721.10	2,530.00
1	FRONT LH HEADLAMP LOWER BRACKET	NOT NECESSARY	172.45	-
1	FRONT LH KNUCKLE ARM	BENT	485.00	485.00
1	FRONT LH KNUCKLE BEARING	JAMMED	517.00	65.00
1	FRONT LH LOWER ARM	NOT NECESSARY	435.00	-
1	FRONT LH LOWER BALL JOINT	NOT NECESSARY	127.00	-
1	FRONT LH SHOCK ABSORBER	BENT	375.00	375.00
1	FRONT LH SHOCK ABSORBER TOP MOUNTING	NOT NECESSARY	151.00	-
1	FRONT LH SPORT RIM HUB CAP	SCRATCHED	378.30	100.00
1	FRONT LH STABILIZER LINK	NOT NECESSARY	117.00	-
1	FRONT LH TIE ROD END	NOT NECESSARY	93.00	-
1	ROCKER LH GARNISH	DENTED	947.00	722.50
1	STEERING RACK & PINION	NOT NECESSARY	1,580.00	-

Report Ref No. CS/FCI18021005/Bvbe2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 25% DISCOUNT		-3,463.26	-2,241.90
			10,389.79	6,725.71
	<u>SPECIAL NETT ITEMS</u>			
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	50.00	40.00
1	SET FRONT LH DOOR INNER TRIM BOARD CLIPS (SN)	NOT NECESSARY	50.00	-
1	SET FRONT LH DOOR VERTICAL GARNISH CLIPS (SN)	NECESSARY	20.00	20.00
1	SET FRONT LH FENDER INNER SHIELD CLIPS (SN)	NECESSARY	50.00	40.00
1	SET FRONT LH FENDER VERTICAL SHIELD CLIPS (SN)	NOT NECESSARY	40.00	-
1	FRONT LH SPORT RIM (SN)	CUT	1,555.00	1,250.00
1	FRONT LH TYRE (SN)	NOT NECESSARY	400.00	-
1	SET ROCKER LH GARNISH CLIPS (SN)	NECESSARY	60.00	60.00
			2,225.00	1,410.00
	<u>LABOUR</u>			
	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING. (TO FR)		60.00	60.00
	TO REMOVE, REINSTALL WINDOW GLASS. (TO FR)		80.00	60.00
	TO REMOVE, CHANGE FRONT SUSPENSION PARTS, ABSORBER, LOWER ARM, KNUCKLE ARM, WHEEL BEARING, BEARING HUB, DRIVE SHAFT, ANTI-ROLL BAR, TOP ARM AND STEERING RACK AND PINION.	NOT NECESSARY	350.00	-
	TO ROAD TEST DRIVING, CHECK AND RESETTNG WHEEL ALIGNMENTS SYSTEM.		100.00	60.00
	TO REMOVE, REINSTALL ROOF TOP TRIM UPHOLSTERY, CUSHION SEAT, TRIM GARNISH, TRIM LINER CARPET (TO FR)	NOT NECESSARY	100.00	-
	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT.		1,050.00	700.00
	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT.		850.00	600.00
	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL.		100.00	60.00
			2,690.00	1,540.00
	GRAND TOTAL		15,304.79	9,675.71

Report Ref No. CS/FCI18021005/Bvbe2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			7,700.00
---	--	--	----------

Report Ref No. CS/FCI18021005/Bvbe2

LIM TEOW GUAN

Asst. Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.