

ASS. REG. BY:

REF: CS/FCL18021013 /Agbn2

Special Instruction:

Surveyor:

ASSIGNMENT (Office)From (Person): WGS Sithura of FCL Date/Time: 20/11/2018 5:10pm

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLK 2026m Insured: SHA 964Tat Workshop m/s Kah major Tel: 8288 6304of 15 Ubi Rd 4Policy No: _____ Claim No: D18008233 MFSH

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 17/11/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS wpi 21.11.2018 @ 12pm H.O.D. Endorsement: _____Date/Time: 20-11-2018 5:28 pm Person Contacted: Faeuz Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SLK 2026m - X
	SHA 964T - X
20/11/18 @ 2.17pm	revised to Sithura by email.
17/12/18 @ 3.57pm	confirmed with our car final fig to 4679.99, 5 days. (Red to 1580, 25%)

REF: FCI

ASSIGNMENT

From: Date: 21-11-2018

Estimated Cost:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLK 2026M

at Workshop m/s: Kah Motor

of: 15 Ubi Rd A

Insured:

Policy No:

Claims No:

Sum Insured: Excess:

(Client's Record)

Make of Veh: Fuelix

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent?: Yes or No

GIA / PR Seen: Consistent?: Yes or No

Est. Repairs: 05 hrs days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS 'wp'

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SLK 2026M Yr Regn: 2017 / Jan.

Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Kah Motor Odyssey c.c 2356

Colour: Purple A/C: Insured / Std / NI / NA

Sp. Reading: 31507 T/Radio: Insured / Std / NI / NA

Eng/No:

Chassis No: JHMRU8S0G20.8481

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 245/55R17

R: 215/55R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. D.O.I. 21/11/18

Survey held at: Kah Motor

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

T1 / 1st Cap.

RECEIVED 10 DEC 2018

Date/Time, File Pass to?

☐ : Preli. Report

11/12/18 Fuelix

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 5

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)

) \$ + RS. SI

) Photos

) Others

TOTAL

Report Format: TP

Lump Sum / I.B.I. (\$) 4679.99

145

50

50

24

269



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18008233MESH

Date: 21 November 2018

Our Ref: CS/FCI18021013/Aqb

The Motor Claims Department
First Capital Insurance Ltd


Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SLK 2026M .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 21/11/2018 at the premises of M/s KAH MOTOR, and have the following to report:-

Workshop Estimate Amount	: S\$ 5,894.92 .
Revised Estimate Amount	: S\$ 4,314.92 .
"Check" Items Amount	: S\$ 320.00 .
Market Value	: S\$ - .
LTA Reimbursement Value	: S\$ - .
Nett Value	: S\$ - .

Description of Damage:
The vehicle sustained damages
at the rear portion.



Yours faithfully

ADRIAN LING WAI PING
B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	20-11-2018	Our Ref No. D18008233MFSH
Accident Date	17-11-2018	Claim Type. Third Party
Insured Vehicle	SHA0964T	Third Party Vehicle. SLK2026M
Survey Location	15 UBI ROAD 4	
Contact Person.	MOHD FAEAZ BIN YAACOB	
Contact No.	68465678/ 82886304	Fax No. 0
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	KAH MOTOR CO SDN BHD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SITHARA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Monday, 17 December 2018 3:52 PM
To: 'Lim Chou Siong'; SUR
Subject: RE: Pre-Invoice Of Vehicle No: SLK2026M For Finalising

Dear Mr Lim,

WITHOUT PREJUDICE

Confirm final fig \$4,679.99 before GST and 5 repair days.

Kindly send the relevant documents to First Capital Insurance company.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Lim Chou Siong <cslim@honda.com.sg>
Sent: Friday, 14 December 2018 5:57 PM
To: SUR <sur@lkkauto.com>
Subject: Pre-Invoice Of Vehicle No: SLK2026M For Finalising

Dear,

We enclosed the total final repair costs of...

Vehicle No. SLK2026M

Final Repair Costs (include GST) \$5,007.59

Repair Period*(Working Day) 05

*Note: Repair period does not include Sunday And Public Holiday.

Please examine the above information carefully. If no discrepancy is reported within 7 days (exclude Sunday and Public Holiday) from the date of this email, the information will be considered as correct. Thereafter, no adjustment will be made.

Thanks & best regards,

Lim Chou Siong

Contact No: 81006303 HP

KAH MOTOR CO. SDN. BHD.

(A member of Oriental Holdings Berhad)

Body Repair & Paint Centre

15 Ubi Road 4 Singapore 408610

Tel: +65 6841 3838 Fax: +65 6748 0770

This is a computer-generated e-mail no signature is necessary Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Thursday, 22 November 2018 2:17 PM
To: 'CWS Motor Claims'; assignments
Cc: 'Sithara'; SUR
Subject: RE: SURVEY ASSESSMENT - D18008233MFSH/1
Attachments: CSFCI180210138Aqb.pdf

Dear Sithara,

Enclosed herewith preliminary advice of SLK 2026M.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Tuesday, 20 November 2018 5:28 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Sithara' <Sithara@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18008233MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Please be informed that vehicle currently not in the workshop, repairer will arrange.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Tuesday, 20 November, 2018 5:10 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Sithara <Sithara@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D18008233MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,



Certificate of Insurance

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

Policy No.: 17-MU000144-R00 (Private Motor Car 24 Months)

- | | | |
|--|-----------------|--------------------------------|
| 1. Index Mark and Registration Number of Vehicle | SLK2026M | Chassis No.: JHMRC1890GC208481 |
| 2. Name of Policyholder | MS YAO MEE CHEE | |
| 3. Effective date of the Commencement of Insurance for the purposes of the Act | 09/01/2017 | |
| 4. Date of Expiry of Insurance | 08/01/2019 | |
| 5. Persons or Class of Persons entitled to drive* | | |
- (a) The Policyholder.
 (b) Any other person who is driving on the Policyholder's order or with his permission.

* Provided that the Person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle. And provided further that the Motor Vehicle is registered under the Road Traffic Act and its registration under the Road Traffic Act has not been cancelled at the time of the accident loss or damage.

6. Limitations as to use*

Use only for social domestic and pleasure purposes and for the Policyholder's business.

The policy does not cover use for hire or reward, racing, pace-making, reliability trial, speed-testing or the carriage of goods (other than samples) in connection with any trade or business or use for any purpose in connection with the Motor Trade.

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

We hereby certify that the Policy to which this Certificate relates is issued in accordance with the provision of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

Please refer to the Policy Schedule for full details, terms and conditions of the insurance.

IMPORTANT NOTICE

This Certificate is not transferable. During its currency, if the insurance is cancelled for whatsoever reason, you must return the Certificate to Tokio Marine Insurance Singapore Ltd. within 7 days thereof or, if the Certificate has been lost destroyed, you must make a statutory declaration to that effect. Failure to comply with this duty is an offence under Motor Vehicle (Third-Party Risks and Compensation) Act (Chapter 189).

ADDITIONAL INFORMATION

Account: E2316DDA

Insurance Plan:	Comprehensive Approved Workshop Plan	
Limit for total loss or theft:	Prevailing Market Value	
Policy Excess:	Own Damage Claims	SGD 1,000
	Windscreen Excess	SGD 100
Financial Interest:	OCBC BANK LIMITED	

Tokio Marine Insurance Singapore Ltd.

Authorised Signature



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)
Service and Body Repair

Tel: +65 6841 3838 Website: www.honda.com.sg
For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
Company Ref: No.: S60FC1380G

Customer : MS FIRST CAPITAL INSURANCE
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877
Registration No : SLK2026M
Chassis No : JHMRC1890GC208481
Model : ODYSSEY 2.4 EXV-S 16YM
Owner's Name : YAO MEE CHEE
Ins Policy No. :
Date of Accident : 17/11/2018

Document No. : SQT18004949 Page 1
Date : 19. Nov 2018
Customer No. : WZF002
Svc Advisor : LIM CHOU SIONG
Engine No : K24W72013551
Date | Time : 19. Nov 2018 12:32:51 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: YAO MEE CHEE OWNER INSURER: TOKIO MARINE INSURANCE ACC DATE: 17/11/2018 SURVEYED BY: DATE: REF NO: TP INSURER: FIRST CAPITAL INSURANCE TP VEH: SHA964T						
73214-T6A-003	MOLDINGRR.WINDSHIELD SIDE	2	18.00	25	27.00	1.89	28.89
73215-T6A-003	MOLDINGR.RR.WINDSHIELD CORNER	1	16.90	25	12.67	0.89	13.56
73216-T6A-003	MOLDINGL.RR.WINDSHIELD CORNER	1	16.90	25	12.67	0.89	13.56
73221-SR4-000	SPACERRR.W/SHIELD	4	3.90	25	11.70	0.82	12.52
73225-TM8-000	RUBBER A WINDSHIELD DAM	1	3.70	25	2.77	0.19	2.96
73226-SZW-000	DAMPERSTD 5X5	2	8.50	25	12.75	0.89	13.64
76711-T6A-003	CAPPIVOT	1	4.80	25	3.60	0.25	3.85
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	1	60.00		60.00	4.20	64.20
68100-T6A-Q10ZZ	TAILGATE COMP	1	1070.80	25	803.10	56.22	859.32
04715-T6A-900ZZ	FACERR.BUMPER	1	568.30	25	426.22	29.84	456.06
71593-T6A-003	SPACERR.RR.BUMPER SIDE	1	19.10	25	14.32	1.00	15.32
71598-T6A-003	SPACERL.RR.BUMPER SIDE	1	19.10	25	14.32	1.00	15.32
91505-TM8-003	CLIP,BUMPER	8	2.30	25	13.80	0.97	14.77
NMRS-4P-TM3040L	4PCS ACT RR.SENSOR	1	320.00		320.00	22.40	342.40
Sum Item					1734.92	121.45	1,856.37
BOSUN	SUNDRIES	1	50.00		50.00	3.50	53.50
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	280.00		280.00	19.60	299.60
BG02D	REMOVE & INSTALL RR. WINDSCREEN.(N)	1	300.00		300.00	21.00	321.00
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	100.00		100.00	7.00	107.00



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : MS FIRST CAPITAL INSURANCE
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877
Registration No : SLK2026M
Chassis No : JHMRC1890GC208481
Model : ODYSSEY 2.4 EXV-S 16YM
Owner's Name : YAO MEE CHEE
Ins Policy No. :
Date of Accident : 17/11/2018

Document No. : SQT18004949
Date : 19. Nov 2018
Customer No. : WZF002
Svc Advisor : LIM CHOU SIONG
Engine No : K24W72013551
Date | Time : 19. Nov 2018 12:32:51 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 2

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	350.00		350.00	24.50	374.50
BKRP21S	STRAIGHTEN ALIGN RR PANEL RR L FENDER & RENEW 1		1680.00		1680.00	117.60	1797.60
BP03R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (3P)	1	1400.00		1400.00	98.00	1498.00
Sum Labor					4160.00	291.20	4451.20

Survey By

Date & Time

Excess

Status

Signature

Total Amount 5,894.92 412.65 6,307.57

Total (Inclusive of GST) 6,307.57

Extra / Item - buzzer

Adrian King.
P/P 21/11/18.
05 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 20/11/2018 10:55:59 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)

6759.99



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer	: MS FIRST CAPITAL INSURANCE	Document No.	: SQT18005199	Page	1
	: 36 ROBINSON ROAD	Date	: 4. Dec 2018		
	: #16-01 CITY HOUSE	Customer No.	: WZF002		
	: SINGAPORE 068877	Svc Advisor	: LIM CHOU SIONG		
Registration No	: SLK2026M	Engine No	: K24W72013551		
Chassis No	: JHMRC1890GC208481	Date Time	: 4. Dec 2018 5:57:38 PM		
Model	: ODYSSEY 2.4 EXV-S 16YM	Surveyor Name	: ADRIAN LING		
Owner's Name	: YAO MEE CHEE	Survey Date	: 21/11/2018		
Ins Policy No.	:	Authorisation Date	: 26/11/2018		
Date of Accident	: 17/11/2018				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount Incl GST
	TP DIRECT SETTLEMENT (J/NO: 71718)						
	OWNER: YAO MEE CHEE						
	OWNER INSURER: TOKIO MARINE INSURANCE SINGAPORE L						
	ACC DATE: 17/11/2018						
	SURVEYED BY: ADRIAN LING						
	DATE: 21/11/18						
	REF NO:						
	TP INSURER: MS FIRST CAPITAL INSURANCE LIMITED						
	TP VEH: SHA964T						
	SUPPLEMENTARY LABOUR & PARTS						
BOMISC1	RESET SMART ENTRY SYSTEM AND REMOVE NECESSARY	1	320.00		320.00	22.40	342.40
					Sum Labor	320.00	22.40
							342.40
74940-TR0-003	BUZZER ASSYSMART <i>Damaged</i>	1	60.10	25	45.07	3.15	48.22
					Sum Item	45.07	3.15
							48.22

Survey By	_____						
Date & Time	_____				Total Amount	365.07	25.55
Excess	_____						390.62
Status	_____				Total (Inclusive of GST)		390.62
Signature	_____						

Printed on 4/12/2018 6:03:54 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

05/12/2018. Page 1/3
 (C) SERVICE PRE-INVOICE

Attn: Adrian Ling
 5 days

GST Reg No.: M200050223
 Company Ref. No.: S60FC1380G

Customer: WZF002 / MS FIRST CAPITAL
 Chassis No: JHMRC1890GC208481
 License No: SLK2026M
 Mileage: 32121
 Engine No: K24W72013551

Document No: SVO18070890
 Printed By: CSLIM
 Order Date: 28. November 2018
 Order Time: 12:01:11 PM
 Service Advisor: LIM CHOU SIONG

ITEM	DESCRIPTION	QTY	UNIT PRICE	DISC %	AMOUNT	7% GST Amount incld	Amount	GST
	TP DIRECT SETTLEMENT (J/NO: 71718) OWNER: YAO MEE CHEE OWNER INSURER: TOKIO MARINE INSURANCE ACC DATE: 17/11/2018 SURVEYED BY: ADRIAN LING DATE: 21/11/18 REF NO: TP INSURER: FIRST CAPITAL INSURANCE TP VEH: SHA964T							
73214-T6A-003	MOLDINGRR.WINDSHIELD SIDE	2	18.00	25	27.00	1.89		28.89
73215-T6A-003	MOLDINGR.RR.WINDSHIELD CORNER	1	16.90	25	12.67	0.89		13.56
73216-T6A-003	MOLDINGL.RR.WINDSHIELD CORNER	1	16.90	25	12.67	0.89		13.56
73221-SR4-000	SPACERRR.W/SHIELD	4	3.90	25	11.70	0.82		12.52
73225-TM8-000	RUBBER A WINDSHIELD DAM	1	3.70	25	2.77	0.19		2.96
73226-SZW-000	DAMPERSTD 5X5	2	8.50	25	12.75	0.89		13.64
76711-T6A-003	CAPPIVOT	1	4.80	25	3.60	0.25		3.85
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	1	60.00		60.00	4.20		64.20
68100-T6A-Q10ZZ	TAILGATE COMP	1	1,070.80	25	803.10	56.22		859.32
04715-T6A-900ZZ	FACERR.BUMPER	1	568.30	25	426.22	29.84		456.06
71593-T6A-003	SPACERR.RR.BUMPER SIDE	1	19.10	25	14.32	1.00		15.32
71598-T6A-003	SPACERL.RR.BUMPER SIDE	1	19.10	25	14.32	1.00		15.32
91505-TM8-003	CLIP.BUMPER	8	2.30	25	13.80	0.97		14.77
74940-TR0-003	BUZZER ASSYSMART	1	60.10	25	45.07	3.15		48.22
	SUM PARTS:				1,459.99	102.20		1,562.19
BOSUN	0760	1	30.00		30.00	2.10		32.10
	SUNDRIES							
BMI03D	EXT-YJ	1	280.00		280.00	19.60		299.60
	REMOVE & INSTALL REAR COMPARTMENT LININGS GARNISHES.(N)							
BG02D	EXT-YJ	1	300.00		300.00	21.00		321.00
	REMOVE & INSTALL RR. WINDSCREEN. (N)							
BA02R	EXT-YJ	1	100.00		100.00	7.00		107.00
	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)							
BKTG02R	EXT-YJ	1	350.00		350.00	24.50		374.50
	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST & ALIGN TAILGATE.(N)							
BKRP21S	EXT-YJ	1	840.00		840.00	58.80		898.80
	STRAIGHTEN ALIGN RR PANEL RR L FENDER & RENEW DAMAGE PARTS.							
BP03R	EXT-YBH	1	1,000.00		1,000.00	70.00		1,070.00
	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.(3P)							
BOMISC1	0760	1	320.00		320.00	22.40		342.40
	RESET SMART ENTRY SYSTEM AND REMOVE NECESSARY							



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer: WZF002 / MS FIRST CAPITAL
Chassis No: JHMRC1890GC208481
License No: SLK2026M
Mileage: 32121
Engine No: K24W72013551

Document No: SVO18070890
Printed By: CSLIM
Order Date: 28. November 2018
Order Time: 12:01:11 PM
Service Advisor: LIM CHOU SIONG

COMPONENT.(N)

SUM LABOUR:	3,220.00	225.40	3,445.40
TOTAL SGD	4,679.99	327.60	5,007.59

Total Payable (SGD) 5,007.59

GST Amount is calculated from individual line(s)




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18021013/Aqbn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 19-12-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 964T	Veh. Inspected	SLK 2026M	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18008233MFSH	Excess (\$)	0.00	
Assign From	SITHARA	Assign Date	20/11/2018	
2. Vehicle Particulars & Condition				
Make & Model	HONDA ODYSSEY	c.c	2356	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JHMRC1890GC208481	Colour	PURPLE	
Odometer	31507	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/55 R17	YOKOHAMA	6 mm	
L/H Front Tyre	215/55 R17	YOKOHAMA	6 mm	
R/H Rear Tyre	215/55 R17	YOKOHAMA	6 mm	
L/H Rear Tyre	215/55 R17	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	17/11/2018	Inspection Date	21/11/2018	
Survey held at	KAH MOTOR CO SDN BERHAD 15 UBI ROAD 4 SINGAPORE 408610			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLK 2026M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
2	MOLDINGRR WINDSHIELD SIDE (SN)	NECESSARY	27.00	27.00
1	MOLDINGR.RR WINDSHIELD CORNER (SN)	NECESSARY	12.67	12.67
1	MOLDINGL.RR WINDSHIELD CORNER (SN)	NECESSARY	12.67	12.67
4	SPACERRR W/SHIELD (SN)	NECESSARY	11.70	11.70
1	RUBBER A WINDSHIELD DAM (SN)	NECESSARY	2.77	2.77
2	DAMPERSTD 5X5 (SN)	NECESSARY	12.75	12.75
1	CAPPVOT (SN)	NECESSARY	3.60	3.60
1	WINDSCREEN SEALANT (SN)	NECESSARY	60.00	60.00
1	TAILGATE COMP (SN)	DENTED	803.10	803.10
1	FACERR BUMPER (SN)	DEFORMED	426.22	426.22
1	SPACERR RR BUMPER SIDE (SN)	NECESSARY	14.32	14.32
8	CLIP,BUMPER (SN)	NECESSARY	13.80	13.80
1	4PCS ACT RR SENSOR (SN)	NOT NECESSARY	320.00	-
1	SUNDRIES (SN)	NECESSARY	50.00	30.00
1	BUZZER ASSYSMART (ADDITIONAL)(SN)	DAMAGED	45.07	45.07
1	SPACERL RR BUMPER SIDE (SN)	NECESSARY	14.32	14.32
			1,829.99	1,489.99
LABOUR				
	RESET SMART ENTRY SYSTEM AND REMOVE NECESSARY. (ADDITIONAL)		320.00	320.00
	REMOVE & INSTALL REAR COMPARTMENT LININGS.		280.00	280.00
	REMOVE & INSTALL RR WINDSCREEN.		300.00	300.00
	REMOVE & RENEW REVERSE SENSOR-4 PCS.		100.00	100.00
	REMOVE & TRANSFER ITEMS TO NEW TAILGATE ADJUST.		350.00	350.00
	STRAIGHTEN ALIGN RR PANEL RR L FENDER & RENEW.		1,680.00	840.00
	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.		1,400.00	1,000.00
			4,430.00	3,190.00
GRAND TOTAL			6,259.99	4,679.99
RECOMMENDED COST OF REPAIRS				4,679.99

Report Ref No. CS/FCI18021013/Aqbn2



Report Ref No. CS/FCI18021013/Aqbn2

A handwritten signature in black ink, appearing to read 'A. Ling'.

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.