

BH AUTO SERVICES PTE LTD

Blk 1, Sector C, Sin Ming Industrial Estate #01-111 / 113 / 115 / 117 Singapore 575636
Tel: 6559 8944 / Fax: 6269 2404

ATTN : MOTOR CLAIMS DEPARTMENT
AIG ASIA PACIFIC INSURANCE PTE LTD
AIG BUILDING
78 SHENTON WAY
#07-16 SINGAPORE 079120
TEL : 6419 3000

DATE : 17/11/2018
PAGE : 1 OF 2

Not Authorized
L1 Pump &
Resurvey After Paint

ACCIDENT REPAIR ON : SJT2348K
MODEL : HONDA AIRWAVE 1.5M
POLICY NO : GA059425/1
CHASSIS NO : GJ11307135
YEAR OF MANUFACTURE : 2008
DATE / TIME OF ACCIDENT : 14/11/2018@09:50HRS
LOCATION : ALONG LORNIE EXPRESSWAY TOWARDS FARRER ROAD
THIRD PARTY VEHICLE NO : SLB177X

REPLACEMENT OF PARTS		QUANTITY	UNIT PRICE	AMOUNT	
1	REAR TAILGATE	1	<i>BH</i>	\$ 936.00	✓
2	REAR TAILGATE WINDSCREEN MOULDING	1		\$ <i>Me</i> 55.00	✓
3	REAR TAILGATE "AIRWAVE" EMBLEM	1		\$ <i>Me</i> 45.00	✓
4	REAR TAILGATE "LOGO" EMBLEM	1		\$ <i>me</i> 28.00	X
5	REAR TAILGATE OUTER CHROME MOULDING	1	<i>Sm</i>	\$ 245.00	X
6	REAR TAILGATE OUTER GARNISH	1	<i>Si</i>	\$ 398.00	?
7	REAR TAILGATE OUTER LOCK HANDLE	1		\$ <i>Sm</i> 65.00	X
8	REAR TAILGATE REVERSE CAMERA	1	<i>Sm</i>	\$ 480.00	✓
9	REAR TAILGATE NUMBER PLATE WITH HOLDER	1	<i>Not</i>	\$ 55.00	✓
10	REAR TAILGATE NUMBER PLATE LAMP LH	1	<i>Sm</i>	\$ 65.00	X
11	REAR TAILGATE NUMBER PLATE LAMP RH	1	<i>Sm</i>	\$ 65.00	X
12	REAR TAILGATE MECHANISM LOCK	1	<i>Al</i>	\$ 115.00	X
13	REAR TAILGATE INNER TRIM BOARD	1		\$ <i>Sm</i> 585.00	X
14	REAR TAILGATE HINGE LH	1		\$ <i>Al</i> 62.00	X
15	REAR TAILGATE HINGE RH	1		\$ <i>Al</i> 62.00	X
16	REAR TAILGATE WEATHERSTRIP	1	<i>Sm</i>	\$ 151.00	X
17	REAR BUMPER	1	<i>BH</i>	\$ 739.00	✓
18	REAR BUMPER SIDE RETAINER LH	1		\$ <i>Sm</i> 28.00	X
19	REAR BUMPER SIDE RETAINER RH	1		\$ <i>Sm</i> 28.00	X
20	REAR END PANEL LOCK STRIKER	1		\$ <i>Al</i> 35.00	✓
21	REAR END PANEL INNER TOP GARNISH	1		\$ <i>Sm</i> 145.00	✓
		SUB TOTAL		\$ 4,387.00	
		LESS 20%		\$ (877.40)	
		PARTS TOTAL		\$ 3,509.60	

SPECIAL NETT ITEMS		QUANTITY	UNIT PRICE	AMOUNT	
1	REAR TAILGATE WINDSCREEN SEALANT	1	<i>Me</i>	\$ 100.00	<i>405m</i>
2	REAR TAILGATE OUTER CHROME MOULDING CLIPS	4	\$ 5.90	\$ <i>me</i> 23.60	X
3	REAR TAILGATE OUTER GARNISH CLIPS	6	\$ 5.90	\$ <i>me</i> 35.40	X
4	REAR TAILGATE INNER TRIM BOARD CLIPS	10	\$ 5.90	\$ <i>me</i> 59.00	X
5	REAR BUMPER CLIPS	10	\$ 5.50	\$ <i>Me</i> 55.00	✓
6	REAR END PANEL INNER TOP GARNISH CLIPS	4	\$ 6.50	\$ <i>me</i> 26.00	X
		PARTS TOTAL		\$ 299.00	

ACCIDENT REPAIR ON : SJT2348K

MODEL : HONDA AIRWAVE 1.5M

POLICY NO : GA059425/1

CHASSIS NO : GJ11307135

YEAR OF MANUFACTURE : 2008

DATE / TIME OF ACCIDENT : 14/11/2018@09:50HRS

LOCATION : ALONG LORNIE EXPRESSWAY TOWARDS FARRER ROAD

THIRD PARTY VEHICLE NO : SLB177X

DATE : 17/11/2018

PAGE : 2 OF 2

LABOUR CHARGES FOR REAR PORTION		AMOUNT
1	PROVIDE SKILL LABOUR TO REMOVE ALL DAMAGED PARTS, PANEL BEAT, CUT AND WELD IF NECESSARY AND ALIGN ALL PANEL AND REINSTALL ALL DAMAGED PARTS.	\$ 500.00
2	PROVIDE SKILL LABOUR AND MATERIAL TO PUTTY ALL DAMAGED PARTS AND PANEL AND TO RESPRAY WITH 2K PAINT WITH OVEN SPRAY BOOTH FACILITIES.	\$ 500.00
3	REMOVE AND REFIX REAR TAILGATE WINDSCREEN GLASS TO FACILITATE REPAIRS	\$ 120.00
4	TUFF KOTE AND ANTI RUST COATING ALL REPLACE AND REPAIR PARTS.	\$ 80.00
5	DISCONNECT, CHECK, RESET AND DIAGNOSTIC ELECTRICAL SYSTEM WIRING, HARNESS, WIRE SOCKETS AND ETC. REMOVE AND REINSTALL DAMAGED PARTS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	\$ 80.00
LABOUR TOTAL		\$ 1,280.00

TOTAL PARTS & LABOUR	\$ 5,088.60
GST 7%	\$ 356.20
GRAND TOTAL	\$ 5,444.80
ESTIMATE REPAIR DURATION	5 DAYS

YOURS SINCERELY,

ESTIMATOR : KIT

TEL : 8405 4058

FAX : 6269 2404

EMAIL : karkit.ngai@bhauto.com.sg

SURVEY ATTENDED BY :

NAME	Kenneth
COMPANY	LKIC
DATE	20/11/18
TIME	10.55am
TEL	96910663
EMAIL	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

4001
4801
301
201

4 days