

2/10/2002

ASS. REC. BY:

REF:

CS/AWA18021035/Tigber

Special Instruction:

Surveyor

ASSIGNMENT (Office)

From (Person):

Peggy Chan.

of

AWA

Date/Time: 21-11-2018 1032am

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

SFH 4822E

Insured:

at Workshop m/s

Yew Hock Muter.

Tel:

6747 2384

of

Blk 9006 Tampines St 93 #01-210

Policy No:

OVPPSB05H9151801

Claim No:

NSV1800600/SH

Sum Insured:

Excess:

Waived

Make of Veh:

D.O.A. 05-11-2018

(Client's Record)

CA / KEY / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

21-11-2018 10:48am

Person Contacted:

Chris

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SFH 11811E - x
21/11/18 @ 9.49am	revert to Peggy Chan by email.
23/11/18 @ 9.11am	Stella informed c/a by email.
23/11/18 @ 9.32am	Informed Chris c/a SA-SWAIVED by email.
24/11/18 @ 5.02pm	2nd revert to Stella Goh by email (supplementary).
28/11/18 @ 11.26am	Stella Goh informed c/a \$5501.28 by email.

Tampin

REF: AWA

ASSIGNMENT

From: Date: 21/12/18

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SFH 4822E
at Workshop m/s Yew Hock Motor
of Blk 9006 Tampines St 93 #01-210

Insured

Policy No.


Claims No.

Sum Insured: Excess: Waived

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: \$58K

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 8 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SFH4822E Yr Regn: 2016 April

Type: M.Capt / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mazda C.C. 1496

Colour: Blue A/C Insured / Std / NI / NA

Sp. Reading: 488/4 T/Radio: Insured / Std / NI / NA

Eng/No:

ChNo:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / R/Rim / STD A/Rim or

Tyre Size: F: 185/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mm

L/Bal. 6 mm

D.O.A.

Survey held at

Des. of Damages: Frt / Rear O/S / N/S UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

28/11/18 @ 3.57pm 3rd visit to Stella Goh by email. (Supplementary 2).

28/11/18 @ 4.20pm Stella Goh informed C/A \$5637.78 by email.

01/12/18 @ 2.10pm confirmed with Chris final fig \$5601.78. (Red \$1551, 27%).

RECEIVED 07 DEC 2018

Date/Time. File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time. File Return to?

2)

Days Of Repair: 8

Resurvey No. of Trip: 1

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)

Survey Fee:

Transportation:

) S + RS \$1

) Photos

) Others

TOTAL

Report Format: DD

Lump Sum / I.B.I: (\$ 5601.78)

200

200

7/12/2018

Catherine Chong (LKK Auto)

From: Chan, Peggy <Peggy.Chan@awac.com> on behalf of Motorsurvey <Motorsurvey@awac.com>
Sent: Wednesday, 21 November, 2018 10:32 AM
To: assignments
Cc: SUR
Subject: OD survey assignment for SFH 4822E - DOA: 05/11/2018 Our Ref: NSV1800600/SG

The above captioned accident refers. Please conduct an "OWN DAMAGE" survey on the following:

Insured Vehicle	:	SFH 4822 E		
Policy Number	:	DVPPSB0549151801	Account Code:	C999SD2
Policy Excess	:	\$ 500.00	(Allied World waived \$ 500.00) (Insured to pay \$ 0.00)	
Voluntary Excess	:	\$ NA	(No waiver)	
Sum Insured	:	Market Value with COE & PARF		
Make / Model	:	Mazda 2 / 2016		
Name of Workshop	:	Yew Hock Motor		
Contact Number	:	6747 2384		
Person to Contact	:	Chirs		
Estimated Cost of repairs	:	\$ 6,956.28		
(x)	Please take photographs of the front windscreen area from inside to ascertain whether the insured vehicle is equipped with a car camera. (Compulsory)			
(x)	Please revert with your preliminary survey report with photographs			
Remarks				

Regards,

Claims Division

The information contained in this e-mail and any attachments hereto is confidential. If you are not the intended recipient, you must not use or disseminate any of this information. If you have received this e-mail in error, please immediately notify the sender by reply e-mail and permanently delete the original e-mail (and any attachments hereto) and any copies or printouts thereof. Although this e-mail and any attachments hereto are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by Allied World Assurance Company Holdings, GmbH or its subsidiaries or affiliates, either jointly or severally, for any loss or damage arising in any way from its use.

Shiau Chan (LKKAUTO)

From: Goh, Stella <stella.goh@awac.com>
Sent: Wednesday, 28 November 2018 4:29 PM
To: Shiau Chan (LKKAUTO); Motorsurvey; assignments
Cc: SUR
Subject: RE: OD survey assignment for SFH 4822E - DOA: 05/11/2018 Our Ref: NSV1800600/SG

Dear Shiau Chan,

Please proceed with \$ 5,637.78 (inclusive of supp 2 & check items).

Thank you.

Regards
Stella Goh
Claims Analyst
Claims Group
Global Markets

Allied World Assurance Company, Ltd
60 Anson Road #08-01 Mapletree Anson Singapore 079914
T: +65 6423 0857
F: +65 6423 0864
E: stella.goh@awac.com
W: www.awac.com

From: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>
Sent: Wednesday, 28 November 2018 3:57 PM
To: Motorsurvey <Motorsurvey@awac.com>; assignments <assignments@lkkauto.com>
Cc: SUR <sur@lkkauto.com>; Goh, Stella <stella.goh@awac.com>
Subject: RE: OD survey assignment for SFH 4822E - DOA: 05/11/2018 Our Ref: NSV1800600/SG

Dear Stella,

Enclosed herewith 3rd preliminary advice of SFH 4822E.

Kindly approve on check items & supplementary.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Goh, Stella <stella.goh@awac.com> **On Behalf Of** Motorsurvey
Sent: Wednesday, 28 November 2018 11:26 AM
To: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>; Motorsurvey <Motorsurvey@awac.com>; assignments <assignments@lkkauto.com>
Cc: SUR <sur@lkkauto.com>; Goh, Stella <stella.goh@awac.com>
Subject: RE: OD survey assignment for SFH 4822E - DOA: 05/11/2018 Our Ref: NSV1800600/SG

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Wednesday, 28 November 2018 3:57 PM
To: Motorsurvey; assignments
Cc: SUR; Goh, Stella
Subject: RE: OD survey assignment for SFH 4822E - DOA: 05/11/2018 Our Ref: NSV1800600/SG
Attachments: CSAWA18021035T1qb(3).pdf; SFH4822 SUPP 2.pdf

Dear Stella,

Enclosed herewith 3rd preliminary advice of SFH 4822E.

Kindly approve on check items & supplementary.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Goh, Stella <stella.goh@awac.com> **On Behalf Of** Motorsurvey
Sent: Wednesday, 28 November 2018 11:26 AM
To: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>; Motorsurvey <Motorsurvey@awac.com>; assignments <assignments@lkkauto.com>
Cc: SUR <sur@lkkauto.com>; Goh, Stella <stella.goh@awac.com>
Subject: RE: OD survey assignment for SFH 4822E - DOA: 05/11/2018 Our Ref: NSV1800600/SG

Dear Shiau Chan,

Please proceed with repair at \$ 5,501.28 (inclusive of sup & check items).

Thank you.

Regards
Stella Goh
Claims Analyst
Claims Group
Global Markets

Allied World Assurance Company, Ltd
60 Anson Road #08-01 Mapletree Anson Singapore 079914
T: +65 6423 0857
F: +65 6423 0864
E: stella.goh@awac.com
W: www.awac.com

From: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>
Sent: Tuesday, 27 November 2018 5:02 PM
To: Motorsurvey <Motorsurvey@awac.com>; assignments <assignments@lkkauto.com>



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: NSV1800600/SG

Date: 28th November 2018

Our Ref: CS/AWA18021035/T1qb

The Motor Claims Department
Allied World Assurance Company Ltd

Attn: Peggy Chan

Dear Sirs/Mdm

PRELIMINARY ADVICE OF VEHICLE NO. SFH 4822E.


We thank you for the instruction on 21/11/2018.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 21/11/2018 at the premises of M/s YEW HOCK MOTOR and have the following to report:-

Workshop Estimate Amount	: <u>S\$7,152.78 (EST \$7,136.28 + SUPP 2 \$16.50).</u>
Revised Estimate Amount	: <u>S\$5,637.78 (INCLUSIVE OF SUPP 2 & CHECK ITEMS) ____.</u>
"Check" Items Amount	: <u>S\$ - ____.</u>
Market Value	: <u>S\$ 58,000.00 ____.</u>
Salvage Value	: <u>S\$ 41,129.00 ____.</u>
Nett Value	: <u>S\$ 16,871.00 ____.</u>

Description of Damage:

The vehicle sustained damages at the o/s body & undercarriage.



Comments/ Present Status:

Damages consistent.

Repair cost economical.

Days of repair: 8 days.

Kindly approve on check items & supplementary.

Yours faithfully

MOHD TAUFIKH
Automotive Assessor

Shiau Chan (LKKAUTO)

From: Goh, Stella <stella.goh@awac.com> on behalf of Motorsurvey <Motorsurvey@awac.com>
Sent: Wednesday, 28 November 2018 11:26 AM
To: Shiau Chan (LKKAUTO); Motorsurvey; assignments
Cc: SUR; Goh, Stella
Subject: RE: OD survey assignment for SFH 4822E - DOA: 05/11/2018 Our Ref: NSV1800600/SG

Dear Shiau Chan,

Please proceed with repair at \$ 5,501.28 (inclusive of sup & check items).

Thank you.

Regards
Stella Goh
Claims Analyst
Claims Group
Global Markets

Allied World Assurance Company, Ltd
60 Anson Road #08-01 Mapletree Anson Singapore 079914
T: +65 6423 0857
F: +65 6423 0864
E: stella.goh@awac.com
W: www.awac.com

From: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>
Sent: Tuesday, 27 November 2018 5:02 PM
To: Motorsurvey <Motorsurvey@awac.com>; assignments <assignments@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: OD survey assignment for SFH 4822E - DOA: 05/11/2018 Our Ref: NSV1800600/SG

Dear Stella,

Enclosed herewith 2nd preliminary advice of SFH 4822E.

Kindly approve on check items and supplementary.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Goh, Stella <stella.goh@awac.com> **On Behalf Of** Motorsurvey
Sent: Friday, 23 November 2018 9:11 AM
To: Motorsurvey <Motorsurvey@awac.com>; Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>; assignments <assignments@lkkauto.com>

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Tuesday, 27 November 2018 5:02 PM
To: Motorsurvey; assignments
Cc: SUR
Subject: RE: OD survey assignment for SFH 4822E - DOA: 05/11/2018 Our Ref: NSV1800600/SG
Attachments: CSAWA18021035T1qb(2).pdf; SFH4822 SUPP.pdf

Dear Stella,

Enclosed herewith 2nd preliminary advice of SFH 4822E.

Kindly approve on check items and supplementary.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Goh, Stella <stella.goh@awac.com> **On Behalf Of** Motorsurvey
Sent: Friday, 23 November 2018 9:11 AM
To: Motorsurvey <Motorsurvey@awac.com>; Shiau Chan (LKKAuto) <siewsc@lkkauto.com>; assignments <assignments@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: OD survey assignment for SFH 4822E - DOA: 05/11/2018 Our Ref: NSV1800600/SG

Dear Shiau Chan,

We refer to your email dated 22.11.2018.

Please authorize repair at \$ 3,698.78 with check items of \$ 1,866.00 to be verified.

Please also let us have the final cost of repair after verification.

Thank you.

Regards
Stella Goh
Claims Analyst
Claims Group
Global Markets

Allied World Assurance Company, Ltd
60 Anson Road #08-01 Mapletree Anson Singapore 079914
T: +65 6423 0857
F: +65 6423 0864
E: stella.goh@awac.com
W: www.awac.com



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: NSV1800600/SG

Date: 27th November 2018

Our Ref: CS/AWA18021035/T1qb

The Motor Claims Department
Allied World Assurance Company Ltd

Attn: Peggy Chan

Dear Sirs/Mdm


PRELIMINARY ADVICE OF VEHICLE NO. SFH 4822E

We thank you for the instruction on 21/11/2018.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 21/11/2018 at the premises of M/s YEW HOCK MOTOR and have the following to report:-

Workshop Estimate Amount	: <u>S\$7,136.28 (EST \$6,956.28 + SUPP \$180.00)</u>
Revised Estimate Amount	: <u>S\$5,501.28 (INCLUSIVE OF SUPP & CHECK ITEMS)</u>
"Check" Items Amount	: <u>S\$ 150.00</u>
Market Value	: <u>S\$ 58,000.00</u>
Salvage Value	: <u>S\$ 41,129.00</u>
Nett Value	: <u>S\$ 16,871.00</u>

Description of Damage:
The vehicle sustained damages at the o/s body & undercarriage.



Comments/ Present Status:
Damages consistent.
Repair cost economical.
Days of repair: 8 days.
Kindly approve on check items & supplementary.

Yours faithfully

MOHD TAUFIKH
Automotive Assessor

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Friday, 23 November 2018 9:32 AM
To: yhmotor@singnet.com.sg
Cc: SUR
Subject: VEHICLE SFH 4822E (DOA: 05/11/2018)

Dear Chris,

As spoken with you.

As instructed by our client, please proceed to repair the insured vehicle **SFH 4822E (Excess WAIVED)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Shiau Chan (LKKAUTO)

From: Goh, Stella <stella.goh@awac.com> on behalf of Motorsurvey <Motorsurvey@awac.com>
Sent: Friday, 23 November 2018 9:11 AM
To: Motorsurvey; Shiau Chan (LKKAUTO); assignments
Cc: SUR
Subject: RE: OD survey assignment for SFH 4822E - DOA: 05/11/2018 Our Ref: NSV1800600/SG

Dear Shiau Chan,

We refer to your email dated 22.11.2018.

Please authorize repair at \$ 3,698.78 with check items of \$ 1,866.00 to be verified.

Please also let us have the final cost of repair after verification.

Thank you.

Regards
Stella Goh
Claims Analyst
Claims Group
Global Markets

Allied World Assurance Company, Ltd
60 Anson Road #08-01 Mapletree Anson Singapore 079914
T: +65 6423 0857
F: +65 6423 0864
E: stella.goh@awac.com
W: www.awac.com

From: Goh, Stella **On Behalf Of** Motorsurvey
Sent: Friday, 23 November 2018 9:10 AM
To: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>; Motorsurvey <Motorsurvey@awac.com>; assignments <assignments@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: OD survey assignment for SFH 4822E - DOA: 05/11/2018 Our Ref: NSV1800600/SG

Dear Shiau Chan,

We refer to your email dated 22.11.2018.

Please authorize repair at \$ 3,698.78 with check items to be verified.

Please also let us have the final cost of repair after verification.

Thank you.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Thursday, 22 November 2018 11:49 AM
To: 'Motorsurvey'; assignments
Cc: SUR
Subject: RE: OD survey assignment for SFH 4822E - DOA: 05/11/2018 Our Ref: NSV1800600/SG
Attachments: SFH4822 photo.pdf; CSAWA18021035T1qb.pdf

Dear Peggy,

Enclosed herewith preliminary advice of SFH 4822E.

We have not authorise repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Wednesday, 21 November 2018 10:50 AM
To: 'Motorsurvey' <Motorsurvey@awac.com>; assignments <assignments@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: OD survey assignment for SFH 4822E - DOA: 05/11/2018 Our Ref: NSV1800600/SG

Dear Peggy,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Chan, Peggy [<mailto:Peggy.Chan@awac.com>] On Behalf Of Motorsurvey
Sent: Wednesday, 21 November, 2018 10:32 AM
To: assignments <assignments@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: OD survey assignment for SFH 4822E - DOA: 05/11/2018 Our Ref: NSV1800600/SG

The above captioned accident refers. Please conduct an "OWN DAMAGE" survey on the following:

Insured Vehicle	:	SFH 4822 E		
Policy Number	:	DVPPSB0549151801	Account Code:	C999SD2



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: NSV1800600/SG

Date: 22nd November 2018

Our Ref: CS/AWA18021035/T1qb

The Motor Claims Department
Allied World Assurance Company Ltd

Attn: Peggy Chan

Dear Sirs/Mdm

PRELIMINARY ADVICE OF VEHICLE NO. SFH 4822E


We thank you for the instruction on 21/11/2018.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 21/11/2018 at the premises of M/s YEW HOCK MOTOR and have the following to report:-

Workshop Estimate Amount	: S\$ <u>6,956.28</u>
Revised Estimate Amount	: S\$ <u>3,698.78</u>
"Check" Items Amount	: S\$ <u>1,866.00</u>
Market Value	: S\$ <u>58,000.00</u>
Salvage Value	: S\$ <u>41,129.00</u>
Nett Value	: S\$ <u>16,871.00</u>

Description of Damage:

The vehicle sustained damages at the o/s body & undercarriage.



Comments/ Present Status:

Damages consistent.

Repair cost economical.

Days of repair: 8 days.

We have NOT authorise repair.

Yours faithfully

MOHD TAUFIKH
Automotive Assessor

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	5237Z
Vehicle Details	
Vehicle No.:	SFH4822E
Vehicle to be Exported:	No
Intended Deregistration Date:	22 Nov 2018
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA2 SEDAN 1.5L SP.6EAT
Primary Colour:	Grey
Manufacturing Year:	2016
Engine No.:	P520345616
Chassis No.:	MM6DL2SAAGW191584
Maximum Power Output:	85.0 kW (113 bhp)
Open Market Value:	\$14,364.00
Original Registration Date:	21 Apr 2016
First Registration Date:	21 Apr 2016
Transfer Count:	0
Actual ARF Paid:	\$9,364.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	20 Apr 2026
PARF Rebate Amount:	\$7,023.00
Intended COE Rebate Details	
COE Expiry Date:	20 Apr 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$46,009.00
COE Rebate Amount:	\$34,106.00
Total Rebate Amount:	\$41,129.00

The information contained herein is correct as at 22 Nov 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	07/11/2018 13:22
Date Of Accident	05/11/2018 17:40
Exact Location Of Accident	KPE TUNNEL EXIT PIE/TUAS
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SFH4822E
Insured/Policyholder	
Name Of Registered Owner	TAN CHYE HIN PATRICK PETER
NRIC No	S1465237Z
Email Address	PTANCH@YAHOO.COM.SG
Mobile Phone No	(LOCAL) +65-98331670
Alternative Phone No	OFFICE-98331670

Vehicle Particulars

Manufacturer	MAZDA
Model	MAZDA2
Exact Purpose for which vehicle was being used at time of accident	PRIVATE

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	ALLIED WORLD ASSURANCE COMPANY, LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DVPPSB0549151801
Cover Note Number	

Driver

Name of Driver	TAN CHYE HIN PATRICK PETER
NRIC No	S1465237Z
Date Of Birth	02/08/1954
Occupation	INDOOR
Date Of Driving Pass	28/10/1977
Driving Experience	41 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98331670
Fax Number	
Contact Number	OFFICE-98331670
E-Mail Address	PTANCH@YAHOO.COM.SG

Address	BLK 94E BEDOK NORTH AVENUE 4 #03-1433
Postcode	464094
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
Insurance Company of Driver's Own Vehicle	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	YES
Foreign Vehicle Registration Number	JRX2465 (COMMERCIAL VEHICLE)
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
POLICE STATION NAME [OTHER]	TRAFFIC POLICE DIVISION HQ
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO POLICE REPORT - T/20181105/2177 LODGED AT TRAFFIC POLICE DIVISION HQ. ON 05/11/2018 AT ABOUT 1740HRS, I WAS DRIVING MY VEHICLE SFH4822E ALONG KPE EXITING TOWARDS PIE TUAS WHEN I MET UP WITH AN ACCIDENT INVOLVING ANOTHER MALAYSIAN TRAILER, JRX2465. I WAS ON THE EXTREME LEFT LANE WANTED TO EXIT OUT OF THE TUNNEL AND AS THE EXIT IS ONLY A SINGLE LANE THUS I MOVED INTO THE EXITING LANE WHEN I NOTICED THERE WAS NO ONCOMING VEHICLE INTO MY LANE. HOWEVER WHEN I WAS DRIVING IN THE EXITING LANE, THERE WAS THIS TRAILER COMING FROM BEHIND TOWARDS MY RIGHT AND INCREASING ITS SPEED THUS CAUSING A SIDE SWIPE AGAINST MY RIGHT SIDE OF MY CAR. I WISHED TO STATE THAT AFTER THE COLLISION, BOTH PARTIES STOPPED THE VEHICLE AND CAME OUT OF THE VEHICLE TO EXCHANGE PARTICULARS. THERE WAS NOBODY INJURED DURING THE ACCIDENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	PENDING VIDEO FROM INSURED
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	JRX2465
Vehicle Make/Model/Colour	UNKNOWN
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	ASAHI LOGISTIC SDN BHD
NRIC/Passport Number	
Contact Number	0162710168

SKETCH PLAN

[illegible]

4574

Ice Cream 1/40

$$\frac{d}{dt} \left(\frac{1}{\sqrt{1 - v^2/c^2}} \right) = \frac{v}{c^2} \frac{dv}{dt}$$

Along KPE exiting PIE towards TuoS.

A. SFH482F

B. JRX 2465

YEW HOCK MOTOR

Reg. no: 251827/00C

Blk 9006 Tampines Street 93 #01-210 Singapore 528840

Tel: 67472384 Fax: 67482758

GST Reg. No: MX-0655172-L0

EMAIL:

motorsurvey@awac.com

MOTOR CLAIMS DEPARTMENT

M/S ALLIED WORLD ASSURANCE COMPANY LIMITED

60 ANSON ROAD

#08-01 MAPLETREE ANSON

SINGAPORE 079914

DATE: 20/11/2018

LKK (Catherine) called on
21/11/2018 @ 10.47AM

DEAR SIR/MADAM,

RE : ACCIDENT REPAIR ON : SFH 4822 E
INSURED : TAN CHYE HIN PATRICK PETER
DATE OF ACCIDENT : 5/11/2018
POLICY NUMBER : DVPPSB0549151801 (TAMPINES)

APPENDED BELOW ARE THE ESTIMATED COST OF REPAIR & PARTS TO BE REPLACED:-

REPLACEMENT OF PARTS

SS

1 PC	FRONT DOOR (RH)	520.00 Rx
1 PC	FRONT DOOR LOCK	85.00 x mm
1 PC	FRONT DOOR OUTER HANDLE	40.00 cut
1 PC	FRONT DOOR INNER RUBBER	50.00 x mm
1 PC	FRONT DOOR OUTER RUBBER	65.00 x mm
1 PC	REAR DOOR	520.00 bt
1 PC	REAR DOOR LOCK	85.00 x mm
1 PC	REAR DOOR OUTER HANDLE	40.00 cut
1 PC	REAR DOOR INNER RUBBER	55.00 new
1 PC	REAR DOOR OUTER RUBBER	65.00 new
1 PC	REAR DOOR TOP HINGE	60.00 ? bt
1 PC	REAR DOOR LOWER HINGE	55.00 ? bt
1 PC	ROCKER PANEL	345.00 Rx
1 PC	REAR WINDSCREEN MOULDING	38.00 new
1 PC	REAR FENDER	420.00 bt
1 PC	REAR FENDER COWLING	35.00 ? cut
1 PC	REAR BUMPER	380.00 de
1 PC	REAR BUMPER SIDE BRACKET	18.00 new
6 PCS	REAR BUMPER CLIPS @\$2.30	13.80 new
1 PC	REAR WHEEL RIM LOGO	15.00 ? adv

YEW HOCK MOTOR

Reg. no: 251827/00C

Blk 9006 Tampines Street 93 #01-210 Singapore 528840

Tel: 67472384 Fax: 67482758

GST Reg. No: MX-0655172-L0

1 PC	REAR ABSORBER	140.00	? ba ✓
1 PC	REAR AXLE	950.00	? ba ✓
1 PC	REAR WHEEL BEARING WITH HUB	220.00	? dis ✓
		<hr/> 4,214.80	
	ADD 10%	421.48	
		<hr/> 4,636.28	

1 PC	REAR WINDSCREEN SEALANT	S/NETT	40.00	na ✓
1 PC	REAR WHEEL RIM	S/NETT	300.00	cut ✓

TO REMOVE AND REFIX CUSHION AND LINING.
TO REMOVE AND REFIX REAR UNDERCARRIAGE.
LABOUR CHARGES TO REMOVE AND REPLACE ALL
DAMAGED PARTS.
SPRAY PAINTING ON AFFECTED AREAS.
TOTAL BEFORE GST :

80.00	60.
150.00	120? photo ✓
850.00	750 ✓
900.00	800 ✓
<hr/> 6,956.28	

7152.78

YOURS FAITHFULLY,



 22/11/18

Taufik 97495749
'WP'

21/11/18 @ 345pm.

8 days

Ex: Waived.
part by part.
Resurvey before repair.

sure@lklauto.com.

Not Authorise.

Attn: Ms Shiau Chan
Fax: 62564315

YEW HOCK MOTOR

Reg. no: 251827/00C

Blk 9006 Tampines Street 93 #01-210 Singapore 528840

Tel: 67472384 Fax: 67482758

GST Reg. No: MX-0655172-L0

MOTOR CLAIMS DEPARTMENT

M/S ALLIED WORLD ASSURANCE COMPANY LIMITED

60 ANSON ROAD

#08-01 MAPLETREE ANSON

SINGAPORE 079914

DATE: 23/11/2018

DEAR SIR/MADAM,

(SUPPLEMENTARY)

RE	ACCIDENT REPAIR ON	:	SFH 4822 E
	INSURED	:	TAN CHYE HIN PATRICK PETER
	DATE OF ACCIDENT	:	5/11/2018
	POLICY NUMBER	:	DVPPSB0549151801 (TAMPINES)

APPENDED BELOW ARE THE ESTIMATED COST OF REPAIR & PARTS TO BE REPLACED:-

REPLACEMENT OF PARTS

SS

1 PC	TYRE	S/NETT	80%	180.00	cut
------	------	--------	-----	--------	-----

YOURS FAITHFULLY



Attn: Ms Shian Cha

Fax: 625 64315

As spoken. Tce.

YEW HOCK MOTOR

Reg. no: 251827/00C

Blk 9006 Tampines Street 93 #01-210 Singapore 528840

Tel: 67472384 Fax: 67482758

GST Reg. No: MX-0655172-L0

MOTOR CLAIMS DEPARTMENT**M/S ALLIED WORLD ASSURANCE COMPANY LIMITED**

60 ANSON ROAD

#08-01 MAPLETREE ANSON

SINGAPORE 079914

DATE: 28/11/2018

DEAR SIR/MADAM,

(SUPPLEMENTARY 2)

RE :	ACCIDENT REPAIR ON	:	SFH 4822 E
	INSURED	:	TAN CHYE HIN PATRICK PETER
	DATE OF ACCIDENT	:	5/11/2018
	POLICY NUMBER	:	DVPPSB0549151801 (TAMPINES)

APPENDED BELOW ARE THE ESTIMATED COST OF REPAIR & PARTS TO BE REPLACED:-**REPLACEMENT OF PARTS****SS**

1 PC	REAR DOOR STICKER		15.00
		ADD 10%	1.50
	TOTAL BEFORE GST :		<u>16.50</u>

YOURS FAITHFULLY



YEW HOCK MOTOR

Reg. no: 251827/00C
Blk 9006 Tampines Street 93 #01-210 Singapore 528840
Tel: 67472384 Fax: 67482758
GST Reg. No: MX-0655172-L0

Arrange resurvey
check items on
23/11/18 @ 11.18AM
Mirta

MOTOR CLAIMS DEPARTMENT

M/S ALLIED WORLD ASSURANCE COMPANY LIMITED
60 ANSON ROAD
#08-01 MAPLETREE ANSON
SINGAPORE 079914

EMAIL:

motorsurvey@awac.com

Authorise / 22/11/18.

DATE: 20/11/2018

LKK (Catherine) called on
21/11/2018 @ 10.47AM.

DEAR SIR/MADAM,

RE : ACCIDENT REPAIR ON : SFH 4822 E
INSURED : TAN CHYE HIN PATRICK PETER
DATE OF ACCIDENT : 5/11/2018
POLICY NUMBER : DVPPSB0549151801 (TAMPINES)

APPENDED BELOW ARE THE ESTIMATED COST OF REPAIR & PARTS TO BE REPLACED:-

REPLACEMENT OF PARTS

SS

1 PC	FRONT DOOR (RH)	520.00 Ryo
1 PC	FRONT DOOR LOCK	85.00 x
1 PC	FRONT DOOR OUTER HANDLE	40.00 cut
1 PC	FRONT DOOR INNER RUBBER	50.00 x BFFX
1 PC	FRONT DOOR OUTER RUBBER	65.00 x BFFX
1 PC	REAR DOOR	520.00 bt
1 PC	REAR DOOR LOCK	85.00 ? x
1 PC	REAR DOOR OUTER HANDLE	40.00 cut
1 PC	REAR DOOR INNER RUBBER	55.00 rel
1 PC	REAR DOOR OUTER RUBBER	65.00 mlt
1 PC	REAR DOOR TOP HINGE	60.00 ? BFW
1 PC	REAR DOOR LOWER HINGE	55.00 ? BFW
1 PC	ROCKER PANEL	345.00 Ryo
1 PC	REAR WINDSCREEN MOULDING	38.00 rel
1 PC	REAR FENDER	420.00 bt
1 PC	REAR FENDER COWLING	35.00 ? cut
1 PC	REAR BUMPER	380.00 de
1 PC	REAR BUMPER SIDE BRACKET	18.00 rel
6 PCS	REAR BUMPER CLIPS @\$2.30	13.80 rel
1 PC	REAR WHEEL RIM LOGO	15.00 ? cut

Supplementary :

Type #180/- s/nett ✓ cut

YEW HOCK MOTOR

Reg. no: 251827/00C

Blk 9006 Tampines Street 93 #01-210 Singapore 528840

Tel: 67472384 Fax: 67482758

GST Reg. No: MX-0655172-L0

1 PC	REAR ABSORBER		140.00	? BT ✓
1 PC	REAR AXLE		950.00	? BT ✓
1 PC	REAR WHEEL BEARING WITH HUB		220.00	? cut ✓
			4,214.80	
			ADD 10%	
			421.48	
			4,636.28	
1 PC	REAR WINDSCREEN SEALANT	S/NETT	40.00	new ✓
1 PC	REAR WHEEL RIM	S/NETT	300.00	cut ✓
			80.00	60 ✓
			150.00	120? ✓
			850.00	750 ✓
			900.00	800 ✓
			6,956.28	

YOURS FAITHFULLY,



Tan Jiah 97495749

WP

21/11/18 @ 345pm.

8 days

Ex: Waived.
part by part.

Reserving before repair.

sur@hkauto.com

Not Authorise.

TEO HIN TYRES

11 KAKI BUKIT ROAD 1
#01-01 EUNOS TECHNOLINK
SINGAPORE 415939
TEL:67455711

Work Order: R003326
Company: YEW HOCK MOTOR
License: SFH 4822 E
Date: 22.11.18 16:20

Mazda : Mazda3 : 2013- (BM) : except Rough Road Suspension

Front : Left

Actual	Before	Specified Range
		-1°12' 0°48'
4°53'		5°29' 7°29'
-0°48'		-0°05' 0°16'
12°45'		
12°28'		

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
		-1°12' 0°48'
5°18'		5°29' 7°29'
0°34'		-0°05' 0°16'
15°33'		
14°58'		

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	Before	Specified Range
		-1°30' 1°30'
		-1°30' 1°30'
-2°48'		
-0°14'		-0°09' 0°31'

Rear : Left

Actual	Before	Specified Range
		-1°59' 0°01'
		-0°05' 0°15'

Camber
Toe

Rear : Right

Actual	Before	Specified Range
-2°26'		-1°59' 0°01'
-1°35'		-0°05' 0°15'

Rear

Cross Camber
Total Toe
Thrust Angle

Actual	Before	Specified Range
		-1°30' 1°30'
-1°22'		-0°10' 0°30'
0°54'		-0°48' 0°48'

YEW HOCK MOTOR

Reg. no: 251827/00C
Blk 9006 Tampines Street 93 #01-210 Singapore 528840
Tel: 67472384 Fax: 67482758
GST Reg. No: MX-0655172-L0

① Arrange resurvey
check items on
23/11/18 @ 11:18AM
Mirita

OK Mr Lim

② Arrange resurvey B4/painting on 28/11/18
OK @ 1pm 28/11/18 @ 9:05AM
Mirita

EMAIL: motorsurvey@awac.com

MOTOR CLAIMS DEPARTMENT

M/S ALLIED WORLD ASSURANCE COMPANY LIMITED
60 ANSON ROAD
#08-01 MAPLETREE ANSON
SINGAPORE 079914

Authorse / 22/11/18.

DATE: 20/11/2018

LKK (Catherine) called on
21/11/2018 @ 10:47AM

DEAR SIR/MADAM,

RE : ACCIDENT REPAIR ON : SFH 4822 E
INSURED : TAN CHYE HIN PATRICK PETER
DATE OF ACCIDENT : 5/11/2018
POLICY NUMBER : DVPPSB0549151801 (TAMPINES)

APPENDED BELOW ARE THE ESTIMATED COST OF REPAIR & PARTS TO BE REPLACED:-

REPLACEMENT OF PARTS

SS

1 PC	FRONT DOOR (RH)	520.00 Rx
1 PC	FRONT DOOR LOCK	85.00 X
1 PC	FRONT DOOR OUTER HANDLE	40.00 cut
1 PC	FRONT DOOR INNER RUBBER	50.00 Rx
1 PC	FRONT DOOR OUTER RUBBER	65.00 Rx
1 PC	REAR DOOR	520.00 bt
1 PC	REAR DOOR LOCK	85.00 Rx
1 PC	REAR DOOR OUTER HANDLE	40.00 cut
1 PC	REAR DOOR INNER RUBBER	55.00 net
1 PC	REAR DOOR OUTER RUBBER	65.00 net
1 PC	REAR DOOR TOP HINGE	60.00 ? BT
1 PC	REAR DOOR LOWER HINGE	55.00 ? BT
1 PC	ROCKER PANEL	345.00 Rx
1 PC	REAR WINDSCREEN MOULDING	38.00 net
1 PC	REAR FENDER	420.00 bt
1 PC	REAR FENDER COWLING	35.00 ? CATV
1 PC	REAR BUMPER	380.00 de
1 PC	REAR BUMPER SIDE BRACKET	18.00 net
6 PCS	REAR BUMPER CLIPS @\$2.30	13.80 net
1 PC	REAR WHEEL RIM LOGO	15.00 ? CATV

Supplementary :

Tyre #180/- s/nett ✓ cut

Attn: Ms Shiau Chan

Fax: 625 64315

As spoken. Tce.

YEW HOCK MOTOR

Reg. no: 251827/00C
 Blk 9006 Tampines Street 93 #01-210 Singapore 528840
 Tel: 67472384 Fax: 67482758
 GST Reg. No: MX-0655172-L0

MOTOR CLAIMS DEPARTMENT
M/S ALLIED WORLD ASSURANCE COMPANY LIMITED
 60 ANSON ROAD
 #08-01 MAPLETREE ANSON
 SINGAPORE 079914

DATE: 28/11/2018

DEAR SIR/MADAM,

(SUPPLEMENTARY 2)

RE :	ACCIDENT REPAIR ON	:	SFH 4822 E
	INSURED	:	TAN CHYE HIN PATRICK PETER
	DATE OF ACCIDENT	:	5/11/2018
	POLICY NUMBER	:	DVPPSB0549151801 (TAMPINES)

APPENDED BELOW ARE THE ESTIMATED COST OF REPAIR & PARTS TO BE REPLACED:-

<u>REPLACEMENT OF PARTS</u>		SS
1 PC	REAR DOOR STICKER	15.00
	ADD 10%	1.50
	TOTAL BEFORE GST :	<u>16.50</u>

YOURS FAITHFULLY



3,079.80
 307.98
 3,387.78
 s/nest 520.00
 LC 1,730.00
 # 5,637.78

Attn: Ms Shiau Chan
Fax: 62564315

YEW HOCK MOTOR

Reg. no: 251827/00C
Blk 9006 Tampines Street 93 #01-210 Singapore 528840
Tel: 67472384 Fax: 67482758
GST Reg. No: MX-0655172-L0

MOTOR CLAIMS DEPARTMENT

M/S ALLIED WORLD ASSURANCE COMPANY LIMITED

60 ANSON ROAD

#08-01 MAPLETREE ANSON

SINGAPORE 079914

DATE: 23/11/2018

DEAR SIR/MADAM,

(SUPPLEMENTARY)

RE :	ACCIDENT REPAIR ON	:	SFH 4822 E
	INSURED	:	TAN CHYE HIN PATRICK PETER
	DATE OF ACCIDENT	:	5/11/2018
	POLICY NUMBER	:	DVPPSB0549151801 (TAMPINES)

APPENDED BELOW ARE THE ESTIMATED COST OF REPAIR & PARTS TO BE REPLACED:-

REPLACEMENT OF PARTS

SS

1 PC	TYRE	S/NETT	180.00
------	------	--------	--------

YOURS FAITHFULLY





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ALLIED WORLD ASSURANCE COMPANY LTD		Ref : CS/AWA18021035/T1qbe2		
(SINGAPORE BRANCH) 60 ANSON ROAD #08-01 (8th FLOOR) MAPLETREE ANSON SINGAPORE 079914		Date : 20-12-2018		
		Code : AWA		
1. Policy Particulars :- OWN DAMAGE				
Insured Veh.		Veh. Inspected	SFH 4822E	
Policy No.	DVPPSB0549151801	Coverage (\$)	0.00	
Claim No.	NSV1800600/SG	Excess (\$)	0.00	
Assign From	PEGGY CHAN	Assign Date	21/11/2018	
2. Vehicle Particulars & Condition				
Make & Model	MAZDA 2	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	MM6DL2SAAGW191584	Colour	BRONZE	
Odometer	48814	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/65 R15	DUNLOP	6 mm	
L/H Front Tyre	185/65 R15	DUNLOP	6 mm	
R/H Rear Tyre	185/65 R15	DUNLOP	6 mm	
L/H Rear Tyre	185/65 R15	DUNLOP	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY AND UNDERCARRIAGE PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	05/11/2018	Inspection Date	21/11/2018	
Survey held at	BLK 9006 TAMPINES ST 93 #01-210			
Repairer	YEW HOCK MOTOR			
5a. Remarks				
A)THE MARKET VALUE IS S\$58,000.00(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		8 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SFH 4822E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT DOOR (RH)	TO REPAIR SEE LABOUR	520.00	-
1	FRONT DOOR LOCK	NOT NECESSARY	85.00	-
1	FRONT DOOR OUTER HANDLE	CUT	40.00	40.00
1	FRONT DOOR INNER RUBBER	NOT NECESSARY	50.00	-
1	FRONT DOOR OUTER RUBBER	NOT NECESSARY	65.00	-
1	REAR DOOR	BENT	520.00	520.00
1	REAR DOOR LOCK	NOT NECESSARY	85.00	-
1	REAR DOOR OUTER HANDLE	CUT	40.00	40.00
1	REAR DOOR INNER RUBBER	NECESSARY	55.00	55.00
1	REAR DOOR OUTER RUBBER	NECESSARY	65.00	65.00
1	REAR DOOR TOP HINGE	BENT	60.00	60.00
1	REAR DOOR LOWER HINGE	BENT	55.00	55.00
1	ROCKER PANEL	TO REPAIR SEE LABOUR	345.00	-
1	REAR WINDSCREEN MOULDING	NECESSARY	38.00	38.00
1	REAR FENDER	BENT	420.00	420.00
1	REAR FENDER COWLING	CUT	35.00	35.00
1	REAR BUMPER	DEFORMED	380.00	380.00
1	REAR BUMPER SIDE BRACKET	NECESSARY	18.00	18.00
6	REAR BUMPER CLIPS @\$2.30	NECESSARY	13.80	13.80
1	REAR WHEEL RIM LOGO	CUT	15.00	15.00
1	REAR ABSORBER	BENT	140.00	140.00
1	REAR AXLE	BENT	950.00	950.00
1	REAR WHEEL BEARING WITH HUB	DISTORTED	220.00	220.00
1	REAR DOOR STICKER (ADDITIONAL)	NECESSARY	15.00	15.00
	COST PLUS 10%		422.98	307.98
			4,652.78	3,387.78
SPECIAL NETT ITEMS				
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	40.00	40.00
1	REAR WHEEL RIM (SN)	CUT	300.00	300.00
1	TYRE (SN) (80%) (ADDITIONAL)	CUT	180.00	144.00
			520.00	484.00

Report Ref No. CS/AWA18021035/T1qbe2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TO REMOVE AND REFIX CUSHION AND LINING.		80.00	60.00
	TO REMOVE AND REFIX REAR UNDERCARRIAGE.		150.00	120.00
	LABOUR CHARGES TO REMOVE AND REPLACE ALL DAMAGED PARTS. INCLUSIVE OF THE REPAIR OF FRONT DOOR (RH) AND ROCKER PANEL.		850.00	750.00
	SPRAY PAINTING ON AFFECTED AREAS.		900.00	800.00
			1,980.00	1,730.00
	GRAND TOTAL		7,152.78	5,601.78
RECOMMENDED COST OF REPAIRS				5,601.78

Report Ref No. CS/AWA18021035/T1qbe2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.