

Massive Trading & Auto

Mailing address : Blk 225 #07-579 Ang Mo Kio Ave 1 Singapore 560225
H/P 91082728

Fax : 64816131

India International Insurance Pte Ltd
64 Cecil Street
#05-01 Singapore 048711

Vehicle No : SJD 6527 T
Make : Honda Stream
Year : 2009

Not Authorized
6/1/09 & ?
Resurvey After Paint
8 days

Oty	Description	Unit Price	Amount
-----	-------------	------------	--------

Estimate Cost Of Repair

1 pc	Rear tail-gate assy			<i>By</i>	\$1,250.70	<i>✓</i>
1 pc	Rear tail-gate outer handle			<i>By</i>	\$220.10	<i>X</i>
1 pc	Rear tail-gate inner lock			<i>By</i>	\$255.30	<i>✓</i>
1 pc	Rear tail-gate glass moulding			<i>By</i>	\$75.10	<i>✓</i>
1 pc	Rear tail-gate inner trim board			<i>By</i>	\$285.70	<i>?</i>
1 pc	Rear tail-gate emblem " Stream "			<i>By</i>	\$48.20	<i>✓</i>
1 pc	Rear tail-gate emblem " H "			<i>By</i>	\$35.10	<i>X</i>
2 pcs	Rear fender inner trim board	<i>CM</i>	\$487.10		\$974.20	<i>✓</i>
2 pcs	Rear tail-lamp assy	<i>O/S by</i>	\$485.70		\$971.40	<i>✓</i>
1 pc	Rear end panel			<i>By</i>	\$550.10	<i>✓</i>
1 pc	Rear end panel inner garnish			<i>By O/S</i>	\$185.70	<i>✓</i>
1 pc	Rear end panel inner garnish lower cover			<i>By CM</i>	\$135.60	<i>✓</i>
1 pc	Rear boot rubber				\$165.80	<i>?</i>
2 pcs	Rear bumper			<i>By CM</i>	\$950.70	<i>✓</i>
1 pc	Rear bumper side retainer	<i>O/S O/S</i>	\$65.20		\$130.40	<i>✓</i>
2 pcs	Rear tow cover			<i>By</i>	\$25.70	<i>✓</i>
1 pc	Rear bumper bracket		\$48.60		\$97.20	<i>?</i>
1 pc	Rear spare tyre floor panel			<i>By 1/2 by</i>	\$855.60	<i>✓</i>
1 pc	Rear o/s spare tyre cover board			<i>By</i>	\$355.60	<i>X</i>
1 pc	Rear spare tool sponge			<i>CM</i>	\$192.50	<i>X</i>
1 pc	Rear exhaust silencer				\$846.70	<i>?</i>
					\$8,607.40	
					Less 20 %	\$1,721.48
						\$6,885.92

S Nett

1 pc	Rear reverse sensor			<i>By</i>	\$200.00	<i>✓</i>
1 pc	Rear windscreen sealant			<i>By</i>	\$55.00	<i>40% by</i>
1 pc	Rear no plate			<i>By</i>	\$45.00	<i>✓</i>
10 pcs	Rear bumper clip			<i>By</i>	\$25.00	<i>✓</i>
1 pc	Rear floor panel black insulator			<i>By</i>	\$200.00	<i>Join</i>
					\$525.00	
					balance c/f	\$7,410.92

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SJD 6527 T

balance b/f \$7,410.92

Labour Charges

Remove/renew the above parts including knocking, welding & cutting.	\$1,800.00	1200/
To putty & spray paint on accident affected portion.	\$1,400.00	900/
Check/reconnect wiring.	\$40.00	20/
To spray anti rust on accident affected portion.	\$180.00	90/
Remove/renew rear windscreen glass	\$100.00	✓
Remove/refit rear boot upholstery to facilitate repair	\$120.00	100/
Remove/renew rear exhaust silencer	\$120.00	60/
Total	<u>\$11,170.92</u>	